

940552
 +0553
 +0554
~~0554~~

1962 RAMBLER AMERICAN.

NAME ROBERT.	SHIP TO
ADDRESS	ADDRESS
CITY, STATE, ZIP	CITY, STATE, ZIP

ORDER NUMBER	DEPARTMENT	SALESPERSON	WHEN SHIP	TERMS	HOW SHIP	DATE / /
--------------	------------	-------------	-----------	-------	----------	-------------

QUANTITY	DESCRIPTION	PRICE	AMOUNT
	REPLACE FRONT WHEEL CYLINDERS, SECURE BRAKE HOSES PROPERLY, REPACK WHEEL BEARINGS, GREASE FRONT SUSPENSION POINTS		
	REPLACE FRONT SHOCK ABSORBERS, REMOVE REAR SHOCK ABSORBERS, DRAIN TRANS FLUID		
	DRAIN ENGINE OIL, DISCONNECT REAR END HOUSING	5 HRS	125 —
	REMOVE REAR END AND DRIVE SHAFT, REPLACE TRANSMISSION TAIL SHAFT SEAL, REINSTALL REAR END, REPLACE REAR SHOCK ABSORBERS, REPLACE REAR BRAKE HOSE, CHECK REAR END OIL, REMOVE OIL PAN CROSS BRACE, REMOVE OIL PAN, REPLACE FUEL FILTER AT TANK	5 HRS	125 —
	CLEAN, REPAIR, PAINT OIL PAN, REPLACE TRANS MOUNTS	4 HRS	100 —
	RE FIT OIL PAN AND OIL PAN CROSS BRACE, REPLACE REAR WHEEL CYLINDERS, REPLACE REAR BRAKE SHOES, ADJUST PARK BRAKE	4 HRS	100 —
	REMOVE BRAKE MASTER CYLINDER, STRIP, HONE + RE BUILD, REPLACE BRAKE MASTER CYLINDER		
	REPLACE GENERATOR BELT, REPLACE OIL FILTER, REPLACE WINDSHIELD WIPERS, FILL ENGINE WITH 20/50 OIL	3 HRS	75 —

BUYER:

940553

+0552
+0554

1962 RAMBLER AMERICAN.

NAME ROBERT	SHIP TO
ADDRESS	ADDRESS
CITY, STATE, ZIP	CITY, STATE, ZIP

ORDER NUMBER	DEPARTMENT	SALESPERSON	WHEN SHIP	TERMS	HOW SHIP	DATE / /
--------------	------------	-------------	-----------	-------	----------	-------------

QUANTITY	DESCRIPTION	PRICE	AMOUNT
	REPLACE POWER STEERING BELT, REPLACE RAD CAP, REMOVE CARBURATOR, STRIP, CLEAN + REPLACE ACCELERATOR PUMP, REPLACE CARB. REPAIR HIGH BEAM WARNING LAMP REPAIR TURN SIGNAL WARNING LAMPS	2 HRS	50 —
	REPLACE FRONT MOTOR MOUNTS, SECURE FRONT VALANCE BLEED BRAKES, ADJUST MASTER CYLINDER PUSH ROD. ADJUST CAMBER + CASTER ANGLE BY EYE (DRIVERS SIDE CAMBER WAS SET WAY WRONG)	3 HRS	75 —
	REMOVE TRANS PAN CLEAN + PAINT, REPLACE TRANS PAN GASKET, RE FILL TRANS WITH FLUID, REPLACE FUEL HOSE FROM PUMP TO CARB. REPLACE THERMOSTAT + GASKET REPLACE HEATER HOSE, GET TOP MOTOR TO WORK	4 HRS	100 —
	FILL + BLEED CONVERTIBLE TOP MOTOR, LUBE ALL TOP JOINTS, REPAIR BROKEN TOP FRAME	2 HRS	50 —
	TOTAL LABOUR CONTINUE FOR PARTS		800 —

BUYER:

940554
 + 0553
 + 0552

1962 RAMBLER AMERICAN.

NAME ROBERT	SHIP TO
ADDRESS	ADDRESS
CITY, STATE, ZIP	CITY, STATE, ZIP

ORDER NUMBER	DEPARTMENT	SALESPERSON	WHEN SHIP	TERMS	HOW SHIP	DATE
--------------	------------	-------------	-----------	-------	----------	------

QUANTITY	DESCRIPTION	PRICE	AMOUNT
	TOTAL LABELS		800 -
	PARTS:		
10/9	O'REILLY AUTO PARTS	58-49	
"	AUTO ZONE	187-95	
10/14	O'REILLY AUTO PARTS	13-53	
10/15	NAPA AUTO PARTS	49-98	
"	AUTO ZONE	19-49	
10/17	MAKCO TRANSMISSION PARTS	13-37	
10/18	NAPA AUTO PARTS	17-12	
	TOTAL PARTS	360-13	360 13
	11-7-13	TOTAL TO PAY/OWING	\$1160 13
		THANK YOU	

BUYER:

415-382-0368

Terminal ID : 01002233

02/25/15

12:07 PM

VISA

SALE
BATCH #: 475REF#: 521
AUTH #: 01553G

AMOUNT

\$283.90

APPROVED

CUSTOMER COPY

Novato, CA 94949-0000

Shop Phone: (415) 382-0368

Fax: (415) 382-9468

Email: GenuineMotors@sbcglobal.net

Estimate Ref #13,735

Date Printed: 02/25/2015

Printed Time: 12:08 pm

BAR # AM242762

COMPLETE AUTOMOTIVE REPAIR

Time Promised:

1962 AMERICAN MOTORS AMERICAN 400 L6 3.2L 3206cc 196CID CARB GAS N A

VIN: B408103

License: 2AEM306

Unit #: Convertibl

Mileage In: 43,131

Mileage Out: 43,131

DOM: n/a

Date Written: 02/19/2015

Written By: Jeff Zell

Save Old Parts: No

Job Name	Description	Technician	Qty	List	Extended
Trans Leak	Check & advise for transmission fluid leak.				
Labor Rate 1	Work Requested - Check & advise for transmission fluid leak.		0.50	115.00	57.50
	Work Performed - Racked and inspected found P/S ram, trans speedo seal and shift shaft seal leaking.				
Labor Rate 1	Work Requested - Reseal Speedo Housing		0.80	115.00	92.00
	Work Performed - Removed and resealed speedo gear housing, cleaned area and rechecked OK. Slight leak at shift shaft seal				
Part	seal		1.00	0.00	0.00
Part PC	Parts Cleaner		1.00	4.95	4.95
				Job Total:	154.45
Power Steering Leak	Power Steering Leak				
Labor Rate 1	Work Requested - Power Steering Leak		1.00	115.00	115.00
	Work Performed - Removed p/s fluid, installed p/s conditioner and stop leak, operated and road tested for 1 hour as per instructions .				
Part OBX00232	P/S Stop Leak		1.00	12.85	12.85
				Job Total:	127.85

Recommendations

Job Name	Description	Recommended Date	Mileage
Parts		2/23/2015 12:00:00AM	3,000

Payment Date	Type	Method	Amount
2/25/2015	Credit	Visa	283.90
Payment Totals:			\$283.90

Parts: \$17.80
 Labor: \$264.50
 Sublet: \$0.00
 Misc: \$0.00

Hazmat: \$0.00
 Supplies: \$0.00

Tax Total: \$1.60

Invoice Total: **\$283.90**

Less Paid: 283.90

Balance Due: \$0.00

Thank you for your business!

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

Date _____ Time _____

Terminal ID : 01002233

11/25/14 4:39 PM

VISA
*****7979

SALE
BATCH #: 418

REF#: 186
AUTH #: 007346

AMOUNT \$547.80

Novato, CA 94949-0000
Shop Phone: (415) 382-0368
Fax: (415) 382-9468
Email: GenuineMotors@sbcglobal.net

Estimate Ref #13,083
Date Printed: 11/25/2014
Printed Time: 4:41 pm
BAR # AM242762

COMPLETE AUTOMOTIVE REPAIR

Time Promised:

1962 AMERICAN MOTORS AMERICAN 400 L6 3.2L 3206cc 196CID CARB GAS N A

VIN: B408103

License: 2AEM306

Unit #: Convertibl

Mileage In: 43,127

Mileage Out: 43,127

DOM: n/a

Date Written: 10/31/2014

Written By: Jeff Zell

Save Old Parts: No

APPROVED

CUSTOMER COPY

Cell: (415) 382-0368 Email: Robert@GenuineMotors.com

Job Name	Description	Technician	Qty	List	Extended
Complete Inspection	Complete inspection.				
Labor Rate 1	Work Requested - Complete vehicle inspection to include the following: - All interior & exterior lights - Suspension mounting boots - Steering operation, tie rods & steering gear - All fluid levels & quality - Engine & transmission leaks - Brakes remaining - All belts & hoses - Throttle body operation - Battery - Tires		1.00	115.00	115.00
	Work Performed - Inspected vehicle and found the following: - Approximate brakes remaining: - Front = 75% - Rear = 75% - Gas tank leaks from plug - Front timing cover leaks oil - Steering ram leaking - Shift shaft seal at transmission - Convertible top motor leaks - Needs new top or rear window repair - Battery fails load test and cable end is bad				
				Job Total:	115.00
Battery	Replace battery and cable ends.				
Labor Rate 2	Work Requested - Replace battery.		0.30	115.00	34.50
	Work Performed - Installed new battery. Installed large straps to hold battery down.				
Part 24PG	Battery - Delco (List \$132.36)		1.00	114.03	114.03
Labor Rate 1	Work Requested - Replace both cable ends.		0.50	115.00	57.50
	Work Performed - Installed new positive and negative cable ends.				
Part 22101	Battery - Cable End		2.00	4.75	9.50
Part P604	Wire Tie, Black 20"		2.00	2.18	4.36
				Job Total:	219.89
Repair Leaking Gas Tank	Repair leaking gas tank.				
Labor Rate 1	Work Requested - Repair leaking gas tank.		1.50	115.00	172.50
	Work Performed - Drained fuel tank. Removed drain plug. Installed new seal. Refilled with fuel. Rechecked, OK.				
Part 3965092	Seal		1.00	8.78	8.78
				Job Total:	181.28
P/S Leak	P/S Leak				
Labor Rate 1	Work Requested - Repair P/S leak.		0.50	0.00	0.00
	Work Performed - Installed P/S system stop leak and conditioner.				
Part 10008	Lucas Stop Leak		1.00	14.98	14.98
				Job Total:	14.98