

1979 Rolls Royce Silver Shadow II

VIN: SRK36401

CAR INVOICE
AND
BILL OF SALE

SUPERIOR MOTORS INC.



"This is the place... where you'd send a friend!"

630 Murfreesboro Road · Nashville, Tennessee 37210
615/254-5641

N 0234

DATE		4/21/80		STOCK NO.		512		
S O L D T O	UDIO INC. 17TH MAGNOLIA ORLANDO FLORIDA 32801			CHASSIS OR SERIAL NUMBER				
				S SRE-36401				
	YEAR		MAKE - BODY STYLE		NEW		CAR SALES SOURCE	
	79		ROLLS ROYCE SILVER SHADOW II 4-D		NEW		MODEL ACCT. NO. COST SALE	
	COLOR CODE		COLOR		KEY NUMBERS		SILVER SHADOW II G 4181 C - 79008.00	
	CARIBN BLUE				1216		OVERALL/DISCOUNTING G - +	
	SALESMAN		NO.		ACQ. DATE		DLR. CODE	
	CALDWELL 999							
							SERVICE CONTRACT G 9163 -	
							CAR DEAL NO. F 3840	
						LICENSE & DOCUMENTARY FEE G 9151 -		
						SALES TAX G 2221 -		
						COUNTY TAX G 2283 -		
						TOTAL CASH PRICE 79008.00		
						FINANCING G -		
						INSURANCE G 9165 -		
						TOTAL TIME PRICE		
						CASH ON DELIVERY G 1302 + 40000.00		
						G +		
						USED CAR ALLOWANCE 39008.00		
						MONTHS @ DOLLARS		
						BEG. 4/21/80		
						TOTAL		
						LIEN PAYOFF G 2281 -		
						CONTRACTS IN TRANSIT G 1202 +		
						OVERALLOWANCE G 4181 +		
						FIN RECEIVABLE G +		
						F & I G 9161 -		
						USED CAR TRADED		
						YEAR MAKE - BODY STYLE COLOR		
						71 ROLLS ROYCE		
						SERIAL NO. LBX-9831		
						VALUE OF TRADE V 512-1 G 1412 +		
						G 1412 +		

THE UNDERSIGNED DEALER HAS THIS DAY SOLD UNDER CONDITIONAL SALES CONTRACT TO THE ABOVE NAMED PURCHASER, THE HEREINABOVE DESCRIBED MOTOR VEHICLE, WARRANTS AND COVENANTS THAT THE UNDERSIGNED DEALER IS THE LAWFUL OWNER THEREOF WITH A GOOD RIGHT TO SELL SAME. THAT THERE IS NO LIEN OR ENCUMBRANCE THEREON EXCEPT CONDITIONAL SALES CONTRACT OR CHATTEL MORTGAGE, SIGNED BY ABOVE PURCHASER AND TO BE ASSIGNED TO

LIENHOLDER _____

ADDRESS _____

AMOUNT _____ DATE OF LIEN _____ TYPE LIEN _____

SIGNED WILL WARRANT AND DEFEND TITLE AGAINST ALL PERSONS EXCEPT AND UNDER-ABOVE LIENHOLDERS.

SUPERIOR MOTORS Inc.

BY *William W. Caldwell*
OWNER(S)-PRES.-VICE PRES.-SECTY. TREAS.

SWORN TO AND ACKNOWLEDGED BEFORE ME THIS _____ DAY OF 4/21/80 19


NOTARY PUBLIC *Jonathan Best* IN AND FOR THE COUNTY OF DAVIDSON

MY COMMISSION EXPIRES 06/13/81

P.O. Box 829
LARKSPUR
CALIF 94977

(415) 847-8870

MJV Automotive




SONOMA

OCTOBER 31, 2019

Enclosed is the billing and breakdown of the work performed. I hope you find it in order and self-explanatory but should you have any questions please do not hesitate to call.

Additional charges involved were the hydraulic reservoir for the braking system which was both leaking a little and the sensors for the low level warning light malfunctioning. The battery cut-off switch is RR factory style as used on the next generation of models. The instrumentation lights are as good as I can make them since, apart from the 4 in 1 gauge (oil, fuel, coolant, amps) there are no brighter bulbs available in the design for these gauges. I hope the enclosed note from the workshop manual makes sense with respect to the air flow into the cabin with A/C off.

MJV Automotive



I also rebuilt the L/S height control valve as a courtesy since the R/S was so gunged up I felt the other side would be equally as bad and would affect the height control performance.

I visited the Bodyshop in Petaluma (Business Card enclosed) for him to look at the car with a paint estimate. The cost would be approx \$17,500 plus any parts like windshield rubber surrounds, door seals etc. He would not take the doors off to do the door jams as this would really escalate the price. Door panels would have to come off for window frame removal + seal removal. Since the door cap wood would be coming off it would make sense to have them relacquered and the dash wood too. Front + Rear Windshields would be removed.

Please call if you have any questions

Michael.


MJV Automotive

1979 SILVER SHADOW II


VIN# 36401

LIC# 5SMN960

Mileage: 73140



LABOUR	\$ 2500 —
SUBLET SERVICES	\$ 110 — 75
PARTS	\$ 3041 — 53
SALES TAX	\$ 288 — 95
GASOLINE	\$ 50 — 00
<hr/>	
TOTAL	\$ 5991 — 23



SUMMARY

LABOUR


- | | |
|---------------------------|----------|
| 1) FUEL SYSTEM | \$ 450 - |
| 2) HEIGHT CONTROL | \$ 400 - |
| 3) AIR CONDITIONING | \$ 500 - |
| 4) HYDRAULIC
RESERVOIR | \$ 350 - |
| 5) SERVICE | \$ 400 - |
| 6) INSTRUMENTATION | \$ 150 - |
| 7) BATTERY CUT-OFF | \$ 250 - |

TOTAL LABOUR \$ 2500 -

OUTSIDE SERVICES

SMOG + EXHAUST \$ 110 - 75


M J V Automotive



PARTS

1) FUEL SYSTEM	\$ 787 - 39
2) HEIGHT CONTROL	\$ 288 - 40
3) AIR CONDITIONING	\$ 1126 - 92
4) HYDRAULIC RESERVOIR	\$ 279 - 57
5) SERVICING	\$ 430 - 42
6) INSTRUMENTATION	\$ 69 - 59
7) BATTERY CUT-OFF	\$ 59 - 24
8) HOOD PADS	\$ 290 - 00
	<hr/>
	\$ 3041 - 53
SALES TAX ON PARTS	\$ 288 - 95
	<hr/>
PARTS TOTAL	\$ 3330 - 48

MJV Automotive



LABOUR

A/ FUEL SYSTEM:

Defective Fuel Pump. Replaced fuel pump to correct European style system. Fabricate new fuel pipe to fit and wire in new connections and mounting points for fuel pump location. Replace fuel hoses and filter as needed.


\$450-

B/ HEIGHT CONTROL:

R/s height control valve leaking. Remove valve, dismantle, clean and rebuild with new seals and bushings. Remove height control restrictors and clean and reseal (all gunged up).

L/s height control valve was in poor condition and all gunged up also. As a courtesy rebuilt this valve to prevent leakage and problems in the future.

\$400-



LABOUR (contd)

C/ AIR CONDITIONING:

No cold air blowing through vents. Tested system and showed a charge of freon. Checked operation of all flaps for air-flow control - Good.


Diagnosis revealed a bad compressor not working internally and pumping freon thru' system. Replaced A/C compressor and related components and converted system to modern eco-friendly R134a system. Evacuate and recharge system as needed.

\$500 -

D/ HYDRAULIC RESERVOIR:

- Reservoir was leaking and low-level fluid warning light not illuminating. Remove top plate and clean out reservoir and replace defective reed switch magnet. Reseal sight glass 'o' rings and top cover plate gaskets and low-level sensor wiring (chewed up)

MJV Automotive



LABOUR (CONTD)

- check for operation of warning light and leak-proof. Bleed braking and height control system and set fluid levels at correct level. Road test and set rear ride levelling to correct adjustment.

\$350-

E SERVICING

Change all fluids, and replace engine oil filter and carburettor fuel filters. Drain engine coolant and grease all chassis components and perform overall safety inspection. Replace spark plugs, check ignition system and timing. Check and clean air filter as needed. Change differential oil and "top-up" half-shafts as needed.


Sublet vehicle for smog inspection.

\$400-

F Instrument Lights.

Check operation of dimmer switch - works fine. Remove wood and gauges and check integrity of

M J V Automotive



dimmer switch - works fine. Replace bulb for 4 in 1 gauge (fuel, oil coolant, amps) with higher wattage (50 ^{watts} ~~amps~~). Also replace bulbs in ignition switch unit, and below wood dash where windshield wipers and air-conditioning controls are located. Replace bulb for gear selector.

\$150 -

9/ Battery Cut-off Switch.

Fabricate bracket to house switch behind carpet panel near battery. Make two new ground cables for ~~one~~ ON/OFF operation. Tidy up wiring connections at battery terminals as needed.

\$250 -


11/ Sublet vehicle for Smog Inspection and repair of small exhaust leak in centre pipe.

N/C.

1/ Clean up engine bay from 'critter' debris and interior of car too. Treat leather with leather restorer/conditioner.

N/C.

M J V Automotive



OUTSIDE SERVICES

SUBLET :

SMOG INSPECTION

\$67⁵⁰

CERTIFICATE


\$8²⁵

EXHAUST REPAIR

\$35⁰⁰

\$110⁷⁵

MJV Automotive




FUEL SYSTEM

1	UD 22715	Negative Ground Fuel Pump	\$423 —
2	UD 10944	MOUNTING CLAMPS	\$ 74 - 30
2	UD 16245	NOZZLES - INLET & OUTLET	\$ 86 - 40
2	UD	FUEL PUMP PROTECTIVE GUARDS	\$ 58 — ⁰⁰
1	CD4299	FUEL FILTER	\$ 42 - 81
3	FEET	SOLID FUEL PIPE	\$ 31 - 18
5	FEET	FUEL HOSE	\$ 17 - 50
10	BS 16	STAINLESS HOSE CLAMPS	\$ 30 —
2	UD 20219	FUEL HOSE INSULATION SLEEVE	\$ 24 - 20

\$ 787 - 39

MJV Automotive



HEIGHT CONTROL


2	RH2436	HEIGHT CONTROL 3/4 KIT	\$101-90
4	UR17828	BEARING SLEEVE BUSHINGS	\$132-
2	CD6244	HEIGHT CONTROL HOSES	\$46-20
2	UD10149	HEIGHT CONTROL RESTRICTOR 10' RINGS	\$8-30

\$288-40

AIR CONDITIONING

1	UE439342	COMPRESSOR	\$744-42
1	UD11868	RECEIVER-DRIER (FILTRATION UNIT)	\$148-10
1	UD25952	THERMOSTATIC EXPANSION VALVE	\$96-52
1	UD21300	THERMAL LIMITER FUSE	\$23-15
1	909352	R134a REFRIGERANT RETROFIT KIT	\$47-23

MJV Automotive



AIR CONDITIONING (contd)

2.25 lbs R134a REFRIGERANT

\$67⁵⁰


\$1126⁹²

HYDRAULIC RESERVOIR

1	UR 13120	SIGHT GLASS	\$27 ⁴⁰
2	SPC 1958	✓ ✓ SEAL	\$9 ⁰⁰
2	CD 558 CORK	CORK CAP SEAL GSKT	\$5 ⁰⁰
2	UR 15985	RESERVOIR CORK GSKT	\$19 ⁰⁰
1	UR 13113	RESERVOIR SCREEN MESH	\$42 ⁷⁵
1	UR 18259	FLOAT + MAGNET (FOR REED SWITCH)	\$69 ²³
2	UR 18402	SEAL (REED SWITCH)	\$58 ⁰⁹
1	UD 20988	FLOAT LEVEL RESISTOR UNIT	\$49 ¹⁰

\$279⁵⁷

MJV Automotive




SERVICING

8	RN14YC	SPARK PLUGS	\$30 -
1	07V121717	OIL FILTER	\$32 - ⁵⁰
3	XB1093R	DRAIN SEALING WASHERS	\$6 - ⁴⁸
2.5	QUARTS	GEAR DIFFERENTIAL FLUID	\$34 - ⁵²
1.5	GALLONS	COOLANT	\$33 - ⁷⁵
10	QUARTS	10W/40 ENGINE OIL	\$75 -
4	QUARTS	TRANSMISSION FLUID	\$28 - ⁸⁴
3	QUARTS	RR363 BRAKE FLUID	\$120 - ⁰⁰
3	P-37	Brake Cleaner Solvent	\$13 - ⁵⁰
1	P-38	Carburettor Induction Cleaner	\$8 - ⁹⁵
2	CD 5447	SU CARB 'O' RING (fuel filter)	\$17 - ⁹⁸
2	VE 35892	SU CARB FUEL FILTER (FLOAT CHAMBER)	\$28 - ⁹⁰

\$430 -⁴²

MJV Automotive




INSTRUMENTATION

1	NO177535	5watt Bulb	\$ 6-97
7	UD 8912	DASH LIGHT 1-75watt BULB	\$ 55-12
1	UD 15848	DASH LIGHT .56watt (gear Selector)	\$ 7-50
			<hr/>
			\$ 69-59

BATTERY

1	UD 22765	Battery Cut-off Switch	\$ 38-50
1	115005	GROUND Battery Cable	\$ 8-24
1	728530	Negative Battery Clamp (SOLDER)	\$ 12-50
			<hr/>
			\$ 59-24

MJV Automotive



Hood PADS

1 UB 13544 Reconditioned
Insulation Pad \$ 145 —

1 UB 13545 Reconditioned
Insulation Pad \$ 145 —

\$ 290 —

DEALER PACIFIC RIM AUTO REPAIR 505 WEST NAPA STREET SONOMA, CA 95476 PHONE (707) 935-4444 B.A.R. NUM ARD263818 E.P.A. NUM CAL000255698		CUSTOMERS NAME & ADDRESS SONOMA CA 95476 -		DATE & TIME 08/30/17 10:36
				WRITTEN BY: AH
				PROMISED: 08/30

VEHICLE LICENSE NO. 5SMN960	ODOMETER 73,140	VEHICLE DESCRIPTION 79 ROLLS ROYCE	VEHICLE IDENTIFICATION NO. SRK36401
PAYMENT METHOD	<input type="checkbox"/> MC/VISA <input type="checkbox"/> OTHER	CREDIT CARD NO.	CREDIT AUTHORIZATION

<input type="checkbox"/> DELIVER <input type="checkbox"/> WILL CALL <input type="checkbox"/> CALL WHEN READY
SERVED BY RD
INSPECTED BY AH

SERVICE REPAIR INSTRUCTIONS/SYMPTOMS

SMOG CHECK
 AIR CONDITIONER INOPERATIONAL
 CHECK BATTERY CONNECTION AND BRAKE FLUID LIGHT BLINKIN

TECH	QTY	PART NO.	REPAIR/SERVICE DESCRIPTION	PARTS	LABOR
RD	01		SMOG PASSED CONGRATULATIONS! Your car has passed the California Smog Check. The smog Certificate has been sent to the DMV via electronic mail.		80.00
RD	01	SMOG	I AND M SMOG CERTIFICATE	8.25	
S	01		AIR CONDITION INOP Inspect cause of air conditioner inoperational and advise.		135.00
S	01	[SA]	FOUND FAULTY RESISTER. REPLACED AND TEST CONDITION - OK AT THIS TIME.		
S	01		A/C RESISTER Remove and replace air conditioner resister.	33.62	
S	01		BRAKE FLUID LIGHT Inspect cause of brake fluid light on and advise customer.		40.50
S	02	RR363 DOT 3	FOUND BRAKE MASTER CYLINDER HAS SLOW LEAK - ADDED BRAKE FLUID AS NEEDED. BRAKE FLUID CASTRO Add brake fluid as needed.	12.60	

CUSTOMER REQUESTED RETURNED PARTS <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	SAFETY RECOMMENDATIONS				TOTALS	
--	-------------------------------	--	--	--	---------------	--

I, the registered owner, authorize you to perform the above repairs and furnish necessary materials. I understand any cost quoted heretofore is an estimate only. You employees may operate vehicle for inspection, testing, delivery at my risk. You will not be responsible for loss or damages to vehicle or articles left in it. I agree to pay reasonable storage on vehicle left more than 48 hours after notification that repairs are completed. An express Mechanic's Lien is acknowledged on above vehicle to secure the amount of repairs thereon, including those from any prior work or repair contract on this vehicle. In the event an attorney is retained to foreclose on this lien or to bring suit for collection of any sums due, I agree to pay cost of collection and any reasonable attorney fees. Receipt of a copy of this order is hereby acknowledged.

CUSTOMER SIGNATURE X	TIRES, BRAKES, BATTERY & COOLANT						LABOR 255.50
	TIRES	RF	LF	RR	LR	SPARE	PARTS 46.22
	TREAD						SALES TAX 3.99
	PSI						GASOLINE GALS
	BRAKES-F	%		BRAKES-R	%		SMOG CER 8.25
BATTERY						SUB-LET	
COOLANT						DEPOSIT ()	
						TOTAL 313.96	

REVISED ESTIMATE	PARTS	LABOR	TOTAL	DATE	TIME	<input type="checkbox"/> IN PERSON <input type="checkbox"/> BY PHONE	I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE.
	BY	AUTHORIZED BY CUSTOMER	PHONE NO.				

X

SMOG CHECK VEHICLE INSPECTION REPORT

(08/30/2017 @ 10:27:05 am)

Vehicle Information

Model Year..... 1979	Make..... ROLLS-ROYCE	Model..... SILVER SHADOW
License..... 5SMN960	State..... California	VIN..... SRK36401
Engine Size..... 6.8 Liters	Type..... Passenger	Transmission..... Automatic
GVWR..... N/A	Test Weight..... N/A	Cylinders..... 8
Odometer..... 731400	Certification..... Federal	VLT Record #..... 13262
Fuel Type..... Gasoline	Exhaust..... Single	Inspection Reason..... Biennial
Engine Year..... N/A	Engine Make..... N/A	Bar Number..... N/A
Fleet BAR File #..... N/A		

Overall Test Results

Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Visual Inspection..(Pass) Functional Check..(Pass) Emissions Test..(Pass)

DMV ID Number..(0578V145Z931)
Smog Check Certificate Number..(ZV791081)

Your Smog Check certificate will be electronically transmitted to DMV
This certificate is valid for ninety (90) days from the date of issuance.

Please keep this copy for your records.

Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist the identification of oxides of nitrogen, crankcase, and cold start emissions which are not measured during the idle tests)

<u>ECS</u>	<u>Result</u>	<u>ECS</u>	<u>Result</u>	<u>ECS</u>	<u>Result</u>
PCV.....	Pass	Thermostatic Air Cleaner.....	Pass	Fuel Evaporative Controls.....	Pass
Catalytic Converter.....	Pass	EGR (Visual).....	Pass	Spark Controls.....	Pass
Carburetor.....	Pass	Pump Air Injection.....	Pass	Vacuum lines sensors/switches..	Pass
Other related emis. components.	Pass	Liquid Fuel Leak.....	Pass	Fuel Cap Integrity Test.....	Pass
EGR (Functional).....	Pass	Fuel Cap Visual.....	Pass	Ignition Timing (13 BTDC).....	Pass

Idle Emission Test Results

Test	%CO2			HC (PPM)			CO (%)			Result
	RPM	MEAS	MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	
M1: 0 MPH	656	12.6	3.4	220	60	9	2.00	0.30	0.00	Pass
M2: 0 MPH	2288	12.4	3.6	180	52	3	1.70	0.50	0.00	Pass

MAX = Maximum Allowed Emissions AVE = Average Emissions For Passing Vehicles MEAS = Amount Measured

Smog Check Station Information

PACIFIC RIM AUTO REPAIR
505 W. NAPA ST
SONOMA, CA 95476
1 707 935 4444

Technician Name/Number..... DAVIS, FREDERICK/EO141878
Repair Tech Name/Number..... N/A
Software Version/EIS Number... 1401/SX060173
Station Number..... RC263818

I certify under penalty of perjury under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and correct.

8.30.17

Date

Technician's Signature

William's Auto Care Center inc

18380 Sonoma Hwy
Sonoma Valley, Ca. 95476
Phone: 707-996-1056 Fax: 707-996-6125
Serving our Customers & Friends 45 Years

REPAIR ORDER #

009555

Org. Est. # 018585

ARD00248938

RSC00248938

REPAIR ORDER - RO

Scheduled : 09/25/2015 08:18 AM

Print Date : 09/25/2015

1979 ROLLS ROYCE - SILVER SHADOW 11 -

Lic # : 5SMN960 - CA

Sonoma, CA 95476

Office: _____ Spouse: _____

Cust ID : 1026

VIN # : SRK36401

MFG Date : 9/25/2015

Last Service :

Cur. Odometer : 72,704

Prev. Odometer : 0

Elapsed Mileage : 0

Labor Requested / Part Description	Part #	Qty	Parts List	Extended
AAA - Inspection				0.00
Smog Evap Test				8.00
Smog Inspection				59.00
Smog Certificate	Smog Certificate	1.00	8.25	8.25
Discount				
\$15.00 off labor				
Hazardous Materials				1.33

for total smog \$40.00

Sonoma Valleys Oldest and Largest

Parts: 8.25

HazMat: 1.33

Labor: 67.00

Discount: 15.00

Total: \$ 61.58

TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within ___ days of the date shown above if I choose not to authorize the service recommended. All Parts removed will be discarded unless instructed otherwise: Save all Parts ____. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE.
DISCOUNTS AND COUPONS NOT TO SUCCEED \$150.00 PER CUSTOMER AT EACH VISIT

Authorized By *Jar* Date _____ Time _____

Service Advisor: William, Murray



AAR Maintenance Inspection

California State Automobile Association
Approved Auto Repair

William's Auto Care Sonoma

707-996-1056
williamsautocare.com



MEMBER'S NAME		MEMBERSHIP NUMBER		DATE	
MAKE <i>Volvo</i>	YEAR <i>79</i>	MODEL	ODOMETER	LICENSE	
NAME OF REPAIR FACILITY				TECHNICIAN'S NAME	

GENERAL INSPECTION	S	P	U	BELTS-PULLEYS	S	P	U	RECOMMENDATIONS
Wiper Blades L R Rear	/			Alternator Belt Pulley	/			
Washer Fluid Level Pump	/			Air Conditioning Belt Pulley	/			
Horn	/			Power Steering Belt Pulley	/			
Mirrors L R Inside	/			Air Pump Belt Pulley				
LIGHTS	S	P	U	Water Pump Leak Pulley				<i>Radi pump leak and tap some hoses show signs of</i>
Lens Covers	/			Belt Tensioner				
Headlights L R Lo Hi	/			HOSES	S	P	U	
Park Lights LF RF LR RR	/			Heater Inlet Outlet	/			
Turn Signal LF RF LR RR	/			By-Pass	/			
Tail Lights L R	/			Radiator Upper Lower	/			
Brake Lights L Cntr R	/			Power Strg. Hi Press Lo Press				
License L R Backup L R	/			Vacuum				
Side Lights LF RF LR RR	/			Fuel (under hood only)				
LUBRICANTS-FLUIDS	S	P	U	OTHER	S	P	U	
Engine Oil Level Cond. Leaks	/			Air Filter				
Trans. Fluid Level Cond. Leaks	/			Glass & Windows	/			
P/Steering Level Cond. Leaks	/			Body Damage (Note)	/			
Anti-Freeze Level Leaks °F	/			Radiator Cooling Fan(s)	/			
Brake Fluid Level	/			TIRES	S	P	U	
BATTERY	S	P	U	Tire Pressure:	/			
Battery Carrier Hold-Down	/			LF LR RR RF	/			Check Engine Light
Battery Cables Clamps Terminals	/			Tread Depth: (min 3/32)	/			
Battery Test	/			LF LR RR RF	/			CV Boots
Readings CCA	/			Tire Size:	/			

[S] - Checked and Okay Satisfactory [P] - Poor May Need Future Attention [U] - Unsatisfactory Requires Immediate Attention

NOTICE

I have reviewed the Car Maintenance Report and understand that it is given to show the condition of the vehicle at the time of its inspection and evaluation only and made without warranty of any kind, either expressed or implied, or arising by operation of law. I acknowledge that no action has been taken to correct any condition(s) reported and that the safe operation and maintenance of the vehicle following the inspection is my sole responsibility. I also understand that the results recorded above may be used in the collection of statistics relative to vehicle maintenance, and that copies of this report may be given to program sponsors upon request.

I also acknowledge that this Maintenance Inspection Report is made solely by the facility performing the inspection, which is an independent business, and that neither the AAA nor the California State Automobile Association certify, guarantee, warrant or make any representations concerning the quality, accuracy or completeness of this Maintenance Inspection Report, the inspection itself or any repairs.

MEMBER'S SIGNATURE	DATE
--------------------	------

MJV AUTOMOTIVE
 P.O. Box 829
 LARKSPUR, CALIF 94977
 (415) 847-8870

MATERIAL USED		QTY.	PART NO.	DESCRIPTION	PRICE	WARRANTY
1	UEK0893	01L FILTER			29	
1	XB1093	DRAIN WASHER			2	
10	QVARTS	20W/50		ENGINE OIL	60	
1	UE40361	TEMPERATURE SENDING UNIT			48	
2	GALUNS	COOLANT			36	
1	VD19341	FLASHER UNIT			32	
2	RH2619	ACCUMULATOR VALVE BODY O/A			282	
2	RH2435	ACCUMULATOR SPHERE O/A			227	
1	UE10382	OUTSIDE REPAIRS WASHER			22	
2	UE36145	SEALING DISC			21	
1	UR14201	RETURN HOSE			32	
4	XB1048	ALUMINIUM WASHER			10	
2	VD1872	PRES. SWITCH DIAPHRAGM			63	
PARTS SAVED						
BROUGHT FORWARD						
TOTAL PARTS						
RETURNED						
ACCESSORIES		QTY.	AGENCY	DESCRIPTION	PRICE	WARRANTY
2	VD17876	PRESSURE SWITCH PLUNGER			46	
3	RR363L	HYDRAULIC BRAKE FLUID			114	
2	P-37	BRAKE SOLVENT CLEANER			7	
TOTAL ACCESSORIES					1037	

NAME: T. SANDOMA, CALIF. PHONE: 4-5-15
 ADDRESS: SONOMA, CALIF.
 2ND AUTHORIZED NAME: (707)
 MAKE: ROUS-ROYCE TYPE OR MODEL: SURE SHOW YEAR: 1979
 SERIAL #/VIN: SKK 36401 ENGINE NO.:
 ODOMETER: 12598 LICENSE NO.: 55HN1960 TERMS:
 MAKE: RECEIVED (DATE & TIME) A.M./P.M.
 PROMISED (DATE & TIME) A.M./P.M.
 PHONE WHEN READY: YES NO
 CUSTOMER'S ORDER NO.:

OPER. NO. INSTRUCTIONS: CHARGE FOR HAZARDOUS OR OTHER WASTE REMOVAL*

4/1. Perform L.O.F. and check all levels, adjust as needed. Change coolant temp sending unit and re-fill with coolant. Replace Flasher Unit.
 B/. Hydraulic pressure test revealed "uncharged" accumulator spheres. Remove #1 + #2 spheres and O/H valve body, spheres + pressure switches as needed. Recharge with nitrogen and bleed brakes / height control hydraulic system.

Estimated cost \$ Estimate Charge

PLEASE READ CAREFULLY, CHECK ONE OF THE STATEMENTS BELOW, AND SIGN:
 I UNDERSTAND THAT, UNDER STATE LAW, I AM ENTITLED TO A WRITTEN ESTIMATE, INCLUDING A COMPLETION DATE, IF MY FINAL BILL WILL EXCEED \$100. (\$50 in Maryland)
 I REQUEST A WRITTEN ESTIMATE. THE FINAL BILL MAY NOT EXCEED THIS ESTIMATE WITHOUT MY WRITTEN APPROVAL.
 I DO NOT REQUEST A WRITTEN ESTIMATE, AS LONG AS THE REPAIR COSTS DO NOT EXCEED \$_____. THE SHOP MAY NOT EXCEED THIS AMOUNT WITHOUT MY WRITTEN OR ORAL APPROVAL.
 I DO NOT REQUEST A WRITTEN ESTIMATE.

*Checked lines apply (Preparer must check at least one):

This charge represents costs and profits to the motor vehicle repair facility for miscellaneous shop supplies or waste disposal.
 This amount includes a charge of \$_____, which is required under law.

METHOD OF PAYMENT:

- CASH CHECK CHARGE
- LABOR
- FLAT RATE HOURLY BOTH
- RETAIN PARTS DESTROY PARTS

GAS, OIL, & GREASE

GAS, OIL, & GREASE	PRICE
GALS. GAS	
QTS. OIL	
LBS. GREASE	
TOTAL GAS, OIL, & GREASE	

Daily storage fee after repair work has been completed and customer has been notified. No charges shall accrue or be due and payable for a period of 3 working days from date of notification.
 \$_____

GUARANTEED ITEMS:	PRICE
TOTAL LABOR	1200
TOTAL PARTS	1037
ACCESSORIES	
GAS, OIL, & GREASE	
OUTSIDE REPAIRS	
STORAGE FEE (if applies)	
TAX	45.96
TOTAL AMOUNT	2333.96

You are entitled by law to the return of all parts replaced, except those for which there is a core charge, unless you agree otherwise by initialing the following: I do not desire the return of any of the parts that are replaced during the authorized repairs.
 Estimate good for 30 days. Not responsible for damage caused by theft, fire, or acts of nature. I authorize the above repairs, along with any necessary materials, to authorize you and your employees to operate my vehicle for the purpose of testing, inspection, and delivery at my risk. An express mechanic's lien is hereby acknowledged on the above vehicle to secure the amount of the repairs thereon. If I cancel repairs prior to their completion for any reason, a tear-down and reassembly fee of \$_____ will be applied.

SIGNED _____

DATE _____

2333.96

REPAIR ORDER

MJV Automotive
 P.O. Box 829
 LARKSPUR, CA 94977

(415) 844-8870

QTY	PART NO.	DESCRIPTION	PRICE	WARRANTY
1	UE40893	OIL FILTER	27.50	NO
10	QUARTS 20W/50	engine oil	59.50	NO
1	XB1094R	Drain Plug	7.16	NO
		Washer		
2	QUARTS	LMA Castrol		
		Brake Fluid	32.00	
1	R9903	Light Bulb	2.50	
		OUTSIDE REPAIRS		
		SMOG INSPECTION + CERTIFICATE	45.00	
		BROUGHT FORWARD		
		TOTAL PARTS		
		ACCESSORIES		
1	P-37	Brake Solvent	3.95	NO
		Cleaner		
		TOTAL ACCESSORIES		

NAME: _____ DATE: 11-29-13

ADDRESS: _____

MAKE: RLS-RKE TYPE OR MODEL: S. SHAW II YEAR: 79 RECEIVED: _____

SERIAL NO.: SRK36401 ENGINE NO.: _____ PROMISED: _____

ODOMETER: 72036 LICENSE NO.: 55MN960 TERMS: _____ PHONE WHEN READY: YES NO

ORDER WRITTEN BY: MVJ (Signature) IPHONE: (81)

OPER NO.	INSTRUCTIONS	DSS	ISJ	LABOR CHARGE
A.	Part Up + Deliver vehicle			
B.	Perform O.T. to filter change, bleed brakes, hydraulics + check all fluid levels - adjust as necessary, check lights + tyre pressures, adjust parking brake, g.			100.00
C.	Repair front fork mechanism + adjust for center closing - lubricate system.			100.00
D.	Perform pre-test smog inspection - check + adjust random timing, fuel adjustments, carburetor - smog valve.			100.00

You are entitled to a price estimate for the repairs you have authorized. The repair price may be less than the estimate, but will not exceed the estimate without your permission. Your signature will indicate your estimate selection.

Tear-down estimate - I understand that my car will be reassembled _____ days of the date shown if I choose not to authorize the services recommended.

1. I request an estimate in writing before you begin repairs. _____

2. Please proceed with repairs, but call me before continuing if the price will exceed \$ _____.

3. I do not want an estimate. _____

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND OUR CONTROL.

GAS, OIL, & GREASE	PRICE
GAL. GAS @	
QTS. OIL @	
LBS. GREASE @	
TOTAL GAS, OIL, & GREASE	

METHOD OF PAYMENT:

CASH CHECK CHARGE

LABOR: FLAT HOURLY BOTH

TOTAL LABOR	TOTAL PARTS	ACCESSORIES	GAS, OIL, & GREASE	OUTSIDE REPAIRS	TAX	TOTAL AMOUNT
300.00	123.66	3.95	75.00		11.49	514.10

Smog Check Vehicle Inspection Report (VIR)

Vehicle Information

Test Date/Time: 11/29/2013 @ 16:46

Model Year: 1979	Make: ROLLS-ROYCE	Model: SILVER SHADOW
License: 5SMN960	State: CA	VIN: SRK36401
Engine Size: 6.8 L	Type: Passenger	Transmission: Automatic
GVWR: N/A	Test Weight: N/A	Cylinders: 8
Odometer: 72033	Certification: Federal	VLT Record #: 13262
Fuel Type: Gasoline	Exhaust: Dual	Inspection Reason: Change of Ownership

Overall Test Results

Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Smog Check Certificate Number: PA869784
DMV ID Number: 0947A549P331

Your Smog Check certificate has been electronically transmitted to DMV.
Your certificate is valid for 90 days from date of issuance.
Please keep this copy for your records.

Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of oxides of nitrogen, crankcase and cold start emissions which are not measured during the Idle test)

Result	ECS	Result	ECS	Result	ECS
Pass	PCV	Pass	Thermostatic Air Cleaner	Pass	Fuel Evaporative Controls
Pass	Catalytic Converter	Pass	Air Injection	N/A	OBD System Checks
Pass	EGR Visual	Pass	Vacuum Lines to Sensors/ Switches	Pass	Carb./Fuel Injection
Pass	EGR Functional	Pass	Ignition Timing: 13 BTDC	Pass	Other Emission Related Components
Pass	Fuel Cap Functional	Pass	Wiring to Sensors	N/A	Oxygen Sensor
Pass	Fuel Cap Visual	N/A	Fillpipe Restrictor	Pass	Liquid Fuel Leaks
Pass	Spark Controls				
N/A	Fuel Evaporative Controls Functional				

Idle Emission Test Results

Test	RPM	%CO ₂		%O ₂			HC (PPM)			CO (%)			Results
		MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	
Idle	565	11.3	5.1	220	60	8	2.00	0.30	0.00				PASS
2500 RPM	2579	11.2	5.3	180	52	0	1.70	0.50	0.00				PASS

MAX = Maximum Allowable Emissions

AVE = Average Emissions For Passing Vehicles

MEAS = Amount Measured

Smog Check Inspection Station Information

Marinwood Smog Check
100 Marinwood Ave, San Rafael, Ca, 94903
415-479-7050
Station Number: TH265564

Technician Name/Number: GROMOV, OLEKSANDR/EO146280
Repair Tech Name/Number:
Software Version/EIS Number: 1301/ES419543

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

11-29-13

Date

Technician's Signature

REPAIR ORDER

MICHAEL J. VEYS
 P.O. Box 829
 MARKSPUR, CALIF 94977

(415) 847-8870

QTY.	PART NO.	MATERIAL USED DESCRIPTION	PRICE	WARRANTY YES	WARRANTY NO
2	UD1184	HEATER DUCT SLEEVE		123	46
2	UD1163	Flap Seals		23	76
1	UD22127	WATER TAP CABLE		148	85
1	UD14989	HEATER DUCT STRAP		76	88
1	VB19273	SCUTTLE GRILLE FILTER		21	08
1	XB829	IN-LINE FUSE HOLDER		9	80
1	UD71838	CHROME BEZEL - LOCKS		31	04
		OUTSIDE REPAIRS			
		REAR L/R DOOR LOCK SOLENOID		175	-
		BROUGHT FORWARD			
		TOTAL PARTS			
		ACCESSORIES			
		PRICE			
		WARRANTY YES			
		WARRANTY NO			
		TOTAL ACCESSORIES			

NAME: _____ DATE: 5-18-12
 ADDRESS: _____
 MAKE: RLS-RYOC TYPE OR MODEL: SILVER SHINY 79 YEAR: 79 RECEIVED: _____
 SERIAL NO.: SRK 36401 ENGINE NO.: _____ PROMISED: _____
 ODOMETER: 71604 LICENSE NO.: 55MN TERMS: YES NO PHONE WHEN READY: YES NO
 ORDER WRITTEN BY: ANV. PHONE: _____

DSS	ISJ	LABOR CHARGE
<input type="checkbox"/>	<input type="checkbox"/>	Lubrication
<input type="checkbox"/>	<input type="checkbox"/>	Change Oil
<input type="checkbox"/>	<input type="checkbox"/>	Change Oil Filter Cart.
<input type="checkbox"/>	<input type="checkbox"/>	Change Trans.
<input type="checkbox"/>	<input type="checkbox"/>	Change Diff.
<input type="checkbox"/>	<input type="checkbox"/>	Pack Front Wheel Brgs.
<input type="checkbox"/>	<input type="checkbox"/>	Adjust Brakes
<input type="checkbox"/>	<input type="checkbox"/>	Rotate Tires
<input type="checkbox"/>	<input type="checkbox"/>	Wash Polish
<input type="checkbox"/>	<input type="checkbox"/>	State Inspection

OPER NO. _____ INSTRUCTIONS: A. Customer complains of no heat. - replace duct seals add straps around heater duct system. Repair inside. Replace shirking water duct tape. 350-
 B. Remove L/R door lock solenoid and adjust for proper install and make adjustments for correct opening closing and locking of door. 200-
 C. Check seals & complimentary details. N/A

You are entitled to a price estimate for the repairs you have authorized. The repair price may be less than the estimate, but will not exceed the estimate without your permission. Your signature will indicate your estimate selection. Teardown estimate - I understand that my car will be reassembled _____ days of the date shown if I choose not to authorize the services recommended.

1. I request an estimate in writing before you begin repairs. _____
 2. Please proceed with repairs, but call me before continuing if the price will exceed \$ _____
 3. I do not want an estimate. _____

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE THEFT OR ANY OTHER CAUSE BEYOND OUR CONTROL.

GAS, OIL, & GREASE	PRICE
GAL GAS @	
QTS. OIL @	
LBS. GREASE @	
TOTAL GAS, OIL, & GREASE	

METHOD OF PAYMENT: CASH CHECK CHARGE LABOR: FLAT HOURLY BOTH

TOTAL LABOR	TOTAL PARTS	TOTAL AMOUNT
550-	435 59	
	ACCESSORIES	
	GAS, OIL, & GREASE	
	OUTSIDE REPAIRS	
	TAX	
	TOTAL AMOUNT	1198 73

REPAIR ORDER

MICHAEL J. VEYS
 P.O. Box 829
 LARKSPUR, CA 94947

(415) 847-8870

QTY.	PART NO.	DESCRIPTION	PRICE	WARRANTY YES	WARRANTY NO
1	439345X	REMANUFACTURED			
	AIR CON COMPRESSOR	6450			
2	CD 6812	COMPRESSOR 0' ring	14	44	
1	VD11868R	RECEIVER -			
	DRIVER	45			
2	CD 6831	0' RING	3	60	
1	RH14135	THERMOSTATIC			
	EXPANSION VALVE	114			
1	CD 609R	0' ring	1	75	
1	CD 6811	0' ring	6	11	
3	25 lbs	R12 Refrigerant GAS	178	75	
3	QUAKETS	LMV CASTROL BRAKE FLUID	47	28	
1	(USED)	HIGH PRESSURE PDE (OUTSIDE REPAIRS ACCOR TO BRAKE RIMP)	64	02	
1	R#434	SWITCH DIAPHRAGM	31	15	
1	RH 6311	SWITCH CONTACT	16	25	
1	MT-27H	BATTERY	131	10	
BROUGHT FORWARD \$1103.41					
TOTAL PARTS					
ACCESSORIES					
1	P-37	Brake Cleaner			
		Solvent	3	95	
TOTAL ACCESSORIES					

NAME: _____ DATE: 10-16-11

ADDRESS: _____ SONOMA, CA 9

MAKE: RLS RYCE TYPE OR MODEL: SILVER SHD 199 YEAR: 1999 RECEIVED: _____ AM P.M.

SERIAL NO: SRK 36401 ENGINE NO. _____ PROMISED: _____ AM P.M.

ODOMETER: 71302 LICENSE NO. 55MN960 TERMS: _____ PHONE WHEN READY: YES NO

ORDER WRITTEN BY: MCV PHONE: _____

OPER. NO. INSTRUCTIONS

A/ REPLACE DEFECTIVE AC COMPRESSOR, REPLACE RECEIVER-drier and Thermostatic expansion-valve. Evacuate system and recharge w/ 3.25 lbs of R-12 refrigerant.

B/ Replace leaking/condoled #2 high-pressure brake pipe (Pump to Accumulator) and overhaul #1 brake pressure switch as needed. Perform hydraulic pressure test and bleed hydraulic circuit.

C/ Replace Battery and Insulate fuel lines and radio antenna motor from possible vibration.

You are entitled to a price estimate for the repairs you have authorized. The repair price may be less than the estimate, but will not exceed the estimate without your permission. Your signature will indicate your estimate selection.

Teardown estimate - I understand that my car will be reassessed _____ days of the date shown if I choose not to authorize the services recommended.

1. I request an estimate in writing before you begin repairs. SUBLET FOR SMOG INSPECTION

2. Please proceed with repairs, but call me before continuing if the price will exceed \$ 4 CERTIFICATE

3. I do not want an estimate.

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck, herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND OUR CONTROL.

GAS, OIL, & GREASE	PRICE
12 GAL. GAS @	50
QTS. OIL @	
LBS. GREASE @	
TOTAL GAS, OIL, & GREASE	

METHOD OF PAYMENT: CASH CHECK CHARGE LABOR: FLAT HOURLY BOTH

TOTAL LABOR	TOTAL PARTS	ACCESSORIES	GAS, OIL, & GREASE	OUTSIDE REPAIRS	TAX	TOTAL AMOUNT
700	1103	3	50	58	96	2013
						15

DSS	ISJ	LABOR CHARGE
Lubrication	<input type="checkbox"/>	
Change Oil	<input type="checkbox"/>	
Change Oil Filter Cart.	<input type="checkbox"/>	
Change Trans.	<input type="checkbox"/>	
Change Diff.	<input type="checkbox"/>	
Pack Front Wheel Bigs.	<input type="checkbox"/>	
Adjust Brakes	<input type="checkbox"/>	
Rotate Tires	<input type="checkbox"/>	
Wash Polish	<input type="checkbox"/>	
State Inspection	<input type="checkbox"/>	

Smog Check Vehicle Inspection Report (VIR)

Vehicle Information

Test Date/Time: 09/03/2011 @ 12:16 PM

Model-Year: 1979
 License: 5SMN960
 Engine Size: 6.80 L
 GVWR: 0
 Odometer: 71102
 Fuel Type: Gasoline
 Make: ROLLS-ROYCE
 State: California
 Type: Passenger
 Test Weight: 5500
 Certification: Federal
 Exhaust: Single
 Model: SILVER SHADOW
 VIN: SRK36401
 Transmission: Automatic
 Cylinders: 8
 VLT Record #: 13262
 Inspection Reason: Change of Ownership

Overall Test Results

Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Comprehensive Visual Inspection: **PASS**

Functional Check: **PASS**

Emissions Test: **PASS**

Smog Check Certificate Number: **OG372803C**

DMV ID Number: **0173G1460071**

Your Smog Check certificate will be electronically transmitted to DMV. Please keep this copy for your records.

Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of oxides of nitrogen, crankcase and cold start emission which are not measured during the idle tests.)

TEST	RESULT	TEST	RESULT	TEST	RESULT	TEST	RESULT
PCV	PASS	Thermostatic Air Cleaner	PASS	Fuel Evaporative Controls	PASS	EC	RESULT
Catalytic Converter	PASS	Pump Air Injection	PASS	Fuel Tank Cap Visual	PASS	EC	RESULT
Visual EGR	PASS	Ignition Spark Controls	N/A	Carburetor	N/A	EC	RESULT
Fuel Injection	PASS	O2 Sensors and Connectors	PASS	Wiring of Other	PASS	EC	RESULT
Vacuum Line Connections	PASS	Other Emission Related	PASS	Sensors or Switches	PASS	EC	RESULT
MIL	N/A	Functional EGR	PASS	Ignition Timing: 10 BTDC	PASS	EC	RESULT
Fuel Evap Test	N/A	Fill Pipe Restrictor	PASS	Liquid Fuel Leaks	PASS	EC	RESULT

Idle Emission Test Results

Test	RPM	MEAS	MAX	AVE	MEAS	MAX	AVE	CO (%)
CO2 (%)	2411	12.00	4.00	180	52	8	1.70	0.50
HC (PPM)	604	11.50	4.80	220	60	13	2.00	0.30
CO (%)	2500 RPM	12.00	4.00	180	52	8	1.70	0.50
MEAS								
MAX = Maximum Allowable Emissions								
AVE = Average Emissions For Passing Vehicles								
MEAS = Amount Measured								

Smog Check Inspection Station Information

COUNTRY CLUB AUTOMOTIVE

19 DIGITAL DR.

NOVATO 94949

415-883-0997

Station Number: RH127133

Software Version/EIS Number: 1008/WP381177

Technician Name/Number: CASTANO, LAWRENCE/EA123542

Repair Tech. Name/Number: N/A

I certify, under penalty of perjury under the laws of the State of California, that I inspected the vehicle described above, that I performed the inspection in accordance with all bureau requirements, and that the information listed on the vehicle inspection report is true and correct.

Date

Technician's Signature

Certificates are valid for 90 days from date of issuance

REPAIR ORDER

MATERIAL USED

QTY	PART NO.	DESCRIPTION	PRICE	WARRANTY YES/NO
1	UF40803	OIL FILTER		27 "
1	XB1093R	DENNY DUBLY WASH		1 qm
1	W1281	OIL STABILIZER		12 35
9	QUARTS	20W/50 ENGINE OIL		42 75
6	QUARTS	ATF		28 50
2	QUARTS	CASTROL LMA		33 98
7	UB1248	MOULDING CLIP		15 47
4	UB1248	FEMALE STUD		15 68
		CLIP		15 68
		OUTSIDE REPAIRS		\$178 40
BROUGHT FORWARD				
TOTAL PARTS				
TOTAL ACCESSORIES				

MICHAEL J. VEYS
 P.O. Box 829
 LARKSPUR, CAL 94977

(415) 847-8870.

NAME: _____ DATE: 2-28-11
 ADDRESS: _____
 MAKE: RLS RYCE | TYPE OR MODEL: SONOMA, CA 95
 SERIAL NO.: _____ | ENGINE NO.: _____
 ODOMETER: 70787 | LICENSE NO.: 5SMU960 | TERMS: _____
 ORDER WRITTEN BY: NGV (707) _____ | PHONE WHEN READY: YES NO
 PROMISED: _____

OPER. NO. INSTRUCTIONS

A/ Passenger moulding strip.
 - remove from vehicle and straighten as best as possible. Remove broken clips and re-install. 125 -
 B/. Change engine oil & filter transmission fluid and bleed/flush hydraulic circuits check and adjust all levels, tyres, lights. Adjust all doors to eliminate "clunk" & "rattles." 150 -

You are entitled to a price estimate for the repairs you have authorized. The repair price may be less than the estimate, but will not exceed the estimate without your permission. Your signature will indicate your estimate selection. Teardown estimate - I understand that my car will be reassembled within _____ days of the date shown if I choose not to authorize the services recommended.

- I request an estimate in writing before you begin repairs.
- Please proceed with repairs, but call me before continuing if the price will exceed \$_____
- I do not want an estimate.

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways or elsewhere for the purpose of testing and / or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND OUR CONTROL.	GAS, OIL, & GREASE	PRICE
<input checked="" type="checkbox"/>	GALS. GAS	①
	QTS. OIL	②
	LBS. GREASE	③
	TOTAL GAS, OIL, & GREASE	

METHOD OF PAYMENT:

CASH CHECK CHARGE FLAT RATE HOURLY BOTH

TOTAL LABOR	TOTAL PARTS	TOTAL AMOUNT

DSS	ISU	LABOR CHARGE
<input checked="" type="checkbox"/>	Lubrication	
<input checked="" type="checkbox"/>	Change Oil	
<input checked="" type="checkbox"/>	Change Oil Filter Cart.	
<input checked="" type="checkbox"/>	Change Trans.	
<input type="checkbox"/>	Change Diff.	
<input type="checkbox"/>	Pack Front Wheel Brgs.	
<input checked="" type="checkbox"/>	Adjust Brakes	
<input type="checkbox"/>	Rotate Tires	
<input type="checkbox"/>	Wash Polish	
<input type="checkbox"/>	State Inspection	

REPAIR ORDER

MICHAEL J. VEYS

MATERIAL USED				
QTY	PART NO.	DESCRIPTION	PRICE	WARRANTY NO.
		BROUGHT FORWARD		
		TOTAL PARTS		
		ACCESSORIES		
		PRICE		
		TOTAL ACCESSORIES		

NAME	DATE	ISS	ISJ	LABOR CHARGE
ADDRESS	2-28-11	Lubrication	<input type="checkbox"/>	
MAKE	TYPE OR MODEL	Change Oil	<input type="checkbox"/>	
RIS RYE	YEAR	Change Oil Filter Cart	<input type="checkbox"/>	
SERIAL NO.	ENGINE NO.	Change Trans.	<input type="checkbox"/>	
ODOMETER	RECEIVED	Change Diff.	<input type="checkbox"/>	
90787	ENGINE NO.	Pack Front Wheel Brgs.	<input type="checkbox"/>	
LICENSE NO.	PROMISED	Adjust Brakes	<input type="checkbox"/>	
SSN 960.	PHONE WHEN READY	Rotate Tires	<input type="checkbox"/>	
ORDER WRITTEN BY	<input type="checkbox"/> YES <input type="checkbox"/> NO	Wash Polish	<input type="checkbox"/>	
	PHONE	State Inspection	<input type="checkbox"/>	

INSTRUCTIONS:

OPER. NO.

a) Remove R/R passenger door panel and make adjustments so door operates correctly. \$100 -

b) Lubricate all internal parts as necessary.

c) Remove driver's door panel - check for power to window operation - Good. Remove window regulator & examine - worn gear bearing and internal components all good. Further diagnosis revealed an intermittent window motor function, Sublet for overhaul, Reft upon return and Test - operating fine. 400 -

1. I request an estimate in writing before you begin repairs.

2. Please proceed with repairs, but call me before continuing if the price will exceed \$

3. I do not want an estimate.

I hereby authorize the above repair work to be done using the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways or elsewhere for the purpose of testing and / or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND OUR CONTROL.

METHOD OF PAYMENT:

CASH

CHECK

CHARGE

FLAT RATE

HOURLY

BOTH

TOTAL LABOR	475 -	
TOTAL PARTS	178 40	
ACCESSORIES	3 50	
GAS, OIL & GREASE	50 -	
OUTSIDE REPAIRS	255 -	
RIGHT INVOICE	22 50	
TAX	15 37	
TOTAL AMOUNT	1299 77	

REPAIR ORDER

MICHAEL J. VEYS
P.O. Box 829
LARKSPUR, CA 94977
(415) 847-8870

NAME: _____ DATE: 7-12-09
ADDRESS: _____
MAKE: _____ TYPE OR MODEL: SONORA
YEAR: 79 RECEIVED
SERIAL NO.: SRK36401 ENGINE NO.: _____
ODOMETER: 69782 LICENSE NO.: SSMN960
TERMS: _____ PHONE WHEN READY: YES NO
ORDER WRITTEN BY: _____ PHONE: _____
A.M. P.M.

DSS	ISJ	LABOR CHARGE
<input type="checkbox"/>	<input type="checkbox"/>	Lubrication
<input type="checkbox"/>	<input type="checkbox"/>	Change Oil
<input type="checkbox"/>	<input type="checkbox"/>	Change Oil Filter Cart.
<input type="checkbox"/>	<input type="checkbox"/>	Change Trans.
<input type="checkbox"/>	<input type="checkbox"/>	Change Diff.
<input type="checkbox"/>	<input type="checkbox"/>	Pack Front Wheel Bigs.
<input type="checkbox"/>	<input type="checkbox"/>	Adjust Brakes
<input type="checkbox"/>	<input type="checkbox"/>	Rotate Tires
<input type="checkbox"/>	<input type="checkbox"/>	Wash Polish
<input type="checkbox"/>	<input type="checkbox"/>	State Inspection

QTY	PART NO.	DESCRIPTION	PRICE	WARRANTY YES
1	5K34900-2	TRANSMISSION RESEAL KIT	74.88	
1	34661A	TRANSMISSION FILTER + BASKET	28.14	
12	QUARTS	ATF	54.00	
3	PS110173PA	10' RING SEALS	4.50	
1	RA12342	TIMING COVER GASKET	27.91	
1	VE33113	BOBBIN ROPE	229.45	
1	CK955	SEAL: VEHIC CASE	11.82	
2	XB6211	10' RING SEALS	16.22	
1	RH1256	BOBBIN GASKET	12.40	
2	VE9333	BOBBIN 10 RINGS	18.60	
1	VE5608	TIMING COVER NEOPRENE SEAL	31.04	
2	UG139	SR TRANSMISSION OUTSIDE REPAIRS COOLER HOSES	182.50	
1	VE41094ASX	WATER PUMP	485.00	
3	VR5665	EXHAUST NUT	18.75	
3	UR5666	EXHAUST BOLTS	25.74	
8	QUARTS	20W/50 ENGINE OIL BROUGHT FORWARD	36.00	
TOTAL PARTS			11256.95	
ACCESSORIES				
4	P-33	BRAKE-SOLVENT CLEANER	15.80	
2	QUARTS	COOLANT	27.00	
1	LCS10001	OIL STABILIZER	12.39	
TOTAL ACCESSORIES			55.19	

OPER NO: _____ INSTRUCTIONS:

A/ REMOVE TRANSMISSION AND RESEAL FRONT PUMP AND TAIL HOUSING + PERFORM OUTER WATER RESEAL OF UNIT. REPLACE TRANSMISSION FILTER, AND COOLER HOSES TO TRANS, RADIATOR

B/ RESEAL LEAKING FRONT ENGINE TIMING COVER + REPLACE LEAKING WATER PUMP ALSO.

C/ SUBLET TO EXHAUST SHOP FOR REPAIR OF EXHAUST CROSS-OVER / BALANCE PIPE 25.00

You are entitled to a price estimate for the repairs you have authorized. The repair price may be less than the estimate, but will not exceed the estimate without your permission. Your signature will indicate your estimate selection.
Teardown estimate - 1 - understand that my car will be reassembled within _____ days of the date shown if I choose not to authorize the services recommended.

1. I request an estimate in writing before you begin repairs.
2. Please proceed with repairs, but call me before continuing if the price will exceed \$ _____
3. I do not want an estimate.

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND OUR CONTROL.

METHOD OF PAYMENT:

CASH CHECK CHARGE FLAT RATE HOURLY BOTH

TOTAL LABOR	TOTAL PARTS	TOTAL AMOUNT
1675.00	1256.95	2931.95
	55.19	2987.14
		TAX

1979 Rolls-Royce

OIL LEAKS :

- 1) FRONT TIMING COVER OF ENGINE
- 2). FRONT PUMP SEAL OF TRANSMISSION.

ENGINE NOISE :

Ticking noise is normal on start ups while brake system pressurizes. If it does so when engine is warm and has been running a while with the brakes fully pressurized then there may be a "lifter" noise coming from the "valve train" of the engine. If the ticking noise comes & goes with the engine warm then the brakes may be pressurizing if the brakes have been used in stop & go traffic.

The front brakes may need replacing @ next service interval and the brake pressure system (accumulators) may need rebuilding too. (Next service should be in spring of 2010 with an oil change in between depending on how many miles driven.

In the rear of the car you may hear a whining noise with the engine idling. This is the fuel pump -

it is starting to get a little old. They are no longer available but I have sourced a replacement that works just as well with the same pressure and is relatively inexpensive.

Please call with any questions. As mentioned the speedometer needs ~~rebuilding~~ ^{opening up} in order to find out the problem of its lights and the battery will need replacing ~~it~~ within the year. Keep it on its "battery tender" unit.

REPAIR ORDER

MICHAEL J. VEYS
P.O. Box 829
LARKSPUR, CA 94941
(415) 847-8870.

NAME: _____ DATE: 12-16-08
ADDRESS: 151 ST. SAN ANTONIO CA 95436
MAKE: _____ TYPE OR MODEL: _____ YEAR: 99 RECEIVED
DRIS RYFE SILVER SHDN 39 ENGINE NO. _____ PROMISED
SERIAL NO. _____ ENGINE NO. _____ A.M. P.M.
ODOMETER: 69461 LICENSE NO. 55MND60 TERMS: _____ PHONE WHEN READY
ORDER WRITTEN BY: _____ PHONE: _____ NO

DSS	ISI	LABOR CHARGE
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	

QTY	PART NO	DESCRIPTION	PRICE	WARRANTY YES	WARRANTY NO
1	VF40093	OIL FILTER		35	21
1	XB1093R	DRAIN Plug Washer		2	14
2	QUARTS	LMA CASTROL			
		BRAKE FLUID		31	50
4	QUARTS	ATF		18	00
2	GALLONS	COOLANT		32	-
1	RSOLENE	ENGINE OIL		8	75
		CLEANSER			
9	QUARTS	20W/50 ENGINE OIL		36	-
2	50/100	Light Bulbs		4	-
			\$157		60
		OUTSIDE REPAIRS			
		BROUGHT FORWARD			
		TOTAL PARTS			

QTY	ACCESSORY NO	ACCESSORIES	PRICE	WARRANTY YES	WARRANTY NO
1	P-37	CARS CLEANER		3	95
		TOTAL ACCESSORIES		3	95

INSTRUCTIONS

1. Perform 6-month service including Hydraulic Pressure Test
- change engine oil & filter
- transmission & coolant
- Flush hydraulic systems
- Check carbration & timing, Perform overall safety inspection
2. Lubricate & clean contacts of both front & rear switches & gearing
3. 300 -
95 -

You are entitled to a price estimate for the repairs you have authorized. The repair price may be less than the estimate, but will not exceed the estimate without your permission. Your signature will indicate your estimate selection.
Tear-down estimate - I understand that my car will be reassembled within _____ days of the date shown if I choose not to authorize the services recommended.

1. I request an estimate in writing before you begin repairs. _____
2. Please proceed with repairs, but call me before continuing if the price will exceed \$ _____
3. I do not want an estimate. _____

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

METHOD OF PAYMENT:		TOTAL LABOR
<input type="checkbox"/> CASH	<input type="checkbox"/> CHECK	385 -
<input type="checkbox"/> CHARGE	<input type="checkbox"/> FLAT RATE	167.60
<input type="checkbox"/> HOURS	<input type="checkbox"/> HOURLY	37.95
<input type="checkbox"/> BOTH	<input type="checkbox"/> BOTH	20 -
TOTAL PARTS		
TOTAL LABOR		
TOTAL ACCESSORIES		
GAS, OIL & GREASE		
OUTSIDE REPAIRS		
TAX		
TOTAL AMOUNT		576.55

GOODYEAR AUTO SERVICE CENTER

INVOICE
117959

A DIVISION OF THE GOODYEAR TIRE & RUBBER COMPANY
1790 SOUTH BASCOM AVE
CAMPBELL, CA 95008-0608
BAR REG# AK180689, I.D. CAL000141541
FEDERAL TAX ID# 340253240
(408)369-8293 HOURS 7-6MON-FRI, 8-5SAT, 9-4SUN



PAGE: 01
BILL TO: RD
SUNUMA, CA 95470

PHONE 1..... (707)484-5551 EXT.
PHONE 2.....
RETURN PARTS.. NO
PRIOR INVOICE. NEW CUSTOMER
DATE REQUESTED 03/23/07

VEH YEAR/MAKE. 79 ROLLS ROYCE
VEHICLE MODEL. SILVER SHADOW II
VEHICLE COLOR. BLUE
LICENSE/STATE. 5SMN960 / CA
TIME REQUESTED

ODOMETER IN/OUT 067572 / 067572
VEHICLE IN.....03/23/07 07:20 AM
VEHICLE OUT....03/23/07 08:41 AM
TERR/NONSIG... 8723/908723
SALESMAN..... 003 / 003

ACCOUNT # COB TC CUST# TYPE/STATE AUTHORIZATION CREDIT CARD NO.
872300005 A 01 01659 0 CA 505230 2000

SLS TECH	PRODUCT CODE	BC QTY	DESCRIPTION	UNIT PRICE	LBR/EXCISE	LINE TOTAL
003	187-019-026-0 QTY. 1 NO.	R 4	P235/75R15 105S S2 REGATTA 2 XNWRPTL MKHLNTJR3105 QTY. 3 NO. MKHLNTJR3906	102.95	2.95- .00	400.00
003 063	044-275	R 4	WHEEL BALANCE - AUTO - LIFETIME	5.95	10.00	63.80
003 063	041-263	R 4	NEW VALVE STEM	3.25	.00	13.00

SUMMARY:

PARTS TOTAL..... 448.60
LABOR TOTAL..... 40.00
TAXABLE AMOUNT 436.80
DISCOUNT PARTS..... 11.80
SUB TOTAL..... 476.80
SALES TAX(8.250%) 36.04

X-----
CUSTOMER AUTHORIZATION FOR TOTAL

INVOICE TOTAL

CHARGED AMOUNT 519.84
STATE TIRE FEE 7.00

\$519.84

WE RECOMMEND OUR ROAD HAZARD WARRANTY AND ROTATE EVERY 5000 MILES

IF APPLICABLE.

I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATE PRICE. SIGNATURE _____

THANK YOU FOR YOUR BUSINESS! IF YOU ARE NOT 100% SATISFIED,
PLEASE CONTACT THE STORE MANAGER, AT (408)369-8293

SLS ASSOC(S)
003 ROBERT B.

TECHNICIAN(S)
063 THANH C.

TREAD DEPTH L/F..... 10/32
TREAD DEPTH R/F..... 10/32
TREAD DEPTH R/R..... 10/32
TREAD DEPTH L/R..... 10/32

AUTHORIZED BY. JEFF
AUTH PHONE.... 000-0000
REVISED TOTAL. 483.80

AUTH REC'D BY. ROBERT B
AUTH DATE.... 03/23/07
ADD'L AMOUNT.. 483.80

MANNER REC'D.. IP
AUTH TIME.... AM
REPAIRS DESC.. TIRES

ALL PARTS ARE NEW UNLESS OTHERWISE SPECIFIED
SEE REVERSE SIDE FOR IMPORTANT SAFETY WARNING AND WARRANTY INFORMATION

REPAIR ORDER

MICHAEL J. VEYS
 P.O. Box 829
 LARKSPUR, CA 94977
 (415) 847-8870.

NAME	1	DATE	5-2-07
ADDRESS			
MAKE	TYPE OR MODEL	YEAR	RECEIVED
RLS-Ryce	SILVER SHAWA	99	SONOMA CALIF
SERIAL NO.	ENGINE NO.	PROMISED	
ODOMETER	LICENSE NO.	TERMS	PHONE WHEN READY
67798	5SMN960		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
ORDER WRITTEN BY		PHONE	
			90

OPER NO.	INSTRUCTIONS	DSS	ISU	LABOR CHARGE
	Brake Pressure Switch Lighted - stays on.	Lubrication	<input type="checkbox"/>	
	- contacts in switch were faulty - overhauled as needed.	Change Oil	<input type="checkbox"/>	
	Replace left rear indicator bulb for turn signal operation.	Change Oil Filter Cart.	<input type="checkbox"/>	
		Change Trans.	<input type="checkbox"/>	
		Change Diff.	<input type="checkbox"/>	
		Pack Front Wheel Bgs.	<input type="checkbox"/>	
		Adjust Brakes	<input type="checkbox"/>	
		Rotate Tires	<input type="checkbox"/>	
		Wash Polish	<input type="checkbox"/>	
		State Inspection	<input type="checkbox"/>	

QTY	PART NO.	DESCRIPTION	PRICE	WARRANTY YES	WARRANTY NO
1	UD18721	Diaphragm		34	12
1	UD18796	Plunger		28	40
1	QUART	Castrol Brake Fluid		12	50
1	CB1156	Light Bulb		2	-
		OUTSIDE REPAIRS			
		BROUGHT FORWARD			
		TOTAL PARTS		77	02
		TOTAL ACCESSORIES			

You are entitled to a price estimate for the repairs you have authorized. The repair price may be less than the estimate, but will not exceed the estimate without your permission. Your signature will indicate your estimate selection. Teardown estimate - I understand that my car will be reassembled within _____ days of the date shown if I choose not to authorize the services recommended.

1. I request an estimate in writing before you begin repairs. _____

2. Please proceed with repairs, but call me before continuing if the price will exceed \$ _____

3. I do not want an estimate. _____

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND OUR CONTROL.

GAS, OIL, & GREASE	PRICE
GALS. GAS @	
QTS. OIL @	
LBS. GREASE @	
TOTAL GAS, OIL, & GREASE	

METHOD OF PAYMENT:

CASH CHECK CHARGE

LABOR: FLAT RATE HOURLY BOTH

TOTAL LABOR	
TOTAL PARTS	77.02
ACCESSORIES	
GAS, OIL & GREASE	
OUTSIDE REPAIRS	
TAX	
TOTAL AMOUNT	77.02

REPAIR ORDER

MICHAEL J. VEYS
 P.O. Box 829
 LARKSPUR, CALIF 94977
 (415) 847-8870

paid 1/10
 2/1/06
 ck # 877 (JW)

QTY	PART NO.	MATERIAL USED	DESCRIPTION	PRICE	WARRANTY YES	WARRANTY NO
			WIRE & CONNECTORS		5--	
BROUGHT FORWARD						
TOTAL PARTS						
TOTAL ACCESSORIES						

NAME: _____ DATE: 1-31-06.
 ADDRESS: _____
 MAKE: RUS RYCE SONOMA CALIF
 TYPE OR MODEL: SWR SHDN 79 YEAR: 79
 SERIAL NO.: _____ ENGINE NO.: _____
 ODOMETER: 66250 LICENSE NO. F93 RBH TERMS: _____
 ORDER WRITTEN BY: _____ PHONE WHEN READY: YES NO
 PROMISED: _____
 A.M. P.M.

OFFER NO. _____ INSTRUCTIONS: _____

DSS	ISU	LABOR CHARGE
<input type="checkbox"/>	<input type="checkbox"/>	
<input type="checkbox"/>	<input type="checkbox"/>	
<input type="checkbox"/>	<input type="checkbox"/>	
<input type="checkbox"/>	<input type="checkbox"/>	
<input type="checkbox"/>	<input type="checkbox"/>	
<input type="checkbox"/>	<input type="checkbox"/>	
<input type="checkbox"/>	<input type="checkbox"/>	
<input type="checkbox"/>	<input type="checkbox"/>	
<input type="checkbox"/>	<input type="checkbox"/>	
<input type="checkbox"/>	<input type="checkbox"/>	
<input type="checkbox"/>	<input type="checkbox"/>	
<input type="checkbox"/>	<input type="checkbox"/>	

A. Repair wiring to ignition coil from ignition amplifier.
 B. SITE VISIT: road test and check fluids & operation of vehicle = OK

You are entitled to a price estimate for the repairs you have authorized. The repair price may be less than the estimate, but will not exceed the estimate without your permission. Your signature will indicate your estimate selection.
 Teardown estimate - I understand that my car will be reassembled within _____ days of the date shown if I choose not to authorize the services recommended.

1. I request an estimate in writing before you begin repairs. _____
 2. Please proceed with repairs, but call me before continuing if the price will exceed \$ _____
 3. I do not want an estimate. _____

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck therein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

X

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND OUR CONTROL.	GAS, OIL, & GREASE	PRICE
<input type="checkbox"/>	GALS GAS @	
<input type="checkbox"/>	QTS OIL @	
<input type="checkbox"/>	LBS. GREASE @	
<input type="checkbox"/>	TOTAL GAS, OIL, & GREASE	

METHOD OF PAYMENT: CASH CHECK CHARGE FLAT RATE HOURLY BOTH

TOTAL LABOR	TOTAL PARTS	ACCESSORIES	GAS, OIL & GREASE	OUTSIDE REPAIRS	TAX	TOTAL AMOUNT
175-	5-					180-

REPAIR ORDER

MICHAEL J. VEYS
P.O. Box 829
LARKSPUR, CA 94977
(415) 847-8870.

QTY.	PART NO.	DESCRIPTION	PRICE	WARRANTY	
				YES	NO
1	UE40893	OIL FILTER		36	03
1	XE10932	DRAIN PUL WSKR		2	09
1	UD1511	FLASHER UNIT		47	51
2	UD11158	GRONMET		23	90
1	1-45552	TRANSMISSION FILTER		25	14
2	QAL00NS	COOLANT		23	-
5	QVARS	ATF		14	75
2	QVARS	CASTROL BRAKE			
		LMA FLUID		23	92
2	QVARS	MOBIL 1 10W/30		11	90
1	6418	BULBS		2	89
1	7911	BULBS		1	89
		"			
		"	\$2.13		02
		OUTSIDE REPAIRS			
		BROUGHT FORWARD			
		TOTAL PARTS			
		TOTAL ACCESSORIES			
		TOTAL ACCESSORIES		10	15

NAME: _____ DATE: 1-26-07
ADDRESS: _____
MAKE: _____ TYPE OR MODEL: SONOMA
YEAR: 79 RECEIVED: _____
SERIAL NO.: _____ ENGINE NO.: _____ PROMISED: _____
AM. P.M.

ODOMETER: 67194
LICENSE NO.: 5SMN960
TERMS: _____
PHONE WHEN READY: YES NO
ORDER WRITTEN BY: _____ PHONE: _____

INSTRUCTIONS

OPER. NO. _____

1/ REPLACED PERISHED GRONMETS OF BLEND FLAP FOR INTERIOR / EXTERIOR AIR CONTROL

2/ INDICATORS DO NOT FLASH

3/ Change signal flasher unit. Replaced as needed.

4/ Change Engine oil + filter, transmission fluid + filter, coolant + flush / bleed out entire hydraulic system.

5/ ADJUST WIPERS TO PARK PROPERLY

LABOR CHARGE: N/C

You are entitled to a price estimate for the repairs you have authorized. The repair price may be less than the estimate, but will not exceed the estimate without your permission. Your signature will indicate your estimate selection.

Teardown estimate - I understand that my car will be reassembled within _____ days of the date shown if I choose not to authorize the services recommended.

1. I request an estimate in writing before you begin repairs. _____

2. Please proceed with repairs, but call me before continuing if the price will exceed \$ _____

3. I do not want an estimate. _____

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and / or your employees permission to operate the car or truck herein described on streets, highways or elsewhere for the purpose of testing and / or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND OUR CONTROL.

GAS, OIL & GREASE

PRICE: 35-
35-
20 65

LABOR: FLAT RATE CHECK CHARGE

HOURLY BOTH

METHOD OF PAYMENT:		TOTAL LABOR	LABOR CHARGE
<input type="checkbox"/> CASH	<input type="checkbox"/> CHECK	490	-
<input type="checkbox"/> CHARGE	<input type="checkbox"/> FLAT RATE	213	02
<input type="checkbox"/> BOTH	<input type="checkbox"/> HOURLY	10	15
	<input type="checkbox"/> BOTH	55	65
		TOTAL PARTS	
		TOTAL ACCESSORIES	
		TOTAL LABOR	
		TOTAL AMOUNT	768 82

Mr. _____

11/23/05

This alternator has a slightly different set up when the engine is started.

The amp gauge will show no reaction until you give the engine a rev-up. This is because you are kicking in the "field current" of the alternator when you give the engine some revs. After this everything works as normal and before.

The amp gauge is very accurate in terms of the current being supplied to the battery. A fully charged battery @ idle with no excessive draws (ie headlights, blower motor on high) will show the amp gauge ~~a notch~~ ^{just} on the positive side of the centre. Excessive draw @ idle + in gear will show a negative reading but raise the revs slightly and it goes straight to positive charge.

Any questions please call.

You have had a squirrel making a home in the engine. He took the insulation of the hood sound insulation and made a really nice nest on the carburettors! There appears to be no damage but if

REPAIR ORDER

MATERIAL USED

QTY	PART NO.	DESCRIPTION	PRICE	WARRANTY YES	WARRANTY NO.
1	UD7528	ALTERNATOR (EXCH)	430	02	
2	H5001	HIGH BEAM LIGHTS	24	50	
BROUGHT FORWARD					
TOTAL PARTS					
ACCESSORIES					
PRICE					
WARRANTY					
TOTAL ACCESSORIES					

MICHAEL J. VEYS
 P.O. Box 829
 LARKSPUR, CA 94977
 (415) 847-8870

NAME: _____ DATE: 11-23-05
 ADDRESS: SONOMA CALIF
 MAKE: RLS-RYCE TYPE OR MODEL: SILVER SHADOW II YEAR: 79
 SERIAL NO.: _____ ENGINE NO.: _____
 ODOMETER: 66078 LICENSE NO.: F93 BBH TERMS: _____
 ORDER WRITTEN BY: _____ PHONE: _____

OPER NO. INSTRUCTIONS

A/ BATTERY LOSING CHARGE!
 - replace defective alternator and
 check charging - OK. 130 -
 B/ Replace both High Beam headlights.

DSS	ISJ	LABOR CHARGE
<input type="checkbox"/>	<input type="checkbox"/>	Lubrication
<input type="checkbox"/>	<input type="checkbox"/>	Change Oil
<input type="checkbox"/>	<input type="checkbox"/>	Change Oil Filter Cart.
<input type="checkbox"/>	<input type="checkbox"/>	Change Trans.
<input type="checkbox"/>	<input type="checkbox"/>	Change Diff.
<input type="checkbox"/>	<input type="checkbox"/>	Pack Front Wheel Brgs.
<input type="checkbox"/>	<input type="checkbox"/>	Adjust Brakes
<input type="checkbox"/>	<input type="checkbox"/>	Rotate Tires
<input type="checkbox"/>	<input type="checkbox"/>	Wash Polish
<input type="checkbox"/>	<input type="checkbox"/>	State Inspection

You are entitled to a price estimate for the repairs you have authorized. The repair price may be less than the estimate, but will not exceed the estimate without your permission. Your signature will indicate your estimate selection. Teardown estimate - I understand that my car will be reassembled within _____ days of the date shown if I choose not to authorize the services recommended.

1. I request an estimate in writing before you begin repairs.
 2. Please proceed with repairs, but call me before continuing if the price will exceed \$ _____
 3. I do not want an estimate.

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

QTY	ACCESSORY NO.	ACCESSORIES	PRICE	WARRANTY YES	WARRANTY NO.
TOTAL PARTS					
ACCESSORIES					
PRICE					
WARRANTY					
TOTAL ACCESSORIES					

METHOD OF PAYMENT:		TOTAL LABOR	TOTAL PARTS	TOTAL AMOUNT
<input type="checkbox"/>	CASH	130	-	
<input type="checkbox"/>	CHECK	454	50	
<input type="checkbox"/>	CHARGE			
<input type="checkbox"/>	FLAT RATE			
<input type="checkbox"/>	HOURLY			
<input type="checkbox"/>	BOTH			
LABOR:				
GAS, OIL & GREASE				
OUTSIDE REPAIRS				
TAX				
TOTAL AMOUNT		584	50	

(707) 996 8306

To:

Sept 2, '05.

From: Michael Vays.

(415) 384-0772 tel.

(415) 847-8870 cell.

I am hoping that this weekend the car will be finished. I have not yet received the Fan Clutch from England, a delay in shipping it as a result of waiting for another part to be shipped with it. Hopefully it will arrive today as they confirmed it was shipped out last Friday.

I will top up the A/C refrigerant as it can blow colder and you will notice the difference. The only variable left @ this stage is the clicking noise under the dash.

I have had two additional keys made.

Is there a contact number I can reach you over the weekend. The reason being is that I am moving shop to a slightly larger unit @ the other end of the alley and one less car with all the clutter of moving makes it a little easier!

Thank you,

Michael Vays.

REPAIR ORDER

MICHAEL J. VEYS
 P.O. Box 829
 LARKSPUR, CA 94977
 (415) 384-0772

paid 10/1/05 \$830

QTY	PART NO.	DESCRIPTION	PRICE	QTY	PRICE
1	UG133FT	CAP SEAL	49	15	
1	UE33635	THERMOSTAT gskt	8	12	
1	UE36600	THERMOSTAT	138	66	
1	USED	AUXILIARY FAN SWITCH	54	06	
1	UR13808	UPPER RAD. HOSE	74	39	
1	UR13807	UPPER RAD. HOSE	74	90	
1	UR13761	BYPASS RAD HOSE	63	20	
1	UR13725	EXPTANK/RAD HOSE	31	14	
1	UR13739	HEATER FEED HOSE	36	95	
2	QALONS	COOLANT	22	50	
1	UE37810	WATER PUMP BELT	45	52	
1	SPC2680	AIR PUMP BELT	35	08	
1	SPC2183	ALTERNATOR BELT	23	28	
1	SPC2717	AIR CON BELTS	59	88	
1	WE821	FAN CLUTCH	32	13	
8	HOSE	OUTSIDE REPAIRS CLAMPS	12	-	
6	QUARTS	TRANSMISSION FLUID	17	70	
1	USED	LICENSE PLATE LENS ST	-	-	
2	UBR2425	BONNET STOPS	8	56	
BROUGHT FORWARD			1128	72	
TOTAL PARTS					

NAME: _____ DATE: **OCT 3, '05**

ADDRESS: _____

MAKE: **RIS-RYCE** TYPE OR MODEL: **S. SHDW II** YEAR: **'79** RECEIVED: _____ AM/PM

SERIAL NO.: _____ ENGINE NO.: _____ PROMISED: _____ AM/PM

ODOMETER: _____ LICENSE NO.: _____ TERMS: _____ PHONE WHEN READY: YES NO

ORDER WRITTEN BY: _____ PHONE: _____

VEHICLE OVERHEATS:
 - remount radiator & sublet for RECORE
 - flush engine & replace thermostat
 - replace auxiliary fan switch
 - replace radiator coolant hoses

REPAIRS:
 B. Replace Engine Drive Belts
 C. Repair wiring to auxiliary fan switch & "ICE" wiring sensor
 D. Replace Engine Oil

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND OUR CONTROL.

TOTAL GAS, OIL, & GREASE: _____

TOTAL OIL, & GREASE: _____

QTS. OIL: **20W/50** PRICE: **26 55**

LABOR: FLAT RATE HOURLY BOTH

METHOD OF PAYMENT: CASH CHECK CHARGE

TOTAL LABOR: **480 -**

TOTAL PARTS: **1128 72**

ACCESSORIES: **578 41**

GAS, OIL & GREASE: **26 55**

OUTSIDE REPAIRS: _____

SHIPPING: **27 78**

TAX: _____

TOTAL AMOUNT: **2241 46**

To: _____

Sept 2, '05.

From: Michael Vays.

(415) 384-0772 tel.

(415) 847-8870 cell.

I am hoping that this weekend the car will be finished. I have not yet received the Fan Clutch from England, a delay in shipping it as a result of waiting for another part to be shipped with it. Hopefully it will arrive today as they confirmed it was shipped out last Friday.

I will top up the A/C refrigerant as it can blow colder and you will notice the difference. The only variable left @ this stage is the clicking noise under the dash.

I have had two additional keys made.

Is there a contact number I can reach you over the weekend. The reason being is that I am moving shop to a slightly larger unit @ the other end of the alley and one less car with all the clutter of moving makes it a little easier!

Thank you,
Michael Vays.

P.O. Box 829
LARKSPUR, CA 94977

To:
FROM: MICHAEL VEYS.

Work has begun and everything is removed and ready for re-installation.

The cost of a FAN CLUTCH from England (and it is new) is £175-, so with shipping @ the current exchange rate of approx £1 = \$1.73 the total cost will be about \$335-. Therefore the repairs, excluding the clicking of the relay in the dash, will be approx \$2000-.

I will go ahead and order the fan clutch from England, unless you say otherwise.

I have about 4 jobs ongoing at the moment, which have made a big dent in my cash flow. If it is possible to advance a $\frac{1}{3}$ of the proposed costs to offset some of the costs it would be very much appreciated.

Please call if you have any questions.

Michael Vey's.

paid \$1,000 on 8/4/05
J.A. ck # 810

7/29/05

To: _____

FROM: MICHAEL VEYS.

I did some diagnostic work before removing the radiator to see if any other problems existed with the cooling system efficiency. Unfortunately there are a couple of other items that need attention.

a). The fan clutch → this is designed to rotate @ a fast speed when the engine is idling in order to draw air thru' the radiator fins to maximise air flow and cooling efficiency. This fan clutch is not operating. I can stop the fan rotating while the engine is running because the fan clutch has not "locked" on. A new fan clutch is \$475, but since they are normally fairly reliable units I am trying to source a good used one.

b). Auxilliary fan switch - this is located in the thermostat housing and is designed to activate the auxilliary fan (electric fan behind radiator grille + pushes air thru' radiator matrix) when the engine starts getting hot. Did you hear the auxilliary fan "kick-

in" when the engine got hot? Again I am trying to source a good used one as the new style is not a very clever design in my opinion.

c). RADIATOR = is in poor condition - has poor "cross-flow" and is corroding @ the joints due to exposure to salt air (according to radiator shop). It needs to be recored - cost of recore is \$575 -

As I mentioned it is prudent to replace the remainder of the coolant hoses and thermostat as well as radiator cap seal as vapour seeps out of a worn seal.

d). With the radiator removed + bonnet (hood) off the car, as well as radiator grille removed to access ICE warning sensor, accessibility and viewing the condition of the drive belts is excellent. Again the condition of these is far worse than I thought and I am actually surprised some haven't broken. It is therefore essential that they be replaced as you are driving on "borrowed time" for these belts. Labour charge to replace the belts is also reduced by more than half since accessibility is so good.

e). ICE warning sensor - the location of this is ~~by the~~ behind the radiator grille and upon

inspection the problem lies in the wiring - it is either completely corroded or very brittle. The same can be said for the auxiliary fan (same location) but this was still intact. The cost to clean up ~~the~~ all the wiring and make good is 1 hour = \$65 -

f). The clicking noise under the dash is coming from a relay clicking in and out. Of course when I removed the "knee-roll" panel to access the relays it stopped doing it so I have yet to isolate the problem.

To summarize the costs:

	LABOUR	PARTS.
a). Radiator repair/recore		\$575 -
Replace coolant hoses	\$350 -	\$300 -
Replace thermostat &		\$150 -
Radi. Cap Seal & auxiliary fan switch		\$475 NEW
*Fan clutch		? USED
b). Replace all drive belts	\$65 -	\$150 -
c). Repair wiring behind radiator grille	\$65 -	N/c.
d). Clicking relay in dash	?	

Please contact me if you have any questions,
but this work is almost mandatory in order to
prevent any further and possible bigger problems.

Michael ~~Ng~~

Michael: Go ahead and begin the work,
but let me know the cost
of the fan clutch.

uuu

7/31/05

To: T ... fax 16
tel 70

FROM: MICHAEL VEYS

11 ~~20~~ PAGES BEING FAXED.

Enclosed is an itemization of the bill and a breakdown of each cost in total against the ~~the~~ original estimate including revisions.

Most of the actual costs are close to the estimate, some a little less. The service costs includes all the solvents, chemicals and brake fluid for all work done on the car.

The biggest difference is in the Accumulator and Hydraulic Reservoir. The very original estimate was \$1285 total cost and then when you asked for a total cost estimate before the rear brake repair I mis-quoted the revised estimate to be \$990 instead of \$1442, but there were a couple of extra parts that brought the cost to \$1599. If this is confusing I understand but I will explain when you pick up the car.

There was "one more problem" that had to be fixed. I was on the way to get a smog inspection when I

noticed a "surging" motion in the drive of the car. I got out to inspect the engine area and could smell a strong fuel odor. What had happened was an 'o' ring that ~~feels~~^{seals} the carb fuel ~~pipe~~ feed pipe had perished. This fuel smell had to be fixed because of a fire threat. I removed the carburetors and resealed, cleaned all necessary components.

I have made as many savings as possible but it was necessary to replace the parts I have in the interest of safety and preferred maintenance.

I mentioned that the front brakes were not of factory type and missing their spring retaining clips. I have a good set of factory pads and spring clips which I will put on the car - hopefully this will take care of the intermittent brake squeal.

Look forward to seeing you tomorrow @ 2:00pm.
My cell phone is (415) 847-8870 if you need directions.

Thank you,

Michael Voss.

BREAKDOWN OF COSTS

<u>W/</u>	<u>ACTUAL</u>	<u>ESTIMATE</u> (includes revisions)
A/.	SERVICE \$ 1293 - ⁰⁹	1225 -
B/.	ACCUMULATORS + HYDRAULIC RESERVOIR \$ 1599 - ⁸²	1442 -
C/.	POWER STEERING \$ 387 - ⁹¹	380 -
D/.	ENGINE MOUNT \$ 124 - ¹⁴	126 -
E/.	VALVE COVERS \$ 700 - ⁸⁵	750 -
F/.	FRONT SUSPENSION \$ 2388 - ³⁷	2265 -
G/.	DISTRIBUTION VALVES BRAKE PUMPS \$ 488	450 -
H/.	LEFT REAR DOOR LOCK \$ 200 -	200 -
I/.	EXHAUST MANIFOLD \$ 414 - ⁹⁵	325 -
J/.	REAR BRAKES + HOSES \$ 1646 - ⁵⁴	1625 -
K/.	CLIMATE CONTROL \$ 162 162 - ⁵⁰	1625 425 -
L/.	REPAIR BROKEN PIPE \$ 65 -	65 -
M/.	EXHAUST MUFFLER SHOP \$ 310	250 -
N/.	SMOG CERTIFICATE \$ 77 - ²⁵	80 -
O/.	CARBURETTORS \$ 185 - ¹³	0
P/.	COWL TRIM PIECE \$ 75 -	0
	SALES TAX \$ 230 - ⁸⁸	250 -
	TOTAL \$ 10349 - ⁴³	\$ 9252 -

4/13/05

To: _____

From: Michael Veys

- my fax was out of paper so when we spoke I didn't know about this leak.

I received your hand-written note about the 10"-12" diameter of "petroleum product" under the left front end of the car.

The left front end of the car would be the ~~end~~ driver's side. The view of the engine is always taken as if you are sitting in the driver's side. The left side therefore being where the hydraulic reservoir is and the right side where the chain and bellow is for the cruise control.

I don't know whether this makes a difference towards the location of the petroleum product? If this leak is now located on the right front end of the car and is greenish/yellow in colour I know what & why it probably occurred - otherwise I haven't got a clue @ this point.

Please let me know if this changes anything and if the leak persists.

Thank you,

Michael Veys.

3-30-05.

To: JEFF WALTER

From: MICHAEL VEYS

1979 R-R.

The car is at the detail shop, and I will pick it up tomorrow (Thursday). I would like to arrange delivery for this weekend - either Saturday or Sunday.

I will fax to you the bill for you to review, and I wanted to ask if you would like a "battery tender" installing. If you are not using the car on a regular basis it might be a good idea to have a battery tender. It is effectively a battery charger that maintains the state of full charge to the battery while the car is not being used. It is permanently installed in the trunk (a small item) and plugs into an extension cord from a household socket. It costs about \$60 -

Thank you,

Michael Vey's.

REPAIR ORDER

MICHAEL J. VEYS
P.O. Box 829
LARKSPUR, CA 94977
(415) 384-0772

1

QTY	PART NO.	DESCRIPTION	PRICE	WARRANTY YES/NO
	SERVICE			
1	VE40893	OIL FILTER		31 24
3	X61093R	DRAIN PLUG WSHR		1 59
1	VE36200	AIR FILTER		46 09
2	VE35002	10' RING BREATHER		8 52
8	RN1490	SPARK PLUGS		26 32
1	QM-12401	TRANSMISSION FILTER		29 11
2	VE40809	AIR INT HOSE		68 94
1	VE40811	AIR INT. HOSE		106 27
1	UD24320	INJECT HEATER HOSE		53 62
1	VD22219	RETURN HEATER HOSE		65 10
6	FEET	FUEL HOSE		28 11
6	FEET	VACUUM HOSE		10 14
6	XO	HOSE CLAMPS		13 50
4	XO0	HOSE CLAMPS		7 80
4	VE4B342	OUTSIDE REPAIRS IGNITION WIRE CURS		48 -
2	P-37	INTAKE CARB CLEAN		7 90
8	P-38	BRAKE CLEANER		26 -
1	VE40872	FUEL FILTER		22 14
			\$ 600	39
BROUGHT FORWARD				
TOTAL PARTS				

NAME: _____ DATE: MAR 31, '05

ADDRESS: _____

MAKE: ROYCE TYPE OR MODEL: SILVER SHOU YEAR: 79 RECEIVED: _____ AM/PM

ROLL NO: _____ ENGINE NO: _____ PROMISED: _____ AM/PM

SERIAL NO: SAK 36401

ODOMETER: 65466 LICENSE NO: F93 BBH TERMS: _____ PHONE WHEN READY: YES NO

ORDER WRITTEN BY: _____ PHONE: _____

INSTRUCTIONS: PERFORM MAJOR SERVICE:
-replace all fluids & filters.
-replace spark plugs
-perform overall safety inspection
-also replace engine heater hoses (cooling)
-all fuel hoses & vacuum lines & air injection hoses.

STATE INSPECTION:

LABOR CHARGE: _____

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND OUR CONTROL.

LABOR: FLAT RATE HOURLY BOTH

METHOD OF PAYMENT: CASH CHECK CHARGE

TOTAL LABOR: _____

TOTAL PARTS: _____

ACCESSORIES: _____

GAS, OIL & GREASE: _____

OUTSIDE REPAIRS: _____

TAX: _____

TOTAL AMOUNT: _____

REPAIR ORDER

MICHAEL J. VEYS

#2

QTY	PART NO.	DESCRIPTION	PRICE	WARRANTY YES	WARRANTY NO
		BRAKE ACCUMULATORS			
2	RH2435	ACCUM VALVE BODY			
		SEAL KIT	168		52
2	RH2619	ACCUM SPHERE			
		SEAL KIT	196		45
2	UE10318	SEALING WASHERS	34		08
2	UE10147	CIRCUIT	6		52
2	UE10146	SPRING	8		74
2	UE10148	WASHER	14		46
2	UD18721	DIAPHRAGM	37		25
2	UD17876	PUNGER	19		26
2	VE36145	ALUMINUM WASHER	11		26
2	VE38482	VALVE	51		14
			\$544		68
		HYDRAULIC RESERVOIR			
		OUTSIDE REPAIRS			
2	SPC 1958	'01 RING SIGHT GLASSES	18		84
2	UR13114	GASKETS	35		34
2	UR14202	BRAKE PUMP FEEDER	57		64
4	UR1312	SIGHT GLASS SCREW	37		04
1	UR15342	ASSY OUTLET FILTER	65		42
1	UR13119	BROUGHT FORWARD FILTER	88		13
		TOTAL PARTS	\$502		14
		ACCESSORIES			
		PRICE			
		WARRANTY YES			
		WARRANTY NO			

NAME: _____ DATE: _____
 ADDRESS: _____
 MAKE: R-R TYPE OR MODEL: S. SHAWM. YEAR: _____ RECEIVED: _____
 SERIAL NO.: SRK 36401 ENGINE NO.: _____ PROMISED: _____
 ODOMETER: 65466 LICENSE NO.: _____ TERMS: _____ PHONE WHEN READY: YES NO
 ORDER WRITTEN BY: _____ PHONE: _____

OPER. NO. _____ INSTRUCTIONS: _____

DSS	ISJ	LABOR CHARGE
<input type="checkbox"/>	<input type="checkbox"/>	Lubrication
<input type="checkbox"/>	<input type="checkbox"/>	Change Oil
<input type="checkbox"/>	<input type="checkbox"/>	Change Oil Filler Cart.
<input type="checkbox"/>	<input type="checkbox"/>	Change Trans.
<input type="checkbox"/>	<input type="checkbox"/>	Change Diff.
<input type="checkbox"/>	<input type="checkbox"/>	Pack Front Wheel Bigs.
<input type="checkbox"/>	<input type="checkbox"/>	Adjust Brakes
<input type="checkbox"/>	<input type="checkbox"/>	Rotate Tires
<input type="checkbox"/>	<input type="checkbox"/>	Wash Polish
<input type="checkbox"/>	<input type="checkbox"/>	State Inspection

1. I request an estimate in writing before you begin repairs. _____
 2. Please proceed with repairs, but call me before continuing if the price will exceed \$ _____
 3. I do not want an estimate. _____

You are entitled to a price estimate for the repairs you have authorized. The repair price may be less than the estimate, but will not exceed the estimate without your permission. Your signature will indicate your estimate selection.
 Tear-down estimate - I understand that my car will be reassembled within _____ days of the date shown if I choose not to authorize the services recommended.

OVERHAUL BRAKE ACCUMULATORS:
 - reseat valve body
 - reseat sphere body
 - reseat pressure switch
 - Change sphere body with 1000 PSI of NITROGEN.
 OVERHAUL HYDRAULIC RESERVOIR:
 replace, seals, gaskets & screen filters.

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND OUR CONTROL.

GAS, OIL, & GREASE _____ PRICE _____
 GALS. GAS @ _____
 QTS. OIL @ _____
 LBS. GREASE @ _____
 TOTAL GAS, OIL, & GREASE _____

METHOD OF PAYMENT:
 CASH
 CHECK
 CHARGE
 FLAT RATE
 HOURLY
 BOTH

TOTAL LABOR _____
 TOTAL PARTS _____
 ACCESSORIES _____
 GAS, OIL & GREASE _____
 OUTSIDE REPAIRS _____
 TAX _____
 TOTAL AMOUNT _____

REPAIR ORDER

MICHAEL J. VEYS

#3

MATERIAL USED

QTY	PART NO.	DESCRIPTION	PRICE	WARRANTY YES	WARRANTY NO
		POWER STEERING			
1	RH2819	HIGH PRESSURE STEERING HOSE		152	01
1	WR27332	RESERVOIR RETURN HOSE		58	68
1	RH28191	CHASSIS HOSE		18	92
2	WR27331	COOLER HOSES		8	30
		ENGINE MOUNT		\$237	91
1	WR19203	FRONT ENGINE MOUNT		91	14
		VALVE COVERS		\$91	14
2	WV11305PA	GASKET		96	15
6	VE42838	OUTSIDE REPAIRS SEALING WASHERS		46	33
6	WV11307PB	SPACERS		108	34
				\$250	85
		BROUGHT FORWARD			
		TOTAL PARTS			
		ACCESSORIES			
		PRICE			
		WARRANTY			
		TOTAL ACCESSORIES			

NAME: _____ DATE: _____
 ADDRESS: _____
 MAKE: R-R TYPE OR MODEL: S. SHOW YEAR: 79
 SERIAL NO.: SRK 36401 ENGINE NO.: _____
 ODOMETER: 65466 LICENSE NO.: _____ TERMS: _____
 ORDER WRITTEN BY: _____ PHONE: _____
 RECEIVED: _____ PROMISED: _____
 PHONE WHEN READY: YES NO

OPER NO.

INSTRUCTIONS

1. REPLACE ALL POWER ASSISTED STEERING HOSES \$150 -
 2. REPLACE FRONT ENGINE MOUNT \$33 -
 3. REPLACE ENGINE VALVE COVER GASKETS \$450 -

You are entitled to a price estimate for the repairs you have authorized. The repair price may be less than the estimate, but will not exceed the estimate without your permission. Your signature will indicate your estimate selection. Teardown estimate - I understand that my car will be reassembled within _____ days of the date shown if I choose not to authorize the services recommended.

1. I request an estimate in writing before you begin repairs. _____
 2. Please proceed with repairs, but call me before continuing if the price will exceed \$ _____
 3. I do not want an estimate _____

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

X

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND OUR CONTROL.

DSS	IS	LABOR CHARGE
		Lubrication <input type="checkbox"/>
		Change Oil <input type="checkbox"/>
		Change Oil Filter Cart. <input type="checkbox"/>
		Change Trans. <input type="checkbox"/>
		Change Diff. <input type="checkbox"/>
		Pack Front Wheel Bgs. <input type="checkbox"/>
		Adjust Brakes <input type="checkbox"/>
		Rotate Tires <input type="checkbox"/>
		Wash Polish <input type="checkbox"/>
		State Inspection <input type="checkbox"/>

METHOD OF PAYMENT:		TOTAL LABOR	TOTAL PARTS	TOTAL ACCESSORIES	TOTAL GAS, OIL & GREASE	TOTAL OUTSIDE REPAIRS	TAX	TOTAL AMOUNT
<input type="checkbox"/>	CASH							
<input type="checkbox"/>	CHECK							
<input type="checkbox"/>	CHARGE							
<input type="checkbox"/>	FLAT RATE							
<input type="checkbox"/>	HOURLY							
<input type="checkbox"/>	BOTH							

REPAIR ORDER

MICHAEL J. VEYS

#4

QTY	PART NO.	DESCRIPTION	PRICE	WARRANTY YES	WARRANTY NO
		FRONT SUSPENSION			
2	RH3369	SHOCK ABSORBERS	936	18	
2	UR71238	CAMBER BUSHINGS	158	67	
2	UR17155	LOWER PN CONE	64	31	
2	UR10490	LOWER PN CONTROL BUSHING	154	12	
			\$1313	28	
		DISTRIBUTION VALVES			
2	UR15649	DIST. VALVE 'BOON'	59	17	
2	UR16075	' SEAL	7	84	
		OUTSIDE REPAIRS	\$67	01	
		BROUGHT FORWARD			
		TOTAL PARTS			
		ACCESSORIES			
		PRICE			
		WARRANTY YES			
		WARRANTY NO			
		TOTAL ACCESSORIES			

NAME: _____ DATE: _____

ADDRESS: _____

MAKE: R.R. TYPE OR MODEL: S.SHDW YEAR: _____ RECEIVED: _____ A.M. P.M.

SERIAL NO.: SRK36401 ENGINE NO.: _____ PROMISED: _____ A.M. P.M.

ODOMETER: 65466 LICENSE NO.: _____ TERMS: _____ PHONE WHEN READY: YES NO

ORDER WRITTEN BY: _____ PHONE: _____

OPER NO. INSTRUCTIONS

9. REBUILD FRONT SUSPENSION

- remove upper & lower BALL JOINTS + re-shim to grade and O/H as needed.

- replace camber bushings + front shock absorbers

- replace rear lower control arm pin bushing + cone.

H. REMOVE BRAKE ACTIVATION COVER: remove, clean + reset #1 + #2 Brake Distribution valves \$150-

You are entitled to a price estimate for the repairs you have authorized. The repair price may be less than the estimate, but will not exceed the estimate without your permission. Your signature will indicate your estimate selection.

Teardown estimate - I understand that my car will be reassembled within _____ days of the date shown if I choose not to authorize the services recommended.

1. I request an estimate in writing before you begin repairs. _____

2. Please proceed with repairs, but call me before continuing if the price will exceed \$ _____

3. I do not want an estimate. _____

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

X NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND OUR CONTROL.

GAS, OIL, & GREASE	PRICE
GALS. GAS @	
QTS. OIL @	
LBS. GREASE @	
TOTAL GAS, OIL, & GREASE	

METHOD OF PAYMENT:		LABOR:	
<input type="checkbox"/> CASH	<input type="checkbox"/> CHECK	<input type="checkbox"/> FLAT RATE	<input type="checkbox"/> HOURLY
<input type="checkbox"/> CHARGE		<input type="checkbox"/> BOTH	
TOTAL LABOR	TOTAL PARTS	TOTAL ACCESSORIES	TOTAL AMOUNT
		GAS, OIL & GREASE	
		OUTSIDE REPAIRS	
		TAX	

DSS	ISU	LABOR CHARGE
<input type="checkbox"/>	<input type="checkbox"/>	Lubrication
<input type="checkbox"/>	<input type="checkbox"/>	Change Oil
<input type="checkbox"/>	<input type="checkbox"/>	Change Oil Filter Cart.
<input type="checkbox"/>	<input type="checkbox"/>	Change Trans.
<input type="checkbox"/>	<input type="checkbox"/>	Change Diff.
<input type="checkbox"/>	<input type="checkbox"/>	Pack Front Wheel Bgs.
<input type="checkbox"/>	<input type="checkbox"/>	Adjust Brakes
<input type="checkbox"/>	<input type="checkbox"/>	Rotate Tires
<input type="checkbox"/>	<input type="checkbox"/>	Wash Polish
<input type="checkbox"/>	<input type="checkbox"/>	State Inspection

REPAIR ORDER

MICHAEL S. VEYS

#5

MATERIAL USED

QTY	PART NO.	DESCRIPTION	PRICE	WARRANTY YES	WARRANTY NO
	BRAKE PUMPS				
2	RH 2438	BRAKE PUMP		109	85
	O/H KIT				
2	UE35616	BRAKE PUMP		12	06
	PIPE FEED 1/2" RING				
	PIPE FEED 1/2" RING		\$ 121	91	
	Door Lock				
1	USED	LEFT REAR DOOR		150	-
	LOCK SOLENOID			150	-
	EXHAUST				
4	UE 73544	MANIFOLD GASKT		18	51
2	Q110	OWF JOINT		18	00
4	UR 5665	BRASS NUT		33	76
	OUTSIDE REPAIRS				
4	UR 5666	STAINLESS BOLT		44	68
			\$ 114	95	
BROUGHT FORWARD					
TOTAL PARTS					
TOTAL ACCESSORIES					

NAME	ADDRESS	DATE
MAKE	TYPE OR MODEL	YEAR
SERIAL NO.	ENGINE NO.	RECEIVED
ODOMETER	LICENSE NO.	PROMISED
65466	ORDER WRITTEN BY	PHONE WHEN READY
		<input type="checkbox"/> YES <input type="checkbox"/> NO
		PHONE

OPER NO. INSTRUCTIONS

1/ Remove #1 & #2 Brake Pumps and overhaul as needed - clean and ressth.	150
3/ Remove left rear door lock panel and replace defective door lock solenoid	50
K/ Replace 'B' Bank exhaust manifold gaskets and catalytic converter olive joints. Necessary to replace joint clamp nuts + bolts.	300

DSS	ISU	LABOR CHARGE
<input type="checkbox"/>	<input type="checkbox"/>	Lubrication
<input type="checkbox"/>	<input type="checkbox"/>	Change Oil
<input type="checkbox"/>	<input type="checkbox"/>	Change Oil Filter Cart.
<input type="checkbox"/>	<input type="checkbox"/>	Change Trans.
<input type="checkbox"/>	<input type="checkbox"/>	Change Diff.
<input type="checkbox"/>	<input type="checkbox"/>	Pack Front Wheel Bigs.
<input type="checkbox"/>	<input type="checkbox"/>	Adjust Brakes
<input type="checkbox"/>	<input type="checkbox"/>	Rotate Tires
<input type="checkbox"/>	<input type="checkbox"/>	Wash Polish
<input type="checkbox"/>	<input type="checkbox"/>	State Inspection

You are entitled to a price estimate for the repairs you have authorized. The repair price may be less than the estimate, but will not exceed the estimate without your permission. Your signature will indicate your estimate selection. Teardown estimate - I understand that my car will be reassembled within _____ days of the date shown if I choose not to authorize the services recommended.

1. I request an estimate in writing before you begin repairs. _____

2. Please proceed with repairs, but call me before continuing if the price will exceed \$ _____

3. I do not want an estimate. _____

I hereby authorize the above repair work, to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck (herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND OUR CONTROL.	GAS, OIL, & GREASE	PRICE
X	GALS. GAS @	
	QTS. OIL @	
	LBS. GREASE @	
	TOTAL GAS, OIL, & GREASE	

METHOD OF PAYMENT:		TOTAL LABOR	
<input type="checkbox"/> CASH	<input type="checkbox"/> CHECK	TOTAL PARTS	
<input type="checkbox"/> CHARGE	<input type="checkbox"/> FLAT RATE	ACCESSORIES	
<input type="checkbox"/> LABOR:	<input type="checkbox"/> HOURLY	GAS, OIL & GREASE	
<input type="checkbox"/> BOTH	<input type="checkbox"/> TAX	OUTSIDE REPAIRS	
		TOTAL AMOUNT	

REPAIR ORDER

Michael J. Veys

#6

QTY	PART NO.	DESCRIPTION	PRICE	WARRANTY YES	WARRANTY NO
		MATERIAL USED			
	BRAKE	Hoses (Hydraulic)			
1	RH14071	CHASSIS Accum Hose	95		23
1	RH14070	CHASSIS Accum. Hose	95		23
2	UR1729	HYDRAULIC HOSE	90		68
2	CD6224	HEIGHT CONTROL HOSE	88		30
1	CD6045	HYDRAULIC HOSE	41		16
2	VE10149	SOLENOID RESTRICTOR	9		45
1	CD4820	Rear Brake Consensors			
		Pressure limiting Valve (q' valve) o/h kit	15		85
			\$435		90
	REAR BRAKES				
2	UQ10045	WASHER	21		98
2	UQ1161	OUTSIDE REPAIRS 10' RING	24		62
2	XC520R	WOODRUFF KEY	18		25
2	UQ1015	HUB NUT	24		84
4	QR33	WHEEL BEARING GREASE 20			
1	CD6396	REAR BRAKE PADS 151			70
		BROUGHT FORWARD			
		TOTAL PARTS			
		ACCESSORIES			
		PRICE			
		WARRANTY			
		YES			
		NO			
		MACHINE ROTORS	30		
1	CD5847	CAUPER O/H KIT	106		19
2	CD4074	CAUPER PISTONS	82		10
1	UQ13565	BEARING CUP	18		13
1	UQ13564	BEARING CONE	42		83
		TOTAL ACCESSORIES	\$450		64

NAME: _____ DATE: _____
 ADDRESS: _____
 MAKE: R-R TYPE OR MODEL: S-5HDW YEAR: 79 RECEIVED: _____
 SERIAL NO.: SRK 36401 ENGINE NO.: _____ PROMISED: _____
 ODOMETER: 65466 LICENSE NO.: _____ TERMS: _____ PHONE WHEN READY: _____
 ORDER WRITTEN BY: _____ PHONE: _____

OPER NO.	INSTRUCTIONS	LABOR CHARGE
1/	REPLACE HYDRAULIC/BRAKE HOSES WHERE needed.	
	Reset, clean & inspect/rebuild 'q' valve, height control solenoid restrictors	160-
	Remove rear brake hub assemblies, clean, inspect & rebuild, and sublet rear brake rotors for machining. Rebuild & reset rear brake calipers.	500-

You are entitled to a price estimate for the repairs you have authorized. The repair price may be less than the estimate, but will not exceed the estimate without your permission. Your signature will indicate your estimate selection.
 Teardown estimate - I understand that my car will be reassembled within _____ days of the date shown if I choose not to authorize the services recommended.
 1. I request an estimate in writing before you begin repairs.
 2. Please proceed with repairs, but call me before continuing if the price will exceed \$ _____
 3. I do not want an estimate.

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car on truck, street, highway or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND OUR CONTROL.	GAS, OIL, & GREASE	PRICE
	GALS. GAS	
	GALS. GREASE	
	QTS. OIL	
	LBS. GREASE	
	TOTAL GAS, OIL, & GREASE	

METHOD OF PAYMENT:	TOTAL LABOR	TOTAL PARTS	TOTAL AMOUNT
<input type="checkbox"/> CASH			
<input type="checkbox"/> CHECK			
<input type="checkbox"/> CHARGE			
<input type="checkbox"/> FLAT RATE			
<input type="checkbox"/> HOURLY			
<input type="checkbox"/> BOTH			
	TOTAL LABOR		
	TOTAL PARTS		
	ACCESSORIES		
	GAS, OIL & GREASE		
	OUTSIDE REPAIRS		
	TAX		
	TOTAL AMOUNT		

REPAIR ORDER

MICHAEL J. VEYS

7

CITY	PART NO.	DESCRIPTION	PRICE	WARRANTY YES	WARRANTY NO
		CARBURETTERS			
	2	CD5865 FLOAT KIT	64	15	
	2	VE35892 CARB FUEL FILTERS	22	06	
	2	VE6308 INTAKE SEALING			
		'01 RINGS	76	93	
	2	CD5447 FUEL FILTER SEAL	21	99	
			\$185	13	
		OUTSIDE REPAIRS			
		BROUGHT FORWARD			
		TOTAL PARTS			
		TOTAL ACCESSORIES			
		TOTAL ACCESSORIES			

NAME _____ DATE _____
 ADDRESS _____
 MAKE R-R TYPE OR MODEL S-5HDW YEAR 79 RECEIVED
 SERIAL NO. SRK 36401 ENGINE NO. 79 PROMISED
 ODOMETER 65466 LICENSE NO. _____ TERMS _____ PHONE WHEN READY
 ORDER WRITTEN BY _____ PHONE YES NO

OPER NO. INSTRUCTIONS

M. Carburetors leaking fuel.
 - remove carburetors from engine.
 - dismantle and inspect.
 - replace all '01 rings and retight gaskets N/C.
 - replace float assemblies
 - adjust and synchronize / tune.

DSS	ISJ	LABOR CHARGE
		Lubrication <input type="checkbox"/>
		Change Oil <input type="checkbox"/>
		Change Oil Filter Cart. <input type="checkbox"/>
		Change Trans. <input type="checkbox"/>
		Change Diff. <input type="checkbox"/>
		Pack Front Wheel Brgs. <input type="checkbox"/>
		Adjust Brakes <input type="checkbox"/>
		Rotate Tires <input type="checkbox"/>
		Wash Polish <input type="checkbox"/>
		State Inspection <input type="checkbox"/>

You are entitled to a price estimate for the repairs you have authorized. The repair price may be less than the estimate, but will not exceed the estimate without your permission. Your signature will indicate your estimate selection.
 Takedown estimate - I understand that my car will be reassembled within _____ days of the date shown if I choose not to authorize the services recommended.
 1. I request an estimate in writing before you begin repairs.
 2. Please proceed with repairs, but call me before continuing if the price will exceed \$ _____
 3. I do not want an estimate.

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and / or your employees permission to operate the car or truck herein described on streets, highways or elsewhere for the purpose of testing and / or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs hereon.

METHOD OF PAYMENT:

CASH
 CHECK
 CHARGE
 FLAT RATE
 HOURLY
 BOTH

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CAR OR ARTICLES LEFT IN CAR IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND OUR CONTROL.	GAS, OIL, & GREASE	PRICE
	GALS. GAS	
	QTS. OIL	
	LBS. GREASE	
	TOTAL GAS, OIL, & GREASE	
	TOTAL LABOR	
	TOTAL PARTS	
	ACCESSORIES	
	GAS, OIL & GREASE	
	OUTSIDE REPAIRS	
	TAX	
	TOTAL AMOUNT	

REPAIR ORDER

MICHAEL J. VEYS

#8

QTY	PART NO.	MATERIAL USED DESCRIPTION	PRICE	WARRANTY YES/NO
1	USED	UPPER STEERING COLUMN COME TRIM FS		
1	NC 45	BATTERY TENDER N/C		
4		DOOR SEAL Tape N/C.		
TOTAL PARTS BROUGHT FORWARD				

NAME: _____ DATE: _____
 ADDRESS: _____
 MAKE: PR-R TYPE OR MODEL: 5. SHDW YEAR: 79 RECEIVED: _____
 SERIAL NO.: SRK 36401 ENGINE NO.: _____ PROMISED: _____
 ODOMETER: 65466 LICENSE NO.: _____ TERMS: _____ PHONE WHEN READY: YES NO
 ORDER WRITTEN BY: _____ PHONE: _____

OPER. NO. _____ INSTRUCTIONS: N/A. Repair broken Hydraulic pressure pipe in engine compartment

9/ CLIMATE CONTROL: no interior heat - repair "shock closed" coolant heater tap.

You are entitled to a price estimate for the repairs you have authorized. The repair price may be less than the estimate, but will not exceed the estimate without your permission. Your signature will indicate your estimate selection.
 Teardown estimate - I understand that my car will be reassembled within _____ days of the date shown if I choose not to authorize the services recommended.
 1. I request an estimate in writing before you begin repairs.
 2. Please proceed with repairs, but call me before continuing if the price will exceed \$ _____
 3. I do not want an estimate.

METHOD OF PAYMENT:		TOTAL LABOR	TOTAL PARTS	TOTAL AMOUNT
<input type="checkbox"/> CASH	<input type="checkbox"/> CHECK	4445	5285	80
<input type="checkbox"/> FLAT RATE	<input type="checkbox"/> CHARGE			
<input type="checkbox"/> HOURLY	<input type="checkbox"/> BOTH			
LABOR:				
GAS, OIL, & GREASE				
TOTAL GAS, OIL, & GREASE				
TOTAL AMOUNT		10349	43	

Mar 22, 2005.

To: _____
FROM: MICHAEL VEYS

3 pages being faxed.

I enclose the smog vehicle inspection report (VIR) for the car. The actual certificate is on file (in the database) @ the DMV. You can now go to the DMV and register the car, along with all the other paperwork and put the car ~~into~~ onto California license plates.

Tomorrow or Thursday the car will be "detailed" and then I can arrange to deliver the car @ the weekend or a time of your choice. I may have the wheels balanced as I notice a little "shimmy" from them when driving on the highway.

I haven't finished preparing the itemised bill but will advise you and fax a copy before delivering or you picking up the car.

Michael Vey's. The attached goes to #8

SMOG CHECK VEHICLE INSPECTION REPORT

(03/21/2005 @ 12:33:25 pm)

Vehicle Information

Model Year.....	1979	Make.....	ROLLS-ROYCE	Model.....	SILVER SHADOW
License.....	F93BBN	State.....	Florida	VIN.....	SRK36401
Engine Size.....	6.8 liters	Type.....	Passenger	Transmission.....	Automatic
GWR.....	N/A	Test Weight.....	5900 lbs.	Cylinders.....	8
Odometer.....	65266	Certification.....	California	VLT Record #.....	4811
Fuel Type.....	Gasoline	Exhaust.....	Single	Inspection Reason.....	Initial Reg
Engine Year.....	N/A	Engine Make.....	N/A	Bar Number.....	N/A
Fleet BAR File #.....	N/A				

Overall Test Results

Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Visual Inspection..(Pass) Functional Check..(Pass) Emissions Test..(Pass)

DMV ID Number..(0352T141F481)

Smog Check Certificate Number..(PT514763)

Your Smog Check certificate has been electronically transmitted to the DMV. This certificate is valid for ninety (90) days from the date of issuance.

No match has been found or test performed off-line. The consumer is responsible for retaining the VIR for reference throughout the vehicle registration process.

If this vehicle has been identified as a gross polluter or has been issued a hardship extension (or for other reasons requiring a Referee/Test-Only center inspection), the certificate issued as a result of this inspection shall be invalid.

Please keep this copy for your records.

Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist the identification of oxides of nitrogen, crankcase, and cold start emissions which are not measured during the idle tests)

<u>ECS</u>	<u>Result</u>	<u>ECS</u>	<u>Result</u>	<u>ECS</u>	<u>Result</u>
PCV.....	Pass	Fuel Evaporative Controls.....	Pass	Catalytic Converter.....	Pass
PCV (Visual).....	Pass	Spark Controls.....	Pass	Carburetor.....	Pass
Wiring to Sensors.....	Pass	Vacuum lines sensors/switches..	Pass	Other related emis. components.	Pass
Liquid Fuel Leak.....	Pass	Fuel Cap Integrity Test.....	Pass	Fillpipe Restrictor.....	Pass
Fuel Cap Visual.....	Pass	Ignition Timing (15 BTDC).....	Pass		

SMOG CHECK VEHICLE INSPECTION REPORT

(03/21/2005 @ 12:33:25 pm)

Page # 2

VIN..... SRK36401

License.. F93BEH

ASM Emission Test Results

Test	RPM	%CO2	%O2	HC (PPM)			CO (%)			NO (PPM)			Result
	MEAS	MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	
M1: 15 MPH	1421	14.4	1.0	173	47	11	1.16	0.20	0.06	1206	554	186	Pass
M2: 25 MPH	1408	14.4	1.0	140	37	7	0.96	0.17	0.06	1066	468	186	Pass

MAX = Maximum Allowed Emissions AVE = Average Emissions For Passing Vehicles MEAS = Amount Measured

Smog Check Station Information

MILL VALLEY ARCO
 351 SHORELINE HWY.
 MILL VALLEY, CA 94941
 T 415 383 6969

Technician Name/Number..... LEE HEE JUNG/EA127641
 Repair Tech Name/Number..... N/A
 Software Version/EIS Number... 0311/SX110158
 Station Number..... RM231370

I certify under the penalty of perjury under the laws of the State of California, That I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and correct.

3/21/05
 Date

Lee Hee Jung
 Technician's Signature

Feb 3, 2005.

To: _____


From: Michael Veys

I enclose an illustration of the exhaust system of your car. Where I have circled and arrowed shows the area where a hole has ~~been~~ developed in the pipe (not muffler). A good muffler shop would be able to weld in a couple of new pipes, and I think the surrounding metal is "intact" enough to make a good weld.

I would prefer to have it done as I can "fine tune" the car better without a "muffler blow" but if you know of a good muffler shop in your area then that would be fine too.



Thank you

Michael Veys.



I estimate approx \$250 - to fix.

exhaust system has
holes in pipes where circled.



J

- 1 UR10798 OLIVE
- 2 UR5639 HALF CLAMP
- 11 SPC3207 JUBILEE CLIP
- 14 UR18216 ABSORBER
- 17 UR18956 OLIVE
- 18 UR19099 MOUNTING BRACKET
- 19 UR19153 ABSORBER & BRAC
- 20 UR18174 CLAMP ASSEMBLY
- 25 UR19758 OLIVE
- 26 UR19759 HALF CLAMP
- 27 UR20163 OLIVE

K

- 1 UR10798 OLIVE
- 2 UR5639 HALF CLAMP
- 11 SPC3207 JUBILEE CLIP
- 17 UR18956 OLIVE
- 20 UR18174 CLAMP ASSEMBLY
- 25 UR19758 OLIVE
- 26 UR19759 HALF CLAMP
- 27 UR20463 OLIVE N. Au
- 28 UR21335 ABSORBER
- 29 UR21341 ABSORBER
- 30 UR21630 ABSORBER
- 31 UR21526 MOUNTING
- 32 UR21273 ABSORBER
- 33 UR21629 ABSORBER

To:

FROM: MICHAEL VEYS

(415) 384-0772

(415) 384-0789 fax.

The car is almost complete. I apologise for not being in touch; the only thing left apart from some road-testing and finer-tuning of the servicing is a smog test and detailing of the car.

I had to wait two weeks for a wheel bearing for the rear brakes. The overheating had compromised the ^{structural} integrity of the bearing but otherwise that job went smoothly.

The muffler repair is complete. Evidently the piping was all bent of shape, being strapped and bound in parts in order to stop it banging the undercarriage. The cost was slightly over \$300.

Good news on the Air Conditioning / Heating system. The relays checked out fine. The cause of no heat in the interior / cockpit was a stuck heater tap. Reworking and freeing it up was all that was needed. The total cost for this work is \$175 (not \$420).

One problem ~~created~~ has arisen since I last was in

touch with you, and that is one of the new front shock absorbers started leaking. It has been replaced under warranty. Incidentally all work done is covered for 12 months or 12,000 miles.

I might have the car finished by the weekend, or otherwise in the early part of next week.

Please call or fax if you have any questions.

Michael Neg.

3 PAGES BEING FAXED

Jan 26, 2005.

To: _____ Fax # () _____

FROM: MICHAEL VEYS
Tel # (415) 384-0772
Cell # (415) 847-8870
Fax # (415) 384-0789

Re: Rolls-Royce

I enclose the costs incurred so far both from the original estimate and costs involved as the work progressed including the bigger repairs like the shock absorbers and rear brakes. Since the rear brake repair is the last major repair that I have recommended there is hopefully no more major expenses that would be deemed "essential". I have proposed some repair work @ the muffler shop and a wheel alignment. With respect to the wheel alignment you could hold off because while the tires have decent tread-life on them they are not of the highest quality (Michelin + Avon are recommended by R-R) and therefore wait until you replace them. I recall the cost of an alignment at the dealership is in the region of \$325⁰⁰.

Your fax mentions getting the car back into

operating condition. The majority of the proposals have been performed save the last repair of the rear brakes and tidying up a few loose ends associated with the service.

One of the things about working on a car over an extended period of time is that you may notice some additional things that the initial inspection didn't catch. I mention this not to scare you of a whole list of expensive repairs but to be aware of and give thought to as preventative maintenance down the road and as you start to drive and enjoy the car.

- ① The article I enclosed talks about the cooling system. Doing this service work would be a good idea to prevent overheating in the hot summer months. The radiator would need to be serviced too, I recall discussing this with you.
- ② I cleaned off the undercarriage of the vehicle and there is still some seepage, the most notable one coming from the transmission front pump seal - not an excessive leak but will leave a spot on the floor when parked.
- ③ You may have noticed that the brakes squeal on application. It may be the rear brakes causing

this ~~but~~ which will be cured with the rear brake repair. It could quite possibly be the front brakes. I took the pads out of the calipers to examine them more closely - they have plenty of service life but are not ~~original~~ genuine R-R brake pads - I think these pads are the guilty suspect for the squeaking brakes, but we'll wait and see.

(iv) I mentioned that the air-conditioning is blowing cold, and it still is. When I drove the car on the journey that overheated the rear brakes it was a cold day. I turned the ~~dials to~~ dials to get interior heat but unfortunately the "blend flaps" didn't move to give "cockpit" heat. I suspect the servo-relays are defective. The car having lived in Florida may never have wanted/^{needed} to go into the interior heat mode. I meant to mention this to you but my mind was preoccupied with the rear brake issue. I believe that the servo relays are about \$260 each and 2 are required. I could source 2 good used ones.

(v) Obviously I don't have a crystal ball to foresee any or all future work needed. If you do the coolant work/service it would also be a good time to replace the drive belts and determine if the water pump is not leaking or has shown signs of leakage since all this work ties ~~into~~ in together.

vi) The air conditioning compressor works but the clutch of this component is a little noisy. You will only hear the noise when the compressor is engaged to operate for the A/C system. Likewise the radiator fan clutch has a small amount of play in it (the bearing may be a little worn) but operates fine otherwise. The A/C compressor can be rebuilt rather than pay R-R prices and the fan clutch could be replaced with a good used one as they rarely fail - it works fine as mentioned so its performance can be monitored. Should you wish to do the cooling system service these ^{repairs} can be performed @ that time as they tie in to this area of work.

If I drove the car for another 100 miles I would probably notice some other things, but I believe this catches the main areas of work. As you have mentioned and are probably aware the car has suffered from deferred maintenance. The internal parts of the engine are very dirty from either infrequent oil changes and/or short journeys. Long highway journeys and regular oil changes will be good for the car.

If it is any consolation - should you have had this work done @ the dealership you would be into repair costs of at least \$15,000 so far. I don't profess

to being the best R-R mechanic in the world but I know I am thorough and everyday I learn something new about the car - each and every one has their own idiosyncracies.

I will be out of the Bay Area from Thursday 27TH to Sunday 30TH, but you can reach me on my cell phone should you wish.

Thank you,

Michael Vass.

N.B. all of the above mentioned items I will point out to you when you pick up the car.

COSTS

Charges incurred so far : (parts + labour).

- 1). 1 year schedule maintenance service \$ 850 - ✓
- * 2). Rebuild Brake Accumulator + Spheres
Clean + Reseal Hydraulic Fluid Reservoir \$ 990 - ✓
- 3). Oil Leaks:
 - a). Valve Cover reseal \$ 750 - ✓
 - b). Power Steering Hoses \$ 380 - ✓
- 4). Exhaust manifold Reseal \$ 325 - ✓
- 5). Front Engine Mount replacement \$ 126 - ✓
- 6). Front Suspension
 - camber bushings
 - upper + lower Ball Joints \$ 925 - ✓
 - * (part only) → - control arm pin \$ 65 - ✓
- * 7). Left Rear Door Lock solenoid repair \$ 200 - ✓

additional charges incurred over and above original estimate :

- 8). a) replace fuel + vacuum hoses \$40 - ✓
b). rebuild + reseal brake pumps +
brake distribution valves \$450 - ✓
c). Air injection hoses \$190 - ✓
d). Ignition wire clips + coolant hoses \$145 - ✓
9). Repair broken brake pipe \$65 - ✓
10). Replace front shock absorbers +
rebuild shock ball joints \$1275 - ✓
(The rear shock absorbers are quite
new also).

- *** 11). Replace hydraulic hoses, rebuild rear
brake calipers, 'G' valve, rear brake pads +
rebuild/reseal rear hub assemblies \$1625 - ✓
-

* additional parts used while work was
being performed causing an increase in costs
over estimate

*** this work is still in progress. I expect
the brake rotor that got red hot to machine
cleanly and evenly. If not I will have to
replace it - the cost of a rear brake rotor is \$265⁰⁰

Therefore to summarize:

Costs incurred so far, including
work in progress is:

\$ 8400 —

there will be some

sales tax of approx \$ 250 —

Total: \$ 8650 —

Additional costs to be
incurred + recommended:

- 1). Muffler shop \$ 250 — ± SUBLET
- 2). Servo Relays for Climate Control: \$ 320 — PARTS
Labour: \$ 100 — includes initial diagnosis
- 3). Wheel Alignment \$ 325 ± (OR YOU CAN WAIT).

1/19/05

To: JEFF WALTER : : '16

From: MICHAEL VEYS. (415) 387-0772
(415) 847-8870.

Re: 1979 Rolls-Royce

Following our conversation I quote the repairs that will prevent "one more problem" and fix the damage from the rear brakes overheating.

1). Remove rear hub assemblies, dismantle and machine rotors, rebuild with new grease and seals and new brake pads and locking nuts.

Rebuild and reseal rear brake calipers.

Parts: \$500-

Labour: \$550-

2). Replace 7 of the 13 high pressure flex hoses for the hydraulic system - the remainder appear to have been replaced during the car's life. These hoses are approx \$45 → \$60 each. Also remove and reseal and clean the conscious pressure limiting valve ('Q' valve)

I have a couple of these hoses as new old stock (they are brand new). In good faith I will perform this repair for \$575⁻:

Parts : \$415⁻

labour : \$160⁻

Therefore these two repairs will cost \$1625⁻ ✓

The only variables are the muffler repair and wheel alignment.

I enclose the article I mentioned to you from an authority of the car. He explains the brakes and other maintenance issues in layman's terms. It will help you to understand the idiosyncracies of the Silver Shadow.

Please call if you have any questions.

Michael Keys.

1/15/05

To: JEFF WALTER (-)

From: MICHAEL VEYS (415) 384-0772 phone
(415) 847-8870 cell phone.

Re: 1979 ROLLS-ROYCE

The shock absorber replacement went very smoothly and the front end seems very tight, secure and rides very well. The replacement shocks are of an improved design and you definitely notice it, in my opinion.

The left rear door actuator/solenoid hasn't arrived yet so I shall have to chase that up on Monday.

I went for a good thirty mile roadtest on Thursday and the car, upto a point, drove very well. However we have a problem and I would very much appreciate any feedback on how long a journey you have taken in the car, how long you have driven it on any occasion before bringing it to me and if you have experienced what happened to me - and this has happened to me before and other colleagues I know who work on R-R.

After about 15 miles of driving I felt a rumble coming from the rear and when I stopped after another 5 miles (I was on the freeway) I

noticed the left rear wheel "smoking" - closer inspection showed that the brake rotor was glowing red as a result of the brakes sticking on. Obviously I had to limp back to the shop stopping frequently to let the brakes cool down.

What has happened is one of two things, or both. The rear caliper has seized, working when the brakes are applied but not ~~not~~ releasing and thus causing the brakes to drag. The other problem, and which is more ~~probabal~~ probable is the rear high pressure hoses that feed the rear braking system have collapsed internally causing ^{fluid} pressure to go through but not return because there is no pressure to push it back or "let off" and therefore causes the brakes to be "on" all the time. Rolls-Royce recommend the all hydraulic hoses be changed every 7 years or 90,000 miles. I believe these hoses to be the original ones. This has probably come about as a result of recharging the braking system. When fully charged the high pressure side can be up to 2500 PSI.

This means that the hoses have to be replaced, the calipers rebuilt, probably the brake pads replaced and more than likely the rear hub needs to be rebuilt because the grease for the bearings has

1/5/05

To: T

FROM: MICHAEL VEYS.

Thank you for your response for the last fax. To answer your questions regarding the door lock and stereo chop:

1). The door lock solenoid has completely seized necessitating a new solenoid. I honestly thought a linkage had come adrift and that it would be a simple case of re-securing that linkage. I have managed to source a good used one for \$150 - as they are over \$300 new. They don't usually go bad so this used one should last awhile. There is no additional labour charge.

2). I have located the stereo person on Louise St in San Rafael. ~~He~~ He works by appointment only but the last time I used him his work was excellent and prices very competitive - there is no doubt that this will still be the case.

With respect to the shock absorbers, unfortunately they are out of stock and won't be in until early next week. Therefore by the time the alignment is done I

TO: Michael Veys

FROM:

RE: 1979 Rolls-Royce

DATE: Dec. 9, 2004

VIA FAX

Your note about the additional repairs that you effected and that you propose was warmly received. Yes, please proceed with the repairs that you have recommended.

By the way, as you can tell, the leather needs to be re-dyed and the interior needs some attention. Do you have any recommendations as to a good leather dying company – maybe in Sonoma?

We also intend to have the car painted. We have located a very good painter in Sonoma and plan on using him, unless you have some person you could recommend. Additionally, is it best to get the car painted and then take care of the leather and interior? Or vice-a-versa?

Thanks for your help.

To: —

(---)

FROM: MICHAEL VEYS

(415) 384-0789 fax

(415) 384-0772 phone.

Re: 1979 Rolls-Royce SILVER SHADOW II

The work [REDACTED] is nearing completion, although there have been a few challenging repairs and some waiting of parts that were either on back-order or had to come from the U.K.

The wonderful thing about these cars is that almost every part can be rebuilt as opposed to being replaced. Along the way it has been necessary and for safety reasons also to make some additional repairs. Within the engine bay I have replaced all the vacuum hoses as well as the fuel hoses ~~to~~ from the Gas tank to the main pipe that runs to the engine. Approx cost = \$40 ✓

The air-injection hoses (part of the smog emission system) had to be replaced. They had to be removed for the power steering hose repair and literally collapsed/disintegrated during removal. A couple of the ignition wire clips had to be replaced also.

I have taken the liberty of replacing the heater matrix

coolant

↳ fuel and return hoses because access with a multitude of parts removed was so easy.

The main additional repair has been overhauling the brake pumps and brake distribution valves. After removing and rebuilding the accumulator valve body and sphere and seeing ~~the~~ their condition I thought it necessary to rebuild these additional items since they represent an integral and important part of the high pressure braking system. I would be doing you a dis-service if I didn't take care of these items.

Labour costs for these two items is \$300 ✓

* Parts for these add'l items is approx \$150 ✓

* in the original quote for the rebuilding of the accumulator valve body and sphere, the valve-body rebuild kit was left out - two are required and the total parts cost is \$157 for these two kits.

There is no labour charge for the fuel hoses, vacuum hoses, air-injection hoses, ign wire clips and coolant hoses; just the cost of the parts.

I have managed to get the antenna to work, hopefully it will keep working.

I will call you on Friday or Monday to give you a completion day after the alignment & complimentary detail.

Please call if you have any questions.

Michael Vets

12/29/04

To:

(76)

FROM: MICHAEL VEYS

(415) 384-0789 fax

(415) 384-0772 phone

Re: 1979 ROLLS-ROYCE

I have driven the car on a couple of occasions to prepare it for delivery to the alignment shop. However there has been an unfortunate setback in that the right front shock absorber has collapsed internally, causing a knocking noise and unacceptable ride.

Although it is rare, this can happen after front suspension work since the springs have to be compressed and the shock is left hanging and pulled down by the control arms. The shock absorbers are original but they are expensive to replace, unless you want to put a good used pair on which I don't suggest.

With the discount the price of one shock absorber is \$475 - and it is always recommended that they be replaced in pairs. Since there would have been some overlapping labour involved when doing the suspension work it would only be fair to

quote a reduced ~~a~~ labour rate should you wish to replace them. Normally it would be \$525 - but

²⁰⁰ less. I think \$325 - would be a fair reduction* in labour. Total cost, including rebuilding the shock absorber balljoints would be \$1275. ✓

I would like to just recap the costs involved so far:

ORIGINAL ESTIMATE : \$4691 -

Fuel hoses + vacuum lines : \$ 90 -

Labour for Distribution valves + Brake Pumps : \$ 300 -

Parts for above : \$ 150 -

Accumulator valve body kit : \$ 157 -

Air Injection Hoses : \$ 190 - ✓

Ign Wire Clips, coolant hoses : \$ 48 - Clips ✓

\$ 97 - hoses ✓

\$5673 - + wheel alignment

Shock absorber replacement \$1275 -

Repair broken brake line \$ 65 - labour. ✓

- there may be a couple of small parts that I may have overlooked, but no additional labour charges

PLEASE CALL ~~OR~~ OR FAX TO ADVISE.

To:

From: Michael Veys

Thank you for your prompt response - I shall commence work so that the car is finished by the end of the month.

With respect to the radiator and cooling the probability is the cooling passages within the radiator matrix are getting clogged and therefore reducing the flow and efficiency of the air being able to cool the water in the radiator. The repair for this would be to remove the radiator and have it ~~re~~boiled out or re-cored. If this is done it would make sense to replace the coolant hoses and thermostat at the same time. Since there is hardly any overlapping labour with the other repairs we can monitor this.

Obviously in hotter months and use of Air Conditioning it puts a bigger strain on the efficiency of the cooling system so it may be something to consider next spring.

I have managed to get the washer jets to work

- they were clogged up.

- I will look into the antenna - it probably is stuck or very lazy since it may have hardly been used which is often the case.

- the belts and hoses should be okay for another year or so.

I shall arrange to have a complimentary detail done to the car in appreciation of your business.

I do, however, ask that a deposit of \$1000⁻ be paid with a job of this scale.

My mailing address is: P.O. Box 829
LARKSPUR
CALIF 94977

Please call if you have any questions.

Michael Neys.

TO: Michael Veys
FROM: ?
RE: 1979 Rolls
DATE: Nov. 17, 2004
FAX NO. 4)

Your estimate is acceptable. My math indicates that the charge for the parts is \$1,328 and the charge for the labor is \$3,363. Please proceed to complete the repairs and maintenance, as quoted.

In addition, I have noted that the temperature gauge sometimes will spike up. That may indicate that the radiator and/or the cooling system may not be holding pressure.

I also noticed that the radio antennae does not work and the windshield washer doesn't work.

If you could check these additional items out for us, that would be appreciated.

Finally, how much longer do you think the belts and hoses will be OK?

We will be out of State until Nov. 28. I will call you when we return.

Thanks. Jeff Walter

To:

() fax

FROM: MICHAEL VEYS

(415) 384-0789 fax

(415) 384-0772 tel

RE: 1979 ROLLS-ROYCE SILVER SHADOW II

- please find a description and estimate/cost of repairs that are needed.

- please call me to discuss further.

Michael Vey's.

TOTAL OF 7 PAGES BEING FAXED, including cover sheet.

1979 ROLLS-ROYCE SILVER SHADOW II

A. Brakes:

Brake linings are okay with over 50% approx of pad life left, front + rear. The hand-brake was out of adjustment and the linkage needed lubricating so that it doesn't stick anymore.

However the hydraulic and pressure side of the braking system is in need of work. Rolls-Royce use a pressurized braking system that is driven by brake pumps operating off the camshaft in the engine. That is why when the car is started the red light pressure lamps illuminate until the engine is started. The brake pumps charge an accumulator - one for the #1 system and an accumulator for the #2 system (the #2 system also controls the rear ride height levelling system). Within the accumulator is a valve body and a sphere that is charged with nitrogen. The sphere, charged with nitrogen, maintains the pressure within the braking/hydraulic system and also gives reserve braking power/pressure should the engine fail and you have to stop the car. ~~The~~ Your car will stop if the engine is running and has maintained sufficient RPM to pressurize the brakes, but if you are in stop and go traffic @ low RPM or idle the brakes will

get weaker unless you rev the engine to charge the accumulator. This is because the sphere has no nitrogen charge in it. Over a period of 5 years or so the charge of nitrogen ~~in~~ within the sphere will dissipate and then the sphere and valve body have to be rebuilt and ^{be} recharged with nitrogen. This is the case with your car. Of course the whole hydraulic system gets a thorough "flushing" and bleeding. This braking system is very effective but high maintenance. Once a year, at least, the hydraulic system needs to be flushed.

B/ Service :

The vehicle could benefit from a service - a major service, with all new fluids and filters, spark plugs and general inspection/adjustment/lubrication of all components. Typically speaking, after observing your car Rolls-Royce would recommend changing the engine drive belts and coolant hoses but these could hold off if you wish to stagger the repairs over a period of time.

C/ OIL LEAKS:

- there are some leaks - the most obvious is the engine valve covers. It would make sense to reseal these clean everywhere else and observe for any other engine oil leaks @ a later date.

- the Power steering system has some leaks and

an incorrectly routed high pressure steering hose that has caused a kink in it. It would make sense to replace all Power steering hoses.

D/ EXHAUST LEAK:

The driver's side or 'B' bank exhaust manifold has a bad leak and needs to be resealed. It is most noisy and not good for the performance of the vehicle.

E/ Engine Mount:

the front engine mount is starting to split.

F/ SUSPENSION:

The upper ball joint on the passenger side has split its rubber "bellow" and lost most of its grease. Also the "camber" bushings which control alot of the alignment and ride quality have "collapsed" causing wear on the inner tires - it is not that obvious at the moment, but the inner ^{front} tires are definitely wearing out faster than the outer (alignment is out, but no point aligning vehicle unless these repairs are performed). Given the weight of the car it is not unusual to see this condition especially when the car is 25 yrs old.

G/ ~~BA~~ Door Locks:

The left rear door locking knob will not lock

the car, if this door will not lock. It would be necessary to remove the door panel and diagnose the problem.

H. Monitor:

Radiator - it may have been leaking @ some time - seems okay @ present.

Air Conditioning - blowing fairly cold - not necessary to blow any colder @ this time of year.

Fan Clutch - unsure whether this is noisy or whether it is the drive belts - I think the drive belts.

- I charge \$65 / hour and give 10% off the retail price of the part whether you are a R-R owners club member ~~or~~ or not.

PRICE to Repair.

A/

Brakes:

	<u>PARTS</u>	<u>Labour</u>
① overhaul ^{both} Accumulators, flush hydraulic system Recharge nitrogen	\$ 350 -	\$ 780 - for both parts of brakes.
② Clean + Reseal Hydraulic Reservoir	\$ 155	
		(actual 990) ✓

B/ Service:

① Perform Service as described (not belts + hoses)	\$ 850 - total ✓
---	------------------

C/ Oil Leaks

① Reseal valve covers	\$ 300 -	\$ 450 - ✓
② Power Steering hoses (high + low)	\$ 230 -	\$ 150 - ✓

D/ Exhaust Leak

①. Reseal leaking 'B' Bank exhaust manifold	\$ 25 -	\$ 300 - ✓
--	---------	------------

E/ Engine Mount

Replace front engine Mount	\$ 93 -	\$ 33 - ✓
----------------------------	---------	-----------

F/ SUSPENSION

Rebuild Upper & Lower Ball Joints

PARTS
\$175

Labour
\$750 ✓

Replace camber bushings
control arm pin

65 ✓

SUBLET FOR WHEEL ALIGNMENT - ?

G/ Door Lock

Remove door panel and repair
if an easy fix.

\$50 ✓
(200-actual) ✓

Parts prices quoted include 10% discount

1,328

3,363

BENTLEY SAN FRANCISCO

999 Van Ness Avenue
San Francisco, CA 94109
(415) 776-7700
www.bmcd.com



SRK36401

201010

INVOICE



Mission Statement:

"We are a team committed to providing value, quality and excellence in sales and service; inspired by our customers' standards and the Qvale family reputation for integrity since 1947."

462
SONOMA, CA 95476
HOME:

BUS: 90

PAGE 1

SERVICE ADVISOR: 131 MICHAEL HEYWOOD

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
	79	ROLLS ROYCE SILVER S	SRK36401		64981/64981	TY142
DEL DATE	PROD. DATE	WARR EXP	PROMISED	PO NO.	PAYMENT	INV. DATE
01JAN1979	01JAN79	01JAN1979	16:30 2OCT04		0.00 CASH	12NOV2004
R.O. OPENED	READY	OPTIONS:	DLR:0000			
13OCT04	12NOV04					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------


A DELIVERY / DETAIL
CAN CONDITION ABOVE FOR MEMO PURPOSES
27 CRR 0.00 0.00

64981

B TOW CAR FROM MILL VALLEY TO SAN FRANCISCO DUE TO ENGINE RUNNING WARM
S103 TOWING
27 CRR 0.00 0.00
SUBL TOW FROM MILL VALLEY TO SAN FRANCISCO ATLAS INV#211514
CRR 177.50 177.50

C CUST. STATES: NOISE FROM ENGINE WHEN RUNNING
S10 REFER TO ESTIMATE FAXED TO CUSTOMER
27 CRR3 52.00 52.00

D PERFORM VEHICLE HEALTH INSPECTION
VHC PERFORM VEHICLE HEALTH INSPECTION
27 IRR (N/C)
64981



Hours:	ORIGINAL ESTIMATE: \$			FINAL REVISED ESTIMATE: \$			DESCRIPTION	TOTALS
	DATE	TIME	PHONE #	AUTHORIZED	ADDITIONAL AMOUNT	REVISED TOTAL		
Monday - Friday 7:30 am - to 6:00 pm							LABOR AMOUNT	52.00
							PARTS AMOUNT	0.00
							GAS, OIL, LUBE	0.00
							SUBLET AMOUNT	177.50
							MISC. CHARGES	0.00
							TOTAL CHARGES	229.50
							ADJUSTMENTS	0.00
						SALES TAX	0.00	
						PLEASE PAY THIS AMOUNT	229.50	

ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE. BAR# AH 223516 EPA# CAL 000265432
 WARNING: Motor vehicles contain chemicals known to the State of California to cause cancer and birth defects or other reproductive harm. These chemicals are contained in many vehicle components and replacement parts, vehicle fluids, and paints and materials used to maintain vehicles, including, but not limited to, fuel, oil, batteries, brakes, and wheel balancing weights. In addition, motor vehicles emit engine exhaust and fumes, and when serviced, cleaned, or maintained generate used oil, waste fluids, fumes, grease, grime, and particulates from component wear, which contain chemicals known to the State of California to cause cancer and birth defects or other reproductive harm. Posted in accordance with Proposition 65 in Cal. Health & Safety Code 32529.5 et seq. For further information about Proposition 65: http://www.oehha.org/prop65.html
 CUSTOMER COPY

Bentley San Francisco**Fax**

To: _____ From: Michael Heywood
Fax: _____ Pages: 7
Phone: _____ Date: 10/28/04
Re: 1979 Rolls Royce Silver Shadow CC: _____

Urgent For Review Please Comment Please Reply Please Recycle

Dear Mr. Walter,


As per our conversation following please find a list of recommended repairs. Items marked with a number one are recommended for immediate attention. Number two represents items that are recommended now or in the near future. Number three indicates items that are comfort or convenience and are consequently left to your discretion.

There are three lines for engine oil leaks each with a second number. The number represents the sequence in which these leaks should be performed according to the severity of the leak.

The estimate for the radiator includes the price of the radiator. In the event that the radiator can be repaired we will go that route and save the price of the part. Only after the radiator has been removed will it be possible to determine if it can be repaired.

Please call me to discuss any questions you have and to let me know how to proceed.

Best Regards,



Michael Heywood
Bentley San Francisco
415.351.5167
mheywood@bmcd.com

Bentley San Francisco



Parts & Labour Estimate

BENTLEY

Date: 10/28/04 Veh ID: SRK36401 Mileage: 64,981 RO# / Tech #: 201010 64,981

Line:	Parts	Labor	Total Est.
Complaint: Engine temperature climbs too high, cooling system will not hold pressure			
Cause: radiator leaking			
Correction: replace radiator	\$670.00	\$731.42	
	\$726.95	\$731.42	\$1,458.37

①

Line:	Parts	Labor	Total Est.
Complaint: Cooling system will not hold pressure			
Cause: reservoir cap			
Correction: replace coolant tank cap	\$126.00	\$0.00	
	\$136.71	\$0.00	\$136.71

①

Line:	Parts	Labor	Total Est.
Complaint: Engine oil leaks			
Cause: oil pan gasket			
Correction: replace oil pan gasket	\$160.00	\$977.14	
	\$173.60	\$977.14	\$1,150.74

①-③

Parts and Labor prices are estimates and are subject to change. Additional parts and / or labor may be required.

Bentley San Francisco

999 Van Ness Avenue, San Francisco, CA 94109. Tel: 415.776.7700 Fax: 415.292.9977

Bentley San Francisco



Parts & Labour Estimate

BENTLEY

Date: 10/28/04 Veh ID: SRK36401 Mileage: 64,981 RO# / Tech #: 201010 64981

Line: _____	Parts	Labor	Total Est.
Complaint: engine oil leaks			

Cause: timing cover gaskets			

Correction: replace timing cover gaskets	\$300.00	\$1,347.52	

_____	\$325.50	\$1,347.52	\$1,673.02

①-②

Line: _____	Parts	Labor	Total Est.
Complaint: engine oil leaks			

Cause: rocker cover gaskets			

Correction: replace rocker cover gaskets	\$331.00	\$977.14	

_____	\$359.14	\$977.14	\$1,336.28

①-①

Line: _____	Parts	Labor	Total Est.
Complaint: engine and trans mounts deteriorated,			

Cause: oil leaks from engine causing accelerated wear on mounts			

Correction: replace engine and trans mounts	\$300.00	\$486.66	

_____	\$325.50	\$486.66	\$812.16

①

Parts and Labor prices are estimates and are subject to change. Additional parts and / or labor may be required.

Bentley San Francisco

999 Van Ness Avenue, San Francisco, CA 94109. Tel: 415.776.7700 Fax: 415.292.9977

Bentley San Francisco



Parts & Labour Estimate

BENTLEY

Date: 10/28/04	Veh ID:	Mileage: 64,981	RO# / Tech #: 201010	64981
----------------	---------	-----------------	----------------------	-------

Line: _____	Parts	Labor	Total Est.
Complaint: coolant hoses old, thermostat			

Cause: age			

Correction: replace coolant hoses & thermostat	\$650.00	\$671.90	

_____	\$705.25	\$671.90	\$1,377.15

①

Line: _____	Parts	Labor	Total Est.
Complaint: power steering fluid leak from cooler lines			

Cause: age			

Correction: replace p/s cooler hoses & rack to pump hose	\$200.00	\$305.84	

_____	\$217.00	\$305.84	\$522.84

①

Line: _____	Parts	Labor	Total Est.
Complaint: Windshield washer pump not working			

Cause: pump worn out			

Correction: Install aftermarket pump	\$60.00	\$62.98	

_____	\$65.10	\$62.98	\$128.08

②

Parts and Labor prices are estimates and are subject to change. Additional parts and / or labor may be required.

Bentley San Francisco

999 Van Ness Avenue, San Francisco, CA 94109. Tel: 415.776.7700 Fax: 415.292.9977

Bentley San Francisco



Parts & Labour Estimate

BENTLEY

Date: 10/28/04	Veh ID: SRK36401	Mileage: 64,981	RO# / Tech #: 201010	64981
----------------	------------------	-----------------	----------------------	-------

Line: _____	Parts	Labor	Total Est.
Complaint: Loud ticking sound from engine area			

Cause: B bank exhaust manifold			

Correction: Replace B bank exhaust manifold & gasket	\$1,200.00	\$480.14	

_____	\$1,302.00	\$480.14	\$1,782.14

②

Line: _____	Parts	Labor	Total Est.
Complaint: Rear brake pads cracked			

Cause: _____			

Correction: Replace rear brake pads	\$170.00	\$182.98	

_____	\$184.45	\$182.98	\$367.43

①

Line: _____	Parts	Labor	Total Est.
Complaint: Rear License plate bulbs out, missing cover for one other cracked			

Cause: age			

Correction: Replace rear license plate buibs and lenses, lense only available as an assembly.	\$980.00		

_____	\$1,063.30	\$0.00	\$1,063.30

③

Parts and Labor prices are estimates and are subject to change. Additional parts and / or labor may be required.

Bentley San Francisco

999 Van Ness Avenue, San Francisco, CA 94109. Tel: 415.776.7700 Fax: 415.292.9977

Bentley San Francisco



Parts & Labour Estimate

BENTLEY

Date: 10/28/04	Veh ID: SRK36401	Mileage: 64,981	RO# / Tech #: 201010	64981
----------------	------------------	-----------------	----------------------	-------

Line: _____	Parts	Labor	Total Est.
Complaint: Heater not working			

Cause: unknown			

Correction: diagnose		\$242.86	

_____	\$0.00	\$242.86	\$242.86

②

Line: _____	Parts	Labor	Total Est.
Complaint: left rear door lock not working			

Cause: Diagnosis, possible actuator			

Correction: Replace left rear door lock actuator	\$610.00	\$364.64	

_____	\$661.85	\$364.64	\$1,026.49

②

Line: _____	Parts	Labor	Total Est.
Complaint: Brakes two stage, trans fluid dirty, oil dirty, air filter dirty,			

Cause: Mileage and age			

Correction: Perform Service schedule C including fuel filter, spark plugs, ignition cap & rotor, points, engine belts, air filters, service brake reservoir, transmission filter.	\$1,100.00	\$1,347.52	

_____	\$1,193.50	\$1,347.52	\$2,541.02

①

Parts and Labor prices are estimates and are subject to change. Additional parts and / or labor may be required.

Bentley San Francisco

999 Van Ness Avenue, San Francisco, CA 94109. Tel: 415.776.7700 Fax: 415.292.9977

Bentley San Francisco



BENTLEY

Additional Notes

Date: 10/28/04	Veh ID: SRK36401	Mileage: 64,981	RO# / Tech #: 201010 64981
----------------	------------------	-----------------	----------------------------

Line: _____

Notes: Upper ball joint boot torn

Radio antenna inop

Right side moulding on lower side loose

Line: _____

Notes:

Line: _____

Notes:

Parts and Labor prices are estimates and are subject to change. Additional parts and / or labor may be required.

Bentley San Francisco

999 Van Ness Avenue, San Francisco, CA 94109. Tel: 415.776.7700 Fax: 415.292.9977

CENTRAL GARAGE, INC.

1140 SOUTH U.S. 1
 VERO BEACH, FL 32962
 (772)770-6330
 Florida Registration # MV17168

Year Make. 79 ROLLS ROYCE
 Engine
 License F93 BBH
 MLG in/out 64504 / 64504
 Vin SRK36401
 JOE .5

Date 02/09/04 Schedule 02/09/04 **INVOICE : 5623** 03:56PM 1

REMARKS AND LABOR DESCRIPTIONS	HRS	PRICE	PARTS & LUBRICANTS	QTY	PRICE	TOTAL
CLEAN AND REPL. COMPONENTS	0.50	32.50	METAL REPAIR COMPONENTS	2.00	13.50	27.00

DATE	TIME	PHONE	APPROVED	AMOUNT	All Parts Are New Unless Shown As (U) Used or (R) Rebuilt	Labor Sublet	Parts & Lubricants
						32.50 0.00	27.00

I acknowledge notice and oral approval of an increase in the original estimated price

HAZ. DISPOSAL	0.00
SHOP	1.19
Gasoline	0.00
Deposit	0.00
Disc. Applied	0.00
Sub Total	60.69
Sales Tax	4.25

TOTAL 64.94
BALANCE DUE 64.94

X

ACCEPTANCE SIGNATURE

I accept the charges and terms of this agreement.

Thank You For Your Business

I authorize the above repairs and necessary materials. Your employees may operate vehicle for inspection, testing, delivery at my risk. Central Garage will not be responsible for loss or damage to vehicle or items left in it. Labor Rate based on () Flat Rate _____ () Hour Rate _____ () Both Apply _____ Labor is guaranteed for 1 year on new parts. NO warranty on used or customer supplied parts. All other guarantees are made by the manufacturer. Warranty work based on this bill must be performed at this shop. All parts are new unless specified as (U) used or (R) rebuilt. REMOVED PARTS WILL BE DISPOSED OF UNLESS I INITIAL HERE _____.

QUANTITY	PART NUMBER AND DESCRIPTION	UNIT PRICE
----------	-----------------------------	------------

1	Seal	6.95
---	------	------

SIFORD'S EXXON SERVICE
 1550 U.S. 1
 VERO BEACH, FL 32960
 (561) 778-4332 FL LIC. # MV-01145

14948
 RECEIVED: AM PM AM PM
 DATE: / / CALL WHEN READY? YES NO
 CUSTOMER NOTIFIED: AM PM

NAME: MR. [unclear]
 ADDRESS: [unclear]
 CITY: V.B. FL. STATE: FL. ZIP: 32963
 YEAR: 77 MAKE: R/KOM MODEL: _____ LICENSE TAG NO. _____
 VIN: _____ ODOMETER: 64,935 OUT: 1 DATE: 1/1 ODOMETER: _____

DESCRIPTION	SERVICE (LABOR)
EXHAUST WORK - TEMP. REPAIR	6800
WATERPUMP	
STARTER - CHARGED BATTERY	6500
RAD CHECK SYSTEM	
TOTAL PARTS	6.95
TOTAL SUBLET REPAIRS	

ESTIMATED SERVICE DATE	ESTIMATED SERVICE DATE	ESTIMATED SERVICE DATE	ESTIMATED SERVICE DATE	ESTIMATED SERVICE DATE	ESTIMATED SERVICE DATE	ESTIMATED SERVICE DATE	ESTIMATED SERVICE DATE	ESTIMATED SERVICE DATE	ESTIMATED SERVICE DATE

GUARANTEED ITEMS	TECHNICIAN SIGNATURE	TIME AND MILEAGE	CERT. #	INCLUDE IN ESTIMATE	ESTIMATE \$
	X				

PLEASE READ CAREFULLY, CHECK ONE OF THE STATEMENTS BELOW, AND SIGN:
 I UNDERSTAND THAT, UNDER STATE LAW, I AM ENTITLED TO A WRITTEN ESTIMATE.
 I REQUEST A WRITTEN ESTIMATE.
 I DO NOT REQUEST A WRITTEN ESTIMATE AS LONG AS THE REPAIR COSTS DO NOT EXCEED THE SHOP MAY NOT EXCEED THIS MOUNT WITHOUT MY WRITTEN OR ORAL APPROVAL.
 I DO NOT REQUEST WRITTEN ESTIMATE.
 SIGNED: [Signature] DATE: 1-13-04

FLAT RATE HOURLY RATE: 68.00 PER ABOVE
 CHANGE FOR DISASSEMBLY AND/OR REASSEMBLY: 34.00
 WE CANNOT REASSEMBLE: YES NO
 CASH: YES NO
 RETURN REPLACED PARTS: YES NO
 ESTIMATED COST OF REPAIR: 136.00
 REVISED ESTIMATE: 6.95
 ESTIMATE TOTAL: 142.95
 TAX: 12.00
 TOTAL: 154.95

The limited warranties applying to the parts listed herein are those which may be offered by the manufacturer. We hereby expressly disclaim all warranties, either expressed or implied, including any implied warranties of the merchantability or fitness for a particular purpose and neither assume, nor authorize any other person to assume for the company any liability in connection with the sale of this part(s) and/or service. Buyer shall not be entitled to recover from the company any consequential damages, to property, damages for loss of use, loss of time, loss of profits or income, or any other incidental damages.

Pstole

L.M 4:00

DON'S IMPORT AUTO SERVICE, INC.

150 43rd Avenue
Vero Beach, FL 32968
(561)569-4714
State #MV-10015 EPA #18636

INVOICE: 030648
COMPLETED: 11/15/99 17:23:48
ADVISOR: Jeff
ACCOUNT #: 06463 Page: 1

INVOICE FOR SERVICES

CUSTOMER:	LICENSE	UQC67N
ADDRESS:	VEHICLE	79 RollsRoyce Silver Shad
CITY: Vero Beach, FL 32963	V.I.N.	SRK36401
HOME :	MILES	60668
BUSINESS: (561) e	REF:	

The following parts were used when servicing your vehicle:

Quan.	Part #	Description		Charge	Extended
8.00	HCSM	Hose Clamp (small)	CA	0.89	7.12
3.00	RR363	Brake Fluid	AR	26.10	78.30
1.00	UR14201	Hose	ARR	30.64	30.64
1.00	UR20144	Hose	ARR	77.80	77.80
2.00	UR14202Y	Hose	ARR	28.48	56.96
1.00	UPS	Freight	ARR	25.00	25.00

The work performed, and the charges, are:

Check clicking noise when accelerating. Customer said it started occuring after the brake hydraulic resevoir was resealed. Remove resevoir and begin checking system operation. Initial checking found feed to front brake pump was restricted. Further testing revealed a wad of debris in line. Clean out line and pursure further. Inoise was still therel. Check system further and found return lines to resevoir had been improperly replaced with steel lines. Remove and replace with proper rubber hydraulic hoses. Replace resevoir feed hoses also. Bleed out system and recheck operation. [okay]

300.00

Technician: 02

*Paid
Visa
11/16/99*

	Taxable	Non-tax		
Parts:	\$ 275.82		SUBTOTAL: \$	581.82
Labor:	\$ 300.00		Tax: \$	40.73
Sublet:				
Supplies: \$	6.00		TOTAL: \$	622.55
			BALANCE: \$	622.55

Thank you for your patronage!!!
Please call us if you have any questions or problems. We do care.

Signed _____