

1993 Land Rover Range Rover

SALHV124XPA636013



**Heritage Trust
Carfax Report
Records**



BRITISH MOTOR INDUSTRY HERITAGE TRUST

CERTIFIED COPY OF A FACTORY RECORD

BMIHT certifies that the details given below are a true copy of an entry in the original factory records for the vehicle with the chassis number quoted.

This Certificate does not constitute verification of the present condition of a specific vehicle. These are the details of the car as it left the assembly line. Cars were sometimes modified by the manufacturer after production and prior to shipment.

Certificate Number: **2019/2586**

- | | |
|---|--|
| 1. Make & Model | RANGE ROVER 'CLASSIC' |
| 2. Car/Chassis Number | SALLHVMM4KA/636013 |
| 3. Engine Number | 36D20280A |
| 4. Body Number | Not Recorded |
| 5. Specification | LHD, North American Export |
| 6. Colour | |
| a) exterior | Beluga Black |
| b) trim | Light Beige (cloth) |
| c) hood (top) | Not Applicable |
| 7. Date of Build | 12 March 1993 |
| 8. Date of Despatch | 12 March 1993 |
| 9. Destination (Dealer) | Land Rover Encino, USA |
| 10. Other Numbers (where recorded) | - |
| 11. Details of Factory Fitted Equipment | 3.9 litre V8 engine, Automatic gearbox, Electronic air suspension, TWR wheels |
| 12. Other Information | American specification VIN SALHV124XPA/636013 |
| 13. Issued to | Richard Baker |
| 14. Date of Issue | 11 June 2019 |
| 15. Signature of Archivist | |





Vehicle History Report™

US \$39.99

1993 LAND ROVER RANGE ROVER

VIN: SALHV124XPA636013
4 DOOR WAGON/SPORT UTILITY
3.9L V8 F
GASOLINE
ALL WHEEL DRIVE



No accidents or damage reported to CARFAX



21 Service history records



6 Previous owners



Last owned in California



49 Detailed records available



222,013 Last reported odometer reading



This CARFAX Vehicle History Report is based only on [information](#) supplied to CARFAX and available as of 10/8/22 at 1:25:37 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Ownership History

The number of owners is estimated

Year purchased

Owners 1-4

Owner 5

Owner 6

1993

2017

2017

Type of owner

—

—

—

Estimated length of ownership

23 yrs. 7 mo.

1 month

4 yrs. 10 mo.

Owned in the following states/provinces

[See Details](#)

California

California

Estimated miles driven per year

[See Details](#)

—

1,179/yr

Last reported odometer reading

215,573

—

222,013



Title History

CARFAX guarantees the information in this section

[Salvage](#) | [Junk](#) | [Rebuilt](#) | [Fire](#) | [Flood](#) | [Hail](#) | [Lemon](#)



Guaranteed
No Problem



Guaranteed
No Problem



Guaranteed
No Problem

[Not Actual Mileage](#) | [Exceeds Mechanical Limits](#)



Guaranteed
No Problem



Guaranteed
No Problem



Guaranteed
No Problem



GUARANTEED - None of these major title problems were reported by a state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, CARFAX will buy this vehicle back. [Register](#) | [View Terms](#) | [View Certificate](#)



Additional History

Not all accidents / issues are reported to CARFAX

[Total Loss](#)

Owners 1-4

Owner 5

Owner 6

No total loss reported to CARFAX.

Structural Damage

No structural damage reported to CARFAX.

Airbag Deployment

No airbag deployment reported to CARFAX.

Odometer Check

No indication of an odometer rollback.

Accident / Damage

No accidents or damage reported to CARFAX.

Manufacturer Recall

No open recalls reported to CARFAX. Check with an authorized [Land Rover dealer](#) for any open recalls.

Basic Warranty

No data reported to CARFAX.



No Issues Reported



No Issues Reported



No Issues Reported



No Issues Reported



No Issues Reported



No Issues Reported



No Issues Reported



No Issues Reported



No Issues Reported



No Issues Indicated



No Issues Indicated



No Issues Indicated



No Issues Reported



No Issues Reported



No Issues Reported



No Recalls Reported



No Recalls Reported



No Recalls Reported

No Data Reported

No Data Reported

No Data Reported



Detailed History

Owner 1

Purchased: 1993



Low mileage! This owner drove less than the industry average of 15,000 miles per year.

12,559 mi/yr

Date	Mileage	Source	Comments
07/29/1993		California Motor Vehicle Dept.	Title issued or updated - First owner reported
06/23/1997	49,033	California Inspection Station Palmdale, CA	Passed emissions inspection

Owner 2

Purchased: 1999



Low mileage! This owner drove less than the industry average of 15,000 miles per year.

6,406 mi/yr

Date	Mileage	Source	Comments
02/24/1999	75,888	California Motor Vehicle Dept. Hayward, CA	Odometer reading reported
02/25/1999	75,909	Service Facility Belmont, CA	Vehicle serviced
02/25/1999		California Inspection Station Belmont, CA	Passed emissions inspection
06/30/1999		California Motor Vehicle Dept.	Title issued or updated - New owner reported - Loan or lien reported
07/16/1999	80,860	Service Facility	Vehicle serviced

10/27/2000

Belmont, CA
California
Inspection Station
Belmont, CA

 Passed emissions inspection

Owner 3

Purchased: 2001

Date	Mileage	Source	Comments
01/02/2001		California Motor Vehicle Dept. San Francisco, CA	Title issued or updated - New owner reported







Owner 4

Purchased:
2002



Low mileage! This owner drove less than the industry average of 15,000 miles per year.

10,164 mi/yr

Date	Mileage	Source	Comments
06/22/2002	107,282	California Motor Vehicle Dept. San Mateo, CA	Title issued or updated - New owner reported
06/28/2002	107,329	Service Facility Belmont, CA	 Vehicle serviced
06/28/2002		California Inspection Station Belmont, CA	Passed emissions inspection
07/10/2002		California Motor Vehicle Dept. San Mateo, CA	Title issued or updated - Registration updated when owner moved the vehicle to a new location
11/10/2003	127,852	Hubacher Cadillac Sacramento, CA 916-929-2777 hubacher.com  4.4 / 5.0 30 Verified Reviews 	 Vehicle serviced - Steering/suspension checked
06/02/2004	137,844	Service Facility	 Vehicle serviced
06/22/2004	139,205	Service Facility	 Vehicle serviced

09/02/1999

California
Motor Vehicle Dept.
Hayward, CA

Title issued or updated

10/04/2000

86,208

Auto Auction

Listed as a dealer vehicle
- Vehicle sold




Millions of used vehicles are bought
and sold at auction every year.

10/27/2000

86,390

Service Facility

Vehicle serviced

06/30/2004	139,475	California Inspection Station	Passed emissions inspection
04/05/2006	149,458	California Inspection Station	Failed emissions inspection
04/05/2006		Vehicle Repair Center	 Vehicle serviced - Initial timing repaired
04/05/2006		California Inspection Station	Passed emissions inspection
08/01/2008	175,760	California Inspection Station	Passed emissions inspection
06/18/2010	197,030	California Inspection Station San Mateo, CA	Passed emissions inspection
01/21/2011	201,838	California Inspection Station San Mateo, CA	Passed emissions inspection
09/04/2012	211,037	California Inspection Station San Mateo, CA	Failed emissions inspection
09/05/2012	211,095	California Inspection Station San Mateo, CA	Passed emissions inspection
03/15/2017		Auto Auction	Vehicle offered for sale
10/12/2017	215,491	California Inspection Station Gardena, CA	Failed emissions inspection
10/14/2017	215,573	California Inspection Station Gardena, CA	Passed emissions inspection

Owner 5

Purchased: 2017

Date	Mileage	Source	Comments
10/16/2017		California Motor Vehicle Dept. Los Angeles, CA	Title issued or updated - New owner reported


Owner 6









Purchased: 2017







Low mileage! This owner drove less than the industry average of 15,000 miles per year.

1,179 mi/yr

Date	Mileage	Source	Comments
11/21/2017		California Motor Vehicle Dept. Los Gatos, CA	Title issued or updated - New owner reported
07/17/2018	217,507	Exclusive British European Campbell, CA 408-374-0131 ebemotors.com ★ 4.4 / 5.0 7 Verified Reviews ✓ ❤️ 18 Customer Favorites	 Vehicle serviced - Brake fluid flushed/changed - Control arm bushing(s) replaced - Rear shock absorber(s) replaced - Front shock absorber(s) replaced

02/15/2019	218,023	California Inspection Station Los Gatos, CA	Failed emissions inspection
02/15/2019		Speedee Oil Change And Tune-Up Los Gatos, CA 408-356-9301 speedeeoil.com ★ 4.8 / 5.0 46 Verified Reviews ✓ ❤️ 126 Customer Favorites	 Vehicle serviced - Emissions inspection performed
03/05/2019		Vehicle Repair Center Los Gatos, CA	 Vehicle serviced - Catalytic converter repaired - Spark plugs repaired - Ignition wires repaired - CAP/Rotor repaired - Initial timing repaired
03/05/2019	218,055	California Inspection Station Los Gatos, CA	Passed emissions inspection
03/06/2019	218,099	Speedee Oil Change And Tune-Up Los Gatos, CA 408-356-9301 speedeeoil.com ★ 4.8 / 5.0 46 Verified Reviews ✓ ❤️ 126 Customer Favorites	 Vehicle serviced - Emissions inspection performed
05/06/2019	218,305	Exclusive British European Campbell, CA 408-374-0131 ebemotors.com ★ 4.4 / 5.0 7 Verified Reviews ✓ ❤️ 18 Customer Favorites	 Vehicle serviced
06/01/2019	218,320	Speedee Oil Change And Tune-Up Los Gatos, CA 408-356-9301 speedeeoil.com ★ 4.8 / 5.0 46 Verified Reviews ✓ ❤️ 126 Customer Favorites	 Vehicle serviced
07/11/2019	218,332	Exclusive British European Campbell, CA 408-374-0131 ebemotors.com ★ 4.4 / 5.0 7 Verified Reviews ✓ ❤️ 18 Customer Favorites	 Vehicle serviced - Ignition control module replaced
01/27/2020	219,351	North Texas Rover Inc. Dallas, TX 972-869-4881 ❤️ 1 Customer Favorite	 Vehicle serviced
07/08/2020	219,785	North Texas Rover Inc. Dallas, TX 972-869-4881 ❤️ 1 Customer Favorite	 Vehicle serviced - Ignition lock cylinder replaced

11/24/2020	220,801	Mobil 1 Lube Express # 365 Dallas, TX 214-350-9466 take5oilchange.com/locations.htm	 Vehicle serviced - Oil and filter changed
		★ 4.9 / 5.0 101 Verified Reviews ✓ ❤️ 115 Customer Favorites	
04/07/2021		North Texas Rover Inc. Dallas, TX 972-869-4881	 Vehicle serviced - Window(s) checked
		❤️ 1 Customer Favorite	
10/29/2021	221,717	Exclusive British European Campbell, CA 408-374-0131 ebemotors.com	 Vehicle serviced - Drivability/performance checked - Brake fluid flushed/changed
		★ 4.4 / 5.0 7 Verified Reviews ✓ ❤️ 18 Customer Favorites	
12/14/2021	221,728	California Inspection Station Campbell, CA	Passed emissions inspection
05/11/2022	222,013	Exclusive British European Campbell, CA 408-374-0131 ebemotors.com	 Vehicle serviced - A/C receiver/dryer replaced - Oil and filter changed
		★ 4.4 / 5.0 7 Verified Reviews ✓ ❤️ 18 Customer Favorites	

Have Questions? Please visit our Help Center at www.carfax.com.



Glossary

Failed Emissions Inspection

The emissions check performed during a vehicle inspection indicated the vehicle was emitting more than allowable emissions standards and/or had missing or modified parts. Repeated failed emissions records can indicate engine problems and CARFAX recommends you have the vehicle inspected.

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

New Owner Reported

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:



facebook.com/CARFAX



[@CARFAXinc](https://twitter.com/CARFAXinc)



About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2022 CARFAX, Inc., part of S&P Global. All rights reserved.
10/8/22 1:25:37 PM (CDT)



VEHICLE HIGHLIGHTS

1993 LAND ROVER RANGE ROVER

VIN: SALHV124XPA636013

Body Style: 4 DOOR WAGON/SPORT UTILITY

Engine Size: 3.9L V8 F

Drivetrain: ALL WHEEL DRIVE

OWNERSHIP HISTORY:

Number of Owners:	6
Last owned in the following state/province:	California
Annual average mileage:	7,708 LOW MILEAGE*

*Below industry annual average of 15,000 miles

STATE DMV-REPORTED TITLE PROBLEMS:

None of these major title problems were reported by a state Department of Motor Vehicles:



Salvage, Junk, Rebuilt, Fire, Flood, Hail, Lemon

Guaranteed No Problem

Not Actual Mileage, Exceeds Mechanical Limits

Guaranteed No Problem

ACCIDENTS AND OTHER ISSUES:

No issues reported to CARFAX on the following:

Total Loss	<input checked="" type="checkbox"/> No Issues Reported
Structural Damage	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment	<input checked="" type="checkbox"/> No Issues Reported
Odometer Rollback	<input checked="" type="checkbox"/> No Issues Reported
Other Accidents / Damage	<input checked="" type="checkbox"/> No Issues Reported

Information excerpted from the CARFAX Vehicle History Report and/or Safety & Reliability Ratings; see full reports for additional information, glossary of terms, source attributions, disclaimers & limitations. Go to carfax.com for complete Buyback Guarantee terms and conditions.

SHOW ME THE CARFAX



CARFAX BUYBACK GUARANTEE

CARFAX Buyback Coverage

Visit <https://www.carfax.com/Service/bbg> to register your CARFAX Buyback Guarantee and sign up for Car Care

Guarantee Coverage: 10/08/2022 - 10/08/2023

CARFAX Vehicle Description: 1993 LAND ROVER RANGE ROVER

VIN: SALHV124XPA636013

Body Style: 4 Door Wagon/Sport Utility

Driveline: All wheel drive

Engine: 3.9L V8 F

CARFAX will buy this vehicle back if


you find that any of these severe problems were reported by a Department of Motor Vehicles and were not included in this report.



SEVERE DAMAGE
Salvage/Junk
Rebuilt/Reconstructed
Dismantled
Fire/Flood/Hail



ODOMETER PROBLEMS
Exceeds Mechanical Limits
Not Actual Mileage



LEMON HISTORY
Manufacturer Buyback

Visit the [Buyback Guarantee registration page](#) to register the CARFAX Buyback Guarantee and sign up for Car Care.

Terms and Conditions Apply

View [Terms and Conditions](#) for CARFAX Buyback Guarantee coverage

EXCLUSIVE
**BRITISH-
EUROPEAN**

SPECIALIZING IN LAND ROVER & JAGUAR

2921 Winchester Blvd. ■ Campbell, CA 95008
(408) 374-0131 ■ (408) 374-2143 fax
www.ebemotors.com

SERVICE

SALES

PARTS

ACCESSORIES

Invoice No.

37954

Page 1

Order Date 05/11/22 08:00 am

Completed: 05/20/22 01:30 pm



93 LAND ROVER RANGE ROVER B1
222013 Mi. Last in 10/29/2021
Lic: 8ALT492/CA V8Cyl 3.9
Vin: SALHV124XPA636013 03/93
Eq: AT AC PS FI 4W

Quotes

1 05/11/22 09:12am 377.97
Richard in person.

Job01 Fuel Leak

Labor: \$95.00

Customer states that when off road ing on steep uphill grades there is a leak from the fuel tank area. Advise. Upon inspection tech found that fuel tank cap is broken. No other leaks noticable at this time. Replaced cap and retest for leaks. All ok at this time

WLD100820	fuel cap-N	1.0 @	31.13 =\$	31.13	31.13
-----------	------------	-------	-----------	-------	-------

Job02 A/C Warm

Labor: \$760.00

Customer states that AC cools but the compressor only seems to run briefly, so it is not very effective on hot days. Advise on needs. Perform complete a/c service if needed. Upon inspection tech found that front seal on AC compressor is leaking. Converted to 134 since only low side fitting on. Flushed Ac system and replaced AC compressor, receiver drier, and recharged AC system as per customer request. All ok at this time

R134A	Refrigerant-N	2.0 @	45.00 =\$	90.00	
R134ADYE	Dye-N	1.0 @	29.50 =\$	29.50	
EXBRIT.AC	AC SERVICE KIT-N	1.0 @	15.60 =\$	15.60	
ETC7994	COMPRESSOR-S	1.0 @	650.50 =\$	650.50	
BTR3717	reciever drier-N	1.0 @	85.90 =\$	85.90	
EXLC.694U5	PAG OIL-S	1.0 @	20.30 =\$	20.30	891.80

Job03 RR 1993 Classic Oil Service

Labor: \$100.00

Perform oil service as per checklist
Replace oil and filter
Rotate Tires
Set tires to factory spec in ft/rear
Reset maint reminder light

1112	Drain Plug Washer-N	1.0 @	2.95 =\$	2.95	
20W/50	Motor Oil-N	7.0 @	10.99 =\$	76.93	
OSPWASOL	Washer solvent-N	1.0 @	1.95 =\$	1.95	
EBC9658	oil filter-N	1.0 @	21.40 =\$	21.40	103.23

Job04 Clean/Flush Drain Tubes

Labor: \$95.00

----->----->----->-----Continued on the next page----->----->----->-----

ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE

ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE SAVE DISCARD



CREDIT CARDS
ACCEPTED



WE RESERVE THE RIGHT TO REFUSE ANY PERSONAL CHECKS

I acknowledge notice and oral approval of an increase in the original estimated price.

X

CUSTOMER ACKNOWLEDGMENT

By signing below, I hereby authorize the repair work to be done along with the necessary material, and hereby grant your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. If automobile is returned to customer before authorized service is performed, a diagnostic and handling charge will be made. I have read and understand the statements and estimates made on this side and the reverse of this/these pages (connected with this vehicle). I authorize service to be performed, including sublet work, and acknowledge receipt of this estimate. Customer is hereby notified that the said property is not insured or protected against loss occasioned by theft, fire or vandalism while the property remains within the Repair Garage.

CUST. X
SIG.

I ACKNOWLEDGE RECEIPT OF AND AGREE TO THE TERMS AND CONDITIONS OF THIS CONTRACT.

READ IMPORTANT INFORMATION ON REVERSE SIDE

EXCLUSIVE
BRITISH
EUROPEAN
SPECIALIZING IN LAND ROVER & JAGUAR

2921 Winchester Blvd. ■ Campbell, CA 95008
 (408) 374-0131 ■ (408) 374-2143 fax
 www.ebemotors.com

SERVICE
 ■
 SALES
 ■
 PARTS
 ■
 ACCESSORIES

Invoice No.
37954

Page 2

Order Date 05/11/22 08:00 am
 Completed: 05/20/22 01:30 pm

Job04 Clean/Flush Drain Tubes

Customer request to have sunroof drain tubes flushed/cleaned of debris. All ok at this time

Recommendations: Radius/Trailing Arm bushings worn, air filter dirty, wipers streak, battery will not hold charge,

Payments to Exclusive British European

Cost Summary

Status: Completed Work Order

Payments:

Labor	1050.00
Parts	1026.16
Haz Waste	6.75
Subtotal	2082.91
Tax	96.20
Total	\$2179.11
Payments	0.00
Bal Due	2179.11

Thank you for choosing Exclusive British European

ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE

ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE SAVE DISCARD



CREDIT CARDS
 ACCEPTED



WE RESERVE THE RIGHT TO REFUSE ANY PERSONAL CHECKS

I acknowledge notice and oral approval of an increase in the original estimated price.

X

CUSTOMER ACKNOWLEDGMENT

By signing below, I hereby authorize the repair work to be done along with the necessary material, and hereby grant your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. If automobile is returned to customer before authorized service is performed, a diagnostic and handling charge will be made. I have read and understand the statements and estimates made on this side and the reverse of this/these pages (connected with this vehicle). I authorize service to be performed, including sublet work, and acknowledge receipt of this estimate. Customer is hereby notified that the said property is not insured or protected against loss occasioned by theft, fire or vandalism while the property remains within the Repair Garage.

CUST. X
 SIG.

I ACKNOWLEDGE RECEIPT OF AND AGREE TO THE TERMS AND CONDITIONS OF THIS CONTRACT.

READ IMPORTANT INFORMATION ON REVERSE SIDE

EXCLUSIVE
BRITISH
EUROPEAN

SPECIALIZING IN LAND ROVER & JAGUAR

2921 Winchester Blvd. ■ Campbell, CA 95008
(408) 374-0131 ■ (408) 374-2143 fax
www.ebemotors.com

SERVICE

■
SALES

■
PARTS

■
ACCESSORIES

LUBE AND OIL SERVICE

REPLACE ENGINE OIL

REPLACE ENGINE OIL FILTER

REPLACE ENGINE OIL PLUG SEALING WASHER

CHECK ALL FLUID LEVELS AND TOP OFF AS NEEDED

CHECK AND REPORT ON ENGINE OIL LEAKS

CHECK AND REPORT ON TRANSMISSION OIL LEAKS

CHECK AND REPORT ON CONDITION OF COOLANT

CHECK AND REPORT ON COOLING FAN OPERATION

CHECK AND REPORT ON ALL ENGINE

INSPECT AIR FILTER ELEMENT

TEST BATTERY

INSPECT CLUTCH OPERATION (IF APPLICABLE)

TEST AND ADVISE HEATER AND AIR CONDITIONING OPERATION

TEST DISTRIBUTION VACUUM ADVANCE & REPORT (IF APPLICABLE)

CHECK LIGHTS AND HORN OPERATION

INSPECT WIPER AND WIPER BLADE OPERATION & CONDITION

LUBRICATE ALL DOOR HINGES, HOOD/TRUNK LATCH MECHANISMS

ROTATE TIRES, CHECK & ADVISE ON TIRE WEAR (DO NOT ROTATE IF DIFFERENT SIZES)

CHECK WHEEL LUG TORQUE & ADJUST TO SPECS

CHECK PRESSURE AND ADJUST TO SPECS ON ALL TIRES

INSPECT EMERGENCY BRAKE OPERATION

INSPECT SUSPENSION BOLTS/NUTS

BRAKES AND ROTORS FRONT% 11mm REAR% 8mm

INSPECT STEERING AND SUSPENSION & LUBE AS NEEDED

INSPECT EXHAUSE SYSTEM & CATALYTIC CONVERTER

CHECK TRANSMISSION FLUID LEVEL INSPECT

CHECK DIFFERENTIAL FLUID AND CONDITION

RESET OIL SERVICE LIGHT (IF APPLICABLE)

INSTALL SERVICE REMINDER STICKER ON WINDSHIELD

TEST DRIVE CAR AND REPORT

Category	Date	Mileage	Parts Replaced	Part number	Issue
repair	17-Nov-17	215636	none		Inspection at Rover. Doctor before driving the car back from LA.
repair	24-Nov-17		battery		Trouble starting, battery case bulging when inspected
maintenance	24-Nov-17		wiper blades	Bosch 40718A	wiper blades were old, replaced front and rear
repair	24-Nov-17		dome light lenses		dome light lenses were cracked and yellow
maintenance			brake light bulb		Passenger side brake light out
improvement	28-Nov-18		correct OEM keys		Plastic portion of key provided with sale broken off. Parts are cheap, but since they are steel, \$45.52 to cut at a locksmith (Kwik Key Lock and Safe, Mountain View)
maintenance	10-Dec-17		lubricated door latches and locks		Passenger door hard to open. Lubricated all door latches.
improvement	25-Dec-17		floor mats	STC8053	
repair	31-Dec-17		fixed gauge cluster lights		Disassembled the lower dash to see if the dimmer was bad. Found the dimmer connector was disconnected and worked when re-connected.
repair	7-Jan-18		door pin switches	PRC8548	Dome light not operating with the doors. Found the plunger on the rear passenger switch was broken so the switch was always closed.
improvement	7-Jan-18		cup holders	STC531565UC	
repair	7-Jan-18		invited hood prop holder back on		Hood prop holder had one broken rivet and was loose
repair	14-Jan-18		driver side puddle lamp	Philips 194 bright white	Driver side puddle lamp bulb out. Replaced with LED.
maintenance	20-Jan-18		oil change	ERR33405KB	8 quarts of 20w-50
improvement	27-Jan-18		trickle charger connector		Bulb was ok. Pulled the housing and found that the connector for the housing was simply unplugged above the headliner.
repair	25-Feb-18		fixed rear dome light	PRC7045G	
repair	3-Mar-18		windshield washer pumps front and rear	MWC2287	Pull handle on the hood release cable was broken off so it had to be pulled with pliers.
repair	18-Mar-18	217089	hood release cable		Replaced all missing bulbs. Several appear to be removed since they remain lit. Started fixing the lit ones with the oil pressure first.
repair	18-Mar-18	217089	dash warning bulbs	E1P1180LG	
repair	18-Mar-18	217089	low oil control unit (used)		Oil pressure light was not illuminating. Checked the sensor and it was good. Checked the bulb and it was removed. After replacing it would remain lit all the time. Forum guidance suggested the Jaeger oil control unit in the left dash. Replaced with a headlight washer nozzle
repair	25-Mar-18		headlight washer nozzle	PRC5434	Used one and the light now works properly.
improvement	27-Apr-18		1993 owners manual	PRC4615	driver side headlamp washer nozzle missing when the truck was purchased
improvement	29-Apr-18		window switches (used)	PRC5255/PRC5254	
repair	3-May-18		brake light housing (used)		the logos on the old switches were totally rubbed off
repair	12-May-18		tailgate handle	MWC8656G, SE910481A	Just used the plastic part and the lens since the old ones were cracked
repair	13-May-18		passenger side seat switch	PRC8095	Tailgate lock not working with power locks. Removed and found one of the tabs on the lock mechanism broken off and spring inside the handle mechanism broken
repair	13-May-18		hood adjuster rubber bumper		Passenger power seat inoperable
repair	18-May-18		washer fluid sensor	PRC5440	Missing on the driver side and passenger side cracked and brittle. Allowed the hood to wobble.
repair	26-May-18		coolant level sensor	PRC7925G	Light was on regardless of fluid level
repair	26-May-18		exhaust	ESR1053K	Sensor was disconnected. Connecting it would give the light regardless of coolant level.
repair	26-May-18		exhaust hanger	NTC5582	Rear muffler rusted out. Mid pipe and front muffler had holes.
repair	2-Jun-18		positive battery cable	AMR4803AB	insulation was in poor condition and the heat shield was missing
repair	2-Jun-18		negative battery cable	PRC5235AB	replaced at the same time as the positive cable to ensure good connections to the battery
improvement	2-Jun-18		18 ga cable to alternator and fuse holder	FBMBWP	Added an additional cable from the alternator since the original was corroded
improvement	2-Jun-18		positive terminal distribution block	EFXBTCUD08	Solid connectors for the positive cable to starter, amplifier, and alternator cable
repair	2-Jun-18		front door lamp bulbs - Philips 194	127916000KB2	Red lights at the back of the front doors had burned out bulbs.
improvement	10-Jun-18		passenger side seat switch cover	BTR1334	Tabs were broken on the original cover so it was loose and rattled
repair	23-Jun-18		HVAC blower motor resistor bank	PRC8010	Speeds other than maximum were barely functional. Found that Atlantic British makes an improved replacement part and replaced the rusty factory one.
repair	24-Jun-18		hood light switch	PRC8548	Root caused the inoperable hood light to a broken switch that uses the same part as the doors. Replaced with a new switch, added an Philips 194 LED bulb, and cleaned up the cover/lens.
improvement	30-Jun-18		driver side seat switch cover	BTR1333RUN	Tabs were broken on the original cover so it was loose and rattled
repair	30-Jun-18		air inlet vent filter foam	MXC3910	Foam was missing so leaves and other debris were getting sucked in
improvement	30-Jun-18		air vent facia	BTR7072G	Several had broken pivots and were loose or had discolored plastic. Replaced with new parts after replacing the wood trim.
repair	8-Jul-18	217504	fog lights fixed		Wiring was disconnected in the front air dam
repair	8-Jul-18	217504	lock button guide	BRC8965PMA	Driver side door lock button was loose. Caused by a broken lock button guide.
improvement	15-Jul-18	217506	fuel door switch (used)	PRC7130	Loop was worn off the old button so it was blank. Replaced with a used one that still has the gas loop.
improvement	15-Jul-18	217506	bolts for back of front seats		The rear ends of the front seat tracks were not bolted in, allowing the seats to tilt forward. The tracks (95 style) did not have bolt holes on the tops to meet the pedestal. Drilled holes in the pedestal to match the bolt holes in the tracks and tapped them for the threads, and added a nut on the accessible outer sides.
repair	28-Aug-18	217507	Various repairs at Exclusive British European		
			ABS light fixed		After replacing the missing ABS bulb, the ABS light was always on
			brake fluid replacement		unknown when last replaced, always good to replace to get any water out of the system

				front and rear shocks and steering damper			shocks were worn and not damping well
				motor mounts			motor mounts were cracked and old
				suspension bushings (radius arm, trailing arm, panhard rod, AC conversion to R134 and replacement of hoses)			suspension bushings were cracked and old
				heater core replacement			AC not blowing cold
				sunroof drain cleared			heater leaking coolant
				rear lamp guard hardware		STC8027	The sunroof was leaking at the driver side A pillar due to a clogged drain line. Blew out the line with compressed air.
				center console reinforced			rear lamp housings and lamp guards were loose. Replaced the mounting hardware with new aluminum kit from LRNJ
				climate control lighting			the two halves and also reinforced the back edge near the hinge for the lid. Sanded rust off the hinge and repainted it. Replaced all screws
				switch panel bulbs		RTC3635	Climate control panel was missing the wiring harness. Part is NLA, built a new harness and harvested a plug from a used dimmer switch. Replaced all the bulbs.
				control stalk bulb		RTC5604G	Several bulbs in the switch panel with the defroster, ceiling light switch, etc. were burned out. Removed and cleaned all switches so they operate without sticking and replaced the burned out bulbs.
				rear cargo cover (used)		RTC3635	Bulb below the steering column that illuminates the turn signal and wiper stalks was burned out.
				rear ash tray (used)		AWR1399	Found a used one to replace the missing cargo cover
				cigarette lighter		YUJ10037L	Was broken when I bought the car, replaced with a used one from eBay
				oil and filter change		ERR3340SKB	Front cigarette lighter socket never worked
				fuse box cover (used)		BTR3486RUI	7 quarts 5w-30, new drain plug and washer
				replace front fender reflectors		Congleton	All tabs were broken, replaced with used part with all tabs intact
				replace missing windshield wiper cap		Congleton	old ones were faded to a pale yellow
				replace missing lower dash closure part		MXC7032	rear wiper was missing the cap
				powder coat brush guards and tail light		Limitless Coating	the panel under the AC fans was missing, found a used one on eBay and installed it
				replace leaking headlight washer check		DCP6656	paint was peeling in several places
				tires		Goodyear Trailrunner AT LT225/75	check valve was cracked and would slowly leak out all of the washer fluid
				replace faded wheel center caps		ANR2391MNH	Replaced cheap Primewell tires with good Goodyear AT tires
				re-seal tail gate glass		Permatex 81730	water was leaking into the frame
				adjust tailgate to make it easier to close			replaced back up bulb
				fix driver's side backup light		MXCS587PR	
				replace rusty screws for tail lights with stainless hardware		RRD500560	Several were rounded off and no longer fit the correct 1 3/16" socket, replaced all with new parts
				replace broken mud flaps		Congleton	passenger side tail light lens was cracked with a missing piece at the top
				replace lug nuts (all)		Rover Classic 2D Letters	front stickers were 40% worn off
				passenger side tail light reflector		WR9DC, RTC6551, STC8368, STC	failed smog test due to HC over limit and replacement cat on passenger side lacking correct EO number to make it CA legal
				hood stickers			
				spark plugs, wires, cap, rotor			
				driver and passenger side catalytic converters			
				replace instrument bezel fascia		BTR1458RUN	Top of the bezel was cracked with missing pieces (scalloped edge). Also the instrument panel wiring was routed incorrectly causing the back half of the cover to not sit properly.
				RF swivel seal rebuild		PLM085	Right front swivel seal leaking, would eventually cause the ABS sensor to fail like the LF that was already replaced.
				throttle position sensor		STC1184, RTC5090, RTC5971	check engine light with code 17, checked the voltage at the sensor and it was not moving with the throttle
				pick up coil and ignition amp			truck seemed down on power, wasn't idling smoothly like it should
				Various repairs at Exclusive British European			
				oil and filter change			
				replace front brake callipers		RTC75996KIT	pulling to the side when braking
				brake fluid replacement		STC3765, SFP500200	
				front and rear brake pads		FTC4785, FTC3179	
				RF axle seal		FTC4785, FTC3179	
				LR axle seal		FTC5870, RTC1799, RTC5869, RTC8390	
				steering tie rod and drag links		ANR3410	
				panhard bushings			
				alignment			
				Various repairs at Exclusive British European			
				fuel cap		WLD100820	
				AC compressor and drier		ETC7994, BTR3717	AC not cooling well
				oil and filter change			
				clean sunroof drain tubes			sunroof leaking when washing the truck

EXCLUSIVE
BRITISH
EUROPEAN

SPECIALIZING IN LAND ROVER & JAGUAR

2921 Winchester Blvd. ■ Campbell, CA 95008
 (408) 374-0131 ■ (408) 374-2143 fax
 www.ebemotors.com

SERVICE

SALES

PARTS

ACCESSORIES

Invoice No.

37026

Page 1

Order Date 10/29/21 09:01 am

Paid: 12/14/21 04:15 pm



93 LAND ROVER RANGE ROVER B1
 221717 Mi. Last in 7/11/2019
 Lic: 8ALT492/CA V8Cyl 3.9
 Vin: SALHV124XPA636013 03/93
 Eq: AT AC PS FI 4W

Quotes

1 10/29/21 09:12am 311.13
 Richard in person.

Job01 RR 1993 Oil Service

Labor: \$100.00

Perform service as per checklist
 Replace Oil and Fiter
 Rotate Tires
 Set tires to factory spec

1112	Drain Plug Washer-N	1.0 @	2.95 =\$	2.95
EBC9658	oil filter-N	1.0 @	21.40 =\$	21.40
OSPBRACLEEN	Brake cleaner-N	1.0 @	4.25 =\$	4.25
OSPLUBE	Lubricant-N	1.0 @	2.95 =\$	2.95
OSPWASOL	Washer solvent-N	1.0 @	1.95 =\$	1.95
10W/30	AC DEL.-N	7.0 @	9.50 =\$	66.50 100.00

Job02 Surcharge

Sublet: \$90.00

Job03 Brake Calipers

Labor: \$0.00

Customer states that there is a pull from the car when braking. Advise. Upon inspection tech found that brake calipers are old and sticking. Remove and replaced front RH and LH brake calipers as per customer request and retest. All ok at this time. NOTE: labor done at no charge to customer as per Nick

RTC75996KIT	CALIPER-S	2.0 @	250.30 =\$	500.60
SHIPPING	SHIPPING-S	1.0 @	50.00 =\$	50.00 550.60

Job04 Brake Flush

Labor: \$185.00

Complete brake fluid flush and bleed as per customer request and road test vehicle. All ok at this time

DOT4BRAKE	Castrol brake fluid-N	2.0 @	8.25 =\$	16.50
OSPSHOP	shop supplies-N	1.0 @	10.95 =\$	10.95 27.45

Job05 RF Axle Seal

Labor: \$450.00

Replaced worn and leaking RF axle seal as per customer request. All ok at this time

----->----->----->---Continued on the next page--->----->----->----->-----

ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE

ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE SAVE DISCARD



CREDIT CARDS
ACCEPTED



WE RESERVE THE RIGHT TO REFUSE ANY PERSONAL CHECKS

I acknowledge notice and oral approval of an increase in the original estimated price.

X

CUSTOMER ACKNOWLEDGMENT

By signing below, I hereby authorize the repair work to be done along with the necessary material, and hereby grant your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. If automobile is returned to customer before authorized service is performed, a diagnostic and handling charge will be made. I have read and understand the statements and estimates made on this side and the reverse of this/these pages (connected with this vehicle). I authorize service to be performed, including sublet work, and acknowledge receipt of this estimate. Customer is hereby notified that the said property is not insured or protected against loss occasioned by theft, fire or vandalism while the property remains within the Repair Garage.

CUST. X
SIG.

I ACKNOWLEDGE RECEIPT OF AND AGREE TO THE TERMS AND CONDITIONS OF THIS CONTRACT.

READ IMPORTANT INFORMATION ON REVERSE SIDE

EXCLUSIVE
BRITISH
EUROPEAN

SPECIALIZING IN LAND ROVER & JAGUAR

2921 Winchester Blvd. ■ Campbell, CA 95008
 (408) 374-0131 ■ (408) 374-2143 fax
 www.ebemotors.com

SERVICE

SALES

PARTS

ACCESSORIES

Invoice No.
37026

Page 2

Order Date 10/29/21 09:01 am
 Paid: 12/14/21 04:15 pm

Job05 RF Axle Seal

FTC4785	Seals-N	1.0 @	7.92 =\$	7.92	
571752	gasket-N	1.0 @	2.94 =\$	2.94	
FTC3179	lock washer-N	1.0 @	2.85 =\$	2.85	
2420	COMPONENT CLEANER-N	1.0 @	6.50 =\$	6.50	20.21

Job06 RR 1993 Ft Brake Pads

Labor: \$180.00

Replace front brake pads as per customer request and road test car. All ok at this time

DOT4BRAKE	Castrol brake fluid-N	1.0 @	8.25 =\$	8.25	
OSPBRAKLEEN	Brake cleaner-N	1.0 @	4.25 =\$	4.25	
STC3765	Front pads-N	1.0 @	157.42 =\$	157.42	169.92

Job07 LR Axle Seal

Labor: \$285.00

Replaced worn and leaking LH rear axle seals as per customer request and road test. All ok at this time

FTC4785	Seals-N	1.0 @	7.92 =\$	7.92	
FTC3179	lock washer-N	1.0 @	2.85 =\$	2.85	
571752	gasket-N	1.0 @	2.94 =\$	2.94	
2420	COMPONENT CLEANER-N	1.0 @	6.50 =\$	6.50	20.21

Job08 RR 1993 Rear Brake Pads

Labor: \$180.00

Replace rear brake pads as per customer request and road test car. All ok at this time

SFP500200	brake pad set-N	1.0 @	115.20 =\$	115.20	
2420	COMPONENT CLEANER-N	2.0 @	6.50 =\$	13.00	128.20

Job09 Tow Rod

Labor: \$180.00

Replaced cracked and worn tie/toe rod assembly as per customer request. All ok at this time

RTC1799	tie rod assy-N	1.0 @	325.20 =\$	325.20	325.20
---------	----------------	-------	------------	--------	--------

Job10 Drag Link

Labor: \$190.00

Replaced very weak/worn drag link assembly as per customer request and road test car. All ok at this time

RTC5870	tie rod end-N	1.0 @	75.32 =\$	75.32	
RTC5869	tie rod end-N	1.0 @	75.20 =\$	75.20	
NTC8390	drag link-N	1.0 @	180.20 =\$	180.20	330.72

----->----->----->---Continued on the next page--->----->----->----->-----

ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE

ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE SAVE DISCARD



CREDIT CARDS
 ACCEPTED



WE RESERVE THE RIGHT TO REFUSE ANY PERSONAL CHECKS

I acknowledge notice and oral approval of an increase in the original estimated price.

X

CUSTOMER ACKNOWLEDGMENT

By signing below, I hereby authorize the repair work to be done along with the necessary material, and hereby grant your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. If automobile is returned to customer before authorized service is performed, a diagnostic and handling charge will be made. I have read and understand the statements and estimates made on this side and the reverse of this/these pages (connected with this vehicle). I authorize service to be performed, including sublet work, and acknowledge receipt of this estimate. Customer is hereby notified that the said property is not insured or protected against loss occasioned by theft, fire or vandalism while the property remains within the Repair Garage.

CUST. X
 SIG.

I ACKNOWLEDGE RECEIPT OF AND AGREE TO THE TERMS AND CONDITIONS OF THIS CONTRACT.

READ IMPORTANT INFORMATION ON REVERSE SIDE

EXCLUSIVE
BRITISH
EUROPEAN

SPECIALIZING IN LAND ROVER & JAGUAR

2921 Winchester Blvd. ■ Campbell, CA 95008
 (408) 374-0131 ■ (408) 374-2143 fax
 www.ebemotors.com

SERVICE

SALES

PARTS

ACCESSORIES

Invoice No.
37026

Page 3

Order Date 10/29/21 09:01 am
 Paid: 12/14/21 04:15 pm

Job11 Panhard Rod Bushing

Labor: \$360.00

Replaced cracked/worn panhard rod bushings as per customer request and road test. All ok at this time

ANR3410 panhard rod bushing-N 2.0 @ 36.74 =\$ 73.48 73.48

Job12 Alignment

Labor: \$180.00

Performed 4 wheel alignment as per customer request and road test car. All ok at this time

Recommendations: Radius & Trailing Arm bushings very worn, air filter dirty, wipers streak, battery will not hold charge,

Payments to Exclusive British European

Cost Summary

Status: Paid Work Order

Payments: \$4,298.68

- 1 12/14/21 -684.87 Visa
- 2 12/14/21 4893.55 Visa
- 3 12/14/21 90.00 Visa

Labor	2290.00
Parts	1745.99
Haz Waste	9.00
Sublet	90.00
Subtotal	4134.99
Tax	163.69
Total	\$4298.68
Payments	4298.68
Bal Due	0.00

Thank you for choosing Exclusive British European

ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE

ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE SAVE DISCARD



CREDIT CARDS
ACCEPTED



WE RESERVE THE RIGHT TO REFUSE ANY PERSONAL CHECKS

I acknowledge notice and oral approval of an increase in the original estimated price.

X

CUSTOMER ACKNOWLEDGMENT

By signing below, I hereby authorize the repair work to be done along with the necessary material, and hereby grant your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. If automobile is returned to customer before authorized service is performed, a diagnostic and handling charge will be made. I have read and understand the statements and estimates made on this side and the reverse of this/these pages (connected with this vehicle). I authorize service to be performed, including sublet work, and acknowledge receipt of this estimate. Customer is hereby notified that the said property is not insured or protected against loss occasioned by theft, fire or vandalism while the property remains within the Repair Garage.

CUST. X
SIG.

I ACKNOWLEDGE RECEIPT OF AND AGREE TO THE TERMS AND CONDITIONS OF THIS CONTRACT.

READ IMPORTANT INFORMATION ON REVERSE SIDE

EXCLUSIVE
BRITISH
EUROPEAN

SPECIALIZING IN LAND ROVER & JAGUAR

2921 Winchester Blvd. ■ Campbell, CA 95008
(408) 374-0131 ■ (408) 374-2143 fax
www.ebemotors.com

SERVICE

■
SALES

■
PARTS

■
ACCESSORIES

LUBE AND OIL SERVICE

REPLACE ENGINE OIL

REPLACE ENGINE OIL FILTER

REPLACE ENGINE OIL PLUG SEALING WASHER

CHECK ALL FLUID LEVELS AND TOP OFF AS NEEDED

CHECK AND REPORT ON ENGINE OIL LEAKS

CHECK AND REPORT ON TRANSMISSION OIL LEAKS

CHECK AND REPORT ON CONDITION OF COOLANT

CHECK AND REPORT ON COOLING FAN OPERATION

CHECK AND REPORT ON ALL ENGINE

INSPECT AIR FILTER ELEMENT

TEST BATTERY

INSPECT CLUTCH OPERATION (IF APPLICABLE)

TEST AND ADVISE HEATER AND AIR CONDITIONING OPERATION

TEST DISTRIBUTION VACUUM ADVANCE & REPORT (IF APPLICABLE)

CHECK LIGHTS AND HORN OPERATION

INSPECT WIPER AND WIPER BLADE OPERATION & CONDITION

LUBRICATE ALL DOOR HINGES, HOOD/TRUNK LATCH MECHANISMS

ROTATE TIRES, CHECK & ADVISE ON TIRE WEAR (DO NOT ROTATE IF DIFFERENT SIZES)

CHECK WHEEL LUG TORQUE & ADJUST TO SPECS

CHECK PRESSURE AND ADJUST TO SPECS ON ALL TIRES

INSPECT EMERGENCY BRAKE OPERATION

INSPECT SUSPENSION BOLTS/NUTS

BRAKES AND ROTORS FRONT% 12mm REAR% 12mm

INSPECT STEERING AND SUSPENSION & LUBE AS NEEDED

INSPECT EXHAUSE SYSTEM & CATALYTIC CONVERTER

CHECK TRANSMISSION FLUID LEVEL INSPECT

CHECK DIFFERENTIAL FLUID AND CONDITION

RESET OIL SERVICE LIGHT (IF APPLICABLE)

INSTALL SERVICE REMINDER STICKER ON WINDSHIELD

TEST DRIVE CAR AND REPORT

Order information

Shipping address

Order total

Buyer mbak_i_sj4b3honn
Seller mike_6094
Order placed on Monday, Jul 8, 2019
Payment method Credit card
Payment date Monday, Jul 8, 2019

Subtotal	\$28
Shipping	\$5
Total coupon amount	-\$3
Total	\$29

Item(s) bought from mike_6094

Order number 15-03581-30711

Qty	Item name
1	Range Rover Classic Center Console Felt Box Liner (233280929606)

Shipping service	Item price
USPS Priority Mail	\$28.00

Land Rover ■ Jaguar service center

2921 Winchester Blvd. ■ Campbell, CA 95008

(408) 374-0131 ■ (408) 374-2143 fax

www.ebemotors.com

SERVICE
 SALES
 PARTS
 ACCESSORIES

Invoice No.
32734

Page 1

Order Date 07/11/19 09:07 am
 Completed: 07/19/19 03:43 pm



93 LAND ROVER RANGE ROVER B1
 218332 Mi. Last in 05/06/2019
 Lic: 8ALT492/CA V8Cyl 3.9
 Vin: SALHV124XPA636013 03/93
 Eq: AT AC PS FI 4W

Quotes

1 07/11/19 09:14am 190.00
 Richard in person.

Job01 Irratic Idle

Labor: \$680.00

Customer states that when car is idiling it will dip up and down and not stay consistent. Customer swapped idle control valve, coil and cap and rotor and all stayed the same. Advise. Upon inspection tech found that idle is very rough. During inspection tech found that vehicle loosing spark intermit causing vehicle idle to missfire and dip up and down. Replaced ignition module, Distributor pick up coil and new overhaul kit as per customer request and road test car. All ok at this time.

STC1184	ignition module-N	1.0 @	265.32 =\$	265.32
RTC5090	pick up coil-N	1.0 @	265.32 =\$	265.32
RTC5971	dist O.H. kit-N	1.0 @	95.32 =\$	95.32
				625.96

Recommendations: rear swivel joint leaking, rear diff pinion seal leaking, ft/rear diff and tcase fluids dirty, transmission fluid dirty, tie rods worn, transfer case in op, ft/rear suspension components worn, power steering pump and hoses leak

Tire Pressure: LF[] RF[] LR [] RR []

Payments to Exclusive British European

Cost Summary

Status: Completed Work Order

Payments:

Labor	680.00
Parts	625.96
Discount	60.00
Subtotal	1245.96
Tax	52.35
Total	\$1298.31
Payments	0.00
Bal Due	1298.31

Thank you for choosing Exclusive British European

ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE

ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE SAVE DISCARD



CREDIT CARDS
 ACCEPTED



WE RESERVE THE RIGHT TO REFUSE ANY PERSONAL CHECKS

I acknowledge notice and oral approval of an increase in the original estimated price.

X

CUSTOMER ACKNOWLEDGMENT

By signing below, I hereby authorize the repair work to be done along with the necessary material, and hereby grant your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. If automobile is returned to customer before authorized service is performed, a diagnostic and handling charge will be made. I have read and understand the statements and estimates made on this side and the reverse of this/these pages (connected with this vehicle). I authorize service to be performed, including sublet work, and acknowledge receipt of this estimate. Customer is hereby notified that the said property is not insured or protected against loss occasioned by theft, fire or vandalism while the property remains within the Repair Garage.

CUST. X
 SIG.

I ACKNOWLEDGE RECEIPT OF AND AGREE TO THE TERMS AND CONDITIONS OF THIS CONTRACT.

READ IMPORTANT INFORMATION ON REVERSE SIDE

Land Rover ■ Jaguar service center

2921 Winchester Blvd. ■ Campbell, CA 95008

(408) 374-0131 ■ (408) 374-2143 fax

www.ebemotors.com

SERVICE

SALES

PARTS

ACCESSORIES


Invoice No.

32340

Page 1

Order Date 05/06/19 09:10 am

Completed: 05/10/19 05:23 pm



Work Phone:

93 LAND ROVER RANGE ROVER BL
218305 Mi. Last in 07/17/2018
Lic: 8ALT492/CA V8Cyl 3.9
Vin: SALHV124XPA636013 03/93
Eq: AT AC PS FI 4W

Quotes

1 05/06/19 09:27am 190.00
Richard in person.

Job01 Off Road Inspection

Labor: N/C

Customer will be taking vehicle on Land Rover Owner Appreciation day Off Road Event. Inspect vehicle for Off Road Driving. Advise on needs.

Job02 Swivel Kit

Labor: \$1,020.00

Replaced R/F leaking swivel seal kit as per customer request and road test. All ok at this time

STC3435	Swivel grease-N	2.0 @	17.50 =\$	35.00
ROVNOTSWIV	SWIVEL KIT-S	1.0 @	195.32 =\$	195.32
2420	COMPONENT CLEANER-N	2.0 @	6.50 =\$	13.00
				243.32

Recommendations: rear swivel joint leaking, rear diff pinion seal leaking, ft/rear diff and tcase fluids dirty, transmission fluid dirty, tie rods worn, transfer case in op, ft/rear suspension components worn, power steering pump and hoses leak

Tire Pressure: LF[] RF[] LR [] RR []

Payments to Exclusive British European

Cost Summary

Status: Completed Work Order

Payments:

Labor	1020.00
Parts	243.32
Subtotal	1263.32
Tax	22.51
Total	\$1285.83
Payments	0.00
Bal Due	1285.83

Thank you for choosing Exclusive British European

ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE

ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE SAVE DISCARD



CREDIT CARDS ACCEPTED



WE RESERVE THE RIGHT TO REFUSE ANY PERSONAL CHECKS

I acknowledge notice and oral approval of an increase in the original estimated price.

X

CUSTOMER ACKNOWLEDGMENT

By signing below, I hereby authorize the repair work to be done along with the necessary material, and hereby grant your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. If automobile is returned to customer before authorized service is performed, a diagnostic and handling charge will be made. I have read and understand the statements and estimates made on this side and the reverse of this/these pages (connected with this vehicle). I authorize service to be performed, including sublet work, and acknowledge receipt of this estimate. Customer is hereby notified that the said property is not insured or protected against loss occasioned by theft, fire or vandalism while the property remains within the Repair Garage.

CUST. X SIG.

I ACKNOWLEDGE RECEIPT OF AND AGREE TO THE TERMS AND CONDITIONS OF THIS CONTRACT.

Order information

Shipping address

Order total

Buyer mbak_l_sj4b3honn
Seller x8rusa
Order placed on Wednesday, May 1, 2019
Payment method Credit card
Payment date Wednesday, May 1, 2019

Subtotal \$53
Shipping \$5
Total \$58

Item(s) bought from x8rusa

Qty	Item name	Shipping service	Item price
1	Land Rover Rang Rover Classic 1987-1994 Gear Selector Plastic New (264267229364)	USPS First Class Package	\$53.00



Your order has been shipped!

1 message

Lucky8 Off Road <tracking@shipstation.com>

Tue, May 7, 2019 at 12:44 PM

Reply-To: Sales@lk8parts.com

To:

Dear

Thank you for your order from **Lucky 8 Off Road!** We wanted to let you know that your order (#SX2526) was shipped via USPS, USPS First Class Mail on 5/7/2019. You can track your package at any time using the link below.

Shipped To:

Track Your Shipment:

This shipment includes the following items:

Item #	Description	Qty
RRCSB	Rang Rover Classic 1987-1994 Gear Selector Plastic New	1

Thank you for your business and we look forward to serving you in the future!

Lucky8 Off Road

Phone: 7168988153

Email: Sales@lk8parts.com

Website: <https://www.lucky8llc.com/>

Like us on Facebook!

Follow us on Instagram!

https://youtu.be/CmrYdsxY_w8



www.esp-global.com

Smog Check Vehicle Inspection Report (VIR)



www.autorepair.ca.gov

Vehicle Information

Test Date/Time: 03/05/2019@15:01:17

Model Year:	1993	Make:	LAND	Model:	RANGE ROVER COUNTY
License:	8ALT492	State:	CA	VIN:	SALHV124XPA636013
Engine Size:	3.90 L	Type:	Truck	Transmission:	Automatic
GVWR:	6503	Test Weight:	N/A	Cylinders:	8
Odometer:	218,055	Certification:	California	VLT Record #:	1490
Fuel Type:	Gasoline	Exhaust:	Single	Inspection Reason:	High Emitter Profile

Overall Test Results

Smog Check Certificate Number: QI615384

DMV ID Number: 1638I708Q163

Your Smog Check certificate has been electronically transmitted to DMV.
Your certificate is valid for 90 days from date of issuance.
Please keep this copy for your records.

Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of oxides of nitrogen, crankcase and cold start emissions which are not measured during the Idle test)

Result	ECS	Result	ECS	Result	ECS
Pass	PCV	Not applicable	Thermostatic Air Cleaner	Pass	Fuel Evaporative Controls
Pass	Catalytic Converter	Not applicable	Air Injection	Pass	OBD System Checks
Not applicable	EGR Visual	Pass	Vacuum Lines to Sensors / Switches	Pass	Carb. / Fuel Injection
Not applicable	EGR Functional	Pass	Ignition Timing: PB06	Pass	Other Emission Related Components
Pass	Fuel Cap Functional	Pass	Wiring to Sensors	Pass	Oxygen Sensor
Pass	Fuel Cap Visual	Not applicable	Fillpipe Restrictor	Pass	Liquid Fuel Leaks
Pass	Spark Controls	Pass	Fuel Evaporative Controls Functional		

Idle Emission Test Results

Test	RPM	%CO2		%O2			HC (PPM)			CO (%)		Results
		MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	MEAS		
Idle	717	14.9	0.5	100	26	8	1.00	0.00	0.00	Pass		
2500 RPM	2548	15.5	0.0	180	11	7	1.10	0.10	0.00	Pass		

MAX = Maximum Allowable Emissions

AVE = Average Emissions For Passing Vehicles

MEAS = Amount Measured

Repair Actions

Catalytic Converter (Exhaust)	Rep
Spark Plugs (Secondary)	Rep
Ignition Wires (Secondary)	Rep
Cap/ Rotor (Secondary)	Rep
Initial Timing (Secondary)	Rep

Repair Costs

Total Repair Time:	7.6 hours
Emission-Related Repairs (Parts):	\$0
Emission-Related Repairs (Labor):	\$0
Tamper Repairs (Parts and Labor):	\$1800
Estimated Costs of Additional Repairs:	\$0
Hourly Labor Rate:	\$140
Emission-Related Repairs (Parts - LIRAP):	\$0
Emission-Related Repairs (Labor - LIRAP):	\$0

Smog Check Inspection Station Information

SPEEDEE OIL CHANGE & AUTO SEVICE
15643 LOS GATOS BLVD, LOS GATOS CA 95032
408-356-9301
Station Number: RC267838

Technician Name/Number:
Repair Tech Name/Number:
Software Version/EIS Number:

BELDIN, DAVID/EO132701
BELDIN, DAVID/EO132701
1805 / EP728736

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.
All repairs were made in accordance with BAR guidelines.

Date 3-5-19

Technician's Signature

Manual Readings Mode

Station Number.....: RC267838
Analyzer Number.....: EP728736

Date/Time.....: 01-Mar-2019 12:22:10

Cylinders.....: 4
PEF.....: 0.524

Gas	Reading	Limit
HC ppm	222	N/A
CO %	0.66	N/A
CO2 %	13.8	N/A
O2 %	1.5	N/A
NO(x) ppm	27	N/A
RPM		N/A

Snap Test

Manual Readings Mode

Station Number.....: RC267838
Analyzer Number.....: EP728736

Date/Time.....: 01-Mar-2019 12:22:15

Cylinders.....: 4
PEF.....: 0.507

Gas	Reading	Limit
HC ppm	1800	N/A
CO %	3.74	N/A
CO2 %	11.0	N/A
O2 %	2.6	N/A
NO(x) ppm	451	N/A
RPM		N/A

Manual Readings Mode

Station Number.....: RC267838
Analyzer Number.....: EP728736

Date/Time.....: 01-Mar-2019 12:22:18

Cylinders.....: 4
PEF.....: 0.515

Gas	Reading	Limit
HC ppm	828	N/A
CO %	1.23	N/A
CO2 %	13.2	N/A
O2 %	2.4	N/A
NO(x) ppm	271	N/A
RPM		N/A



SpeedDee Oil Change And Tune Up-Los Gatos
 15643 Los Gatos Blvd.
 LOS GATOS, CA, 95032
 408-356-9301 B.A.R.# 267838 EPA# Cal000372679

WE OFFER THE FOLLOWING SERVICES:
 QUICK OIL CHANGE FUEL INJECTOR CLEANING
 TUNE-UPS *COMPLETE BRAKE SERVICE
 SMOG CHECKS *AIR CONDITIONING SERVICE
 ENGINE DIAGNOSTICS *RADIATOR SERVICE

(*at participating locations)

VEHICLE I.D. VEHICLE # PLATE #	SALHV124XPA636013 CA-8ALT492	Workorder # 340384	
CUSTOMER NAME ADDRESS	YEAR MAKE MODEL MILEAGE	1993 Land Rover Range Rover 218099	TRANS # DATE TIME EMP #
			243429 3/6/2019 04:23 PM 7203-Jacob, 571-Cleon, 579-R

STATUS	DESCRIPTION	PART CODE	QTY	PART \$	L QTY	LABOR \$	LINE TOTAL
151	Diagnostic Check Rec major tune up , spark plugs , cap and rotor , these parts are worn and carbon fouled plug wires should also be replaced , o2 sensors are slow responding , the distributor shaft is worn and has 1/16 to 1/8 inch of free play , spec is 0 free play , 2 twc catalytic converters fail functional snap test and O2 retention test , suggest replacing both cats, Ignition timing is out of spec at 11b , spec is 6b ,rec adjust to spec, found distributor installed 1 tooth off, removed and installed distributor correctly and set timing to spec 6 btcd.					140.00	140.00
151	Misc.Service Performed major tune up , new spark plugs , distributor cap and rotor and ignition wires, reinstalled distributor correctly and set timing to spec 6 btcd , per customer auth.					490.00	490.00
	7911 Bosch Spark Plugs @ 8.99	WR9DC	8.0	71.92			71.92
	New Spark Plug Wires(T)	RTC6551	1.0	94.65			94.65
	Distributor Cap(T)	STC8368	1.0	88.99			88.99
	Distributor Rotor(T)	STC1857	1.0	33.99			33.99
151	Misc.Service Sublet ,replace two catalytic converters , per customer auth					880.00	880.00
151	2 Catalytic Convertors(T)	CATALYTIC CONVERTOS		Included			.00
	Emission Retest Vehicle emissions test per B.A.R. Requirements.					Included	
	Smog Certificate Labor					Included	
	Smog Certificate Certificate #:QI615384	Smog Certificate	1.0	8.25			8.25
Pass Recommended Checked Checked	Hook Up And Test System Tire Pressure Tire Pressure Front Tires						

VEHICLE NOTES

***** CONTINUED ON NEXT PAGE *****	PAYMENT SUMMARY	CHARGE SUMMARY



All Parts Are New Unless Otherwise Specified

Each location independently owned and operated

SIGN X



SpeedDee Oil Change And Tune Up-Los Gatos
 15643 Los Gatos Blvd.
 LOS GATOS, CA, 95032
 408-356-9301 B.A.R.# 267838 EPA# Cal000372679

WE OFFER THE FOLLOWING SERVICES:
 QUICK OIL CHANGE FUEL INJECTOR CLEANING
 TUNE-UPS *COMPLETE BRAKE SERVICE
 SMOG CHECKS *AIR CONDITIONING SERVICE
 ENGINE DIAGNOSTICS *RADIATOR SERVICE

(*at participating locations)

& AUTO SERVICE

VEHICLE I.D. VEHICLE # PLATE #	SALHV124XPA636013 CA-8ALT492	Workorder #	340384
CUSTOMER NAME ADDRESS		YEAR MAKE MODEL MILEAGE	1993 Land Rover Range Rover 218099
TRANS # DATE TIME EMP #	243429 3/6/2019 04:23 PM 7203-Jacob, 571-Cleon, 579-R		

STATUS	DESCRIPTION	PART CODE	QTY	PART S	L QTY	LABOR S	LINE TOTAL
Checked	Tire Pressure Front Tires						
Unsafe Recommended	Tire Pressure Front Tires						
Checked	Tire Pressure Front Tires						
	Tire Pressure Rear Tires						

VEHICLE NOTES

PAYMENT SUMMARY	CHARGE SUMMARY
(Visa-MC) 1,832.41	Taxable Total 289.55
	Non Taxable Total 1,518.25
	Parts Total 297.80
	Labor Total 1,510.00
CHANGE .00	Subtotal 1,807.80
	Total Tax 24.61
	TOTAL DUE 1,832.41

I herby authorize the repair work to be done along with the necessary materials, and herby grant you and your employees permission to operate the vehicle here in described on streets, highways or elsewhere for the purpose of testing and/or inspection. I also authorize any sublet repairs that you deem necessary. I also acknowlege and approve all repairs as listed and any increase in the original estimated price. X_____

All Parts Are New Unless Otherwise Specified

Each location independently owned and operated

SIGN X _____



SpeedDee Oil Change And Tune Up-Los Gatos
 15643 Los Gatos Blvd.
 LOS GATOS, CA, 95032
 408-356-9301 B.A.R.# 267838 EPA# Cal000372679

WE OFFER THE FOLLOWING SERVICES:
 QUICK OIL CHANGE FUEL INJECTOR CLEANING
 TUNE-UPS *COMPLETE BRAKE SERVICE
 SMOG CHECKS *AIR CONDITIONING SERVICE
 ENGINE DIAGNOSTICS *RADIATOR SERVICE

(*at participating locations)

& AUTO SERVICE

VEHICLE I.D. VEHICLE # PLATE #	SALHV124XPA636013 CA-8ALT492	Workorder # 340936
CUSTOMER NAME ADDRESS	YEAR MAKE MODEL MILEAGE	TRANS # DATE TIME EMP #
	1993 Land Rover Range Rover 218023	242996 2/15/2019 02:18 PM 7203-Jacob, 571-Cleon, 107-D

STATUS	DESCRIPTION	PART CODE	QTY	PART S	L QTY	LABOR S	LINE TOTAL
151 Fail	Emissions Test Vehicle emissions test per B.A.R. Requirements failed smog , high emissions hc at idle speed , ignition timing fails functional test at 11b speed is 6 , r side catalytic convertor is replaced and has no eo # = tampered ,rec diagnosis and repair 2h/280 , 1x free retest if repaired here Hook Up And Test System					94.95	94.95

VEHICLE NOTES

failed smog 1x free retest if repaired here	PAYMENT SUMMARY		CHARGE SUMMARY	
	(Visa-MC)	94.95	Taxable Total	.00
			Non Taxable Total	94.95
			Parts Total	.00
			Labor Total	94.95
	CHANGE	.00	Subtotal	94.95
			Total Tax	.00
			TOTAL DUE	94.95

I hereby authorize the repair work to be done along with the necessary materials, and hereby grant you and your employees permission to operate the vehicle here in described on streets, highways or elsewhere for the purpose of testing and/or inspection. I also authorize any sublet repairs that you deem necessary. I also acknowledge and approve all repairs as listed and any increase in the original estimated price. X_____

All Parts Are New Unless Otherwise Specified

Each location independently owned and operated

SIGN X



www.esp-global.com

Smog Check Vehicle Inspection Report (VIR)



www.autorepair.ca.gov

Vehicle Information

Test Date/Time: 02/15/2019@11:54:23

Model Year:	1993	Make:	LAND ROVER	Model:	RANGE ROVER COUNTY
License:	8ALT492	State:	CA	VIN:	SALHV124XPA636013
Engine Size:	3.90 L	Type:	Truck	Transmission:	Automatic
GVWR:	6503	Test Weight:	N/A	Cylinders:	8
Odometer:	218,023	Certification:	California	VLT Record #:	24876
Fuel Type:	Gasoline	Exhaust:	Single	Inspection Reason:	High Emitter Profile

Overall Test Results

Comprehensive Visual Inspection: **Tamper** Functional Check: **Fail** Emissions Test: **Fail**

Repairing your vehicle is necessary to help California reduce smog-forming emissions and reach our air quality goals.

Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of oxides of nitrogen, crankcase and cold start emissions which are not measured during the Idle test.)

Result	ECS	Result	ECS	Result	ECS
Pass	PCV	Not applicable	Thermostatic Air Cleaner	Pass	Fuel Evaporative Controls
Modified	Catalytic Converter	Not applicable	Air Injection	Pass	OBD System Checks
Not applicable	EGR Visual	Pass	Vacuum Lines to Sensors / Switches	Pass	Carb. / Fuel Injection
Not applicable	EGR Functional	Fail	Ignition Timing: FB11	Pass	Other Emission Related Components
Pass	Fuel Cap Functional	Pass	Wiring to Sensors	Pass	Oxygen Sensor
Pass	Fuel Cap Visual	Not applicable	Fillpipe Restrictor	Pass	Liquid Fuel Leaks
Pass	Spark Controls	Pass	Fuel Evaporative Controls Functional		

Idle Emission Test Results

Test	RPM	%CO2		HC (PPM)			CO (%)		MEAS	Results
		MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE		
Idle	791	13.9	1.3	100	26	111	1.00	0.00	0.48	Fail
2500 RPM	2548	15.0	0.1	180	11	5	1.10	0.10	0.22	Pass

MAX = Maximum Allowable Emissions

AVE = Average Emissions For Passing Vehicles

MEAS = Amount Measured

Failed smog check? Financial assistance may be available. To get an application, visit the Bureau of Automotive Repair's website at www.smogcheck.ca.gov or call toll-free at 800.952.5210.

Si usted ha fallado el examen de smog, asistencia financiera puede estar disponible. Para obtener una solicitud, visite www.smogcheck.ca.gov o llámenos a BAR al 800.952.5210.

Smog Check Inspection Station Information

SPEEDEE OIL CHANGE & AUTO SEVICE
 15643 LOS GATOS BLVD, LOS GATOS CA 95032
 408-356-9301
 Station Number: RC267838

Technician Name/Number: BELDIN, DAVID/EO132701
 Repair Tech Name/Number:
 Software Version/EIS Number: 1805 / EP728736

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

2-15-19
Date

Technician's Signature




Limitless Powder Coating Corp.
 767 E. Brokaw Rd. San Jose CA.
www.limitlesscoating.com
limitlesscoating@gmail.com
 408-320-7705

Invoice #

Date:

Customer Bill To:



PO #	Estimator/Tech.	Type of Equipment	Qty of Parts/Pcs.	Color(s) to be applied	Projected Date Completion
	will	BRUSH GUARD	3	Satin BLACK + primer	

Parts Received/Additional Details:

Empty box for additional details.

#	Description	QTY.	Unit Price	Line Total
1	Powder Paint	4 lbs	/	
2	Media Blasting Labor	YES	/	
3	Powder Coating Labor*			350.00
4	Consumable Materials:			
5				
6				
7				

Sub Total	
Shipping	
Total	350.00
Paid Deposit	150.00
Total Due	200.00

\$ PAID
 2-7-19

*By signing below, I agree to the terms and conditions form found at www.limitlesscoating.com.

Customer Signature:



Date: 1-31-19

Customer Invoice

145918
02/08/2019

WHEEL WORKS
15553 LOS GATOS BLVD
LOS GATOS, CA. 95032-2503

Service Advisor:

99 BRIAN
408.356.6181

1993 LAND ROVER RANGE ROVER COUNTY
3.9L V8 FI GAS VIN 2 OHV
Lic #: 8ALT492 CA Vin #:
In: 02/08/19 8:14AM Mileage: 218,014
Out: 02/08/19 10:59AM

Store # 119628

RETAIL SALE

REG#ARD275173, EPA#CAL000365233

Description	Rev Hist /Article #	ID	Qty	Unit Price	Extended Price	Job Total
TIRE RACK INSTALLATION - 50 SERIES & HIGHER (All 4)		99				63.60
225/75/16 GOODYEAR WRANGLER TRAIL RUNNER AT						
INSTALLER TIRE VALVE	7003282	14TN	4	2.00	8.00	
TIRE RACK INSTALLATION 50 SERIES & HIGHE	7003227	14NN	4	4.70	18.80	
TIRE RACK WHEEL BALANCE LABOR	7013637	14NN	4	6.70	26.80	
INSTALLER SCRAP TIRE RECYCLING CHARGE	7084301	14TN	4	2.50	10.00	
Computer spin balance each tire / wheel assembly Dismount old tire(s) if applicable, mount new tire(s), install valve stem, inflate to manufactures specifications						
COURTESY CHECK		99				
COURTESY CHECK	7046930	14NN	1	N/C	N/C	
CC - See attached for details of the Courtesy Check						

ORDER NOTES

On Line Customer requested work: Tire Replacement
To comply with the California Air Resources Board, We will check and adjust your vehicles tire pressures.
Actual Measured Tire Pressures (PSI): LF-28, RF-28, LR-28, RR-28.

Technician(s):

14 RICARDO

Payment History:

MasterCard 9685 65.23 05411S Sale
MID: 222220327747
Term: 0001 Card Inserted
AID:A0000000041010 PIN NOT VERIFIED
Total Tendered 65.23

Summary:

Parts	8.00
Labor	55.60
Shop Supplies	0.00
Sub-Total	63.60
Tax (9.00%)	1.63
Total	\$65.23

I have received the above goods and/or services. If this is a credit card purchase, I agree to pay and comply with my cardholder agreement with the issuer.



Customer Signature

All parts are new unless otherwise specified.

Declined Work:

ALIGNMENT SERVICE - ONLINE QUOTE

HOW ARE WE DOING?

Tell us about your experience today!
Complete a 4-minute survey for a chance to win one of ten \$50 gift cards each month!
Visit www.WheelWorksSurvey.com within 4 days and enter Code 119628-145918

www.WheelWorks.net

WHEEL WORKS CA LASER 7008581 - REV 12/12

See reverse side for Warranty Information



7101 Vorden Parkway
 South Bend, IN 46628-8422
 Phone: (574) 287-2345
 800: (800) 428-8355
 Customer Service: Ext. 4360
 Fax: (574) 236-7707


 REPRINT

INVOICE

INVOICE NUMBER DH41427	INVOICE DATE 2/05/19	PAGE 1
PURCHASE ORDER NUMBER RP747280469		

2/06/19
 7:56:20
 G916

BILL TO:



SHIP TO:



SHIP-TO PHONE: 408-356-6181

SHIP METHOD: OnTrac

ORDER DATE	SALES REP. NAME/PHONE EXT	TERMS	MAKE, MODEL AND YEAR	WHSE		
2/05/19	ECOMMERCE ORDERS	MASTER CARD	ROVER CO 93	NV		
PART NUMBER	QUANTITY ORDERED	QUANTITY SHIPPED	GROUP	DESCRIPTION	UNIT PRICE	EXTENSION
275R6WTRAT 742748681	4	4		LT225/75R16 GY WR TRLRUN AT 742748681 115/112R E	160.99	643.96
REGCARDR REGISTRATIONR	1	1		These tires require the use of high pressure valve stems. Tire DOT Number registration has been filed electronically	N/C	
*****9685				Subtotal		643.96
				MASTER CARD PAYMENT		643.96-
				Total Payment		643.96-
* To make a claim, please contact the Road Hazard Program Administrator - (855) 623-0468 http://www.tirerack.com/roadhazard						
Total Amount Due						
Payable in U.S. Funds						

PAID \$.00 USD

ALL PAST DUE ACCOUNTS ARE SUBJECT TO A FINANCE CHARGE OF 1 1/2% PER MONTH, WHICH IS AN ANNUAL PERCENTAGE RATE OF 18%.



Congleton Service, Inc.
354 Prim Rd. Suite 3
Colchester, VT 05446 US
(802) 578-2461
info@congletonservice.com

Packing Slip

BILL TO



SHIP TO



INVOICE # 1151118

DATE 02/06/2019

DATE	ACTIVITY
02/03/2019	Side Lamp RHR Lens Land Rover Parts, 1
02/03/2019	Shipping and Handling Shipping & Handling, 1

Labor and towing will not be covered from other shops. It is the customers responsibility and cost to return a vehicle to Congleton Service for any warranty service. There will be no warranties based on a diagnosis from another repair facility. By signing or paying this invoice the customer agrees that all charges are approved & waives all rights to credit card chargebacks & or stopped checks.

Transaction details

February 2, 2019 at 8:10:58 PM EST | Transaction ID: 70J51778L71639717

eBay payment received from Richard Baker

Gross amount

Payment Status: Completed

\$49.00 USD

Payment Type: Checkout

OK to ship to

Seller protection



Eligible

Transaction Activity	Gross amount	Fee amount	Net amount
Feb 2, 2019 Payment to Paypal Working Capital	-\$14.22 USD	\$0.00 USD	-\$14.22 USD

Order details	Quantity	Price	Subtotal
Item # 162058809125 LAND ROVER WHEEL CENTER CAP SET x4 DISCOVERY I DEFENDER RANGE CLASSIC ANR2391MNH	1	\$49.00 USD	\$49.00 USD
		Purchase Total	\$49.00 USD

Payment details

Purchase Total	\$49.00 USD
Sales Tax	\$0.00 USD
Shipping Amount	\$0.00 USD
Handling Amount	\$0.00 USD
Insurance Amount	\$0.00 USD
Gross Amount	\$49.00 USD
PayPal Fee	-\$1.57 USD
Net Amount	\$47.43 USD

Reversals - Please be aware that this payment can still be reversed (e.g. if it is subject to a chargeback), even after you have sent the item(s) to your buyer. Complying with PayPal's Seller Protection and following the trading guidelines on our Security page helps to protect you from things like chargebacks.

Refund Information - Please accept or refuse this payment. If you accept this payment now and need to refund it later, the Issue a Refund link will be available on the transaction details page for 180 days after the payment was originally sent.

Paid by



Payment Sent to

Custom

EBAY_EMSCX0000873584040914

Need to contact the buyer?

Log in to your eBay account and go to order details.



6 Enterprise Avenue | 4109 Guardian Street
 Clifton Park, New York 12065 USA | Simi Valley, California 93063 USA

INVOICE

Invoice Number
1249001

Customer Number
525038

Bill to:

Ship to:

Range Rover • Discovery • LR3/LR4 • Freelander/LR2 • Defender • LR Series • MINI Cooper

All Returns Must Be Accompanied By Invoice. See Reverse For Return Information and Store Policies.

DATE		SHIP VIA		I.O.B.		TERMS		
02/01/19 03:11 PM		GTRAC		CLIFTON PARK		Cyber Order 5040055		
PHONE NUMBER		ORDER DATE		SALES PERSON		OUR ORDER NUMBER		
XXXXXXXXXX		02/01/2019		Eric Riston - Ext 231		1371296		
ORDERED	SHIPPED	BACK ORD.	ITEM	DESCRIPTION		UNIT PRICE	AMOUNT	
1	1	0	PPPU	PAINT PEN BELUGA BLACK		17.95	17.95	
2	2	0	MXC5587PR	MUD FLAP RANGE ROVER CLASSIC - PAIR		16.95	33.90	
4	4	0	MXC5587	MUD FLAP RANGE ROVER CLASSIC		0.00	0.00	
							Shipping Charges	28.88
							NonTaxable Subtotal	0.00
							Taxable Subtotal	80.73
							Tax (7.25%)	5.85
							Total	86.58
							Less Payments/Credits	86.58
							Balance Due	0.00

Thank You!

PHONE: 800-533-2210 or 518-664-6169

FAX: 518-664-6641

RoverParts.com • MiniCarParts.net • RoverParts.com • MiniCarParts.net

BILL TO:

SHIP TO:



ACCT. NO.	REF.	SOLD BY	ORDER NO.	MEMO	WEIGHT	ORDER DATE	INV. DATE	INV. NO.		
23		RR					12/28/18	20162		
TY. SOLD	BK. ORD.	MFC	PART NUMBER	DESCRIPTION	CORE	LIST	SELL	EXTENDED	T	D
1				R. Clock Cover			250.00	250.00		

ABSOLUTELY NO GOODS ACCEPTED FOR CREDIT OR CASH RETURNED AFTER 10 DAYS: NEVER WITHOUT AN INVOICE. THERE SHALL BE A 15% HANDLING CHARGE ON ALL MERCHANDISE RETURNED IN RESALABLE CONDITION. ABSOLUTELY NO MATERIAL ACCEPTED FOR CREDIT THAT HAS BEEN INSTALLED OR USED FOR TESTING. PURCHASER AGREES TO PAY ATTORNEY'S FEE, COURT COSTS, AND ALL EXPENSES INVOLVED IN THE EVENT LEGAL ACTION IS NECESSARY FOR THE COLLECTION OF THIS INVOICE.

- NO RETURN ON ELECTRICAL ITEMS
- NOT RESPONSIBLE FOR LABOR ON DEFECTIVE MERCHANDISE

SUB-TOTAL	250.00
CORE	
TAX	
LABOR	
FREIGHT	
TOTAL	250.00



Rovers North, Inc.
 1319 VT Route 128
 Westford, Vermont
 05494-9601 USA
 ph 800 403-7591
 fx 802 879-9152

North America's Source for Land Rover Parts at the Best Prices.

WEB INVOICES

Sales Order #
 SO-956052

11/9/2018



Customer



Ship To



Account	Sales Invoice	Terms	PO #	Account Rep	Ship VIA			
57225	SI-1051812	CREDIT CARD		Zack Griswold	USPS First Class			
Item	Coded	Description	Ord	Shp	B/O	Price	Net	Total
PRC4412	PRC4412	FUSE EXTRACTOR	2	2		2.23	2.23	4.46

Shipment Tracking Details

Shipment Date	Delivery Method	Tracking Number
11/02/2018	USPS First Class	9400109898642640473361
11/12/2018	USPS First Class	9400109898642645337958

Thanks for your order!

PAID

Tax Details
 EXEMPT \$0.000

Payment Details

Sub-Total	\$4.46
Sales Tax	\$0.00
Total	\$4.46
Paid Balance	\$0.00
	\$4.46



6 Enterprise Avenue | 4109 Guardian Street
 Clifton Park, New York 12065 USA | Simi Valley, California 93063 USA

INVOICE

Invoice Number
1203233

Customer Number
525038

Bill to:



Ship to:



Range Rover • Discovery • LR3/LR4 • Freelander/LR2 • Defender • LR Series • MINI Cooper

All Returns Must Be Accompanied By Invoice. See Reverse For Return Information and Store Policies.

DATE		SHIP VIA		F.O.B.		TERMS	
06/15/18 03:25 PM		GTRAC		CLIFTON PARK		Cyber Order 5021634	
PHONE NUMBER		ORDER DATE		SALES PERSON		OUR ORDER NUMBER	
[REDACTED]		06/15/2018		Eric Riston - Ext 231		1322485	
ORDERED	SHIPPED	BACK ORD.	ITEM	DESCRIPTION		UNIT PRICE	AMOUNT
5	5	0	BTR7071G	VENT FACIA RAIL		28.95	144.75
1	1	0	PRC8010	RESISTOR A/C-HEATER BLOWER MOTOR		74.95	74.95
2	2	0	EJP1180LG	BULB AND HOLDER INSTRUMENT CLEAR		4.95	9.90
1	1	0	NEXT10	10% REPEAT CUSTOMER DISCOUNT		-22.96	-22.96
						Shipping Charges	12.96
						NonTaxable Subtotal	0.00
						Taxable Subtotal	219.60
						Tax (7.25%)	15.92
						Total	235.52
						Less Payments/Credits	235.52
						Balance Due	0.00

Thank You!

PHONE: 800-533-2210 or 518-664-6169

FAX: 518-664-6641

RoverParts.com • MiniCarParts.net • RoverParts.com • MiniCarParts.net

Land Rover ■ Jaguar service center

2921 Winchester Blvd. ■ Campbell, CA 95008

(408) 374-0131 ■ (408) 374-2143 fax

www.ebemotors.com

SERVICE

SALES

PARTS

ACCESSORIES

Invoice No.

30904

Page 1

Order Date 07/17/18 08:03 am

Completed: 08/28/18 04:17 pm



93 LAND ROVER RANGE ROVER B1

217507 Mi.

Lic: 8ALT492/CA V8Cyl 3.9

Vin: SALHV124XPA636013 03/93

Eq: AT AC PS FI 4W

Quotes

1 07/17/18 08:23am 500.49

Richard in person.

2 07/27/18 05:08pm 5141.43

Richard by phone [REDACTED]
shocks, dampner, ac, mounts,

Job01 ABS Light

Labor: \$850.00

Customer states that ABS light stays on dash. Advise. Upon inspection tech found that multiple fault codes stored in system for ABS. cleared codes and ABS fault came back on dash. Upon testing tech found that ABS sensor and relay are internally shorted and contaminated with leaking wheel bearing grease. Replaced relay and sensor and replaced wheel bearing with good used part and repacked with all new seals and grease and retested. During test drive tech found that air gap fault present in system. Adjusted air gaps and test drove. All ok at this time.

PRC9603	relay, ABS-N	1.0 @	32.00 =\$	32.00
STC1865	sensor, ABS-N	1.0 @	383.16 =\$	383.16
FTC4785	Seals-N	1.0 @	7.92 =\$	7.92
FTC3179	lock washer-N	1.0 @	2.85 =\$	2.85
571752	gasket-N	1.0 @	2.94 =\$	2.94
STC3435	Swivel grease-N	1.0 @	17.50 =\$	17.50
FTC5297	housing, swivel pin-N	1.0 @	450.00 =\$	450.00
USEDELITE	Used unit-S	1.0 @	350.00 =\$	350.00 1246.37

Job02 Brake fluid replacement

Labor: N/C

Complete Brake fluid replacement as per customer request

DOT4BRAKE	Castrol brake fluid-N	2.0 @	8.25 =\$	N/C
OSPSHOP	shop supplies-N	1.0 @	10.95 =\$	N/C

Job03 Shocks/Steering Dampner

Labor: \$850.00

Customer requests to have shocks and steering dampner inspected. Advise. Upon inspection tech found that steering dampner is extremely worn and front and rear shocks and shock bushings are leaking and cracked. Replaced front and rear shocks, shock bushings, and steering dampner as per customer request and road test car. All ok at this time

STC786	steering damper oe-N	1.0 @	135.16 =\$	135.16
STC2831	shock absorber-N	2.0 @	135.00 =\$	270.00

----->----->----->-----Continued on the next page----->----->----->-----

ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE

ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE SAVE DISCARD



CREDIT CARDS ACCEPTED



WE RESERVE THE RIGHT TO REFUSE ANY PERSONAL CHECKS

I acknowledge notice and oral approval of an increase in the original estimated price.

X

CUSTOMER ACKNOWLEDGMENT

By signing below, I hereby authorize the repair work to be done along with the necessary material, and hereby grant your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. If automobile is returned to customer before authorized service is performed, a diagnostic and handling charge will be made. I have read and understand the statements and estimates made on this side and the reverse of this/these pages (connected with this vehicle). I authorize service to be performed, including sublet work, and acknowledge receipt of this estimate. Customer is hereby notified that the said property is not insured or protected against loss occasioned by theft, fire or vandalism while the property remains within the Repair Garage.

CUST. SIG. X

I ACKNOWLEDGE RECEIPT OF AND AGREE TO THE TERMS AND CONDITIONS OF THIS CONTRACT.

Land Rover ■ Jaguar service center

2921 Winchester Blvd. ■ Campbell, CA 95008

(408) 374-0131 ■ (408) 374-2143 fax

www.ebemotors.com

SERVICE

■

SALES

■

PARTS

■

ACCESSORIES

Invoice No.

30904

Page 3

Order Date 07/17/18 08:03 am

Completed: 08/28/18 04:17 pm

Job07 Transfer Case

Customer states that transfer case is stuck in High Range. Advise. Upon inspection tech found that front driveshaft is missing. Installed good used axle at no charge to customer and tested Transfer Case. Found that Transfer Case will not engage. Tested relay and wiring and found that there is an electrical issue with transfer case. Customer declined any further repairs and will return at later date for further diagnosis.

Job08 Rover classic oil service

Labor: N/C

Perform 750 mile service as per checklist

OSPBRACLEEN	Brake cleaner-N	1.0 @	4.25 =\$	N/C
1112	Drain Plug Washer-N	1.0 @	2.95 =\$	N/C
ERR3340	oil filter-N	1.0 @	17.21 =\$	N/C
OSPLUBE	Lubricant-N	1.0 @	2.95 =\$	N/C
OSPWASOL	Washer solvent-N	1.0 @	1.95 =\$	N/C
20W/50	Motor Oil-N	7.0 @	8.50 =\$	N/C

Job09 Heater Core

Labor: \$1,700.00

During inspection tech found that heater hose and heater core are leaking. Replaced leaking heater core and heater hoses as per customer request and retest. All ok at this time

STC250	heater core-N	1.0 @	398.65 =\$	398.65
STC3166	HEATER CORE ORINGS-S	2.0 @	13.00 =\$	26.00
BTR216	Heater Hose-N	2.0 @	23.00 =\$	46.00
ETC6889	Heater Hose-N	1.0 @	18.52 =\$	18.52
ETC6890	Heater Hose-N	1.0 @	29.62 =\$	29.62
				518.79

Recommendations: rear swivel joint leaking, rear diff pinion seal leaking, ft/rear diff and tc case fluids dirty, transmission fluid dirty, tie rods worn, transfer case in op, suspension components worn,

Tire Pressure: LF[] RF[] LR [] RR []

----->----->----->----->-----Continued on the next page----->----->----->----->-----

ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE

ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE SAVE DISCARD



CREDIT CARDS ACCEPTED



WE RESERVE THE RIGHT TO REFUSE ANY PERSONAL CHECKS

I acknowledge notice and oral approval of an increase in the original estimated price.

X

CUSTOMER ACKNOWLEDGMENT

By signing below, I hereby authorize the repair work to be done along with the necessary material, and hereby grant your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. If automobile is returned to customer before authorized service is performed, a diagnostic and handling charge will be made. I have read and understand the statements and estimates made on this side and the reverse of this/these pages (connected with this vehicle). I authorize service to be performed, including sublet work, and acknowledge receipt of this estimate. Customer is hereby notified that the said property is not insured or protected against loss occasioned by theft, fire or vandalism while the property remains within the Repair Garage.

CUST. SIG. X

I ACKNOWLEDGE RECEIPT OF AND AGREE TO THE TERMS AND CONDITIONS OF THIS CONTRACT.



Land Rover ■ Jaguar service center

2921 Winchester Blvd. ■ Campbell, CA 95008

(408) 374-0131 ■ (408) 374-2143 fax

www.ebemotors.com

SERVICE



SALES



PARTS



ACCESSORIES

Invoice No.

30904

Page 2

Order Date 07/17/18 08:03 am

Completed: 08/28/18 04:17 pm

Job03 Shocks/Steering Dampner

552818	SHOCK BUSHING-S	4.0 @	3.24 =\$	12.96	
STC2830	shock absorber-N	2.0 @	121.00 =\$	242.00	660.12

Job04 Motor/Trans Mounts Labor: \$680.00

Customer request to have motor and transmission mounts inspected. Advise. Upon inspection tech found that motor mounts are cracked and worn. Replaced motor mounts as per customer request and road test vehicle

STC434	mounts motor-N	4.0 @	15.45 =\$	61.80	61.80
--------	----------------	-------	-----------	-------	-------

Job05 Suspension Labor: N/C

Customer states that there is a cluck that comes from the vehicle when shifting from D to R. Advise. Upon inspection tech found that there is excessive play in drivetrain which is normal. During inspection tech found that suspension components are worn and cracking. Replaced control arm bushings, radius arm bushings, trail arm bushings, panhard rod bushings and sway bar bushings and links and road tested car. All ok at this time

NTC6860	radius arm bushing-N	2.0 @	23.30 =\$	N/C	
STC618	Bushing trail-N	2.0 @	64.00 =\$	N/C	
NTC1773	control arm bushing-N	2.0 @	35.85 =\$	N/C	
NTC1772	BUSHINGS-S	2.0 @	23.64 =\$	N/C	
ANR3410	panhard rod bushing-N	2.0 @	16.00 =\$	N/C	
552819	SWAY BAR BUSHINGS-S	8.0 @	2.46 =\$	N/C	
NTC1888	SWAY BAR LINK-S	4.0 @	70.00 =\$	N/C	

Job06 AC Warm Labor: \$765.00

Customer states that AC blows warm. Was blowing cold 6 months ago and has slowly gotten warmer. Possible leak. Advise. Customer states that AC system may still be R12. Advise on conversion to R134. Advise. Upon inspection tech found that freon is leaking from ac hoses. Replaced hi and lo pressure AC hoses and receiver drier as per customer request and perform AC service. HVAC working great at this time.

BTR3710	a/c hose-N	1.0 @	298.56 =\$	298.56	
BTR2564	AC LOW PRESSURE-S	1.0 @	95.00 =\$	95.00	
R134A	Refrigerant-N	1.0 @	45.00 =\$	45.00	
BTR3717	reciever drier-N	1.0 @	95.00 =\$	95.00	533.56

Job07 Transfer Case Labor: N/C

----->----->----->-----Continued on the next page----->----->----->-----

ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE

CREDIT CARDS ACCEPTED



WE RESERVE THE RIGHT TO REFUSE ANY PERSONAL CHECKS

I acknowledge notice and oral approval of an increase in the original estimated price.

X

CUSTOMER ACKNOWLEDGMENT

ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE SAVE DISCARD

By signing below, I hereby authorize the repair work to be done along with the necessary material, and hereby grant your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. If automobile is returned to customer before authorized service is performed, a diagnostic and handling charge will be made. I have read and understand the statements and estimates made on this side and the reverse of this/these pages (connected with this vehicle). I authorize service to be performed, including sublet work, and acknowledge receipt of this estimate. Customer is hereby notified that the said property is not insured or protected against loss occasioned by theft, fire or vandalism while the property remains within the Repair Garage.

CUST. SIG. X

I ACKNOWLEDGE RECEIPT OF AND AGREE TO THE TERMS AND CONDITIONS OF THIS CONTRACT.

READ IMPORTANT INFORMATION ON REVERSE SIDE



Land Rover ■ Jaguar service center

2921 Winchester Blvd. ■ Campbell, CA 95008

(408) 374-0131 ■ (408) 374-2143 fax

www.ebemotors.com

SERVICE

SALES

PARTS

ACCESSORIES

Invoice No.

30904

Page 4

Order Date 07/17/18 08:03 am

Completed: 08/28/18 04:17 pm

Payments to Exclusive British European

Cost Summary

Status: Completed Work Order

Payments:

Labor	4845.00
Parts	3020.64
Discount	205.00
Subtotal	7660.64
Tax	279.41
Total	\$7940.05
Payments	0.00
Bal Due	7940.05

Thank you for choosing Exclusive British European

ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE

ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE SAVE DISCARD



CREDIT CARDS
ACCEPTED



WE RESERVE THE RIGHT TO REFUSE ANY PERSONAL CHECKS

I acknowledge notice and oral approval of an increase in the original estimated price.

X

CUSTOMER ACKNOWLEDGMENT

By signing below, I hereby authorize the repair work to be done along with the necessary material, and hereby grant your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. If automobile is returned to customer before authorized service is performed, a diagnostic and handling charge will be made. I have read and understand the statements and estimates made on this side and the reverse of this/these pages (connected with this vehicle). I authorize service to be performed, including sublet work, and acknowledge receipt of this estimate. Customer is hereby notified that the said property is not insured or protected against loss occasioned by theft, fire or vandalism while the property remains within the Repair Garage.

CUST. SIG. X

I ACKNOWLEDGE RECEIPT OF AND AGREE TO THE TERMS AND CONDITIONS OF THIS CONTRACT.

READ IMPORTANT INFORMATION ON REVERSE SIDE



6 Enterprise Avenue | 4109 Guardian Street
 Clifton Park, New York 12065 USA | Simi Valley, California 93063 USA

INVOICE
 Invoice Number:
 1205278
 Customer Number
 525038

Bill to:



Ship to:



Range Rover • Discovery • LR3/LR4 • Freelander/LR2 • Defender • LR Series • MINI Cooper

All Returns Must Be Accompanied By Invoice. See Reverse For Return Information and Store Policies.

DATE	SHIP VIA	F.O.B.	TERMS			
06/25/18 04:29 PM	GTRAC	CLIFTON PARK	MC *****9685 TTID 817573737815460			
PHONE NUMBER	ORDER DATE	SALES PERSON	OUR ORDER NUMBER			
[REDACTED]	06/25/2018	Eric Riston - Ext 231	1324722			
ORDERED	SHIPPED	BACK ORD.	ITEM	DESCRIPTION	UNIT PRICE	AMOUNT
5	1	4	BTR7072G	VENT FACIA RAIL	72.95	72.95

***** IMPORTANT BACK ORDER INFORMATION *****PLEASE NOTE BACK- ORDERED ITEMS. IF YOU WOULD LIKE TO CANCEL, PLEASE CONTACT YOUR SALES REPRESENTATIVE SHOWN ON YOUR INVOICE. OTHERWISE, ANY BACK- ORDERED ITEMS WILL SHIP WHEN RECEIVED AT ATLANTIC BRITISH. THANK YOU FOR CHOOSING ATLANTIC BRITISH AS YOUR PREFERRED SOURCE FOR PARTS & ACCESSORIES FOR YOUR ROVER VEHICLE.

Shipping Charges	12.84
NonTaxable Subtotal	0.00
Taxable Subtotal	85.79
Tax (7.25%)	6.22
Total	92.01
Less Payments/Credits	92.01
Balance Due	0.00

Thank You!

PHONE: 800-533-2210 or 518-664-6169

FAX: 518-664-6641

RoverParts.com • MiniCarParts.net • RoverParts.com • MiniCarParts.net



Rovers North, Inc.
 1319 VT Route 128
 Westford, Vermont
 05494-9601 USA
 ph 800 403-7591
 fx 802 879-9152

North America's Source for Land Rover Parts at the Best Prices.

WEB INVOICES

Sales Order #
 SO-940915


6/11/2018



Customer



Ship To



Account	Sales Invoice	Terms	PO #	Account Rep	Ship VIA
57225	SI-1036083	CREDIT CARD		Nicholas Cota	USPS First Class

Item	Coded	Description	Ord	Shp	B/O	Price	Net	Total
BTR1333RUN	BTR1333RUN	COVER LH SEAT SWITCH R/R CLC BOKHARA	1	1		9.68	9.68	9.68
SH	SH	SHIPPING/HANDLING	1	1		0.00	4.34	4.34

Shipment Tracking Details

Shipment Date	Delivery Method	Tracking Number
06/14/2018	USPS First Class	9400109898642532503657

Thanks for your order!

PAID

Tax Details
 EXEMPT \$0.000

Payment Details

Sub-Total	\$14.02
Sales Tax	\$0.00
Total	\$14.02
Paid	\$0.00
Balance	\$14.02



6 Enterprise Avenue | 8543 Lankershim Blvd.
Clifton Park, New York 12065 USA | Sun Valley, California 91352 USA

INVOICE

Invoice Number
1194532

Customer Number
525038

Bill to:

Ship to:



Range Rover • Discovery • LR3/LR4 • Freelander/LR2 • Defender • LR Series • MINI Cooper

All Returns Must Be Accompanied By Invoice. See Reverse For Return Information and Store Policies.

DATE		SHIP VIA		F.O.B.		TERMS	
05/07/18 03:20 PM		GTRAC		SIMI VALLEY,		Cyber Order 5018175	
PHONE NUMBER		ORDER DATE		SALES PERSON		OUR ORDER NUMBER	
[REDACTED]		05/07/2018		Dave Furiani - Ext 233		1313129	
ORDERED	SHIPPED	BACK ORD.	ITEM	DESCRIPTION		UNIT PRICE	AMOUNT
1	1	0	PRC5440	SENSOR LOW WASHER FLUID		57.95	57.95
1	1	0	PRC8095	SWITCH SEAT RIGHT RR 87/95/D1 W/PWR		239.95	239.95
1	1	0	MWC8656G	HANDLE TAILGATE - ALL		169.95	169.95
2	2	0	391287	HOOD ADJUSTER RUBBER BUFFER		1.95	3.90
2	2	0	SE910481A	BOLT LID HANDLE		0.95	1.90

THANK YOU FOR YOUR ORDER! ANY QUESTIONS PLEASE CALL 1-800-533-2210 EXT.233
THANKS, DAVE.

Shipping Charges	12.58
NonTaxable Subtotal	0.00
Taxable Subtotal	486.23
Tax (7.25%)	35.25
Total	521.48
Less Payments/Credits	521.48
Balance Due	0.00

Thank You!

PHONE: 800-533-2210 or 518-664-6169

FAX: 518-664-6641

RoverParts.com • MiniCarParts.net • RoverParts.com • MiniCarParts.net



6 Enterprise Avenue | 4109 Guardian Street
 Clifton Park, New York 12065 USA | Simi Valley, California 93063 USA

INVOICE

Invoice Number
1196593

Customer Number
525038

Bill to:



Ship to:



Range Rover • Discovery • LR3/LR4 • Freelander/LR2 • Defender • LR Series • MINI Cooper

All Returns Must Be Accompanied By Invoice. See Reverse For Return Information and Store Policies.

DATE		SHIP VIA		F.O.B.		TERMS	
05/16/18 12:20 PM		FHD		CLIFTON PARK		Cyber Order 5019072	
PHONE NUMBER			ORDER DATE		SALES PERSON		OUR ORDER NUMBER
[REDACTED]			05/16/2018		Eric Riston - Ext 231		1315371
ORDERED	SHIPPED	BACK ORD.	ITEM	DESCRIPTION		UNIT PRICE	AMOUNT
1	1	0	PRC7925G	EXPANSION TANK CAP/SENSOR 90/94		57.95	57.95
3	3	0	NTC5582	EXHAUST HANGER RUBBER		5.49	16.47
1	1	0	CRC4579L	EXHAUST OLIVE FROM R9		9.95	9.95
1	1	0	ESR1053K	EXHAUST SYSTEM 90/95 STANDARD		299.95	299.95
2	2	0	WYH500060G	NUT EXHAUST MANIFOLD		3.95	7.90
						Shipping Charges	50.63
						NonTaxable Subtotal	0.00
						Taxable Subtotal	442.85
						Tax (7.25%)	32.10
						Total	474.95
						Less Payments/Credits	474.95
						Balance Due	0.00

Thank You!

PHONE: 800-533-2210 or 518-664-6169

FAX: 518-664-6641

RoverParts.com • MiniCarParts.net • RoverParts.com • MiniCarParts.net



6 Enterprise Avenue | 4109 Guardian Street
 Clifton Park, New York 12065 USA | Simi Valley, California 93063 USA

INVOICE

Invoice Number
1197678

Customer Number
525038

Bill to:

Ship to:



Range Rover • Discovery • LR3/LR4 • Freelander/LR2 • Defender • LR Series • MINI Cooper

All Returns Must Be Accompanied By Invoice. See Reverse For Return Information and Store Policies.

DATE		SHIP VIA		F.O.B.		TERMS	
05/22/18 09:12 AM		GTRAC		CLIFTON PARK		Cyber Order 5019509	
PHONE NUMBER		ORDER DATE		SALES PERSON		OUR ORDER NUMBER	
[REDACTED]		05/21/2018		Brian Westervelt - Ext 238		1316424	
ORDERED	SHIPPED	BACK ORD.	ITEM	DESCRIPTION	UNIT PRICE	AMOUNT	
1	1	0	AMR4803AB	BATTERY CABLE POSITIVE DISCO 1,RC	29.95	29.95	
1	1	0	PRC5235AB	BATTERY CABLE NEGATIVE DISC 1/RC	19.95	19.95	
1	1	0	SE910481A	BOLT LID HANDLE	0.95	0.95	

Shipping Charges	14.66
NonTaxable Subtotal	0.00
Taxable Subtotal	65.51
Tax (7.25%)	4.75
Total	70.26
Less Payments/Credits	70.26
Balance Due	0.00

Thank You!


PHONE: 800-533-2210 or 518-664-6169

FAX: 518-664-6641

RoverParts.com • MiniCarParts.net • RoverParts.com • MiniCarParts.net

books4cars.com

4850 37th Ave South
Seattle, WA 98118 USA



SALES INVOICE

SI-370327

4/27/2018




Customer	Contact	Ship To
[REDACTED]		[REDACTED]

Account	Terms	Due Date	Account Rep	Schedule Date
274017	NET 1 DAY	4/28/2018	Web Site	3/16/2018

Sales Order	PO #	Reference	Ship VIA	Page	Printed
SO-1224983	559464		Standard	1	4/27/2018 8:12:51 AM

L Item	Description	Order	Ship	Price	UM	Discount	Amount
1 93_LRNA1993OM	93 Range Rover Owners Manual Land Rover	1	1	\$159.95	EA	\$60.00	\$99.95
2							
3 SH1	Shipping - 1 Book	1	1	\$8.95	EA		\$8.95

Returns are honored within 30 days with reason provided and in the same condition as originally supplied. All CD & DVD sales are final. There is restocking fee on all returned books of 20% with minimum of \$5.00. Return shipping costs are responsibility of purchaser. You must contact us before returning an item.	Tax Details EXEMPT \$0.000	Taxable \$0.00
	Payment Details 04/27/18 CAP SO APPLIED \$108.90	Total Tax \$0.00
		Exempt \$108.90
		Total \$108.90
		Payment Disc \$0.00
		Paid \$108.90
	Balance \$0.00	



Your RoverParts.com Order Has Been Placed - Order No. RP-5013556

11:00 AM


Atlantic British <orders@atlanticbritish.com>

Sun, Mar 11, 2018 at 6:15 PM



If you cannot see the images below, select "Show Images" in your browser or [Click Here](#) to view this message online.



 **800.533.2210**
M-Th 8am -7pm Eastern (Fri 6pm)



Thank you for shopping with Atlantic British Ltd.! We have received your order and will process it shortly. You will receive a shipping notification with your tracking number via email once your order has shipped.

If you have any questions about your order, please call us at 800-533-2210 or email us by responding to this email. Also, please let us know how we're doing by filling out our [30-second customer survey](#).

Sincerely,

Atlantic British Ltd. Customer Service

Your Order Number:
RP-5013556

Shipping Information:



Items Ordered:

Description	Quantity	Unit Price	Amount
Item #: PRC4615 Washer Jet - Headlamp	1	\$14.95	\$14.95
Item #: EJP1180LG Bulb And Holder Instrument Clear	4	\$4.95	\$19.80
Item #: STC4104 Switch Oil Pressure	1	\$7.95	\$7.95

Subtotal: \$42.70

Shipping: \$3.95

Tax: \$3.38

Total: \$50.03

Follow Us:



Manage email Preferences: Too many emails? [Click Here](#) to choose how often you receive emails.

Unsubscribe: [Click Here](#) to unsubscribe from our promotional email list.

To speak with a Customer Service Representative, call us toll-free at 800-533-2210.

[Click Here](#) to read our privacy statement.

Atlantic British Ltd. is an independent supplier and manufacturer of replacement parts and accessories for Land Rover vehicles. We have no affiliation, real or implied, with Land Rover UK Ltd. or Land Rover North America. Any use of Range Rover, Land Rover or other trademarks used in this message or on our website is intended for reference only. Parts and accessories provided by Atlantic British Ltd. are genuine Land Rover parts only if indicated by suffix 'G' in the part number on the part itself and/or the packaging associated therewith.

Atlantic British Ltd. | 6 Enterprise Ave | Clifton Park, NY 12065 | United States | 800-533-2210

© Atlantic British Ltd. All rights reserved.

Final Details for Order #114-6063929-9350663

Print this page for your records.

Order Placed: March 10, 2018
Amazon.com order number: 114-6063929-9350663
Order Total: \$22.00

Shipped on March 12, 2018

Items Ordered

Price

1 of: *LAND ROVER RANGE ROVER CLASSIC 1987-1994 HOOD - CABLE BONNET*
RELEASE PART: MWC2287
Sold by: LRNJ AUTOPARTS ([seller profile](#))

\$22.00

Condition: New

Shipping Address:


United States

Item(s) Subtotal: \$22.00
Shipping & Handling: \$0.00

Total before tax: \$22.00
Sales Tax: \$0.00

Shipping Speed:
Standard Shipping

Total for This Shipment: \$22.00


Payment information

Payment Method:

Amazon.com Visa Signature | Last digits: 1579

Item(s) Subtotal: \$22.00
Shipping & Handling: \$0.00

Billing address


United States

Total before tax: \$22.00
Estimated tax to be collected: \$0.00

Grand Total: \$22.00

Credit Card transactions

Visa ending in 1579: March 12, 2018: \$22.00

To view the status of your order, return to [Order Summary](#).



6 Enterprise Avenue | 4109 Guardian Street
Clifton Park, New York 12065 USA | Simi Valley, California 93063 USA


INVOICE

Invoice Number
1179574

Customer Number
525038

Bill to:

Ship to:



Range Rover • Discovery • LR3/LR4 • Freelander/LR2 • Defender • LR Series • MINI Cooper

All Returns Must Be Accompanied By Invoice. See Reverse For Return Information and Store Policies.

DATE		SHIP VIA		F.O.B.		TERMS	
02/26/18 02:05 PM		FHD		SIMI VALLEY,		Cyber Order 5012346	
PHONE NUMBER		ORDER DATE		SALES PERSON		OUR ORDER NUMBER	
[REDACTED]		02/26/2018		Eric Riston - Ext 231		1297202	
ORDERED	SHIPPED	BACK ORD.	ITEM	DESCRIPTION		UNIT PRICE	AMOUNT
2	2	0	PRC7045G	WASHER PUMP WINDSHIELD FROM 89 KIT		34.95	69.90
2	2	0	AMR3849	LINK LEAD WASHER PUMP		0.00	0.00
2	2	0	STC1454	WINDSHIELD WASHER PUMP - SEE PRC704		0.00	0.00
1	1	0	ERR3340SKB	OIL FILTER KIT-INCLUDES PLUG AND WA		24.95	24.95
2	2	0	603659	OIL PAN DRAIN PLUG RR DISCO DEF		0.00	0.00
2	2	0	ERR3340	OIL FILTER SHORT		0.00	0.00
2	2	0	ETC7398	OIL PAN DRAIN PLUG WASHER		0.00	0.00

Shipping Charges	12.51
NonTaxable Subtotal	0.00
Taxable Subtotal	107.36
Tax (7.25%)	7.79
Total	115.15
Less Payments/Credits	115.15
Balance Due	0.00

Thank You!

PHONE: 800-533-2210 or 518-664-6169

FAX: 518-664-6641

RoverParts.com • MiniCarParts.net • RoverParts.com • MiniCarParts.net

Final Details for Order #114-7465737-0366614

Print this page for your records.

Order Placed: January 7, 2018
Amazon.com order number: 114-7465737-0366614
Order Total: \$15.21

Shipped on January 8, 2018

Items Ordered

Price

1 of: *Philips 194 Bright White Interior Vision LED light, 2 Pack*
Sold by: Amazon.com Services, Inc.

\$13.95

Condition: New

Shipping Address:



Item(s) Subtotal: \$13.95
Shipping & Handling: \$0.00

Total before tax: \$13.95
Sales Tax: \$1.26

Shipping Speed:
Two-Day Shipping

Total for This Shipment: \$15.21

Payment information

Payment Method:

Amazon.com Visa Signature | Last digits: 1579

Item(s) Subtotal: \$13.95
Shipping & Handling: \$0.00

Total before tax: \$13.95
Estimated tax to be collected: \$1.26

Grand Total: \$15.21



Credit Card transactions

Visa ending in 1579: January 8, 2018: \$15.21

To view the status of your order, return to [Order Summary](#).



15525 LOS GATOS BOULEVARD
LOS GATOS, CA 95032
(408) 358-2774
www.oreillyauto.com

Store hours:
Mon-Sat: 07:30 AM-09:00 PM
Sun: 08:00 AM-08:00 PM

Counter #: 95938 SALVADOR P.
Date: 11/24/2017 10:04 AM Drawer: 8
Invoice #: 2572-113225

SSB 24EXTJ	131.99 T1
BATTERY	
3 YEAR LIMITED WARRANTY	
Battery Fee	1.00 NA
SSB 24EXTJ Core Charge	18.00 T1
SSB 24EXTJ Core Exchange	-18.00 NA

Call 866-830-4351 for Super Start National
Warranty Information

1-Item
Total Local/Stat/Gvt Fees: 1.00

Sub-total	132.99
Tax1	-13.50
Total	146.49
MC 9685	146.49

MC XXXXXXXXXXXX9685 Auth CD: 00778Z
REF# 284704892789

SIGNATURE VERIFIED

Chip Indicator: Y
AID: A0000000041010
4341504954414C204F4E45
TVR: 000008000
TSI: E800
IAD: 0110A04001220000000000000000000000FF
SIGNATURE VERIFIED

Final Details for Order #111-7905801-0059458

Print this page for your records.

Order Placed: November 20, 2017
Amazon.com order number: 111-7905801-0059458
Order Total: \$0.00

Shipped on November 21, 2017

Items Ordered

Price

1 of: *LAND ROVER RANGE CLASSIC 87-95 INTERIOR LAMP LIGHT LENS PRC1634 SET* \$13.00
x2 *NEW*

Sold by: Proper Spec ([seller profile](#))

Condition: New

Shipping Address:



Shipping Speed:

Standard Shipping

Item(s) Subtotal: \$13.00

Shipping & Handling: \$0.00

Total before tax: \$13.00

Sales Tax: \$0.00

Gift Card Amount: -\$13.00

Total for This Shipment: \$0.00

Total paid by Gift Card: -\$13.00

Payment information

Payment Method:

Amazon.com Visa Signature | Last digits: 1579
Gift Card

Item(s) Subtotal: \$13.00

Shipping & Handling: \$0.00


Total before tax: \$13.00

Estimated tax to be collected: \$0.00

Gift Card Amount: -\$13.00

Grand Total: \$0.00

Billing address



To view the status of your order, return to [Order Summary](#).

Final Details for Order #111-1158432-7466638

Print this page for your records.

Order Placed: November 20, 2017
Amazon.com order number: 111-1158432-7466638
Order Total: \$28.95

Shipped on November 20, 2017

Items Ordered

Price

1 of: *Genuine 1987-1994 Range Rover Classic Ignition Key Set of 2*
Sold by: Attic Market Auto ([seller profile](#))

\$28.95

Condition: New
Brand new

Shipping Address:



Item(s) Subtotal: \$28.95
Shipping & Handling: \$0.00

Total before tax: \$28.95
Sales Tax: \$0.00

Shipping Speed:
Standard Shipping

Total for This Shipment: \$28.95

Payment information

Payment Method:

Amazon.com Visa Signature | Last digits: 1579
Gift Card

Item(s) Subtotal: \$28.95
Shipping & Handling: \$0.00

Total before tax: \$28.95
Estimated tax to be collected: \$0.00

Billing address



Grand Total: \$28.95

Credit Card transactions

Visa ending in 1579: November 20, 2017: \$28.95

To view the status of your order, return to [Order Summary](#).