

2002 Carrera Coupe
Seal Grey Metallic
Graphite Grey Sport Seats

5/142

EQUIP

Standard Equipment	Options	Price	Exclusive Options
	Manufacturer's Suggested Retail Price:		Manufacturer's Suggested Retail Price:
Technical/Mechanical			
Water Cooled, 6 Cyl Engine 3.6 Liters	Porsche Base Model	67,900	Graphite Grey Floor Mat <i>115</i>
4 Valves/Cylinder, 320 HP	Seal Grey Metallic	825	Rear Ctr Cons Painted Extr Clr <i>725</i>
Integrated Dry Sump Lubrication	Seal Grey Metallic Top	N/C	Porsche Crest in Headrest <i>215</i>
Cross Flow Cylinder Cooling	Graphite Grey Sport Seats	N/C	Flared Rocker Panels <i>1750</i>
On-Board Diagnosis System II (OBD II)	U.S. Standard/Emissions	N/C	Deviating Carpet Color <i>295</i>
Knock Sensor	Advanced Technic Package	3,240	
Double Inertia Flywheel	Heated Front Seats Package	415	
6-Speed Manual Transmission	Design Package	1,980	
Hydraulic Clutch	Leather Sport Seats	755	
Power Steering	18" Lt Alloy Wheel- Turbo Look	1,325	
Front and Rear Stabilizer Bars	Wheel Caps with Colored Crest	175	
205/60 ZR 17" 255/40 ZR 17" Wheels/Tires	Porsche Stability Management	1,230	
Speed Activated Rear Spoiler			
Safety/Environment			
4-Piston Fixed Alloy Calipers	EXCLUSIVE OPTIONS	3,100	
Vented and Perforated Brake Discs	Destination Charge	765	
Anti Lock Brakes ABS	TOTAL PRICE*	81,710	
Dual Front Airbags with Side Airbags			
3-Way Catalytic Converter			
Fog Lights Integrated into Headlights			
Interior/Accessories			
Power Windows with One Touch			
Heatable Windshield Washer Nozzles			
Carbon Filtered Ventilation System			
Dual Vanity Mirrors Illuminated			
Partial Leather Seats			
Front Seats with Power Beckrest			
Central Locking System			
Immobilizer Anti-Theft System			
Lockable Storage Compartment			
Automatic Full Climate Control with AC			
Power Heated Side Mirrors			
Electric Sliding Roof with Tilt			
AM/FM Cassette Radio			
Warranty/Durability			
10 Year Limited Anti-Corrosion			
Limited 4 Year / 50,000 Mile Warranty-US			
Limited 4 Year / 80,000 KM Warranty-Canada			
Porsche Roadside Assistance			

Ask about financial lease options through Porsche Financial Services

*Gasoline, license and title fees, state and local taxes and dealer installed options and accessories are not included.

Auto Tech, Tassajara
3600 Camino Tassajara
Danville, CA 94506
(925) 736-3100

"THE ALTERNATIVE TO DEALER SERVICE"

Repair Order # 0111625
 Date : 7/21/2017 Page 1 of 1
 Orig Est #: Center : 1

Customer : [REDACTED] Address : [REDACTED] City : [REDACTED] CELL : [REDACTED] HOME : [REDACTED]	Vehicle : 2002 PORS 911 SERIES License : 5EHD368 Prod : 11/01 VIN : WP0AA29932S621349 Engine : 6-3600 3.6L DOHC Trans : STD Mileage : In Out CLR :
---	--

Op	Tech	Description	Part Number	Part Description	Reason for Replacement	Labor	Parts Price	Subtotal
LOF420		OIL CHANGE 0W30 SYNTHETIC				35.50		35.50
		OIL & FILTER SUPPLIED BY CUSTOMER						


WARRANTY INFORMATION

All other products and workmanship are warranted for 36 months or 36000 miles from the date of installation unless otherwise specified. All parts shown are new unless otherwise specified. I hereby authorize you and/or your agents to contact me regarding the products and services provided. An express mechanic's lien is hereby granted. I acknowledge receipt of a copy of this repair order.

Thank you for your business!
 Questions or comments? Call us at 1-925-736-3100
 Visit us online at WWW.AUTOTECHSHOPS.COM
 BAR# ARD282765

Labor :	\$35.50
Parts :	\$0.00
Sublet :	\$0.00
Other Fees :	\$0.00
	\$0.00
Subtotal :	\$35.50
Sales Tax :	\$0.00
Total :	\$35.50
Paid :	\$0.00
Due :	\$35.50

Signature X _____



Pelican Parts
 1600 240th Street
 Harbor City, CA 90710
 310-626-8765
 www.pelicanparts.com

Bill of Sale

Date: 4/3/17
 Invoice No: 1491063671-814



Bill To:
 [Redacted]

Ship To:
 [Redacted]

Phone #	Payment	Sales Rep	Shipping Methods	Car Type
[Redacted]	VISA	OL	FEDEX_GROUND	

QTY	Status	Part Number	Description	Unit Price	Amount
6	Packed & Shipped	997-602-104-00-INT	Ignition Coil - With Spark Plug Connector Brand: Beru Note: w/ Plug Connector (2002 Porsche 911 Carrera Coupe)	33.50	201.00
				Shipping & Handling	0.00
				Sales Tax Rate: 7.25%	14.57
Thank you for your support!				Total:	215.57

Any problems or questions about this order?
 Just give us a call toll-free at: 1-888-280-7799

Billed to Credit Card \$215.57

Pacific Power Motorsports Inc.


2149 North Broadway
Walnut Creek, CA

Phone (925) 937-2277

Fax (925) 937-2277

Service Invoice

Account #	Date	Estimate #
	4/14/2017	2536
Make/ Model	Year / Color	
PORSCHE / 996 BASE	2002 / GREY	
Vin / License Plate		
WP0AA29932S621349 / 5EHD368		
Mileage / Date of Manuf		
43,111 / 11/01		

Name / Address


PAID
04/14/2017

Item	Description	Qty	U/M	Cost	Total
Labor, Oil Service	Porsche Oil Service. Replace engine oil and engine oil filter with new oil and filter. Bring car to operating temperature and check and top off fluid levels.	1.3		160.00	208.00
Filter,Oil,997	Porsche Engine Oil Filter Kit, New. Customer Supplied	1		0.00	0.00T
Oil, 0-40, Mobil...	Oil, Mobile 1, 0-40, Qt. Customer Supplied	8.75		0.00	0.00T
Haz Fee, Oil	Hazardous Waste Disposal Fee, Oil	1		4.20	4.20
Labor, A Shop	Replace Spark Plugs And Ignition Coils With Customer Supplied Parts.	2.6		160.00	416.00
Ignition,SpkPlu...	Porsche 997 S Spark Plugs, New Customer Supplied Parts	6		0.00	0.00T
Ignition,Coil,99...	Porsche Original Equipment Direct Ignition Coil With Spark Plug Boot, New. Customer Supplied Parts	6		0.00	0.00T
Lighting,LvlSnr...	Original Porsche Headlamp Leveling Sensor Support Strut, New.	1		4.40	4.40T

Bureau Of Automotive Repair License # 00239756	Sales Tax (8.25%)
	Total
	Payments/Credits
Customer Signature	Balance Due

I hereby authorize the work outlined above to be complete inclusive of all necessary parts and/or materials. Further, I acknowledge that an express mechanics lien is in force to secure the amount of the fore mentioned repairs. I hereby grant Pacific Power Motorsports and its employees permission to operate the vehicle for the purposes of testing, inspecting and/or delivery.

Most parts are warranted by their manufacturer, usually for 90 days from the date of purchase, unless otherwise specified. Used or customer supplied parts carry NO WARRANTY EXPRESS OR IMPLIED. Pacific Power Motorsports warranties their work for 3 months or 3000 miles. Parts and labor used for track or competition purposes are warranted against manufacturer's defects only. We do NOT recommend illegal modifications for street legal automobiles. PACIFIC POWER MOTORSPORTS' LIABILITY FOR LOSSES OR DAMAGES, ARISING OUT OF ANY CAUSE WHATSOEVER, IS LIMITED TO FULL REFUND OF THE PURCHASE PRICE OR AT OUR OPTION, REPAIR OR REPLACEMENT OF THE PART(S). PACIFIC POWER MOTORSPORTS SHALL NOT BE LIABLE FOR ANY CONSEQUENTIAL OR INCIDENTAL DAMAGES.

www.pacificpowermotorsports.com

Pacific Power Motorsports Inc.


2149 North Broadway
Walnut Creek, CA

Phone (925) 937-2277

Fax (925) 937-2277

Service Invoice

Account #	Date	Estimate #
	4/14/2017	2536
Make/ Model	Year / Color	
PORSCHE / 996 BASE	2002 / GREY	
Vin / License Plate		
WP0AA29932S621349 / 5EHD368		
Mileage / Date of Manuf		
43,111 / 11/01		

Name / Address


PAID
04/14/2017

Item	Description	Qty	U/M	Cost	Total
	<p>NOTES:</p> <p>a. Tire Pressures Set To: Front 36 psi And Rear 44 psi</p> <p>b. Tire Tread Remaining: Front 9/32" And Rear 7/32"</p> <p>c. Brake Pad Material Remaining: Front 14 mm And Rear 8 mm.</p> <p>d. Minor Engine Oil Seepage From Rear Main Seal Area Of Engine. Cleaned Oil Residue From Engine And Ran Engine For Several Minutes To Confirm Oil Leakage Is Not From Oil Supply Line To IMS Bearing.</p> <p>e. Coolant Level Was Slightly Low With No Signs Of External Seepage. Coolant Appears To Be A Mix Of Porsche Coolant And "Green" Standard Coolant. Estimate To Service Cooling System Is \$296.30</p> <p>f. Steering Wheel Points Slightly To The Left While Driving Straight. Estimated Alignment Cost Is \$280.00</p> <p>g. Front Left Headlamp Level Sensor Support Strut Is Broken. Estimate To Replace Support Is \$ 104.40 Or Less</p>				

Bureau Of Automotive Repair License # 00239756	Sales Tax (8.25%)	\$0.36
	Total	\$632.96
	Payments/Credits	\$0.00
Customer Signature	Balance Due	-\$632.96

I hereby authorize the work outlined above to be complete inclusive of all necessary parts and/or materials. Further, I acknowledge that an express mechanics lien is in force to secure the amount of the fore mentioned repairs. I hereby grant Pacific Power Motorsports and its employees permission to operate the vehicle for the purposes of testing, inspecting and/or delivery.

Most parts are warranted by their manufacturer, usually for 90 days from the date of purchase, unless otherwise specified. Used or customer supplied parts carry NO WARRANTY EXPRESS OR IMPLIED. Pacific Power Motorsports warranties their work for 3 months or 3000 miles. Parts and labor used for track or competition purposes are warranted against manufacturer's defects only. We do NOT recommend illegal modifications for street legal automobiles. PACIFIC POWER MOTORSPORTS' LIABILITY FOR LOSSES OR DAMAGES, ARISING OUT OF ANY CAUSE WHATSOEVER, IS LIMITED TO FULL REFUND OF THE PURCHASE PRICE OR AT OUR OPTION, REPAIR OR REPLACEMENT OF THE PART(S). PACIFIC POWER MOTORSPORTS SHALL NOT BE LIABLE FOR ANY CONSEQUENTIAL OR INCIDENTAL DAMAGES.

www.pacificpowermotorsports.com

Auto Tech, Tassajara
 3600 Camino Tassajara
 Danville, CA 94506
 (925) 736-3100

"THE ALTERNATIVE TO DEALER SERVICE"

Repair Order # **0110323**
 Date : 1/5/2017 Page 1 of 2
 Orig Est #: 0001768 Center : 1

Customer	[REDACTED]	Vehicle : 2002 PORS 911 SERIES
Address	[REDACTED]	License : 5EHD368 Prod : 11/01
City	[REDACTED]	VIN : WP0AA29932S621349
CELL :	[REDACTED]	Engine : 6-3600 3.6L DOHC Trans : STD
HOME :	[REDACTED]	Mileage : In 41854 Out 41856 CLR :

Op	Tech	Description	Part Number	Part Description	Reason for Replacement	Labor	Parts Price	Subtotal
HC 0	BC	REMOVE & REPLACE WATER PUMP & coolant		customer supplied water pump, drive belt		594.00	0.00	594.00
	1.00			WATER PUMP			0.00	
	1.00			WATER PUMP GASKET			0.00	
	1.00			DRIVE BELT			0.00	
HC 0	BC	REMOVE & REPLACE THERMOSTAT				198.00	86.30	284.30
	1.00			THERMOSTAT			75.26	
	4.00			ZEBRA HOSE CLAMP			11.04	
FLS110	BC	COOLING SYSTEM FLUID FLUSH				0.00	0.00	
	1.00			COOLANT/ANTIFREEZE - PC			0.00	
DIA0	BC	CUSTOMER IS TOPPING OFF POWER STEERING FLUID REGULARLY. PLEASE INSPECT FOR LEAKS ***				0.00		
		power steering reservoir leaks						
		replace reservoir to correct						
SSP0	BC	REMOVE & REPLACE POWER STEERING RESERVOIR				165.00	114.69	279.69
	1.00			P/S RESERVOIR			103.41	
	0.50			POWER STEERING FLUID			11.28	
CHG0	BC	REMOVE & REPLACE ALTERNATOR				198.00	396.00	594.00
	1.00			ALTERNATOR 120 AMP			396.00	
						Discou -50.00	0.00	-50.00


Payments:
 VISA/MASTERCARD, \$1752.73, on 01/05/17

Auto Tech, Tassajara
3600 Camino Tassajara
Danville, CA 94506
(925) 736-3100

Repair Order # 0110323

Date : 1/5/2017 Page 2 of 2
 Orig Est #: 0001768 Center : 1

"THE ALTERNATIVE TO DEALER SERVICE"



Vehicle : 2002 PORS 911 SERIES
License : 5EHD368 **Prod : 11/01**
VIN : WP0AA29932S621349
Engine : 6-3600 3.6L DOHC **Trans : STD**
Mileage : In 41854 Out 41856 **CLR :**

Op	Tech	Description	Part Description	Reason for Replacement	Labor	Parts	Subtotal
	Quan	Part Number				Price	
✓		BRAKE FLUID	OK				
✓		ANTIFREEZE	OK				
✓		DRIVE BELTS	OK				
✓		HOSES	OK				
✓		WIPER BLADES	OK				
✓		LEAKS	OK				
✓		LIGHTS	OK				
✓		TIRE CONDITION	OK				

FRONT & REAR TIRES SET TO 36psi

WARRANTY INFORMATION

All other products and workmanship are warranted for 36 months or 36000 miles from the date of installation unless otherwise specified. All parts shown are new unless otherwise specified. I hereby authorize you and/or your agents to contact me regarding the products and services provided. An express mechanic's lien is hereby granted. I acknowledge receipt of a copy of this repair order.

Thank you for your business!
 Questions or comments? Call us at 1-925-736-3100
 Visit us online at WWW.AUTOTECHSHOPS.COM
 BAR# ARD282765

Labor : \$1,105.00
 Parts : \$596.99
 Sublet : \$0.00
 Other Fees : \$0.00
 Subtotal : \$1,701.99
 Sales Tax : \$50.74
 Total : \$1,752.73
 Paid : \$1,752.73
 Due : \$0.00


Signature X _____

ELITE AUTO GLASS INC.
P O BOX 2806
SAN RAMON, CA 94583

(925) 820 - 3208 Fax: (925) 820 - 3401

INVOICE NUMBER	
DATE	12/27/2016
REFERENCE #	Wrk: 820
TAX ID NUMBER	20-1972270

5:16PM

ACCOUNT	CUSTOMER TAX ID NUMBER	PO NUMBER	INSTALL DATE:
			INSTALLED BY:
SALES REP:			TERMS:
BILL TO: CUSTOMER PAY			SOLD TO: 

Insurance Information

AGENT: VERIFIED BY: DISPATCH #:
 POLICY NUMBER:
 CLAIM NUMBER:
 CAUSE OF LOSS:
 DATE OF LOSS: DEDUCTIBLE:

Vehicle Information

MAKE: PORSCHE MODEL: 911 CARRERA YEAR: 2002
 BODY: 2 DOOR COUPE VIN: ODOMETER:
 STOCK #: R.O. #: UNIT #: LICENSE #:

Qty	Part Number	Hours	Labor	Adhesive	List Price	Net Price	Line Total
1.00	INSTAL PROVIDED PART OEM # - INSTAL PROVIDED PART	0.00	\$150.00	\$50.00	\$0.00	\$0.00	\$200.00
INSTALL GLASS PROVIDED BY CUSTOMER							

he is geeting part from a dealership// in shop 9 to 10, jan 3rd

Total Labor \$150.00
 Total Kit \$50.00
 Total Parts \$0.00
 Subtotal \$200.00
 Sales Tax @ 9.5000 % \$0.00

Thank you! Elmo

Customer Signature:

Amount Due: \$200.00 Invoice Total \$200.00

I hereby authorize the above repair work to be done, along with the necessary material, and hereby grant you and/or your employees permission to operate the vehicle herein described on street, highways, and elsewhere for the purpose of inspection, testing, and pick-up/delivery to me. AN EXPRESS MECHANIC'S LIEN is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. Not responsible for loss or damage to vehicle or articles therein by causes beyond our control. REPLACEMENT HAS BEEN MADE TO MY SATISFACTION AND I HEREBY ASSIGN SUCH PROCEEDS AS MAY BE REQUIRED TO SATISFY ALL AMOUNTS DUE AND OWING TO THE ABOVE NAMED COMPANY FOR SAID INSTALLATION. IF FOR ANY REASON THE INSURANCE COMPANY DOES NOT PAY FOR THESE REPAIRS/REPLACEMENTS, THE ABOVE SIGNED AGREES TO PAY FOR SAID REPAIRS/REPLACEMENTS.

Auto Tech, Tassajara
3600 Camino Tassajara
Danville, CA 94506
(925) 736-3100


Repair Order # **0109886**

Date : 10/22/2016 Page 1 of 1

Orig Est #: Center : 1

"THE ALTERNATIVE TO DEALER SERVICE"

Customer :
 Address :
 City :
 CELL :
 HOME :



Vehicle : 2002 PORS 911 SERIES
 License : 5EHD368 Prod : 11/01
 VIN : WP0AA29932S621349
 Engine : 6-3600 3.6L DOHC Trans : STD
 Mileage : In 41104 Out 41104 CLR :

Op	Tech	Description	Part Description	Reason for Replacement	Labor	Parts Price	Subtotal	
TRNO	MAT	DRAIN AND FILL STD TRANS WITH CUSTOMER SUPPLIED FLUID. * CUSTOMER HAD REQUESTED THE FLUID CHANGE DUE TO HARD SHIFT.					99.00	99.00

Payments:
 VISA/MASTERCARD, \$99.00, on 10/22/16

TECH NOTES LIGHT OIL SEEP WOULD NEED TO DIAGNOSE ISSUE

WARRANTY INFORMATION

All other products and workmanship are warranted for 36 months or 36000 miles from the date of installation unless otherwise specified. All parts shown are new unless otherwise specified. I hereby authorize you and/or your agents to contact me regarding the products and services provided. An express mechanic's lien is hereby granted. I acknowledge receipt of a copy of this repair order.

Thank you for your business!
 Questions or comments? Call us at 1-925-736-3100
 Visit us online at WWW.AUTOTECHSHOPS.COM
 BAR# ARD282765

Labor :	\$99.00
Parts :	\$0.00
Sublet :	\$0.00
Other Fees :	\$0.00
	\$0.00
Subtotal :	\$99.00
Sales Tax :	\$0.00
Total :	\$99.00
Paid :	\$99.00
Due :	\$0.00

Signature X _____

ABP REPAIR INC

Invoice No.

BAR #: AH 141375

000020039

Order Date 10/06/16 10:47 am

EPA # CAL 000168351


Paid: 10/06/16 04:46 pm

601 Brush Street

Oakland, CA 94607

Phone: 510-834-2772 FAX: 510-834-2776

IMS



02 PORSCHE 996 GREY
40750 Mi. Last in 9/15/2016
Lic: 5EHD368/CA 6Cyl 3.6
Vin: WPOAA29932S621349 11/01
Eq: AC PS FI DC

Quotes

1 10/06/16 04:47pm 1843.70
KEN in person.

DOF / IMS BEARING

Labor: \$1,742.00

INSTALLED CUSTOMER SUPPLIED TUNE RS IMS BEARING, AND DOF KIT. REMOVE OIL PAN, AND CLEAN SUMP SCREEN. CHANGE ENGINE OIL AND FILTER WITH CUSTOMER SUPPLIED PARTS. REPLACED LEAKING REAR MAIN SEAL. REPLACED FOUR REAR LOWER CASE HALF BOLTS AS PER TSB. INSTALLED DUAL MASS FLYWHEEL WITH EIGHT NEW FLYWHEEL BOLTS. INSTALLED TWO NEW TIMING CHAIN TENSIONER O-RINGS AND CRUSH WASHERS, WHICH WERENT INCLUDED IN THE DOF KIT. INSTALLED NEW DRAIN PLUG CRUSH WASHER.

99710121201	Crankshaft Seal-N	1.0 @	27.55 =\$	27.55
99938500401	BOLT-N	4.0 @	2.40 =\$	9.60
99907309202	FLYWHEEL BOLT-N	8.0 @	2.30 =\$	18.40
99970734440	Rubber O-Ring-N	2.0 @	9.65 =\$	19.30
90012314730	Seal Ring 27x30-N	2.0 @	0.97 =\$	1.94
90012310630	Seal Ring-N	1.0 @	1.52 =\$	1.52
CLEANER	PARTS CLEANER-N	2.0 @	5.00 =\$	10.00
				88.31

Job Subtotal: \$1,830.31

Recommendations: WATER PUMP BEARING IS NOISY, WATER PUMP NEEDS TO BE REPLACED.

Payments to ABP REPAIR INC

Cost Summary

Status: Paid Work Order

Payments: \$1,843.70

1 10/06/16 1843.70 Visa 1596-05/20

Labor	1742.00
Parts	88.31
Haz Waste	5.00
Tax	8.39
Total	\$1843.70
Payments	1843.70
Bal Due	0.00

Thank you for choosing ABP REPAIR INC

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) _____

**IMS +
OIL FEED**

TUNERS MALL, CORP

11510 WILES RD.

CORAL SPRINGS, FL 33076

Shop Phone: (954) 345-7877

Fax: (954) 345-7851

Email: service@tunersmall.com

Web Address: www.tunersmall.com

Counter Sale

7762


Estimate Ref #0

Date Printed: 09/28/2016

Printed Time: 4:27 pm

Your #1 PORSCHE Service and Performance Center

Time Promised:



VIN:

License:

Unit #:

Mileage In: 0

Mileage Out: 0

DOM:

Date Written: 09/28/2016

Written By: TAYLOR

Save Old Parts: No

Job Name	Description	Technician	Qty	List	Extended
ORDER 1663					
Part TRS-DOF-9705	DIRECT OIL FEED (DOF) KIT - EARLY STYLE		1.00	799.00	799.00
Part TRS-SKF-SING	TRS SKF SINGLE ROW IMS BEARING		1.00	49.99	49.99
Part	UPS 2ND DAY AIR SHIPPING		1.00	34.62	34.62

Job Total: 883.61

RETURN / EXCHANGES: ALL CLAIMS NEED A RETURN AUTHORIZATION NUMBER, AND MUST BE MADE WITHIN 10 CALENDAR DAYS FROM THE RECEIPT OF MERCHANDISE. ALL CLAIMS ARE SUBJECT TO A 25% RESTOCKING FEE / HANDLING CHARGE. NO RETURNS OR EXCHANGES ON SPECIAL ORDER MERCHANDISE. ALL RETURNS OR EXCHANGES ARE SUBJECT TO INSPECTION. FREIGHT IS F.O.B. CORAL SPRINGS, FL.. ALL RETURNS MUST BE SHIPPED PRE-PAID TO CORAL SPRINGS, FL, USA. PAYMENT: ANY CHARGES INCURRED IN THE COLLECTION OF PAYMENT, RETURNED CHECKS, COURT COSTS, AND/OR ATTORNEY FEES WILL BE THE LIABILITY OF THE CUSTOMER.

DISCLAIMER: TUNERS MOTORSPORTS, a.k.a. TUNERS MALL, CORP, DOES NOT WARRANT LEGALITY OF PRODUCTS WHICH DON'T COMPLY WITH LOCAL, STATE OR FEDERAL REGULATIONS, NOR DOES TUNERS MOTORSPORTS RECOMMEND ILLEGAL MODIFICATIONS. CHECK LAWS AND REGULATIONS BEFORE ORDERING. ALL NON-FACTORY PORSCHE MERCHANDISE IS INTENDED FOR OFF-ROAD USE, AND RACING USE ONLY.

IN NO EVENT WILL THE SELLER BE RESPONSIBLE FOR CONSEQUENTIAL OR INCIDENTAL DAMAGES.

Payment Date	Type	Method	Amount
9/28/2016	Credit	Visa	883.61
Payment Totals:			\$883.61

Parts: \$883.61
 Labor: \$0.00
 Sublet: \$0.00
 Misc: \$0.00
 Hazmat: * \$0.00
 Supplies: * \$0.00

Tax Total: \$0.00
Invoice Total: \$883.61
 Less Paid: 883.61
Balance Due: \$0.00

AMERICA'S TIRE

1559670


americastire.com

DATE: 05-09-2014 TIME: 11:50 AM

CUSTOMER INFORMATION

VEHICLE INFORMATION

STORE LOCATION



2002 PORSCHE
911
995 18-INCH
MILEAGE: 35,851

TORQUE SPECS: 095

CAN 23
4908 SOUTHFRONT RD
LIVERMORE CA 94551
PHONE: 925-449-6787
312 DAVID W D'AUDNEY

WORK ORDER# _____

CODE	CC	QTY	SIZE	DESCRIPTION	F.E.T.	PRICE	AMOUNT
15199	NRM	2	225/40ZR18XL 92Y 26%	CON CONTROLCONTACT SPRTAS	.00	163.00	326.00
WARRANTY: MILEAGE- 50,000 SEE REVERSE SIDE FOR WARRANTY DETAILS							
COMMENT: BOLT PATTERN: 5-130							
COMMENT: INFLATION P:37							
50017	NRM	2	CERTIFICATES FOR	REFUND, REPLACEMENT	.00	23.00	46.00
80075	NRM	2	STATE REQUIRED	ENVIRONMENTAL FEE	.00	1.75	3.50
80224	NRM	2	WASTE TIRE DISPOSAL	FEE	.00	2.50	5.00
80219	NRM	2	INSTALLATION &	LIFETIME SPIN BALANCING	.00	16.00	32.00
80402	NRM	2	VALVES/ROTATIONS/	LIFETIME REPAIRS INCLUDED	.00	.00	.00
26879	NRM	2	265/35ZR18 97Y XL B	CONTI EXTREME CONTACT DWS	.00	199.00	398.00
WARRANTY: MILEAGE- 50,000 SEE REVERSE SIDE FOR WARRANTY DETAILS							
COMMENT: INFLATION R:37							
50017	NRM	2	CERTIFICATES FOR	REFUND, REPLACEMENT	.00	30.00	60.00
80075	NRM	2	STATE REQUIRED	ENVIRONMENTAL FEE	.00	1.75	3.50
80224	NRM	2	WASTE TIRE DISPOSAL	FEE	.00	2.50	5.00
80219	NRM	2	INSTALLATION &	LIFETIME SPIN BALANCING	.00	15.00	30.00
80402	NRM	2	VALVES/ROTATIONS/	LIFETIME REPAIRS INCLUDED	.00	.00	.00
COMMENT: all four. no locks							

The tire and/or wheel you have chosen is different from the original equipment provided with your vehicle and may change its handling or stability characteristics.

Further information is available from your America's Tire salesperson.

SUBTOTAL: 911.00
TAX: 66.08
TOTAL: 977.08

VISA: 977.08
TENDERED: 977.08

XXXXXXXXXXXX 2623

Signature on file



100%
recyclable paper

013070

TED'S FOREIGN CAR

5524 Scotts Valley Dr., #13 • Scotts Valley, California 95066
 Phone (831) 438-3755
 BAR No. AE 078962 • Lic. No. EO 389147

REPAIR INVOICE

LABOR CHARGE PER HR. 120.00

QTY.	* PART NO. & DESCRIPTION	AMOUNT
1	Interstate Battery MTP-81	150.75
1	Polten Filter @ Chem Area	77.00
6	Liters specific Porsche spec Coolant	64.70
1	Coolant Tank Expansion Bottle	150.00
1	Spark Plugs Best Quality Check	108.50
1	K+M Performance Air Intake Filter service KIT AFT MKT.	10.00
1	Accessory Drive Belt serpentine	60.00
1	Bottle Power steering fluid	20.00
1	Bottle Windshield Concentrate	10.00
1	ROAD WAX center Cap Genuine	60.00
TOTAL PARTS		
REPLACED PARTS REQUESTED BY CUSTOMER? <input type="checkbox"/> YES <input type="checkbox"/> NO		
1	Bottle Brake Side Springs - 4 spec	20.00
TOTAL SUBLET REPAIRS		
	GALS. GAS @	
	QTS. OIL @	
	LBS. GREASE @	
TOTAL GAS, OIL & GREASE		
FOLLOWING REPAIRS RECOMMENDED		

DATE 25 MAR 10

STATE CA ZIP 95066

TIME REC'D TIME PROM.

PH. WHEN READY WRITTEN BY

YES NO

MILEAGE 19115 LIC PLATE # 5EHD368

YR/MAKE/MODEL TED G. 019115 G.V.M.R. BEH MOTOR # 368

OR FORSCHER 996-C-2 G speed TRUST. PO#

V.I.N. WPOA A299323421349

OPR. #

REPAIR ORDER • DESCRIPTION OF LABOR

1. Replace Battery cr che system
2. 15K MAJOR services AS SCHEDULED
3. ROAD Test Safety Vehicle

PHONE# • FAX# • EMAIL

DATE TIME

BY PHONE BY FAX

BY PHONE BY FAX

ADD'L COSTS \$

REASON

I ACKNOWLEDGE NOTICE AND APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE. AUTH. BY REC'D BY

REASON

I ACKNOWLEDGE NOTICE AND APPROVAL OF AN INCREASE IN THE REVISED ESTIMATED PRICE. AUTH. BY REC'D BY

ORIGINAL ESTIMATE \$ 960.00

TOTAL LABOR 960.00

TOTAL PARTS 731.85

GAS, OIL, GREASE

HAZARDOUS WASTE DISPOSAL 10.00

SUBLET REPAIRS

SMOG CERTIFICATE

SUBTOTAL

PLEASE PAY THIS AMOUNT

9.4% TAX 67.69

TOTAL 1769.54

TERMS ARE CASH UNLESS PRIOR ARRANGEMENTS ARE MADE

PAYMENT: CASH CHECK CHARGE DEBIT CARD CREDIT CARD

INTEREST WILL BE CHARGED AT A RATE OF 1 1/2% PER MONTH ON ACCOUNTS OVER 30 DAYS

THANK YOU

0131115

TED'S FOREIGN CAR

5524 Scotts Valley Dr., #13 • Scotts Valley, California 95066
 Phone (831) 438-3755
 BAR No. AE 078962 • Lic. No. EO 389147

REPAIR INVOICE

LABOR CHARGE PER HR \$120.00

QTY	* PART NO. & DESCRIPTION	AMOUNT
1	FACTORY OIL FILTER SERV-KIT.	29.95
	AIRCLENNER BOX LOCATOR GRAMMETS 5.00	
	WINTERGREEN CONCENTRATE CLEANER	M/C
	Customer Stock Parts	
	Note used to suffice job orig equip.	
	REPLACED PARTS REQUESTED BY CUSTOMER? <input type="checkbox"/> YES <input type="checkbox"/> NO	TOTAL PARTS \$34.95
	Clutch Job procedure EST COST AS FOLLOWS	
	Aircleaner Box Petro w/ Air Flow Meter 26.00	
	LABOR TOTAL SUBLET REPAIRS \$200.00	
	GALS. GAS @ =	TOTAL GAS, OIL & GREASE
	5-400 OIL SYNTHETIC	
	LBS. GREASE @ =	16 100.90
	FOLLOWING REPAIRS RECOMMENDED	
	SEVERE F STROKELY RECOM REBATTMENT	
	of Stack Air Cleaner Box and	
	Accompanying	
	I BELIEVE YOUR AIR FLOW METER DEVICE !!	
	HAS BEEN COM POINTS IN THIS CASE !!	

NAME: [REDACTED] DATE: NOV 20 2010

PH. WHEN READ, WRITTEN BY: [REDACTED] MILEAGE: 024350 LIC PLATE # 5EHD368

YES NO YR / MAKE / MODEL: 02 PORSCHE 996.C.C.2 G.V.W.R. MOTOR #

V.I.N. WPOA1A299325621349366 CUST. PO# 3.6 COUPE

OPR. # [REDACTED] REPAIR ORDER • DESCRIPTION OF LABOR: S/R

Trouble shoot. MOISTURE CONTAMINATION CAUSING OF
 Drivability Problems, NOTE RECOVERY SHOULD
 Vehicle feels as if its running out of fuel. Repeat
 READ-OUT trouble codes. OVER VEHICLE FIELDS
 P.S.P. REPORTS MISFIRESES RECORDED CYLINDER # 1 3 5
 C/C CRANK POSITION SENSOR CONDITION. P.P. REPORTS
 SENSOR IS COATED IN A OIL LAKE @ REAR CRANK SEN
 AREA as abt'd fall out oil containing exp'd
 Customer knows clutch job LABOR IS EST of Cost.
 REMOVE AT MKT. MR. INT. SYSTEM SERVICE OPERATE
 INCIDENTLY Thru view as a GATEWAY ON 02 - 05 AIR BOX SYST
 LAST OIL SRV MAR 2010 - 19 K miles the Note.
 ORIGINAL OIL COVER WAS MORE STICKY AS PERSON FAX EMAIL

DATE: TIME: PHONE# FAX# EMAIL: BY PHONE EMAIL FAX

ESTIMATE \$ ADD'L COSTS \$

REASON: X

THEIRBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIALS. YOU AND YOUR EMPLOYEES MAY OPERATE ABOVE VEHICLE FOR THE AMOUNT OF REPAIRS THEREO. YOU WILL NOT BE HELD RESPONSIBLE FOR LOSS OF DAMAGE TO VEHICLE OR ARTICLES THEREON IN CASE OF FIRE, THEFT, ACCIDENT, DYNAMOMETER TESTING OR ANY OTHER CAUSE BEYOND YOUR CONTROL. IN THE EVENT OF A CLAIM, YOU WILL BE NECESSARY TO ENFORCE THIS CONTRACT. I UNDERSTAND THAT I AM SOLELY RESPONSIBLE FOR ALL COSTS INCLUDING LABOR FEES AND COURT COSTS. I HAVE READ AND UNDERSTAND THE ABOVE AND ACKNOWLEDGE RECEIPT OF AN ESTIMATE. SIGNATURE OF CUSTOMER: BY LAW YOU MAY CHOOSE ANOTHER SMOG CHECK STATION TO PERFORM ANY REPAIRS, INSTALLATIONS, ADJUSTMENTS OR SUBSEQUENT TESTS.

REVISSED \$ REASON: X

DATE: TIME: PHONE# FAX# EMAIL: AUTH. BY REC'D BY

I ACKNOWLEDGE NOTICE AND APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE. AUTH. BY REC'D BY

REVISSED \$ REASON: X

DATE: TIME: PHONE# FAX# EMAIL: AUTH. BY REC'D BY

I ACKNOWLEDGE NOTICE AND APPROVAL OF AN INCREASE IN THE REVISED ESTIMATED PRICE. AUTH. BY REC'D BY

REVISSED \$ REASON: X

DATE: TIME: PHONE# FAX# EMAIL: AUTH. BY REC'D BY

ESTIMATE \$ ADD'L COSTS \$

SUBTOTAL 665.80

TAX 9 1/2 % 12.57

PLEASE PAY THIS AMOUNT \$ 678.42

PAYMENT: CASH CHECK CHARGE DEBIT CARD CREDIT CARD

INTEREST WILL BE CHARGED AT A RATE OF 1 1/2% PER MONTH ON ACCOUNTS OVER 30 DAYS

THANK YOU

TERMS ARE CASH UNLESS PRIOR ARRANGEMENTS ARE MADE

SMOG CHECK VEHICLE INSPECTION REPORT

(12/18/2009 @ 11:57:45 am)

Vehicle Information

Model Year.....	2002	Make.....	PORSCHE	Model.....	911 CARRERA
License.....	5EHD368	State.....	California	VIN.....	WP0AA29932S621349
Engine Size.....	3.6 Liters	Type.....	Passenger	Transmission.....	Manual
GVWR.....	N/A	Test Weight.....	N/A	Cylinders.....	6
Odometer.....	18626	Certification.....	California	VLT Record #.....	45323
Fuel Type.....	Gasoline	Exhaust.....	Dual	Inspection Reason.....	Biennial
Engine Year.....	N/A	Engine Make.....	N/A	Bar Number.....	N/A
Fleet BAR File #.....	N/A				

Overall Test Results

Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Visual Inspection..(Pass) Functional Check..(Pass) Emissions Test..(Pass)

DMV ID Number..(49590232N179)
Smog Check Certificate Number..(NO975033)

Your Smog Check certificate has been electronically transmitted to the DMV.
This certificate is valid for ninety (90) days from the date of issuance.

Please keep this copy for your records.

Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist the identification of oxides of nitrogen, crankcase, and cold start emissions which are not measured during the idle tests)

<u>ECS</u>	<u>Result</u>	<u>ECS</u>	<u>Result</u>	<u>ECS</u>	<u>Result</u>
PCV.....	Pass	Fuel Evaporative Controls.....	Pass	Catalytic Converter.....	Pass
Spark Controls.....	Pass	Fuel Injection.....	Pass	Pump Air Injection.....	Pass
Oxygen Sensor.....	Pass	Wiring to Sensors.....	Pass	Vacuum lines sensors/switches..	Pass
Other related emis. components.	Pass	Liquid Fuel Leak.....	Pass	Fuel Cap Integrity Test.....	Pass
Fuel Cap Visual.....	Pass	Malfunction Indicator Light....	Pass	Ignition Timing.....	N/A
Fuel EVAP Test.....	Pass				

SMOG CHECK VEHICLE INSPECTION REPORT

(12/18/2009 @ 11:57:45 am)

Page # 2

VIN..... WP0AA29932S621349

License.. 5EHD368

Idle Emission Test Results

Test	RPM	%CO2	%O2	HC (PPM)			CO (%)			Result
	MEAS	MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	
M1: 0 MPH	704	10.7	6.0	100	17	0	1.00	0.00	0.00	Pass
M2: 0 MPH	2601	12.9	3.1	130	12	2	1.00	0.10	0.00	Pass

MAX = Maximum Allowed Emissions AVE = Average Emissions For Passing Vehicles MEAS = Amount Measured

Smog Check Station Information

LARRYS AUTO CARE
5346 SCOTTS VALLEY DR
SCOTTS VALLEY, CA 95066
1 831 438 2080

Technician Name/Number..... MARZAN, BEN/EB136093
Repair Tech Name/Number..... N/A
Software Version/EIS Number... 0311/SX050257
Station Number..... RM151041

I certify under the penalty of perjury under the laws of the State of California, That I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and correct.

12/18/09

Date

Benz

Technician's Signature