





# PERFORMANCE YOU CAN COUNT ON.

## THE CAR CLINIC

Dependable Service with a Personal Touch  
 2216 - F Cemo Circle, Rancho Cordova, CA 95670  
 (916) 638-8290 • EPA # CAD 982341653 • BAR # AM 106598

DATE: 12/12/14  
 WRITTEN BY: [Signature]  
 PHONE: [ ]  
 READY: [ ]  
 RESIDENCE: [ ]  
 BUSINESS: [ ]  
 DELIVER: [ ]

TIME RECEIVED: [ ] NAME: [Redacted]  
 TIME PROMISED: [ ] ADDRESS: [Redacted]  
 CITY: Davis LICENSE: CA 95218  
 STATE: CA JIP CODE: 95218  
 YEAR: 67 MAKE: MATI LICENSE: 4YBSA32  
 MODEL: 8045272 MOTOR NUMBER: 65369  
 SERIAL NUMBER: [Redacted]

I hereby authorize the repair work to be done along with the necessary materials. You and your employees may operate vehicle for purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, or accident or any other cause beyond your control unless prior arrangements have been made. Vehicles not picked up promptly after completion of work will be subject to storage charges.

SIGNED: [Signature] X  
 TERMS CASH UNLESS ARRANGEMENTS MADE PRIOR TO AUTHORIZATION.  
 REPAIR ORDER - LABOR INSTRUCTION

QUAN.	PART NO. OR DESCRIPTION	AMOUNT
1 M	272-273 REAR LOWER BALL JOINT	619.95
1 M	433-725 H.I.D. BULB	60.95
1 M	460-365 SET HOCKER SHOCK STRUTS	35.95
1 M	235-940 SPAN-ON DRIVE BELT	34.95
1 M	466-516 SHIM ON DR. HUB	4.95
1 M	376-180 S/S CR. BRIDGE BUSH	111.90
1 M	360-420 HESTER DRIVE	24.95
1 M	434-840 2 BRAD. SHW	69.95
1 M	459-685 SHW THROTTLE	49.95
1 M	470-370 ROLLER BRIDGE WIRE	13.95
1 M	470-270 TOP BRAD. R. WIRE	5.95
1 M	434-070 WATERS HEAD	44.95
1 M	461-070 WATER PUMP	16.95
1 M	470-370 ROLLER BRIDGE WIRE	77.05
1 M	470-370 ROLLER BRIDGE WIRE	9.90
1 M	190-815 HD. CIRCUIT BREAKER	199.95
1 M	183-201 SPORTS COIL	37.95
1 M	171-689 COIL KIT SET	35.95
1 M	163-810 AIR FILTER	8.35
TOTAL PARTS		1352.15
TOTAL SUBLET REPAIRS		15.00
ESTIMATE AMOUNT - FOR PARTS AND LABOR		1507.15

QUAN.	PARTS	LABOR	TOTAL
✓	SCORPER 1 HT ELECTRONIC IGNITION, REBUILT		
✓	DIAGNOSTIC, WITH H.I.D. BOMB NEW HT WIRE		
✓	DISC BRAKE AND SUPPLY 2 FT NEW COILS COIL		152.50
✓	MODIFY FAN PULLEY TO FIT 2 BRAD. PASTIC SHW		85.50
✓	REPAIR WIRING, REPAIR EXHAUST MOUNT FITTED BY		
✓	SOMEONE ELSE ASSESS I AND CORRECTLY FITTED THE		
✓	PERFORMANCE EXHAUST SYSTEM WITH BRIDGESTONE		
✓	CHECK OIL INDEPENDENT HOLES - TEST HOLES		
✓	THEMSELVES, FINDING HANGERS CONNECTIONS CHECK		38.00
✓	FOR CONTINUITY UP STEERING COLUMN 2 DO LITERS 2		
✓	SLIT CHECK FLOW FOR DISCONNECTED WIRING		
✓	REMOVE OLE PANDA FROM DATA TO ALLOW STEERING		19.00
✓	STROD TO GET NEW 4000VW NEGATIVE GROUND SYSTEM		
TOTAL PARTS		295.00	
TOTAL LABOR		1352.15	
SUBLET REPAIRS		15.00	
HAZARDOUS WASTE FEE			
SUB TOTAL		1672.15	
SALES TAX		108.17	
TOTAL AMOUNT		1780.32	

WE RECOMMEND THE FOLLOWING REPAIRS:  
 ✓ \$1027.27 less bank check #491 3/5/15  
 ✓ TO COVER REMAINING OF INVOICES # 1 THRU 5  
 ✓ \$1000 ON THE US BANK # 688 3/4/15  
 ✓ \$2500 less bank check # 688 2/26/15  
 ✓ \$2500 CHECK 2/2/15  
 ✓ \$1000 CHECK 12/22/14

1177-1179 518 9022-1101



PERFORMANCE YOU CAN COUNT ON.  
**THE CAR CLINIC**

Dependable Service with a Personal Touch  
 2216 - F Cemo Circle, Rancho Cordova, CA 95670  
 (916) 638-8290 • EPA # CAD 982341653 • BAR # AM 106598

3

QUAN.	CODE	N-NEW	U-USED	R-RESULT	PART NO. OR DESCRIPTION	AMOUNT
1	N				222-460 W/BERG CRAB KIT	75.95
1	N				222-251 W/BERG SOFT-VALVE KIT	32.95
1	N				222-245 W/BERG AIR FILTER	91.75
1	N				865-230 SPARK PLUGS HERTH & PAUL	25.95
1	N				260-674 REPAIR KIT BUSHES & SPRINGS	199.95
1	N				230-385 KIT NO. 1010	399.95
1	N				151-805 HO DIR. ASSEMBLY	8.95
1	N				200-023 ELECTRONIC IGN. KIT	119.95
1	N				451-SIR WRITTEN CHECK ENGINE THERM	899.95
1	N				ALUM. IN PLE	70.00
1	N				100 RUSHINGS	22.90
1	N				FREZZE RINGS	12.60
1	N				521-525 HI-TORQUE IMMERSE	277.95
1	N				140-200 CONDENSER	138.95
1	N				6A SPARK PLUGS	192.96
1	N				38-900 MANIFOLD STUDS	6.40
1	N				180-715 CLUTCH RELEASE CYL	38.95
1	N				HYDRAULIC FLUID	8.40
1	N				TERMINATOR STUDS (328-605)	4.65
<b>TOTAL PARTS</b>						<b>2478.61</b>

QUAN.	CODE	SUBLET REPAIRS	AMOUNT
		SPARK PLUG HANDLING CHARGES	24.00
		WASHERS REFLUID & CLEAN	30.00
		70 NEGATIVE GROUND	200.60
		STEERING REBUILD	200.60
<b>TOTAL SUBLET REPAIRS</b>			<b>425.20</b>
<b>ESTIMATE AMOUNT - FOR PARTS AND LABOR</b>			<b>2901.61</b>
ADDITIONAL AMOUNT	DATE	TIME	DIRECT PHONE INITIAL
ADDITIONAL AMOUNT			
ADDITIONAL AMOUNT			
ADDITIONAL AMOUNT			
ADDITIONAL AMOUNT			
<b>ESTIMATE TOTAL</b>			<b>4127.89</b>

DATE: 12/12/14  
 WRITTEN BY: [Signature]  
 NAME: [Redacted]  
 ADDRESS: [Redacted]  
 CITY: DANVILLE, CA  
 LICENSE: 4488432  
 MOTOR NUMBER: [Redacted]  
 ODOMETER: 65369  
 ZIP CODE: 95618

TIME RECEIVED: [Redacted]  
 TIME PROMISED: [Redacted]

YEAR: 67 MAKE: H6  
 MODEL: ROADSTER

I hereby authorize the repair work to be done along with the necessary materials. You and your employees may operate vehicle for purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, or REPAIR ORDER LABOR INSTRUCTION

accident or any other cause beyond your control unless prior arrangements have been made. Vehicles not picked up promptly after completion of work will be subject to storage charges.

SIGNED: [Signature]  
 TITLE: CASH, UNLESS ARRANGEMENTS MADE PRIOR TO AUTHORIZATION

PHONE: [Redacted]  
 RESIDENCE: YES NO  
 BUSINESS: YES NO

DELIVER: YES NO

RETAIN PARTS FOR MY INSPECTION: YES NO

WE RECOMMEND THE FOLLOWING REPAIRS:

✓	REPLACE SPARK PLUGS & CHANGING OIL	86.50
✓	NEW ONE YEAR W/BLADE HOSE & WASHERS CYL FRIE DR	123.50
✓	DESIGN & MANUFACTURE NEW CRACKED HOSE	190.80
✓	LINKAGE COMPONENTS & INSTALL & ADJUST	
✓	REMOVE SPINDLER FOR SERVICE & RECONSTRUCT	
✓	FLY WHEEL & CONVERSION TO NEGATIVE GROUND	
✓	LEFT GRUBS AND REBUILD MOTOR TRANSMISSION	
✓	WIRING & SWITCH LIGHTS SPEED BRK	

TOTAL LABOR	AMOUNT
799.00	
PARTS	3478.61
SUBLET REPAIRS	24.00
HAZARDOUS WASTE FEE	
SUB TOTAL	3901.61
SALES TAX	228.28
<b>TOTAL AMOUNT</b>	<b>4129.89</b>







**PERFORMANCE YOU CAN COUNT ON.**  
**THE CAR CLINIC**

Dependable Service with a Personal Touch  
 2216 - F Cemo Circle, Rancho Cordova, CA 95670  
 (916) 638-8290 • EPA # CAD 982341653 • BAR # AM 106598

DATE: 2/19/15  
 WRITTEN BY: [Signature]

TIME RECEIVED	NAME	ADDRESS	CITY	STATE	ZIP CODE
AM			EL MERCADO	CA	95218
TIME PROMISED	MARKET	LICENSE	MOTOR NUMBER	ODOMETER	SERIAL NUMBER
AM	67	4YRS532		65269	
YEAR	MAKE	MODEL			
67	M6	REARSTEER			

I hereby authorize the repair work to be done along with the necessary materials. You and your employees may operate vehicle for purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, REPAIR ORDER-LABOR INSTRUCTION

accident or any other cause beyond your control unless prior arrangements have been made. Vehicles not picked up promptly after completion of work will be subject to storage charges.

SIGNED: [Signature]  RETAIN PARTS FOR MY INSPECTION

QUAN.	CODE	N-NEW	U-USED	R-RESULT	PART NO. OR DESCRIPTION	AMOUNT
					LA 62070 SHOCK ARMAT 700c.	34.95
					LA 65017 STEER0 axle	18.95
<b>TOTAL PARTS</b>						<b>53.90</b>
<b>TOTAL SUBLET REPAIRS</b>						<b>14.95</b>

ADDITIONAL AUTHORIZED AMOUNT	DATE	TIME	DIRECT PHONE	INITIAL	
<b>ESTIMATE TOTAL</b>					<b>453.16</b>

WE RECOMMEND THE FOLLOWING REPAIRS:	LABOR CHARGED
RESEARCH BODE HEIGHTS SHOCK STRINGS CHASMAN	190.00
TORS BAR 1 RODENT	
ROAD TEST APPROX 35 MILES @ 30/15	
RECHECK UNDERCARTH 3/31/15. FAND AIRLENS	
HAZARDS INSPECTION MISSING. REROUTE HORNETS	190.00
INSURANCE AS BEST POSSIBLE. ROAD TEST AGAIN & RETURN BODE HEIGHTS	
<b>TOTAL LABOR</b>	<b>380.00</b>
<b>PARTS</b>	<b>53.90</b>
<b>SUBLET REPAIRS</b>	<b>14.95</b>
<b>HAZARDOUS WASTE FEE</b>	
<b>SUB TOTAL</b>	<b>448.85</b>
<b>SALES TAX</b>	<b>4.31</b>
<b>TOTAL AMOUNT</b>	<b>453.16</b>

(5)











\*CODE N-NEW U-USED R-REUILT

QUAN.	PART NO. OR DESCRIPTION	AMOUNT
1	N 263-280 STR RACE BOOT	9.95
1	N 18 FUEZE ROLL	1.95
1	N 146.000 RACE LIGHT M11201	64.95
1	N 377.175 FUEZ REND	149.95
1	N 377.350 " " BATTERY	14.95
1	N 377.360 " " SERVICE	3.45
1	N 6180X AIR FUEL PUMP	
1	N 12.400 FUEZ GASKET O-RING	1.65
1	N 296.100 " "	0.75
1	N 242.652 CARBURETOR TOP	53.45
<b>TOTAL PARTS</b>		
<b>SUBLET REPAIRS</b>		
	SHIPPING & HANDLING ON PARTS	15.90
<b>TOTAL SUBLET REPAIRS</b>		
<b>ESTIMATE AMOUNT - FOR PARTS AND LABOR</b>		\$ 530.00
<b>ESTIMATE TOTAL</b>		

**PERFORMANCE YOU CAN COUNT ON.**

**THE CAR CLINIC**

Dependable Service with a Personal Touch  
 2216 - F Cemo Circle, Rancho Cordova, CA 95670  
 (916) 638-8290 • EPA # CAD 982341653 • BAR # AM 106598

DATE 12/17/15  
 WRITTEN BY [Signature]

NAME [Redacted]  
 ADDRESS [Redacted]  
 CITY DANIS  
 LICENSE 4Y45432  
 MOTOR NUMBER [Redacted]  
 SERIAL NUMBER 64153  
 ODOMETER 64253  
 ZIP CODE 95618  
 TIME RECEIVED [Redacted]  
 TIME PROMISED [Redacted]  
 NAME [Redacted]  
 ADDRESS [Redacted]  
 CITY DANIS  
 LICENSE 4Y45432  
 MOTOR NUMBER [Redacted]  
 SERIAL NUMBER 64153  
 ODOMETER 64253  
 ZIP CODE 95618

I hereby authorize the repair work to be done along with the necessary materials. You and your employees may operate vehicle for purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, or accident or any other cause beyond your control unless prior arrangements have been made. Vehicles not picked up promptly after completion of work will be subject to storage charges.

SIGNED X [Signature]  
 TITLE CASH: UNLESS ARRANGEMENTS MADE PRIOR TO AUTHORIZATION.

REPAIR ORDER/LABOR INSTRUCTION	LABOR CHARGED
✓ SUPPLY 9 FT NEW 24 STEERING RACE BOOT	57.00
✓ SUPPLY 9 FT NEW 24 CENTRE FUEZE ROLL	95.00
✓ SUPPLY 9 FT NEW RACE LIGHT SWITCH	38.00
✓ SUPPLY 9 FT NEW OF FUEZ REND 9 BATTERY	95.00
✓ REPLACE CENTRE FUEZ ROLL RACE GASKET 9 O-RING 47.50	

WE RECOMMEND THE FOLLOWING REPAIRS:

TOTAL LABOR	TOTAL PARTS	SUBLET REPAIRS	HAZARDOUS WASTE FEE	SUB TOTAL	SALTS TAX	TOTAL AMOUNT
332.50	802.55	15.90		1150.95	64.20	1215.15

FINANCE = \$715.15 PAID PARTS & US BANK CHECK  
 PAID \$500 ON THE US BANK CHECK # 499 12/16/15

EX-108

2