# 1964 Studebaker

## Gran Turismo Hawk



VIN: 64V7910



Scan or visit verify.add123.com to verify

Verification Code: B7RGCJJ

#### National Title History / Title Pointer (NMVTIS)

Retrieved On: Thu August 29, 2024 07:36:40 PM EDT

Reference ID: 1964 Studebaker Hawk GT

Vehicle Information

VIN: 64V7910

Vehicle Brands

No brand information found in NMVTIS

Title Information

Title: California 10/07/2020 000039306 Miles

Junk/Salvage/Insurance Reporting

No Junk/Salvage Reports

No Insurance Reports

Explanatory Note:

If this VIN has a record in the Junk/Salvage or Insurance information then the business that submitted the VIN to NMVTIS deemed the vehicle to be either a junk, salvage, or in the case of an insurer, a total loss. The information in the DISPOSITION field in the Junk/Salvage section denotes what has happened to the VIN (i.e., vehicle) since it came into the possession of the business.

Brand, Title and Junk/Salvage Insurance Reporting Information provided from the National Motor Vehicle Title Information System (NMVTIS).

View the NMVTIS disclaimer at https://www.add123.com/nmvtisdisclaimer

Auto Data Direct is an Approved NMVTIS Data Provider.

#### Lien / Theft Data

Retrieved On: Thu August 29, 2024 07:36:41 PM EDT

Vehicle Information

VIN: 64V7910

#### Lien/Theft Record Not Found

Lien data does not include information on all motor vehicles in the United States because not all lienholders provide information to the source of this lien data.

Lien / Theft data is restricted to business use only and cannot be distributed to the general consumer.

© 2000-2024 Auto Data Direct, Inc. (850) 877-8804

AUTOMOBILE  VEHICLE ID NUMBER  LHV7910  BODY TYPE MODEL  2D  MOTORCYCLE ENGINE NUMBER  REGISTERED OWNERS.	YR 1ST SOLD CLASS "YR FH" 2020	ACTUAL MALL	10/08/2021 BER
The odometer now reads	x  res that you state the mileage up fines and/or imprisonment.  (no tellowing statements is checked. Mi	SIGNATURE OF REGISTERED OWNE SIGNATURE OF REGISTERED OWNE on transfer of ownership. Fail	Rure to complete or providing a
I certify (or declare) under p	ading is not the actual mileage.   Mileage Mil	f the State of California that th	ne foregoing is true and correct.
Any change of Lienholder 10 days.  LIENHOLDER(S)	IMPORTANT RE (holder of security interest) must	2. X Signature releases i names must be cou	nterest in vehicle. (Company

Missums only TRUMBULL Frescher only TRUMBULL

1884E DATE 03/20/2015

IDEATIFICATION NUMBER 6447910

FURCHASS PRICE

HILEAGE 39,212

MAKE DESCRIPTION STUDEBAKER SUDVIVE NODE NODEL DESCRIPTION 2D HAWK

\$13.50 MESSAR ACTUAL EXIDENCE OH 7802007182

图4的(8)

CONVESTION

DOMES.

340 CORTLAND, OH 44410

PREMICUS OWNER

a Khan

CORTLAND: OH 44410

LIEN DISCHARGE

Lienholder

Authorized signature

CLERK LIEN CANCELLATION

Deputy Clerk

LIEN DISCHARGE

Lienholder

Authorized signature CLERK LIEN CANCELLATION

Deputy Cierk

date

WITNESS MY HAND AND OFFICIAL SEAL THIS 20th DAY OF MARCH, 2015 125234804 (SEAL)

date

date

%125234804

KAREN INFANTE ALLEN CLERK OF COURTS

DO NOT ACCEPT TITLE SHOWING ANY ERASURES, ALTERATIONS OR MUTILATIONS

BMV 3800 Rev. 3/12

#### Studebaker costs

1785. 00 Jim July 2023

364.50. Studebaker International. 8/2023

1090.42. Vaughans Transmission. 11/2023

1993.17. Vaughan's Transmission 02/2024

1415.74. Vintage Air Nov. 2021

14,068.19. TriStar Auto. Oct 2020

18,137.70. Vaughan's Transmission. 5/2022

370.00. Robert Blade's Classic Car Services 5/2021

420.00. Robert Blade 7/2021

2784.54. Pete's Automotive 7/2021

2100.00 Guardian Auto Transport Sept 22, 2020

23,000. 1. Initial purchase 9/21/2020

2466.00. Local Heroes Auto Care. Dept of Motor Vehicles 10/2020

600.00 est. (Lost receipt). 2024 Stephen Allen LLC gas tank, sender

43K =/- invested in repairs and upgrades

27.5K=/-invested in purchase, transport, and Ca registration

#### **Vaughans Transmission**

1026 Petaluma Hill Rd Santa Rosa, CA. 95404

Phone: 707-544-2460

#### INVOICE

4190

Org. Est. # 004600 BAR# ARD00260667 EPA# CAL000466519

#### INVOICE

Printed Date: 02/10/2024

Work Completed: 02/08/2024

1964 Studebaker - Hawk - 289 V8 Lic #: 8TCY664

WITH THE REPAIR

INSPECTION OF RADIO ASSEMBLY AND

INCLUDING ANTENNA ASSEMBLY

INSTALLATION OF NEW WIRING HARNESS

Odometer In: 40292

Sebastopol. CA 95472				210 # . 0101004	Odometer in: 40292
Home 7				VIN # . 04V7040	Odometer Out: 40310
				VIN # : 64V7910	
Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
STUDEBAKER GAUGES SET 883298036.10185	1.00	835.94	835.94	CUSTOMER STATES THE HEATE PROPERLY	R DOES NOT OPERATE
ANTENNA ASSEMBLY OY-UT10	1.00	35.18	35.18	THE DEFROSTER DOES NOT OP	
PCV VALVE GROMMET  MTM-42066	1.00	6.82	6.82	-UPON REMOVAL OF THE DASH OF BLOWER MOTOR HOSE TO HAVE AND NOT SENDING HOT AIR TO HEATER VENTS PROPERLY	E BECOME DISCONNECTED
				CUSTOMER STATES THERE IS A DASH -WE FOUND THE SPEEDOMETER -WE WILL OIL THE GEAR WHILE I	R GEAR TO SQUEAK
				CUSTOMER STATES HE WANTS TAMP GAUGE, FUEL GAUGE AND GAUGE REPLACED. CONTACTED CUSTOMER AT 9:53 EXPLAINED THAT THE STEREO VI WOULD NEED TO BE REPAIRED IS OPERABLE. CUSTOMER AGREED AND GAVE	THE WATER TEMPERATURE  AM ON 1/31/24 AND VIRING HARNESS IS CUT AND TO FIND OUT IF THE STEREO

REPLACEMENT OF INSTRUMENT CLUSTER GAUGES AND REPAIR OF HEATER BLOWER MOTOR HOSE	740.00
FUEL CHARGE	16.52

Org. Estimate 1,993.17 Revisions 0.00 **Current Estimate** 1,993.17

Labor: 1,017.50 Parts: 877.94 Sublet: 16.52 SubTotal: 1,911.96 Tax: 81.21 Total: 1,993.17

277.50

[ Payments - Check (#3580) - \$1,993.17 ]

Vehicle Received: 2/8/2024

Signature

Customer Number: 1324

\$0.00

Local warranty work has to be performed in our shop. Local warranty work is only valid if customer returns in 1-2 weeks for a follow up inspection or 200 miles of original repair work. Out of city shop repairs have to be authorized by original shop before work is performed and emailed written approval is required.

Visit us on the web: www.vaughanstransmission.com

Email Address: vaughans60@yahoo.com

Date

Bal Due:

#### **Vaughans Transmission**

1026 Petaluma Hill Rd Santa Rosa, CA. 95404

Phone: 707-544-2460

#### INVOICE

4078

Org. Est. # 004490 BAR# ARD00260667 EPA# CAL000466519

#### INVOICE

Printed Date: 11/24/2023

Work Completed: 11/22/2023

1

1964 Studebaker - Hawk - 289 V8

Odometer In: 40220

Sebastopol. CA 95472 Home 7\_.\_\_\_.

Lic #: 8TCY664

Odometer Out: 40261

VIN # : 64V7910

				VIII # . 64V/910	
Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
VALVE COVER GASKET SET HS7669S2	1.00	171.92		INSTALLATION OF CUSTOMER SUPPLIED VALVE COVERS INCLUDING RELOCATION OF BRAKE	740.00
ENGINE OIL 20W-50 ( PER QAURT )		POOSTED			
INVENTORY			37.00	RE ADJUSMENT OF SHIFT LINKAGE FOR PROPER PARK ENGAGEMENT	n/c
				FUEL CHARGE	20.00
				RE TORQUE OF ALL GASKETS FOR ANY LEAKS WE HAVE SEEN	n/c
				THE ENGINE OIL PRESSURE GAUGE AND FUEL LEVE NEED REPLACEMENT IN THE DASH	L GAUGE
				ENGINE OIL SERVICE	40.00
				REPLACEMENT OF CUSTOMER SUPPLIED FUEL LEVEL SENDING UNIT AND GAS TANK	555.00
				[ Discount ] \$209.42 off parts, \$284.58 off labor	
				Hazardous Materials Disposal	20.00

Org. Estimate 1,375.00 Revisions 0.00 Current Estimate 1,375.00

Parts: 209.42 Sublet: 20.00 HazMat: 20.00 Discount: -494.00SubTotal: 1,090.42 Tax: 0.00 Total: 1,090.42 Bal Due:

Labor:

\$0.00

1,335.00

[ Payments - Visa - \$1,090.42 ]

Vehicle Received: 11/22/2023

Signature

Customer Number: 1324

Local warranty work has to be performed in our shop. Local warranty work is only valid if customer returns in 1-2 weeks for a follow up inspection or 200 miles of original repair work. Out of city shop repairs have to be authorized by original shop before work is performed and emailed written approval is required.

Visit us on the web: www.vaughanstransmission.com

Email Address: vaughans60@yahoo.com



## Invoice

Date	Invoice number
8/2/2023	71248

111 Aiken St Hope, IN 47246

www.studebaker-intl.com

0910212023
0810

Phone: 317-462-3124

		4000	inci ii iti.c	Offi	U.D.		Fax	: 317-462-88	91			
Bill To						Sł	ір То					
Sebastopol, C	A 9547	<sup>7</sup> 2	-			N 13! Seba	stopol, C	A 95472				
S.O. No. P.O. No. or Vehicle info.							-	Terms	Salespe	rson	Custo	mer number
66104		64 Hawk						NET0	Lean	n		859138
Qty Ord	Item	no.	shipped	B/O'd	Description	n		Unit \$	U/M	S.	O. #	Extended \$

					1 1				100000000000000000000000000000000000000		
66104				64 Hawk			NET0	Lean	n		859138
Qty Ord	Item i	no.	shipped	B/O'd	Description	1	Unit \$	U/M	S.	O. #	Extended \$
1	801459 UPS Gr		1	0	finned rocker cover w/br <ld> UPS ground shipping, tra 1Z02E73W0358264288</ld>		330.00 34.50		2	66104	330.00 34.50

		e e e e				
			Subtota	ıl		\$364.50
			Sales T	ах (7.0	0%)	\$0.00
		,	Total			\$364.50
Your easy ordering custom	Paymer	its/Cre	dits	-\$364.50		
THANK YOU for your bu	Balan	ce D	ue	\$0.00		

	NAME ADDRESS	γ	PHOME ~~ '
	CITY, STATE, ZIP		
MATERIAL: ALL PARTS NEW UNLESS SPECIFIED: U-USED, R-REBUILT, RC-RECONDITIONED  OTY, PART NO. NAME OF PART PRICE WARRANTY	2ND AUTHORIZED NAME		PHONE
UIY. PART NO. NAME OF PART PRICE WARRANTY Y/N		CUSTOMER'S INFORMAT	ION
PS WINDOW RR.		.M. CUSTOMER'S ORDER NO. M.	PROMISED (DATE & TIME) A.M. P.M.
FROM BOMDER TIGHTEN	LICENSE NO.	ODOMETER	SERIAL #/VIN MOTOR # WRITTEN BY
DC HEAD WELL DIN SINDS	LUBE OIL CHA		DIFF. WASH POLISH
DS COPPE MILL CIUS	CHARGE FOR HAZ	ZARDOUS OR OTHER WAS	ΓΕ REMOVAL*
ROST SIF CAD		N120 10	
NSTAL ROCKED PAIRES		JAP 10	00
AJUGO PAN TIRAN	METHOD OF PAYMENT:	Daily Change for the	
MECHANICS RECOMMENDATIONS	CHECK CHARGE	Daily Storage fee after repair work has been completed and customer has been notified. No charges shall accrue or be due and payable of period of 3 working days from date of not light 1.	LABOR ONLY
	LABOR  FLAT RATE HOURLY	GUARANTEED ITEM(S)	GAS, OL & GREASE
LEASE READ CAREFULLY, CHECK ONE OF THE STATEMENTS BELOW, AND SIGN:		GUARANTEE EFFECTIVE UNTIL: TIME	SUBLET REPAIRS
HIM DERCHAND THAT THADED CTATE TAIM I WAS CUITED TALL MOITTEN FORMATE.	/	MILEAGE	STORAGE FEE
I REQUEST A WRITTEN ESTIMATE. THE FINAL BILL MAY NOT EXCEED THIS ESTIMATE WITHOUT MY WRITTEN APPROVAL.		you agree otherwise by initialing the following:	placed, except those for which there is a core charge, unless I do not desire the return of any of the parts that are
I DO NOT REQUEST A WRITTEN ESTIMATE, AS LONG AS THE REPAIR COSTS DO I  S THE SHOP MAY NOT EXCEED THIS AMOUNT WITHOUT MY W  I DO NOT REQUEST A WRITTEN ESTIMATE.	NOT EXCEED RITTEN OR ORAL APPROV	AL. the above repairs, along with any necessary may vehicle for the purpose of testing, inspection, an acknowledged on the above vehicle to secure the	damage caused by theft, fire, or acts of nature. I authorize aterials. I authorize you and your employees to operate my didelivery at my risk. An express mechanic's lien is hereby amount of the renairs begin to their
Checked lines apply (Preparer must check at least one):  This charge represents costs and profits to the motor vehicle repair facility for miscellaneous sho	p supplies or waste disposal.	SIGNED , v	sembly ite(of \$ will be applied.
This amount includes a charge of \$, which is required under	law.	DATE JULY 19	J 2025 GT3870 09-11

#### **Vaughans Transmission**

1026 Petaluma Hill Rd Santa Rosa, CA. 95404

Phone: 707-544-2460 Fax: 707-526-0683

#### INVOICE

3299

Org. Est. # 003305 BAR# ARD00260667 EPA# CAL000376242

#### INVOICE

Sebastopol, CA 95472

Printed Date: 05/05/2022

Work Completed: 05/05/2022

1964 Studebaker - Hawk - 289 V8 Lic#: 8TCY664

Odometer In: 39590

Odometer Out: 39639

Gebasiopol, CA 90412				Odometer	Out: 39639
Home :				VIN # : 64V7910	
Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
EVANS PERFORMANCE INTAKE MANIFOLD NEW	1.00	695.40	695.40	Customer typed up list of things requesting to be done. P notes attached to check in sheet. PRICING IS SUBJECT TO CHANGE DUE LABOR CHAINEEDED MATERIALS	
4 BARREL EDELBROCK 500 CFM CARBURETOR NEW	1.00	547.20	547.20	DISASSEMBLY AND RE-ASSEMBLY OF ENGINE COMPLETE	2,000.00
SMALL CAP HEI DISTRIBUTOR WITH 50K COIL NEW	1.00	247.00	247.00	REBUILD OF FLIGHT-O-MATIC TRANSMISSION ASSEMBLY COMPLETE	1,600.00
OFFENHAUSER FINNED VALVE COVERS	1.00	494.00	494.00	REMOVAL AND INSTALLATION OF ENGINE AND TRANSMISSION ASSEMBLY INSTALLATION OF CUSTOMER SUPPLIED VINTAGE	1,680.00
NEW				AIR ASSEMBLY	2,300.00
THERMOSTAT (160) NEW	1.00	11.40	11.40	CLEAN AND PAINT OF ENGINE COMPARTMENT  MACHINE WORK INCLUDING INSTALLATION OF	800.00
SPARK PLUG SET	8.00	5.32	42.56	CAM BEARINGS, BORE OF ENGINE IF NECESSARY, REBUILD OF HEADS, AND BALANCE OF ENGINE	2,300.00
DUAL IN LINE FUEL FILTER SET	1.00	12.20	12.20	CRIMPING OF A/C LINES	145.00
NEW	1.00	13.30	13.30	FUEL CHARGE	80.00
BUILD-ABLE IGNITION WIRE SET NEW	1.00	167.20	167.20	INSTALLATION OF AUXILIARY FAN FOR A/C SYSTEM Hazardous Materials Disposal	320.00 20.00
FLIGHT-O-MATIC MASTER OVERHAUL KIT W/ BANDS NEW	1.00	653.60	653.60		
ENGINE COOLANT	2.00	19.00	38.00	YD#	
THERMOSTAT OUTLET	1.00	41.80	41.80	3505	
BRAKE LINE <i>NEW</i>	1.00	22.80	22.80	3303	
THROTTLE RETURN SPRING KIT NEW	1.00	15.20	15.20		
RADIATOR HOSE ADAPTOR NEW	1.00	85.50	85.50		
AUXILIARY FAN A/C <i>NEW</i>	1.00	188.10	188.10		
PAINLESS PERFORMANCE HARNESS NEW	1.00	81.70	81.70		
SHIFTER LAMP NEW	1.00	3.80	3.80		
EXHAUST PIPE GASKET	2.00	9.50	19.00		

#### Vaughans Transmission

1026 Petaluma Hill Rd Santa Rosa, CA. 95404

Phone: 707-544-2460 Fax: 707-526-0683

#### INVOICE

3299

Org. Est. # 003305 BAR# ARD00260667 EPA# CAL000376242

INVOICE Printed Date: 05/05/2022 Work Completed: 05/05/2022 1964 Studebaker - Hawk - 289 V8 Lic #: 8TCY664 Odometer In: 39590 Sebastopol, CA 95472 Odometer Out: 39639 Home 7L. \_\_\_\_ VIN #: 64V7910 Part Description / Number Qty Sale Ext **Labor Description** Ext COMPLETE ENGINE OVERHAUL 1.00 2,850.00 2,850.00 KIT INCLUDING RE-GROUND CAMSHAFT, COMPLETE BEARING SET, COMPLETE FREEZE PLUG SET, AND SILVOLITE HYPERUETECTIC PISTONS (SIZE DEPENDING ON DISASSEMBLY) NEW **Shop Supplies** 100.02

17,817.70 8,700.00 **Current Estimate** Org. Estimate 17,817.70 Revisions 0.00 Labor: Parts: 6,317.58 2,525.00 Sublet: 20.00 HazMat: 17,562.58 SubTotal: Tax: 575.12 18,137.70 Total: \$8,137.70 Bal Due: [ Payments - Check - \$10,000.00 ]

Vehicle Received: 5/5/2022

Customer Number: 1324

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. WARRANTY on parts and labor OF TRANSMISSION is YEAR(S) / ,000 MILES, WHICHEVER COMES FIRST. Warranty work has to be performed in our shop & cannot exceed the original cost of repair. WARRANTY WORK IS ONLY VALID IF CUSTOMER RETURNS IN 1-2 WEEKS FOR A FOLLOW UP INSPECTION.

shop a carnot exceed the original cost of repair. With the		
Signature	Date	

From: artc@vintageair.com @ Subject: Vintage Air Sales Quote 898924 Date: November 11, 2021 at 2:44 PM

To:

THANK YOU FOR YOUR INTEREST IN VINTAGE AIR, YOUR SALES QUOTE CONFIRMATION IS ATTACHED. PLEASE NOTE THIS QUOTE IS VALID FOR 30 DAYS.

ANY QUESTIONS OR TO PROCESS THIS QUOTE PLEASE CONTACT:

**ART CAVAZOS** 800-862-6658

X113



### Sales Quote

Order No: 898924 Order Date: 11/11/2021 Sales Person: AC Page: 1

18865 Goli St San Antonio, TX 78265 Phone: (800) 852-6658 Fax: (210) 654-3113 www.vintageair.com

Customer Phone Ship To: .....

Bill To: 103438 Ship To: 103438 SEBASTOPOL CA 95472 SEBASTOPOL, CA 95472

PAYMENTS TERMS PURCHASE ORDER NO REQUESTED DATE SHIPPED DATE CREDIT CARD 11/11 11/11/2021

F.O.B POINT SHIP VIA FREIGHT TERMS

VINTAGE AIR DOCK FedEx - FEDEX GROUND FREIGHT PREPAID & ADDED

The first control of the second party and the secon				QUANTITY		UNIT	
ITEM NO	DESCRIPTION	UNIT	ORDERED	SHIPPED	B/O	PRICE	EXT PRICE
674013	HERITAGE BRUSHED EVAP KIT HEAT/COOL	EA	1 00	0.00		400 00	400.00
047000-SUR	SANDEN 6630 REAR EXIT COMPRESSOR 134A	EA	1 00	0.00		199 00	199.00
151593-SSA	STUDEBAKER 259-289 V8 W/PS COMP BRKT W/PULLEY	EA	1 00	0.00		299 00	299.00
547000	EXTENDED LENGTH HOSE KIT WIDRIER	EA	1 00	0.00		139 00	139.00
386600-MBA	STRM 4 WAY INLINE SKHD #5-#10	EA	1 00	0.00		65 00	65.00
35704-VUD	4 WAY BULKHEAD BL FITTING KIT/V	EA	1 00	0.00		35 00	35,00
03262-VUC	PARALLEL FLOW COND 14 X 22	EA	1 00	0.00		149.00	149.00
11079-VU5	MALE BINARY SWITCH	EA	1 00	0.00		17.95	17.95

A or 0 143 ordered 12/13

1415,74

Sub Total: \$1,303.95 All claims or returned goods must be accompanied by a return authorization number Freight:

\$149.90

#### PETE'S AUTOMOTIVE, INC. 6160 SEBASTOPOL AVE/HWY 12 SEBASTOPOL CA 95472

707.823.6020

BAR # ARD0023564

EPA # CAL0000111143

TODAY'S TECHNOLOGY, OLD FASHIONED HONESTY

WE APPRECIATE YOUR BUSINESS!! - REFERRALS ARE ALWAYS WELCOME!!

9/10/2021 11:12 AM

Invoice #41060

page 1

Day Phone

-fold here -

Vehicle

: 1964 Studebaker Gran Turismo Hawk 4.2 L 259 CID V8

Tag/State

: 8TCY664 / CA

Created: 7/19/2021 10:08:16 AM Complete: 9/10/2021 8:37:05 AM

Odometer In: 39417

Color

: Green

Qty

Invoiced : 9/10/2021 11:11:37 AM

Odometer Out: 39428

Reference CO

CHECK CUSTOMER CONCERN AND ADVISE

Condition Unit Price

Price \$205.25

CUSTOMER NOTES:

Code/Tech\*

1.GAS PROBLEM. ENGINE SPUTTERING==>> FUEL FILTER PLUGGED. REPLACED FILTER.

Description

2. ELECTRICAL PROBLEM, NO START AFTER SITTING==>> ALTERNATOR POWER LEADS LOOSE AND BURNED. REPAIRED CONNECTIONS AT ALTERNATOR AND STARTER RELAY. WARRANTEED BATTERY.

3. EBRAKE NOT WORKING, BRAKE PEDAL SOFT==>> ADJUSTED THE PARKING BRAKE. R&R OF HYDRA VAC AND SEND OUT FOR REBUILD. BLED BRAKE SYSTEM.

4. LEFT REAR TAILLIGHT BULB, SOCKET DOES NOT HOLD BULB==>> BULB CONTACTS TO SHORT, NEW BULB FIXED

5. TRANSMISSION LINKAGE. SHIFT MECHANISM DOES NOT ENGAGE PARK EASILY==>> TRANSMISSION IS NOT SHIFTING CORRECTLY AND THERE IS A HIGH PITCHED SQUEAL WHEN SHIFTING FROM 1ST TO 2ND. RECOMMEND TRANSMISSION SHOP

6. RIGHT SIDE WINDOW PROBLEM==>> FOUND WINDOW IS OFF THE TRACK. R&R DOOR PANEL AND RE-ATTACHED REGULATOR TO TRACK. CLEANED AND LUBED TRACK AND RUN CHANNEL

7. DRIVER SIDE DOOR DOESN'T CLOSE EASILY ==>> LUBED DOOR LATCH AND HINGES, OKAY NOW.

8. EXHAUST PIPE BUSHING NEED ATTENTION? NO, GOOD AT THIS TIME.

9. TRUNK LOCK HARD TO OPEN ==>> LUBED THE LATCH.

10. HORN WORKS INTERMITTENTLY==>> HORNS FOUND TO BE IN-OPERATIVE. RECOMMEND NEW HORNS.

11. ARE BRAKE LINES TOO CLOSE TO EXHAUST? THEY ARE NOT.

12. RUNS HOT IN TRAFFIC==>> RECOMMEND THERMOSTAT TO START.

\*\*\*NOTE GAS GAUGE IS IN-OP.



#### PETE'S AUTOMOTIVE, INC 6160 SEBASTOPOL AVE/HWY 12

#### SEBASTOPOL CA 95472

707.823.6020

BAR # ARD0023564

EPA # CAL0000111143

TODAY'S TECHNOLOGY, OLD FASHIONED HONESTY
WE APPRECIATE YOUR BUSINESS!! - REFERRALS ARE ALMANS.

	2021 11:12					pag
/ehic	de · 1964	Studeboker Cree	Invoice #41060			
Qty	Code/Tech*	Reference	Turismo Hawk 4.2 L 259 CID V8			
<del>- Cty</del>	Odder recir	Reference	Description	Condition	Unit Price	Price
					- Control of the Cont	-
	*					
		co	FUEL FILTER, R&R			
1	FIL	3032	Fuel Filter (Gold)			\$95.78
4		CLAMPS	Hose Clamp	1212	\$9.49	\$9.49
		CO	ALTERNATOR WIRING REPAIR	New	\$1.69	\$6.76
		IBAT	INSTALL NEW BATTERY			\$136.83
1	BAT	9834				\$68.42
1	-	CORE	Battery - NAPA Legend 75 Month 12 Volts Group 34 Core Charge		\$0.00	\$0.00
1	-	CBT	California Battery Tax		\$0.00	\$0.00
1.7		CO	HYDROVAC, R&R FOR SUBLET REBUILD		\$1.00	\$1.00
1	-	379900	Bendix Hydro Vac Brake Unit - Rebuild			\$205.25
4	NBH	H1450	Power Brake Vacuum Hose 11/32"		\$535.50	\$535.50
2	-	56	Bolt		\$2.54	\$10.16
_		CO	BLEED BRAKE SYSTEM		\$0.86	\$1.72
1		BF-1	BRAKE FLUID DOT 4			\$136.83
2	CRC	BRAKE CLEAN		New	\$8.84	\$8.84
2	ONO	CO	BRAKE/PARTS CLEANER ADJUST PARKING BRAKE	New	\$7.76	\$15.52
		CO	INSTALL STOP LIGHT SWITCH			\$136.83
1	ECH	SL134	Application of the control of the co			\$41.05
	LON	CO	Stoplight Switch		\$16.99	\$16.99
1	LMP	1157	LEFT REAR TAILLIGHT BULB, R&R			\$41.05
	LIVIT	CO	Stoplight Bulb		\$2.20	\$2.20
		CO	RIGHT SIDE WINDOW DISASSEMBLE AND REPAIR			\$342.08
	PADIATOR		INSTALL NEW THERMOSTAT FOR OVERHEATING			\$136.83
	***INCLUDES	MAKING A GASKET	ERATURE TOP TO BOTTOM INDICATING A FAILING TH TAND PRESSURE TESTING FOR LEAKS.	IERMOSTAT.		
1	THM	70	Thermostat - Standard - Alternate Temp		640.00	040.00
1	THM	STM1	Thermostat Housing Gasket		\$10.99	\$10.99
•		CO	INSTALLED POINTS AND CONDENSER		\$1.96	\$1.96
1	ECH	CS729A				\$136.83
1	ECH	RR174	Contact Set (Points) - H/D Distributor Condenser		\$19.35	\$19.35
'	2011	CO	DIAGNOSE HORN PROBLEM		\$20.83	\$20.83
		CO	HORNS, R&R			\$68.42
1	ВК	7301056	Horn		000.00	\$164.20
1	BK				\$28.89	\$28.89
1	אט	7301057	Horn		\$29.59	\$29.59

TIRE PRESSURE CHECK **TPCN** 

N/A



#### PETE'S AUTOMOTIVE, INC 6160 SEBASTOPOL AVE/HWY 12

SEBASTOPOL CA 95472 707.823.6020

BAR # ARD0023564

EPA # CAL0000111143

TODAY'S TECHNOLOGY, OLD FASHIONED HONESTY

WE APPRECIATE YOUR BUSINESS!! - REFERRALS ARE ALWAYS WELCOME!!

7 1072	2021 11:12 /	_/1A1					page
	z amonata c			Invoice #410			
ehic		Studebaker G	Gran Turismo Hawk 4	.2 L 259 CID \	/8		
Qty	Code/Tech*	Reference	Description	W	Condition	Unit Price	Price
57		GAS	GAS			\$4.70	\$20.00
^=	8/31/21						
07	9/10/21	GAS	GAS			\$4.90	\$26.00
1		FREIGHT	FREIGHT CHARG	E		\$42.00	\$42.00
		CO	CHECK CUSTOM	ER CONCERN AND	ADVISE	ψ4 <b>2.00</b>	\$0.00
···	SANTA ROSA	ANSMISSION : A hYDRAMATIC A TRANSMISSIC	DON DN: SAM - 100				
			Labor	\$2,052.48	less discount : \$136.83		\$1,915.65
			Parts	\$456.67	less discount: \$273.38		\$183.29
			Sublet/Misc.				\$535.50
			HAZ MAT FEE				\$0.00
			Charges			AND WASHINGTON TO SERVICE OF THE PROPERTY OF T	\$89.00
			Sales Tax		Tax @ \$718.79 * 8.5000%	The state of the s	\$61.10
				Chec	ck# 3451 \$2,784.54 Pa	aid 🧦	\$2,784.54

Transco SikiAu -'NO

Warranty on new parts, to the original purchaser will not exceed the parts manufacturers warranty. Warranty on Labor of installation of New Parts will not exceed 24 months or 24,000 miles from the date of purchase shown above. We are not responsible for theft or damage to vehicles left here after repair work has been completed.

CUSTOMER SATISFACTION AND QUALITY WORKMANSHIP ARE OUR PRIMARY GOALS. If you are less than completely satisfied with our service, please contact us.

24 Month or 24,000 Mile Warranty, which ever comes first, on Repairs.



	A Company of the Comp	FOLLOWING REPAIRS RECOMMENDED	LBS. GREASE @ =	QTS. OIL @	☐ GALS. GAS @ =	TIRE PRESSURE INSPECTION DECLINED, REASON:	TIRE PRESSURE INSPECTION PERFORMED: LF RF	INITIAL TO AUTHORIZE SUBLET REPAIRS: TOTAL SUBLET REPAIRS			OUTSIDE-SUBLET REPAIRS	REPLACED PARTS REQUESTED BY CUSTOMER? [] YES [] NO TOTAL			6				W 12 10		5	TOWN TOWN	The state of the s			CARROL STAR	Nac Dude 10m	) amount		QTY * PART NO. & DESCRIPTION AMO
					TOTAL GAS, OIL & GREASE	INITIALS:	LR RR (psi)	REPAIRS				TOTAL PARTS								December 1						The same of the sa	000			AMOUNT
REASON	REVISED DATE	X NOW THE POST OF	I ACKNOWLEDGE NOTICE AND ORAL APPE	REASON	REVISED DATE		AND COURT COSTS, I HAVE READ AND UNDERST YOU MAY CHOOSE ANOTHER SMOG CHECK STAT	의 된 본	REBY AUTHORIZE THE	ORIGINAL DATE				(1) House	1	5 Ather		1 July 1	OPR.#	V.I.N.		YH / MAKE / MODEL	PH. WHEN READY WRITTEN BY	PHONE / E-MAIL	HSON OF MID	ADDRE	NAME	NO Warranty of Any Ki		4100 G
			5		(33)	1	ਰ≱	2011	100-1		5	1		17	1	-		4	1	-	-		1		0		2 3	25	ø	7 a im
	TIME PHONE# • FAX# • EMAIL	ONAL OF AN INCUENCE IN THE OUIGINAL COLINIALED	OVAL OF AN INCREASE IN THE ORIGINAL ESTIMATED		TIME		AND THE ABOVE AND ACKNOWLEDGE RECEIPT OF AN ESTIMA' TION TO PERFORM ANY REPAIRS, INSTALLATIONS, ADJUSTME	EHETO, YOU WILL NOT BEHELD HESPONSIBLE FOH LOSS OHD DYNAMOMETER TESTING OR ANY OTHER CAUSE BEYOND \ ACT, I UNDERSTAND THATTAM SOLELY RESPONSIBLE FOR AL	DE DONE ALONG WITH TH	TIME PHONE# • FAX# • EMAIL	1		***	500 AMA	, , , , , , , , , , , , , , , , , , , ,	JOSON POON	The second secon	THE DISTANCE AND A PLANCE AND A	REPAIR ORDER DESCRIPTION OF			@V.W.F	MILEAGE LIC. PL	,	220	/-		nd for Used (Code U) or Afferman	BAR No. ARD 256072	Classic Car Services ) Grove St. • Sonomo, CA 95/ Phone (707) 996-3901
	PHONE# • FAX# • EMAIL ☐ BY PHONE	3010.01	ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE. AUTH. BY REC'D BY	ADD'L COSTS \$			AND THE ABOVE AND ACKNOWLEDGE RECEIPT OF AN ESTIMATE. SMOG CHECK CUSTOMERS: BY LAW TION TO PERFORM ANY REPAIRS, INSTALLATIONS, ADJUSTMENTS OR SUBSEQUENT TESTS.	ELD HESPONSIBLE FOH LOSS OF DAN OR ANY OTHER CAUSE BEYOND YOU AM SOLELY RESPONSIBLE FOR ALL C	TO BE DONE ALONG WITH THE NECESSARY MATERIALS, YOU AND YOUR EMPLOYEES MAY OPERATE SPECTION OR DELIVERYAL MY RISK, AN EXPRESS MECHANIC'S LIEN IS ACKNOWLEDGED ON ABOVE	TIME PHONE# • FAX# • EMAIL D BY PHONE D EMAIL	-IMUDEL :			Nick DO		1 NODY SOUR CON	The state of the s	A SIGNATOR SOLD	MEPAIR ORDER DESCRIPTION OF LABOR	COST. PO		G.V.W.R. MOTOR#	MILEAGE LIC. PLATE #	TIME REC'D TIME PROM.	フトO / STATE ZIP		DATE 7-7-2	(Code U) or Affermarket	BAR No. ARD 256072	ic Car Services 31. • Sonomo, CA (707) 994-390

TERMS ARE CASH UNLESS PRIOR ARRANGEMENTS ARE MADE SEE IMPORTANT INFORMATION ON BACK

		Noock + WITTO When SOMING	LBS. GREASE @ =	QTS. OIL @	GALS. GAS @ = TOTAL GAS, OIL & GREASE	TIRE PRESSURE INSPECTION DECLINED, REASON: INITIALS:	THE PRESSURE INSPECTION PERFORMED: LF RF LR RR (psi)	NITIAL TO AUTHORIZE SUBLET REPAIRS: TOTAL SUBLET REPAIRS			OUTSIDE-SUBLET REPAIRS	REPLACED PARTS REQUESTED BY CUSTOMER? Q YES Q NO TOTAL PARTS			- RAM	100	1) mad 500 5 May 10 MSD 5452													Down John State of the state of				Y * PART NO. & DESCRIPTION AMOUNT	* CODE = N-NEW U-USED R-REBUILT O-OEM A-AFTERMARKET C-CUSTOMER SUPPLIED
I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE REVISED ESTIMATED PRICE. AUTH. BY REC'D BY		REVISED DATE TIME PHONE# • FAX# • EMAIL O BY PHONE O EMAIL	I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE: AUTH. BY REC'D BY	REASON ADD'L COSTS \$	REVISED DATE TIME PHONES*TAA** CIMAL DBY PHONE DEMAIL	DATE TIME DUONE# - EAY# - EMAIL	NOUTH COSTS, I HAVE READ AND UNDERSTAND THE ABOVE AND ACKNOWLEDGE RECEIPT OF AN ESTIMATE, SMOUG CHECK COSTOMENS. I MAY CHOOSE ANOTHER SMOUG CHECK STATION TO PERFORM ANY REPAIRS, INSTALLATIONS, ACJUSTMENTS OR SUBSEQUENT TESTS.	WEHICLE ID SECURE I REAMAUNI OF REFINIS INFREIO, TOWNING THE REFORMANCE FOR SECOND OWNER OF THE EVENT LEGAL IN VEHICLE IN CASE OF RIFE, THEFT, ACCIDENT, DYNAMOMETER TESTING OF ANY OTHER CAUSE BEYOND YOUR CONTROL IN THE EVENT LEGAL ACTION IS NECESSARY TO ENFORCE THIS CONTRACT, I UNDERSTAND THAT I AM SOLELY RESPONSIBLE FOR ALL COSTS INCLUDING ATTORNEY'S FRES	HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIALS, YOU AND YOUR EMPLOYEES MAY OPERATE ABOVE VEHICLE FOR PURPOSES OF TESTING, INSPECTION OR DELIVERY AT MY RISK, AN EXPRESS MECHANIC'S LIEN IS ACKNOWLEDGED ON ABOVE ABOVE VEHICLE FOR PURPOSES OF TESTING, INSPECTION OR DELIVERY AT MY RISK, AN EXPRESS MECHANIC'S LIEN IS ACKNOWLEDGED ON ABOVE ABOVE VEHICLE FOR PURPOSES OF TESTING, INSPECTION OR DELIVERY AT MY RISK, AN EXPRESS MECHANIC'S LIEN IS ACKNOWLEDGED ON ABOVE ABOVE VEHICLE FOR PURPOSES OF TESTING, INSPECTION OR DELIVERY AT MY RISK, AN EXPRESS MECHANIC'S LIEN IS ACKNOWLEDGED ON ABOVE ABOVE VEHICLE FOR PURPOSES OF TESTING, INSPECTION OR DELIVERY AT MY RISK, AN EXPRESS MECHANIC'S LIEN IS ACKNOWLEDGED ON ABOVE ABOVE VEHICLE FOR PURPOSES OF TESTING, INSPECTION OR DELIVERY AT MY RISK, AN EXPRESS MECHANIC'S LIEN IS ACKNOWLEDGED ON ABOVE ABOVE VEHICLE FOR PURPOSES OF TESTING, INSPECTION OR DELIVERY AT MY RISK, AN EXPRESS MECHANIC'S LIEN IS ACKNOWLEDGED ON ABOVE ABOVE VEHICLE FOR PURPOSES OF TESTING, INSPECTION OR DELIVERY AT MY RISK, AN EXPRESS MECHANIC'S LIEN IS ACKNOWLEDGED ON ABOVE ABOVE VEHICLE FOR A TO THE PURPOSE OF THE PURPO	ORIGINAL DATE TIME PHONE#+FAX#+EMAIL DBY PHONE D'EMAIL	1 150 market	To but many	7. 6/ 50100 and 6/2 UVS.	1 2 / / 2 / Mar	6 dond lest light		2 though of	2) Colling of the francis of	- The time of	2001 679 600 CONOC	1. Cheloder movemen	OPR.# REPAIR ORDER DESCRIPTION OF LABOR	VI.N.	ROW 2004 61	CLANCE WOLLD GAMBER WOLLD GAMBE	PH. WHEN READY WRITTEN BY MILEAGE LIC. PLATE #	TIME REC'D TIME PROM.	CITY STATE ZIP		ADDRESS STATE OF THE STATE OF T	NAME 1. PATE 11.2	NO Warranty of Any Kind for Used (Code U) or Aftermarket (Code A) Parts	2 4	4100 Grove St. • Sonoma, CA 95476	Paker Blake a Classic Car Services
PLEASE PAY THIS 37011	TAX	SUBTOTAL		CERTIFICATE	S	WASTE DISPO	HAZARDOUS	GAS, OIL, GREASE	TOTAL PARTS	TOTAL LABOR 370	Chr.S. 100	CALL TO THE PARTY OF THE PARTY	V 7501	S CONCES		1		lock							ROTATE TIRES	ODIFF.	TRANS.	CHANGE OIL	CHANGE OIL	LUBRICATION	MAINTENANCE				003714

TERMS ARE CASH UNLESS PRIOR ARRANGEMENTS ARE MADE SEE IMPORTANT INFORMATION ON BACK

707-571-8866

BAR # AK 163405--E.P.A. #CAL000073672

3/22/2021 12:08 PM

: 64V-7910

Created : 10/26/2020 4:04:22 PM

Repair Order #80288

page 1

: 1964 Studebaker Gran Turismo Hawk 4.7 L 289 CID V8

Day Phone Tag/State

: 707-328-1354

: 8TCY664 / CA

Color

: Green

Last Mileage : 39314

Odometer In : 39309

Srv Writer: JD

Odometer Out: 39342

Labor/Notes

Vehicle

Contact

VIN

Code/Tech\*

Description

Price

DIAGNOSE

\$420.00

CHECK AND REPORT:-----CUSTOMER JUST PURSCHASED FROM OUT OF STATE

1. COMPLETE SAFETY INSPECTION

WANTS EVERYTHING WORKING---DONT WORRY ABOUT THE RADIO

- 2. WANTS IT TO TRACK STRAIGHT WITH AND WITHOUT BRAKES APPLIED: NEEDS BRAKE SYSTEM OVERHAUL--REAR
- 3. COMPLETE MECHANICAL ASSEMENT---WAS TOLD IT IS A FRESH REBUILD: ENGINE AND TRANS APPEAR TO HAVE BEEN REBUILT. FRONT AND REAR SUSPENSIONS ARE SAD
- 4. COMPRESSION TEST--CHECK FOR SMOKING:

READINGS: 115,105,115,110,115,115,105,115. -------- CLEAN SPARK PLUGS

- 5. DOES IT NEED TO BE IN NEUTRAL TO START-AS TOLD: NEEDS NEUTRAL SAFETY SWITCH-BACK UP LIGHTS INOP
- 6. HOSES / ELECTRICAL / BATTERY CABLES --- ???? NOT CHARGING
- 7. BRAKES ARE BAD: YES THEY ARE
- 8. DASH LIGHTS IN-OP: BAD INSTRUMENT LIGHT SWITCH
- 9. HEATER AND DEFROSTER DO NOT WORK: FAN WAS UNPLUGGED
- 10. REPLACE WIPER BLADES
- 11. DRIVERS DOOR NEEDS WORK
- 12. TRANSMISSION LURCHES WHEN SHIFTING: SLIPS 2-3 AND SLOW TO ENGAGE REVERSE
- 13. ELECTRIC FUEL PUMP IS REALLY LOUD-RUNS A LOT WHEN KEY IS TURNED ON
- 14. NEEDS HEADLAMP ADJUSTMENT
- 15. LR TAILLIGHT INOP
- 16. RR WINDOW NEEDS TO BE DISASSEMBLED TO FIND OUT WHY IT WON'T GO DOWN
- 17. LF DOOR NEEDS ADJUSTING-STRIKER WORK??

RS\* RS\*

OVERHAUL FRONT END

OH BRAKE SYSTEM

\$1,680.00

\$1,260.00

R&R ALL HYDRAULIC CYLINDERS; REPLACE SHOES, PADS, BRAKE HOSES, FRONT DISC BRAKE PIPING, FITTINGS AS NEC., FRONT HUBS WITH ROTORS, MACHINE REAR DRUMS, PACK WHEEL BEARINGS. ADJUST PARKING BRAKE.

#### TRI\*STAR AUTOMOTIVE 484 KENWOOD COURT

#### SANTA ROSA CA 95407-7895

707-571-8866

BAR # AK 163405-----E.P.A. #CAL000073672

01001000	-
3/22/2021	12.00 014
012212021	LZ UO PIM

#### page 2 Repair Order #80288 : 1964 Studebaker Gran Turismo Hawk 4.7 L 289 CID V8 Labor/Notes (continued) Code/Tech\* Description RS\* Price MACHINE ROTOR RS\* \$30.00 MACHINE BRAKE DRUM RS\* \$30.00 R&R REAR LEAF SPRINGS NECESSARY TO MAKE TOOL TO REMOVE SEIZED BUSHINGS \$630.00 RS\* **R&R U-JOINTS** RS\* \$70.00 COOLING SYSTEM SERVICE RS\* \$60.00 R&R PINION AND AXLE SEALS/BRGS RS\* \$700.00 CORRECT CROSSMEMBER HITTING TRANSMISSION REMOVE CROSSMEMBER AND CUT. "VEE" DOWN AND INSTALL FILLER PIECE. WELD ASSY AND REINSTALL \$210.00 CORRECT EXHAUST SYSTEM HITTING GAS TANK RS\* \$140.00 POWER STEERING REPAIR R&R HOSES, OVERHAUL CONTROL VALVE, \$476.00 CORRECT CHARGING SYSTEM NO IGNITION FEED POWER TO GM 10SI ALTERNATOR. FOUND WIRING TAPED INTO HARNESS AND NOT CONNECTED. \$224.00 INSTALL WIRE TO IGNITION FEED AND INSTALL DIODE TO OPERATE PROPERLY. RS\* R&R ELECTRIC FUEL PUMP RS\* \$84.00 R&R CLOCK HAS POWER TO IT, IS INOP. NO CONTINUITY THROUGH COIL. REMOVE CLOCK AND DISASSEMBLE HSNG. OXIDIZED \$140.00 POINTS, CLEAN POINT CONTACTS AND LUBE MECHANISM. APPLY POWER AND RUN CLOCK. QUIT WORKING AFTER A COUPLE OF DAYS-RECOMMEND QUARTZ CONVERSION. RS\* R&R INSTRUMENT PANEL LIGHT SWITCH \$70.00 RS\* R&R HEATER SWITCH \$42.00 RS\* R&R AND OH HEADLIGHT SWITCH CLEAN CONTACTS AND RELUBE \$140.00 RS\* REPAIR RR WINDOW INOP \$140.00 RS\* INSTALL BACK UP SWITCH AND LINKAGES INSTALL BACK UP SWITCH AND MAKE LINKAGE TO SHIFTER. INSTALL LINKAGE FOR NEUTRAL SAFETY SWITCH AND \$560.00 ADJUST AS BEST AS POSSIBLE. ADJUST SHIFTER. STARTS IN PARK AND NEUTRAL, MAY START IN FORWARD GEARS. CORRECT WIRING TO BACKUP SWITCH, RUN POWER SUPPLY TO FUSE BLOCK. CLEAN RUST OUT OF BOTH BACK UP LAMP SOCKETS AND REPLACE BULBS. INSTALL CUSTOMER SUPPLIED W/W \$140.00 INSTALL BAG AND FOOT PUMP PER INSTRUCTIONS. CLEAN ORIGINAL NOZZLES AND REPLACE HOSES. FILL WITH WASER SOLVENT AND WATER. RS\* ADJUST LAMPS \$25.00 RS\* REPLACE DRIVERS DOOR LATCH \$140.00 REPLACE AND ADJUST DOOR BEST POSSIBLE-POSSIBLE BODY SHOP ADJUSTMENT NEEDED OIL CHANGE \$12.50 Parts Qty Code/Tech\* Description Condition Unit Price Price 2 RS\*

New

\$19.90

\$39.80

REAR BRAKE SPRING SET

707-571-8866

BAR # AK 163405-----E.P.A. #CAL000073672

3/22/2021 12:08 PM

## Repair Order #80288

page 3

an	( continued)	ebaker Gran Turismo Hawk 4.7 L 289 CID V8		
Qty	Code/Tech*	Description		
1	RS*	BRAKE SHOES Condition	Unit Price	Price
1	RS*	BRAKE PADS New	\$80.45	\$80.45
4	RS*	BRAKE PAD SUPPORT	\$59.50	\$59.50
2	RS*	BRAKE PAD RETAINER  Reconditio	\$8.75	\$35.00
1	RS*	FUEL PUMP Reconditio	\$8.00	\$16.00
4	RS*	BRAKE CALIPER New	\$52.79	\$52.79
4	RS*	New	\$179.00	\$716.00
1	RS*	ELECTRICAL CRIMP CONNECTORS  New BRAKE CALIPER LINE	\$0.95	\$3.80
1	RS*	BRAKE CALIPER LINE  New	\$23.65	\$23.65
1	RS*	New	\$23.65	\$23.65
1	RS*	CALIPER CROSSOVER LINE New	\$25.48	\$25.48
2	RS*	CALIPER CROSSOVER LINE  New	\$25.48	\$25.48
1	RS*	BRAKE HOSE, FRONT New	\$25.75	\$51.50
2	RS*	REAR BRAKE HOSE New	\$21.95	\$21.95
1	RS*	WHEEL CYLINDER, REAR MASTER CYLINDER	\$90.50	\$181.00
1	RS*	New	\$97.25	\$97.25
2	RS*	#84032 BRAKE FLUID New	\$20.45	\$20.45
1	RS*	FRONT HUB SEAL New	\$12.75	\$25.50
4	RS*	BRAKE LINE TEE & BRACKET New	\$20.30	\$20.30
	RS*	FITTING	\$1.64	\$6.56
	RS*	WHEEL BEARING GREASE New	\$4.75	\$9.50
	RS*	LEAF SPRING SET New	\$640.00	\$640.00
	RS*	SPRING SHACKLE BOLT KIT  New	\$31.75	\$31.75
í	RS*	LEAF SPRING INSULATOR New	\$6.50	\$26.00
2	RS*	REAR SPRING U-BOLT KIT  New	\$77.56	\$77.56
	RS*	SPRING SHACKLE BUSHING New	\$18.93	\$37.86
	RS*	REAR AXLE SEAL INNER New	\$15.45	\$30.90
	RS*	REAR OUTER WHEEL SEAL New	\$23.45	\$46.90
	RS*	REAR AXLE BEARING New	\$54.25	\$108.50
	RS*	REAR AXLE BEARING RACE New	\$16.45	\$32.90
	RS*	PINION SEAL New	\$19.75	\$19.75
	RS*	DIFF. COVER GSKT. New	\$10.14	\$10.14
	RS*	WHEEL BEARING GREASE New	\$4.75	\$4.75
	₹S*	GEAR OIL New	\$3.49	\$13.96
	3S*	DIFF. ADDIT New	\$15.35	\$15.35
	₹S*	SEMI GLOSS BLACK PAINT New	\$13.12	\$39.36
		RED OXIDE PRIMER New	\$8.04	\$16.08
F	₹\$*	INSTRUMENT PANEL LIGHT SWITCH New	\$120.00	\$120.00

707-571-8866

BAR # AK 163405-----E.P.A. #CAL000073672

3/22/2021 12:08 PM

### Repair Order #80288

page 4

circo (continued)	cer Gran Turismo Hawk 4.7 L 289 CID V8			
Qty Code/Tech*	Description	_		
1 RS*	HEATER SWITCH	Condition	Unit Price	Price
2 RS*	Wiper Blade - Classic - Front	New	\$86.00	\$86.00
1 RS*	FRONT END OH KIT	New	\$13.60	\$27.20
2 RS*	INNER TIE ROD END	New	\$899.00	\$899.00
1 RS*	COIL SPRING SET	New	\$56.70	\$113.40
4 RS*	COIL SPRING INSULATOR	New	\$490.00	\$490.00
2 RS*	UPPER ARM BUMPER	New	\$13.00	\$52.00
4 RS*	SWAY BAR BUSHING	New	\$18.45	\$36.90
1 RS*		New	\$15.00	\$60.00
2 RS*	CENTER STEERING BELL CRANK	New	\$179.00	\$179.00
1 RS*	Shock Absorber - Gas-a-just - Front - KYB P/S PRESSURE HOSE	New	\$88.86	\$177.72
1 RS*		New	\$69.30	\$69.30
1 RS*	P/S RIGHT TURN HOSE	New	\$69.30	\$69.30
1 RS*	P/S LEFT TURN HOSE	New	\$69.30	\$69.30
1 RS*	P/S RETURN HOSE	New	\$58.68	\$58.68
4 RS*	CONTROL VALVE REPAIR KIT	New	\$28.00	\$28.00
1 RS*	DEXRON ATF	New	\$2.89	\$11.56
1 RS*	#310 TRANS ADDITIVE TRANS SEAL	New	\$17.69	\$17.69
1 RS*	U-JOINT	New	\$6.68	\$6.68
1 RS*	U-JOINT	New	\$50.26	\$50.26
1 RS*	FLASHER	New	\$37.02	\$37.02
1 RS*	BACK UP LAMP SWITCH	New	\$13.76	\$13.76
2 RS*	BULB	New	\$119.00	\$119.00
4 RS*		New	\$2.96	\$5.92
.9 RS*	ELECTRICAL CRIMP CONNECTORS FUEL	New	\$0.95	\$3.80
1 RS*	OIL FIL	New	\$3.66	\$69.17
5 RS*	MOTOR OIL	New	\$21.56	\$21.56
1 RS*	DRAIN PLUG SEAL	New	\$4.79	\$26.35
1 RS*		New	\$3.45	\$3.45
5 RS*	COMP CAMS OIL ADDITIVE	New	\$14.95	\$14.95
1 RS*	COOLANT	New	\$19.95	\$29.93
1 RS*	WINDSHIELD WASHER SOLVENT	New	\$2.25	\$2.25
olet/Misc.	DRIVERS DOOR LATCH	Used	\$165.00	\$165.00
y Code/Tech*	Description			
1 RS*	Description		Unit Price	Price
1 RS*	TWO WHEEL ALIGNMENT		\$95.00	\$95.00
1 RS*	SHIPPING & HANDLING		\$173.06	\$173.06
	SHIPPING & HANDLING		\$12.72	\$12.72

707-571-8866

BAR # AK 163405-----E.P.A. #CAL000073672

3/22/2021 12:08						page
		Repair C	Order #8	0288		
Vehicle : 1964 Sublet/Misc. (con Oty Code/Tech*	Studebaker Gi tinued)	ran Turismo Hawk 4.7 L 28	9 CID V8			
1 RS*		SHIPPING & HANDLING		Ļ	Jnit Price	Price
					\$24.68	\$24.68
		Labor				\$7,423.50
,		Parts				\$5,821.52
		Sublet/Misc.				\$95.00
		Other Charges				\$0.00
		Charges				\$210.46
		Sales Tax		Tax @ \$5,752.35 * 9.0000%		\$517.71
ech C	ortification #			Repair Total		\$14,068.19
S	Certification #					1 : 1 = = = = = = = = = = = = = = = = =
ate - Time	A		provals			
1/4/2020 3:00:56 PM	Amount	Authorized By		Means	Employ	yee
1/4/2020 3:00:56 PW	\$12,000.00	michaelnehm@icloud.com 707	7-328-1354	Phone	JD	

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or Inspection. An express garagekeeper's lien is hereby acknowledged on above vehicle to secure the amount or repairs thereto.

All Vehicles left over 48 hrs. after repairs are completed WILL INCUR A \$50.00 PER DAY STORAGE FEE. 24 Month or 24,000 Mile Warranty On Repairs.

Customer	Signature	
	•	