



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 7/29/16 at 5:22:45 PM (EDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with problems inconsistent of the desired by the control of the along with a vehicle inspection and test drive, to make a better decision about your next used car.





Tell us what you know about this vehicle

Make	☐ Cars with no accidents	
Model	☐ 1-Owner Cars	
	$\ \square$ Cars with service records	
within 75	☐ Personal/Lease Only (no fleet, rental, commercial)	(3)
miles of 95476		LICAR IN
	Show Me Now	FOX

Glossary CARFAX Detailed History

ate:	Mileage:	Source:	Comments:
7/10/1991	37,112	California Inspection Station Santa Rosa, CA	Passed emissions inspection
7/16/1993	41,076	California Inspection Station Santa Rosa, CA	Passed emissions inspection
7/19/1995	48,831	California Inspection Station Santa Rosa, CA	Passed emissions inspection
07/19/1999	61,495	Service Facility Santa Rosa, CA	Gas cap Ignition system repaired
07/19/1999		California Inspection Station Santa Rosa, CA	Passed emissions inspection
07/23/1999		California Motor Vehicle Dept. Sonoma, CA	Title issued or updated
10/02/2001	63,142	Service Facility Santa Rosa, CA	Ignition system repaired
10/02/2001		California Inspection Station Santa Rosa, CA	Passed emissions inspection
07/15/2002		Mike Larbre Automotive Sonoma, CA	Battery replaced Battery/charging system checked
07/23/2003	64,179	Service Facility Arnold, CA	Vehicle serviced
07/23/2003		California Inspection Station Amold, CA	Passed emissions inspection
04/15/2004		Mike Larbre Automotive Sonoma, CA	Maintenance inspection completed Recommended maintenance performed Fluids checked Oil and filter changed Tire condition and pressure checked
07/15/2005	67,889	California Inspection Station	Passed emissions inspection
08/04/2007	71,567	California Inspection Station	Passed emissions inspection
07/11/2008	73,208	Mike Larbre Automotive Sonoma, CA	A/C accumulator replaced A/C compressor replaced A/C expansion/orifice valve replaced A/C refrigerant recharged A/C system checked
07/28/2008		Mike Larbre Automotive Sonoma, CA	Vehicle serviced
06/24/2009	74,85	California Inspection Station Sonoma, CA	Passed emissions inspection
07/13/2011	78,46	7 California Inspection Station Glen Ellen, CA	Passed emissions inspection
07/10/2013	79,65	9 California Inspection Station Glen Ellen, CA	Passed emissions inspection
06/24/2015	79,78	California Inspection Station Glen Ellen, CA	Passed emissions inspection

Tell us what you know about this vehicle

Have Questions? Please visit our Help Center at www.carfax.com.

Glossary CARFAX

View Full Glossary

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used

Follow Us: 👔 facebook.com/CARFAX 🍑 @CarfaxReports 🔉 CARFAX on Google+

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF FURTHER EAPKESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WAR MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. CARFAX® © 2016 CARFAX, Inc., a unit of IHS Inc. All rights reserved.

Covered by United States Patent Nos. 7,113,853; 7,778,841; 7,596,512, 8,600,823; 8,595,079; 8,606,648; 7,505,838. 7/29/16 5:22:45 PM (EDT)