

**1997  
Mercedes-Benz SL320  
R129**



**WDBFA63F8VF153299**



# Vehicle History Report™

**1997 MERCEDES-BENZ  
SL320**

VIN: WDBFA63F8VF153299  
CONVERTIBLE  
3.2L I6 F  
GASOLINE  
REAR WHEEL DRIVE

Damage reported

17 Service history records

4 Previous owners

Personal vehicle

Last owned in California

53,677 Last reported odometer reading

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 2/23/23 at 7:13:42 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

*SAME OWNER* *THEIR CHILD*

## Ownership History

The number of owners is estimated

Owners 1-2	Owner 3	Owner 4
------------	---------	---------

	1997	2007	2022
Year purchased	1997	2007	2022
Type of owner	Personal	Personal	Personal
Estimated length of ownership	9 yrs. 11 mo.	15 years	6 months
Owned in the following states/provinces	California, Hawaii	California	California
Estimated miles driven per year	See Details	1,848/yr	--
Last reported odometer reading	18,847	53,677	--

## Title History

CARFAX guarantees the information in this section

Owners 1-2	Owner 3	Owner 4
------------	---------	---------

### Damage Brands

Salvage | Junk | Rebuilt | Fire | Flood | Hail | Lemon

<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem
---	---	---



**Odometer Brands**

Not Actual Mileage | Exceeds Mechanical Limits

Guaranteed No Problem

Guaranteed No Problem

Guaranteed No Problem



**GUARANTEED** - None of these major title problems were reported by a state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, CARFAX will buy this vehicle back.  
View Terms | View Certificate



**Additional History**

Not all accidents / issues are reported to CARFAX

	Owners 1-2	Owner 3	Owner 4
<b>Total Loss</b> No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
<b>Structural Damage</b> CARFAX recommends that you have this vehicle inspected by a collision repair specialist.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
<b>Airbag Deployment</b> No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
<b>Odometer Check</b> No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated	<input checked="" type="checkbox"/> No Issues Indicated	<input checked="" type="checkbox"/> No Issues Indicated
<b>Accident / Damage</b> Inspected for damage: 04/11/2003.	Damage Reported	No New Issues Reported	No New Issues Reported
<b>Manufacturer Recall</b> Check with an authorized Mercedes-Benz dealer for any open recalls.	<input checked="" type="checkbox"/> No Recalls Reported	<input checked="" type="checkbox"/> No Recalls Reported	<input checked="" type="checkbox"/> No Recalls Reported
<b>Basic Warranty</b> Original warranty estimated to have expired.	Warranty Expired	Warranty Expired	Warranty Expired



**Detailed History**







**Owner 1**  
Purchased: 1997



**Low mileage!** This owner drove less than the industry average of 15,000 miles per year.

Personal Vehicle  
2,983 mi/yr

Date	Mileage	Source	Comments
07/31/1997	29	California Motor Vehicle Dept. Santa Rosa, CA	<b>Odometer reading reported</b>

08/21/1997		California Motor Vehicle Dept.		<b>Title issued or updated</b> First owner reported Titled or registered as personal vehicle
08/15/1999		California Motor Vehicle Dept. Santa Rosa, CA		<b>Title issued or updated</b>
07/06/2001	11,595	Service Facility Santa Rosa, CA		<b>Vehicle serviced</b>
07/06/2001		California Inspection Station Santa Rosa, CA		<b>Passed emissions inspection</b>
03/05/2002	12,798	Service Facility		<b>Vehicle serviced</b> Recommended maintenance performed Maintenance inspection completed 15,000 mile service performed Antifreeze/coolant checked Brake fluid flushed/changed Oil and filter changed Tire(s) balanced Tires rotated
04/11/2003	17,119	Damage Report		<b>Vehicle inspected after an accident or other incident</b> Damage to rear Damage to right center pillar  <b>A vehicle inspection completed by your dealer or professional inspector is recommended</b>
06/25/2003	17,490	California Inspection Station		<b>Passed emissions inspection</b>
	<b>Owner 2</b> Purchased: 2004			Personal Vehicle
<b>Date</b>	<b>Mileage</b>	<b>Source</b>		<b>Comments</b>
06/01/2004	18,847	Hawaii Motor Vehicle Dept. Kihei, HI Title #MKU62104		<b>Title or registration issued</b> New owner reported
07/26/2004		Hawaii Motor Vehicle Dept. Kihei, HI Title #MKU62104		<b>Title or registration issued</b>

10/01/2004	Hawaii Motor Vehicle Dept. Kihei, HI Title #MKU62104	Title or registration issued
07/08/2005	Hawaii Motor Vehicle Dept. Kihei, HI Title #MKU62104	Title or registration issued
09/02/2005	Hawaii Motor Vehicle Dept. Kihei, HI Title #MKU62104	Title or registration issued
07/17/2006	Hawaii Motor Vehicle Dept. Kihei, HI Title #MKU62104	Title or registration issued
10/20/2006	Hawaii Motor Vehicle Dept. Kihei, HI Title #MKU62104	Title or registration issued





**Owner 3**



Purchased: 2007









**Low mileage!** This owner drove less than the industry average of 15,000 miles per year.



Personal Vehicle  
1,848 mi/yr

Date	Mileage	Source	Comments
07/01/2007	26,860	California Motor Vehicle Dept. Santa Rosa, CA	Title issued or updated New owner reported
07/31/2007	26,870	California Inspection Station	Passed emissions inspection
05/08/2008		Smothers European Santa Rosa, CA 888-438-6505 ★ 4.7 / 5.0 81 Verified Reviews	 <b>Vehicle serviced</b> Maintenance inspection completed Outside mirror replaced/repared Mirror motor replaced Tires rotated Front brake pads replaced
06/26/2008		Smothers European Santa Rosa, CA 888-438-6505 ★ 4.7 / 5.0 81 Verified Reviews	 <b>Vehicle serviced</b> Electrical system checked Engine oil/fluid leak checked

09/15/2008		Smothers European Santa Rosa, CA 888-438-6505 ★ 4.7 / 5.0 81 Verified Reviews		<b>Vehicle serviced</b>
12/15/2008		California Motor Vehicle Dept. Santa Rosa, CA		<b>Registration updated when owner moved the vehicle to a new location</b>
06/10/2009	33,028	California Inspection Station Santa Rosa, CA		<b>Passed emissions inspection</b>
07/13/2009	33,424	Smothers European Santa Rosa, CA 888-438-6505 ★ 4.7 / 5.0 81 Verified Reviews		<b>Vehicle serviced</b>
09/14/2010	37,162	Smothers European Santa Rosa, CA 888-438-6505 ★ 4.7 / 5.0 81 Verified Reviews		<b>Vehicle serviced</b> Air filter replaced Four tires balanced Four tires mounted Four tires replaced Oil and filter changed Brake fluid flushed/changed
05/13/2011	39,106	Smothers European Santa Rosa, CA 888-438-6505 ★ 4.7 / 5.0 81 Verified Reviews		<b>Vehicle serviced</b> Engine checked Engine/powertrain computer/module checked Camshaft position sensor replaced
06/28/2011	39,540	Smothers European Santa Rosa, CA 888-438-6505 ★ 4.7 / 5.0 81 Verified Reviews		<b>Vehicle serviced</b>
07/20/2011	39,720	California Inspection Station Santa Rosa, CA		<b>Failed emissions inspection</b> Passed emissions inspection
10/04/2011		California Motor Vehicle Dept. Santa Rosa, CA		<b>Registration updated when owner moved the vehicle to a new location</b>
06/19/2013	43,394	California Inspection Station Santa Rosa, CA		<b>Passed emissions inspection</b>



07/24/2013	43,479	Smothers European Santa Rosa, CA 888-438-6505 ★ 4.7 / 5.0 81 Verified Reviews		<b>Vehicle serviced</b> Maintenance inspection completed Electrical system checked Oil and filter changed Tires rotated
06/24/2015	46,040	California Inspection Station Santa Rosa, CA		<b>Passed emissions inspection</b>
05/23/2017	49,175	Smothers European Santa Rosa, CA 888-438-6505 ★ 4.7 / 5.0 81 Verified Reviews		<b>Vehicle serviced</b> Maintenance inspection completed Tire condition and pressure checked
06/13/2017	49,221	BNC Auto Care Santa Rosa, CA 707-540-0248 ★ 4.9 / 5.0 20 Verified Reviews		<b>Vehicle serviced</b> Emissions inspection performed
06/13/2017		California Inspection Station Santa Rosa, CA		<b>Passed emissions inspection</b>
07/20/2017	49,309	Smothers European Santa Rosa, CA 888-438-6505 ★ 4.7 / 5.0 81 Verified Reviews		<b>Vehicle serviced</b> Maintenance inspection completed Tire condition and pressure checked
04/05/2018	50,396	Smothers European Santa Rosa, CA 888-438-6505 ★ 4.7 / 5.0 81 Verified Reviews		<b>Vehicle serviced</b> Maintenance inspection completed Tire condition and pressure checked
06/24/2019	52,356	BNC Auto Care Santa Rosa, CA 707-540-0248 ★ 4.9 / 5.0 20 Verified Reviews		<b>Vehicle serviced</b> Emissions inspection performed
06/24/2019		California Inspection Station Santa Rosa, CA		<b>Passed emissions inspection</b>

05/07/2020	52,975	Smothers European Santa Rosa, CA 888-438-6505 ★ 4.7 / 5.0 81 Verified Reviews		<b>Vehicle serviced</b> Maintenance inspection completed Axle seal(s) replaced Brakes checked Hood insulator replaced Battery replaced Steering/suspension checked Tire condition and pressure checked
10/08/2021	53,245	California Inspection Station Santa Rosa, CA		<b>Failed emissions inspection</b>
10/28/2021	53,408	California Inspection Station Santa Rosa, CA		<b>Failed emissions inspection</b>
12/30/2021	53,677	California Inspection Station Santa Rosa, CA		<b>Passed emissions inspection</b>
01/12/2022		Smothers European Santa Rosa, CA 888-438-6505 ★ 4.7 / 5.0 81 Verified Reviews		<b>Vehicle serviced</b> Maintenance inspection completed Tire condition and pressure checked Tires rotated Engine checked Brake fluid flushed/changed



**Owner 4**

Purchased: 2022

Personal Vehicle

Date	Mileage	Source	Comments
07/27/2022		California Motor Vehicle Dept. Windsor, CA	<b>Title issued or updated</b> New owner reported

Have Questions? Please visit our Help Center at [www.carfax.com](http://www.carfax.com).



**Glossary**

**Damage Indicator**

Damage can be a result of many different types of events. Examples include contact with objects (other cars, trees, traffic signs, road debris, etc), vandalism, or weather-related events. Not every damage event is reported to CARFAX. As details about the damage event become available, those additional details are added to the CARFAX Vehicle History Report. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

- This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 2/23/23 at 7:13:42 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

**Failed Emissions Inspection**

The emissions check performed during a vehicle inspection indicated the vehicle was emitting more than allowable emissions standards and/or had missing or modified parts. Repeated failed emissions records can indicate engine problems and CARFAX recommends you have the vehicle inspected.

**First Owner**

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

**New Owner Reported**

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.




**Ownership History**

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

**Title Issued**

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

---

Follow Us:  [facebook.com/CARFAX](https://facebook.com/CARFAX)  [@CARFAXinc](https://twitter.com/CARFAXinc)  [About CARFAX](#)

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2023 CARFAX, Inc., part of S&P Global. All rights reserved.  
2/23/23 7:13:42 PM (CST)



**SMOTHERS EUROPEAN**

DEAL 13371

▼ SQUARELY WITH BRACKET BELOW

2881 CORBY AVENUE  
SANTA ROSA, CA 95407  
(707) 542-4810

Stock No.	M726
SOURCE	NONE
SALESPERSON	HELLER, RICHARD
DATE	07/31/97
BUS. PHONE	NONE
RES. PHONE	706
ZIP CODE	

2881 CORBY AVE SANTA ROSA, C 95401

BUS. PHONE NONE 707-542-4810 3

RES. PHONE 706

ZIP CODE

words "we," "us," and "our" refer to the creditor (seller) named below. The words "you" and "your" refer to the buyer and co-buyer if any named herein. Enter my order for the and insurance listed below under the terms and agreements set forth below and on the reverse hereof: **SEE OTHER SIDE FOR ADDITIONAL TERMS AND AGREEMENTS:**

**DISCLOSURES PURSUANT TO THE TRUTH-IN-LENDING ACT**

RATE	FINANCE CHARGE	Amount Financed	Total of Payments	Total Sale Price
ONE %	The dollar amount the credit will cost you.	The amount of credit provided to you or on your behalf.	The amount you will have paid after you have made all payments as scheduled.	The total cost of your purchase on credit, including your down payment of \$ 2000.00
NONE	NONE	\$ 92285.50	\$ 92285.50	\$ 94285.50

Number of Payments:	Amount of Payments:	When Payments Are Due:
12	92285.50	Monthly, beginning 08/04/97

giving a security interest in the goods or property being purchased.  
If any payment is more than 10 days late you may be charged 5% of the late amount.  
If you pay early, you may be entitled to a refund of part of the finance charge.  
See other documents for any additional information about nonpayment, default, any required prepayment in full before the scheduled date and prepayment refunds.

MAKE	CYL.	DIESEL	GAS	OTHER	BODY STYLE	MODEL	ODOMETER READING	VEHICLE IDENTIFICATION NUMBER
MERCEDES	6		X		CP	SL320R/95	29	WDBFA63F8VF153299
DATE	COLOR	TRIM	TIRES	TRANS	KEY NO.	LIC. NO.	R.O.S. NO.	
97	012/268					NEW		

mailing addresses of all persons to whom the notices required or sent are set forth at the top of this form.  
This vehicle with this purchase order, as indicated in the table above, federal regulation may require a special buyers notice on the window.  
SEE ON THE WINDOW FORM FOR THIS VEHICLE IS PART OF THE ORDER. INFORMATION ON THE WINDOW FORM OVERRIDES ANY INFORMATION IN THE PURCHASE ORDER.

ACCESSORIES	PERMA PLATE IN AND OUT	780
Top Stand		
MBZ phone		
TOTAL OF ACCESSORIES		\$

**STATEMENT OF INSURANCE**  
required as a condition of financing the purchase of a vehicle, or negotiate, any insurance through a particular agent or broker.  
I agree to include in the balance due under this agreement the following amount to expire WITH  BEFORE  AFTER  the due date of the requests seller to procure insurance upon the described property for the term of this agreement. Any insurance will not be in effect until the insurance carrier.  
DEDUCTIBLE COLLISION NONE Mos. \$ NONE  
LIMITS NONE Mos. \$ NONE  
TOTAL VEHICLE INSURANCE PREMIUMS \$ NONE (a)  
Insurances are hereby acknowledged.

SMOTHERS EUROPEAN BUYER

INSURANCE AUTHORIZATION AND APPLICATION  
I have read the credit insurance checked below, if any, and understand that I am required. You acknowledge disclosure of the cost of such insurance.

**ITEMIZATION OF AMOUNT FINANCED**

- A. Cash Price Motor Vehicle and Accessories \$ 82625.00 (A)

1. Cash Price Vehicle \$ 81845.00

2. Cash Price Accessories \$ 780.00

B. Document Preparation Charge \$ 35.00 (B)(not a governmental fee)

C. Smog Fee Paid to Seller \$ NONE (C)

D. Sales Tax (on A+B+C) \$ 6199.50 (D)

E. Luxury Tax \$ 3730.00 (E)

F. Service Contract (optional)\* \$ NONE (F)

G. Other \$ NONE (G)

To whom paid \_\_\_\_\_

TOTAL CASH PRICE (A to G) \$ 92589.50 (1)
- AMOUNTS PAID TO PUBLIC OFFICIALS

A. License \$ 1696.00 (A)



qualified. Your acknowledgment of the cost of such insurance is included in the balance payable under the security agreement. Any credit insurance premiums shall be applied to sums due under this agreement whose names are signed below are insured.

Mos. Premium \$ NONE  
 Mos. Premium \$ NONE  
 Mos. Premium \$ NONE

TOTAL CREDIT INSURANCE PREMIUMS \$ NONE (b)

Life Insurance  You do not want Credit Life Insurance  
 Disability Insurance (Primary Buyer Only)

Credit Disability Insurance

Credit Life Insurance

on credit insurance marked above. Your signature below means you are not eligible for insurance if you have reached your 65th birthday for disability insurance only if you are working for wages or more on the Effective Date. (3) Only the Primary Buyer is insured.

**COVERAGE MAY NOT COVER CONDITIONS FOR WHICH YOU ARE OR WERE OR WILL BE OR CHIROPRACTOR IN THE LAST 6 MONTHS** (refer to "Covered" in your policy or certificate for details).

*[Signature]*  
 PRIMARY BUYER AGE \_\_\_\_\_ ID-1  
 CO-BUYER AGE \_\_\_\_\_

**BROKER FEE DISCLOSURE**

relates to the retail sale of a new motor vehicle. Subject to a fee received by an autobroker receiving fee, if applicable:

concerning this sale, you should try to resolve it with the seller. If you believe you are being treated unfairly or that the seller is using unfair or deceptive practices or methods by the seller, you may contact the city attorney, the district attorney, or the Department of Consumer Affairs, Division of Investigations and Occupational Licensing, P.O. Box 94232-3890, or any combination thereof. If you do not contact the seller, the seller may not change the financing or payment terms of this agreement to the change. You do not have to agree to any change, and you do not have to practice for the seller to make a unilateral change.

*[Signature]* X  
 THE BUYER'S CURRENT LIABILITY INSURANCE LIMITS PROVIDED IN LAW MUST BE SUFFICIENT TO COVER THE PURCHASE OF A VEHICLE. IF YOU ARE UNSURE YOUR CURRENT INSURANCE POLICY WILL COVER YOUR NEWLY PURCHASED VEHICLE, YOU SHOULD CONTACT YOUR INSURANCE AGENT.

YOUR CURRENT INSURANCE POLICY MAY NOT COVER COLLISION DAMAGE OR MAY NOT COVER REPLACEMENT COSTS FOR THE VEHICLE BEING PURCHASED. IF YOU DO NOT HAVE FULL COVERAGE, SUPPLEMENTAL COVERAGE MAY BE AVAILABLE TO YOU THROUGH YOUR INSURANCE AGENT. HOWEVER, UNLESS OTHERWISE SPECIFIED, THE COVERAGE YOU OBTAIN THROUGH THE DEALER PROTECTS ONLY UP TO THE AMOUNT OF THE UNPAID BALANCE REMAINING ON THE VEHICLE. IF THE VEHICLE HAS BEEN REPOSSESSED AND SOLD, YOUR CURRENT INSURANCE POLICY WILL NOT COVER THE VEHICLE. YOU SHOULD CONTACT YOUR INSURANCE AGENT. SIGN TO ACKNOWLEDGE THAT HE / SHE UNDERSTANDS THE TERMS AND CONDITIONS.

*[Signature]* X

**THERE IS NO COOLING OFF PERIOD**

This agreement does not provide for a "cooling off" or other cancellation period for this agreement. Therefore, you cannot later cancel this contract simply because you do not like the vehicle, you decide the vehicle costs too much, or wish you had acquired a different vehicle. After you sign below, you may only cancel this contract with the seller or for legal cause, such as fraud.

*[Signature]* Co-Buyer's Signature X

B. Registration \$ \_\_\_\_\_ (B)  
 C. Smog Impact Fee \$ NONE (C)  
 TOTAL OFFICIAL FEES (A+B+C) \$ 1696.00 (2)

3. AMOUNT PAID TO INSURANCE COMPANIES:  
 (Total premiums per Statement of Insurance a + b)\* \$ NONE (3)  
 4. SMOG CERTIFICATION FEE PAID TO STATE \$ NONE (4)  
 5. TOTAL (1 TO 4) \$ 94285.50 (5)

6. A. Trade-In (Description)  
 Yr NONE Make NONE  
 Model NONE \$ NONE (A)  
 V.I.N. NONE  
 Odometer NONE  
 B. Less Pay Off \$ NONE (B)  
 C. TRADE-IN (A less B) \$ NONE (C)  
 D. Deferred downpayment due before second installment payment \$ NONE (D)  
 E. MFR'S Rebate \$ NONE (E)  
 F. Remaining cash downpayment \$ 2000.00 (F)  
 TOTAL DOWNPAYMENT (6C+D+E+F) \$ 2000.00 (6)

7. AMOUNT FINANCED (5 less 6) \$ 92285.50 (7)

\* We may retain, or receive, a portion of this amount.

PREPAYMENT REFUND: Any refund for prepayment in full will be calculated as follows:

- according to the Actuarial Method (If no box is checked the method for calculating the prepayment refund will be deemed to be the Sum of the Periodic Time Balances)
- according to the Sum of the Periodic Time Balances
- according to the Rule of 78's

VEHICLE USE:  Personal, Family or Household  Commercial or Agricultural

OFFICIAL FEES (Not Financed): The Buyer will pay the estimated fee(s) of \$ 10.00 to the appropriate public authority in order to transfer registration after payment in full.

SERVICE CONTRACT (Optional) You request a service contract written with the following company for the term below. The cost is shown in item (1F) above.

Company NONE Term NONE Months  
 Buyer X *[Signature]* X

SELLER ASSISTED LOAN: FOR THIS LOAN, BUYER MAY BE REQUIRED TO PLEDGE SECURITY AND WILL BE OBLIGATED FOR THE INSTALLMENT PAYMENTS ON BOTH THE SECURITY AGREEMENT AND THE LOAN.

Proceeds of Loan - From NONE  
 Amount \$ NONE Finance Charge \$ NONE Total \$ NONE  
 Payable NONE installments of \$ NONE  
 \$ NONE from this loan is described in (6D) above.

Legal Owner X

Buyer certifies that he is of legal age, and agrees to sign a Security Agreement according to the terms herein. In the event Payoff figures are more than quoted by the Buyer, Buyer hereby agrees to pay this excess on demand. This purchase order is subject to credit approval and is not binding unless signed by an authorized representative of Seller. All used vehicles sold "AS-IS" and without guarantee as to condition, year or model, unless otherwise specified in writing.

Buyer acknowledges that (1) before signing this agreement Buyer read both sides of this agreement and received a legible, completely filled-in copy of this agreement; and (2) Buyer has received a copy of every other document that Buyer signed during the contract negotiation.

By X *[Signature]* Title MGR  
 Seller SMOTHERS EUROPEAN



Mercedes-Benz

**MAINTENANCE SYSTEM SHEET**  
Passenger Cars (USA) M.Y.'s 1986 - 1997  
Including MY 98 SLK w/o "flexible" maintenance



Retailer Name: SMOTHERS      Retailer Code: 05-106      Customer Name: \_\_\_\_\_  
 Technician: #56      R.O. Number: 180693      Year & Model: 97 SL 320      Mileage: 12797

107      124      126      129      140      170      201      202      210

Shaded areas indicate additional work to be performed together with respective Maintenance Service.

**INSPECTION SERVICE**

All Models → M.Y. 1991: Once at 800 - 1,000 miles/1,300 - 1,600 km.  
All Models M.Y. 1992 → 1995: Once at 800 - 3,000 miles/1,300 - 4,800 km.  
All Models M.Y. 1996: → Inspection service not required.

If job no. required ANY additional service  
please note on R.O. and check

Maintenance  
Job No.

**Wheels and tires**

- Check, correct tire pressure  4060
- Retighten wheel bolts. *Observe tightening torque!*  4070

**Underside of car**

- Adjust engine stop, rear engine mount (4MATIC only)  2291
- Manual transmission oil change  2601
- Transfer case fluid change (4MATIC only)  2801
- Rear axle oil change  3501
- Observe tightening torque!*
- Retighten steering gear bolts (except model 140)  4671
- Retighten exhaust flange  4970
- Retighten exhaust system connections  4971

**Engine compartment**

- Engine oil and filter change  0101
- Check condition and tension of V-belts 1) (engines 116 and 117)  1350
- Check and correct fluid level:*
- Engine coolant  2011
- Automatic transmission fluid ( → M.Y. 1993)  2710
- Level control, ADS, ASD, 4MATIC fluid  3211
- Brake fluid  4210
- Power steering fluid  4611
- Battery electrolyte ( → M.Y. 1990)  5410
- Windshield washer fluid  8210

**Trunk**

- Check, correct tire pressure (spare)  4060
- Check and correct rear window washer fluid level  
 (models 124.090/092/193/290)  8210
- Check and correct hydraulic soft top fluid level  
 (models 124.066, 129)  7710



## LUBRICATION SERVICE

All Diesel models except 140.134, 124.131, 210.020: Every 5,000 miles/8,000 km, or at least once a year.  
 All other models incl. 140.134, 124.131, 210.020: Every 7,500 miles/12,000 km, or at least once a year.

For Severe Operating Conditions, please refer to the respective Maintenance Booklet.

	If job no. required ANY additional service please note on R.O. and check <input checked="" type="checkbox"/>	Maintenance Job No.
<b>Engine compartment</b>		
<input type="checkbox"/> Engine oil and filter change	<input type="checkbox"/>	0101
<input type="checkbox"/> Reset Maintenance Service Reminder	<input type="checkbox"/>	3022
<input type="checkbox"/> Inspect, lubricate throttle linkage ( → M.Y. 1995)	<input type="checkbox"/>	5410
<input type="checkbox"/> Check and correct battery electrolyte level ( → M.Y. 1990)	<input type="checkbox"/>	8821
<input type="checkbox"/> Lubricate hood hinges	<input type="checkbox"/>	
<input type="checkbox"/> Reset Maintenance Service Reminder ( model 170.447)	<input type="checkbox"/>	
<b>Underside of car</b>		
<input type="checkbox"/> Adjust engine stop, rear engine mount (4MATIC only) Once at 7,500 miles/12,000 km	<input type="checkbox"/>	2291

## MAINTENANCE SERVICE

All models: Every 15,000 miles/24,000 km or every 2 years.

	If job no. required ANY additional service please note on R.O. and check <input checked="" type="checkbox"/>	Maintenance Job No.
<input checked="" type="checkbox"/> Brake test, parking brake check	<input type="checkbox"/>	4290
4MATIC vehicles, observe  WARNING! in Maintenance Manual		
<b>Interior</b>		
<input checked="" type="checkbox"/> Check warning and indicator lamps, horn	<input type="checkbox"/>	5451
<input type="checkbox"/> Clean cassette deck tape head	<input type="checkbox"/>	8230
<input checked="" type="checkbox"/> Inspect headlamps and exterior lamps (incl. Daytime Running Lamps (CDN))	<input type="checkbox"/>	8251
<input checked="" type="checkbox"/> Inspect/test windshield, rear window and headlamp wiper/washer system	<input type="checkbox"/>	8252
<input checked="" type="checkbox"/> Heating and ventilation: Replace dust filter (models 202, 210)	<input type="checkbox"/>	8381
<input type="checkbox"/> Inspect seat belts for damage	<input type="checkbox"/>	9150
<input type="checkbox"/> Backrest lock, check operation (models 124.05/06, 140.070/076)	<input type="checkbox"/>	9151

Every 45,000 miles/72,000 km ( → M.Y. 1993)

Every 45,000 miles/72,000 km or 2 years (M.Y. 1994 →)

<input type="checkbox"/> Replace air recirculation filter (model 140)	<input type="checkbox"/>	8383
<input type="checkbox"/> Replace activated charcoal filters (model 210)	<input type="checkbox"/>	8382

## Body

<input checked="" type="checkbox"/> Lubricate door hinges (models 107, 126)	<input type="checkbox"/>	7220
<input checked="" type="checkbox"/> Lubricate door locks (models 107, 126)	<input type="checkbox"/>	7221
<input checked="" type="checkbox"/> Soft top locking lugs, check for wear (model 129)	<input type="checkbox"/>	7750
<input checked="" type="checkbox"/> Clean antenna mast with special cleaning cloth	<input type="checkbox"/>	8231
<input checked="" type="checkbox"/> Check condition of headlamp wiper blades	<input type="checkbox"/>	8252
<input type="checkbox"/> Replace windshield wiper insert(s)	<input type="checkbox"/>	8280

### Every Two Years

<input type="checkbox"/> Clean water drains ( → M.Y. 1993)	<input type="checkbox"/>	6030
<input type="checkbox"/> Clean and lubricate sliding roof rails ( → M.Y. 1993)	<input type="checkbox"/>	7730
<input type="checkbox"/> Inspect body for paint damage	<input type="checkbox"/>	9850

### Every Three Years

<input type="checkbox"/> Clean and lubricate sliding roof rails (M.Y. '94 →, except model 210)	<input type="checkbox"/>	7730
--	--------------------------	------

If job no. required ANY additional service  
please note on R.O. and check

Maintenance  
Job No.

### Wheels, tires & brakes

- Inspect, rotate wheels (please note specific instructions in Maint. Manual regarding models 140.070/076 M.Y. 95, 129.063/067/076 with AMG Sport Package, 170.447, 202.028 [C36 AMG])  4050
- Inspect tires and record tread depth  4051
- Correct tire pressure  4060
- Check brake pad/disk thickness, check condition of discs  4251
- Adjust parking brake (except models 140, 202, 210)  4261
- Once at 15,000 miles/24,000 km (model 129)

### Every Two Years

- Replace brake fluid  4280

### Underside of car

- Inspect condition, routing, leaks, of components, lines and hoses  0053
- Check and correct fluid level:*
- Manual transmission fluid  2610
- Transfer case fluid (4MATIC only)  2810
- Front axle fluid (4MATIC only)  3310
- Rear axle oil ( → M.Y. 1993)  3510
- Check front axle ball joints  3353
- Check steering play  4650
- Retighten steering gear bolts ( → M.Y. 1991)  4671

### Every Two Years

- Inspect suspension and body structure  0090

### Every 30,000 miles/48,000 km

- Check clutch disc for wear  2551
- Automatic transmission fluid and filter change (except [M.Y. 1996] models 140.043/051/057/070/076, 129.067/076, [M.Y. 1997 → ALL])  2702
- Inspect drive shaft flex discs  4152
- Inspect parking brake cables (except models 140, 202, 210)  4256
- Retighten steering gear bolts (M.Y. 1992 → )  4671
- (except models 140, 210) *Observe tightening torque!*

### Every 60,000 miles/96,000 km

- Replace fuel filter (except engines 102, 104, 119, 120<sup>2</sup>)  0780
- Check front axle ball joint freeplay (Models 124, 129, 201)  3355

### Engine compartment

- Inspect condition, routing, leaks, of components, lines and hoses  0053
- Engine oil and filter change  0101
- Reset Maintenance Service Reminder
- Check valve clearance (engine 102.983)  0561
- Check injection timing (engines 602 and 603)  0760
- Once at 15,000 miles/24,000 km (M.Y. 1990 → 1994)
- Check condition and tension of V-belts<sup>1)</sup> (engines 116 and 117)  1350
- Inspect poly-V-belt<sup>1)</sup>  1351
- Check spark plugs, replace if necessary<sup>1)</sup>  1550
- Replace spark plugs. Federal version ( → M.Y. 1987)
- Check and correct fluid level*
- Engine coolant/antifreeze protection  2010
- Automatic transmission fluid ( → M.Y. 1993)  2710
- Level control, ADS, ASD, 4MATIC fluid  3211
- Brake system  4210



If job no. required ANY additional service  
please note on R.O. and check

Maintenance  
Job No.

Engine compartment (continued)

Check and correct fluid level ( continued)

<input checked="" type="checkbox"/>	Power steering fluid	<input type="checkbox"/>	4611
<input type="checkbox"/>	Battery electrolyte (except models 124.034/036, 129, 140, 202, 210)	<input type="checkbox"/>	5410
<input checked="" type="checkbox"/>	Windshield washer fluid	<input type="checkbox"/>	8210
<input checked="" type="checkbox"/>	Inspect, lubricate engine throttle linkage	<input type="checkbox"/>	3022
<input checked="" type="checkbox"/>	Check A/C refrigerant charge (except model 210)	<input type="checkbox"/>	8312
<input type="checkbox"/>	Replace ventilation system dust filter (models 124, 129, 140 without activated charcoal filter)	<input type="checkbox"/>	8381

Every 30,000 miles/48,000 k

<input type="checkbox"/>	Check injection timing (Diesel engines) Once at 30,000 miles/48,000 km (M.Y. 1995 → )	<input type="checkbox"/>	0760
<input type="checkbox"/>	Replace fuel filter (Diesel engines only) ( → M.Y. 1995)	<input type="checkbox"/>	0780
<input type="checkbox"/>	Replace fuel prefilter (Diesel engines only) ( → M.Y. 1995)	<input type="checkbox"/>	0781
<input type="checkbox"/>	Replace air cleaner element (all engines → M.Y. 1996)	<input type="checkbox"/>	0980
<input type="checkbox"/>	Check condition and tension of V-belts 1) ( → M.Y. 1991) (engines 116 and 117)	<input type="checkbox"/>	1350
<input type="checkbox"/>	Inspect poly-V-belt ( → M.Y. 1991)	<input type="checkbox"/>	1351
<input type="checkbox"/>	Replace spark plugs	<input type="checkbox"/>	1580

Every 45,000 miles/72,000 km ( → M.Y. 1993)

Every 45,000 miles/72,000 km or 2 years (M.Y. 1994 →)

<input type="checkbox"/>	Replace dust filter (model 140, with activated charcoal filter only)	<input type="checkbox"/>	8381
--------------------------	--	--------------------------	------

Every 60,000 miles/96,000 km

<input type="checkbox"/>	Replace oxygen sensor. Once at 60,000 miles/96,000 km (model 201.028 California version only)	<input type="checkbox"/>	1480
<input type="checkbox"/>	Replace fuel filter (Diesel engine only) (M.Y. 1996 → )	<input type="checkbox"/>	0780
<input type="checkbox"/>	Replace fuel prefilter (Diesel engine only) (M.Y. 1996 → )	<input type="checkbox"/>	0781
<input type="checkbox"/>	Replace air cleaner element (M.Y. 1996 → )	<input type="checkbox"/>	0980

Every 75,000 miles/120,000 km ( → M.Y. 1993)

Every 75,000 miles/120,000 km or 4 years (M.Y. 1994 →)

<input type="checkbox"/>	Replace activated charcoal filter (model 140)	<input type="checkbox"/>	8382
--------------------------	---	--------------------------	------

Every Three years

<input type="checkbox"/>	Replace coolant (water/anticorrosion/antifreeze mixture)	<input type="checkbox"/>	2080
<input type="checkbox"/>	Battery electrolyte level (except maintenance-free batteries)	<input type="checkbox"/>	5410

Trunk

<input checked="" type="checkbox"/>	Correct tire pressure (spare)	<input type="checkbox"/>	4060
<i>Check and correct fluid level:</i>			
<input type="checkbox"/>	Rear window washer fluid (models 124.090/092/193/290)	<input type="checkbox"/>	8210
<input type="checkbox"/>	Hydraulic soft top fluid (models 124.066, 129)	<input type="checkbox"/>	7710

1) Mercedes-Benz urges that this procedure be performed to maintain peak performance, although it is not required to maintain your emission warranty and will not affect Mercedes-Benz's recall liability.

2) Replacement is not required at 60,000 miles on California version vehicles 1).

# SMOG CHECK VEHICLE INSPECTION REPORT

(06/24/2015 @ 9:40:02 am)

## Vehicle Information

Model Year..... 1997	Make..... MERCEDES-BENZ	Model..... SL320
License..... 5ZLN888	State..... California	VIN..... WDBFA63F8VF153299
Engine Size..... 3.2 Liters	Type..... Passenger	Transmission..... Automatic
GVWR..... N/A	Test Weight..... N/A	Cylinders..... 6
Odometer..... 46040	Certification..... California	VLT Record #..... 27847
Fuel Type..... Gasoline	Exhaust..... Single	Inspection Reason..... HEP
Engine Year..... N/A	Engine Make..... N/A	Bar Number..... N/A
Fleet BAR File #..... N/A		

## Overall Test Results

Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Visual Inspection..(Pass) Functional Check..(Pass) Emissions Test..(Pass)

DMV ID Number..(9200S128P039)  
Smog Check Certificate Number..(PS732360)

Your Smog Check certificate has been electronically transmitted to the DMV.  
This certificate is valid for ninety (90) days from the date of issuance.

Please keep this copy for your records.

## Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist the identification of oxides of nitrogen, crankcase, and cold start emissions which are not measured during the idle tests)

<u>ECS</u>	<u>Result</u>	<u>ECS</u>	<u>Result</u>	<u>ECS</u>	<u>Result</u>
PCV.....	Pass	Fuel Evaporative Controls.....	Pass	Catalytic Converter.....	Pass
Spark Controls.....	Pass	Fuel Injection.....	Pass	Pump Air Injection.....	Pass
Oxygen Sensor.....	Pass	Wiring to Sensors.....	Pass	Vacuum lines sensors/switches..	Pass
Other related emis. components.	Pass	Liquid Fuel Leak.....	Pass	Fuel Cap Visual.....	Pass
OBD System Check.....	Pass	Ignition Timing.....	N/A		

## Idle Emission Test Results

Test	RPM			%CO2			%O2			HC (PPM)			CO (%)			Result
	MEAS	MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	
M1: 0 MPH	701	14.8	0.0	100	17	13	1.00	0.00	0.00							Pass
M2: 0 MPH	2454	14.7	0.0	130	12	7	1.00	0.10	0.02							Pass

MAX = Maximum Allowed Emissions    AVE = Average Emissions For Passing Vehicles    MEAS = Amount Measured

## Smog Check Station Information

THE SMOG CENTER, INC  
968 PINER ROAD  
SANTA ROSA, CA 95403  
1 707 546 7664

Technician Name/Number..... RODIGOU, KATHARINA/EO630667  
Repair Tech Name/Number..... N/A  
Software Version/EIS Number... 1401/SX031103  
Station Number..... TC231510

I certify under penalty of perjury under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and correct.

Date

Technician's Signature



# EMISSION CONTROL WORK ORDER



## THE SMOG CENTER, INC.

968 B Piner Road  
SANTA ROSA, CA 95403  
(707) 546-SMOG (7664)  
BAR# ARD231510



067506

Date	10-24-15
Time Received	
	A.M. P.M.
Promised	A.M. P.M.
Written By	
Phone when ready	Yes <input type="checkbox"/> No <input type="checkbox"/>

<b>BILLING</b>	<input type="checkbox"/> CASH	Name	[Redacted]		<b>PHOTO</b>	
	<input checked="" type="checkbox"/> BANK CARD NO.	Address	[Redacted]			
	<input type="checkbox"/> OIL CO. CARD NO.	City	95492	Zip		
	<input type="checkbox"/> CHECK NO.	Year - Model	1997 Mercedes	Odometer		46040
	<input type="checkbox"/> OTHER	Vin No.	3299 SL320	License No.		5ZLN888

ALL PARTS ARE NEW UNLESS OTHERWISE DESIGNATED				REPAIR ORDER LABOR INSTRUCTION				INTERNAL	
* CODE N-NEW U-USED R-REBUILT				I/M SMOG INSPECTION				66.75	
I/M SMOG CERTIFICATE				EVAP TEST (1976 - 1995 Vehicles Only)				8.25	
NOTE:				Fed/Cal <input checked="" type="checkbox"/> Auto/Man <input checked="" type="checkbox"/> Eng/Change of Owner <input type="checkbox"/> Eng Size 3.2					
NO EVAP Test Performed <input type="checkbox"/>									
EVAP System Not Accessible <input type="checkbox"/>									
AIR									
4025									
MVC									
EVAP									
MVC									
PW									
We are a TEST ONLY facility & can NOT perform any repairs or adjustments to your vehicle if it fails.									
<b>TOTAL PARTS</b>				Smog Inspection Fee Is Due Whether Your Vehicle Passes, Fails, Or The Test Is Aborted.					

THIS IS TO ADVISE YOU THAT SOME EMISSION CONTROL DEVICES MAY STILL BE COVERED UNDER MFG.'S WARRANTY.  
BY LAW, YOU MAY CHOOSE ANOTHER LICENSED SMOG CHECK FACILITY TO PERFORM ANY NEEDED REPAIRS OR ADJUSTMENTS THAT THE SMOG CHECK TEST INDICATES ARE NECESSARY.

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees, permission to operate the car, truck or vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. In the event an attorney is retained to foreclose this lien or to bring suit for collection of any sums due I agree to pay costs of collection and reasonable attorney fees.

Authorized By	CUSTOMER ACKNOWLEDGES RECEIPT OF A COPY HEREOF	DATE	TIME	TOTAL LABOR	
ESTIMATE:				PARTS	
INSPECTION FEE	66.75	RETURN OLD PARTS	<input checked="" type="checkbox"/> Y <input type="checkbox"/> N	OIL & FLUIDS	
CERTIFICATE IF ISSUED	8.25	I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE.			
<b>TOTAL ESTIMATE</b>	75	X INITIALS _____		SUB-TOTAL	
ESTIMATED COST \$ OF ADDITIONAL REPAIR	DATE	TIME	IND. CONTACTED	TAX	
				GAS / GAL.	
				<b>TOTAL AMOUNT</b>	75

**SMILE AUTO SPECIALISTS, INC.**

1759 WILI-PA LOOP  
 Wailuku, HI. 96793  
 Phone - 808-877-2095 Fax - 808-249-0307

INVOICE

**4143**

RD-1173  
 MR-2258

\*\* FOR MILES OF SMILES \*\*

**INVOICE**

Work Completed Date : 08/11/2006

Print Date : 08/11/2006

1997 Mercedes-Benz - SL320  
 3.2L, In-Line6, VIN (Not Avai  
 Lic # : MKU621 Odometer In : 24733  
 Unit # : Odometer Out :  
 Vin # : WDBFA63F8VF153299  
 Hat # :

Hom  
 Cust ID : 745

Ref # :

Part Description / Number	Qty	List	Extended	Labor Description	Hours	Extended
CONTROL UNIT [CONVERTIBLE TOP] 1298203926	1.00	1,510.50	1,510.50	CK, CONV TOP; INOP TEST AS REQUIRED. REPL CONVERTIBLE TOP CONTROL UNIT. CLEAR ALL CODES & RETEST, O/K @ THIS TIME.	3.00	270.00
				SAFTEY INSPECTION;	N/A	15.00

Org. Estimate \$1,870.37 Revisions \$0.00 Current Estimate \$ 1,870.37 Additional Cost Revised Estimate

Labor:	\$285.00
Parts:	\$1,510.50
Sublet:	\$0.00
Sub:	\$1,795.50
	-----
Tax:	\$74.87
Total:	\$1,870.37
Bal Due:	\$1,870.37

[ Payments - ]

MAHALO

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

SIGNATURE..... Date..... Time.....

<none>



HHT printout 28.07.06 Passenger cars  
HHT module HHTWIN Version: 05/06

Quick test result DTC memory

Chassis number: FA63F8UF153299  
Vehicle model: SL 320 A/97  
License plate no.: MKU 621

ME2

MB number: 023 545 24 32  
Diagnostic version 2/02

No fault (DTC) stored

ASR

MB number: 018 545 92 32  
Diagnostic version 3/04

No fault (DTC) stored

ETC.6

MB number: 020 545 92 32  
Diagnostic version 1/04

No fault (DTC) stored

RCL

MB number: 210 820 32 26  
Diagnostic version 0/00

No fault (DTC) stored

RST

MB number: 129 820 31 26 PT.#  
Diagnostic version 2/02

097 Power window motor LF M10/3 Hall sensor	096 Power window motor RF Hall sensor M10/4
128 Power soft top control module N52 ✓	032 Voltage supply Low voltage
160 Power soft top switch S84	161 Roll bar switch S83

ATA

MB number: 140 820 85 26

PL  
Kiwi Hi 96753





Lic. # RD3605

ACROSS FROM KAHULUI FIRE DEPT.  
181 Dairy Road • Kahului, HI 96732  
Mailing Address: P.O. Box 6253 • Kahului, HI 96733-6253  
Phone (808) 877-2091 / Fax (808) 877-4492

INVOICE NO. 66435

MAKE Mercedes MODEL SL300E YEAR 97  
LICENSE NO. \_\_\_\_\_ MILEAGE \_\_\_\_\_

APPT. TIME \_\_\_\_\_ DROP-OFF TIME \_\_\_\_\_ PICK-UP TIME \_\_\_\_\_ CUSTOMER WAITING \_\_\_\_\_  
TIRE MILEAGE RATING: 40M  50M  60M  70M  80M  BATTERY WARRANTY: 40 mos.  50 mos.  60 mos.  72 mos.

WORK AUTHORIZED BY: \_\_\_\_\_

AUTHORIZED PERSON TO ACT IN MY BEHALF: \_\_\_\_\_

USED PARTS: SAVE  DISCARD

I hereby authorize the repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An expressed mechanics lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto.

NAME \_\_\_\_\_ ADDRESS \_\_\_\_\_ CITY Kah STATE Hi ZIP CODE 96753  
HOME PHONE \_\_\_\_\_ BUSINESS PHONE \_\_\_\_\_

**LOW PROFILE TIRE  
NO ROAD HAZARD WARRANTY**

**LIFETIME  
EXTENDED WARRANTY  
AND SERVICE POLICY**

1. Replacement on a pro-rata basis any tire that fails due to defects in workmanship and materials.
2. Replacement on a Pro-rata basis any tire that fails due to a normal road hazard.
3. Free rotations every 3,500 miles to insure maximum tire wear. (Includes Vehicle Maintenance Inspection.)
4. Free alignment check every 3,500 miles or at any time customer requests, if needed you will receive "Preferred Customer Discount".
5. Free brake inspection every 3,500 miles or at any time customer requests. Authorized Repairs at Preferred Customer Discount.
6. Free rebalance every 3,500 miles or anytime at customer request.
7. Free flat repairs for life of tire. \*\*
8. We suggest that you also change your oil and lubricate your vehicle at 3,500 mile intervals. At your request we will perform this service at "Preferred Customer Price".

\* ROAD HAZARD NOT APPLICABLE ON RECREATION OR COMMERCIAL VEHICLES.

\*\* A TIRE IS WORN OUT AT 2/32'S TIRE DEPTH.

YES x \_\_\_\_\_  
NO x \_\_\_\_\_

DATE	STORE	SALESMAN	NO.	CHARGE ACCT. NO.	CUSTOMER P.O. NO.	
12/15/80		91				
QUAN.	DESCRIPTION	OP	CODE	INSTLR #	PRICE	EXTENSION
4	225/55R16 Sport 9000				50%	398 96
	HAWAII STATE ENVIRONMENTAL FEE				100	
	Parade Advance Payment					598 96
	SHOP CHARGES					
	EXTENDED WARRANTY					
	TUBELESS TIRE VALVES					
	WHEEL BALANCE					
	TIRE DISPOSAL FEE					INC.
	ALIGNMENT/ CORRECTION RECOMMENDED					
	STANDARD					
	THRUST					
	4-WHEEL					

On this date the undersigned hereby purchases the listed merchandise for and on behalf of said customer, acknowledges receipt therefor, and agrees to pay the stated price therefor, or return said merchandise at option of seller, 30 days from the 10th of this month. Customer further agrees to pay 18% interest per annum, and all collection cost including attorney fees on overdue accounts. Aftermarket rim must retorque 75 miles after install.

**SUB TOTAL**

**SALES TAX**

PLEASE PAY THIS AMOUNT **598 96**

RECEIVED BY \_\_\_\_\_ THIS IS THE ONLY ITEMIZED INVOICE YOU WILL RECEIVE  
CREDIT CARD NO. \_\_\_\_\_ EXP. DATE \_\_\_\_\_ CHECK NO. \_\_\_\_\_

AMEX  VISAMC  CC1  DISC  CHECK  CASH  CHGE  CRDT MEMO  ROAD ADV





Lic. # RD3605

NAME John D. Kelly STATE HI ZIP CODE 96753  
 ADDRESS Pl.

HOME PHONE 96753 BUSINESS PHONE 96753

**NO ROAD HAZARD WARRANTY**  
**LOW PROFILE TIRE**

**LIFETIME EXTENDED WARRANTY AND SERVICE POLICY**

1. Replacement on a pro-rata basis any tire that fails due to defects in workmanship and materials.
2. Replacement on a pro-rata basis any tire that fails due to a normal road hazard.
3. Free rotations every 3,500 miles to insure maximum tire wear. (Includes Vehicle Maintenance Inspection.)
4. Free alignment check every 3,500 miles or at any time customer requests. If needed you will receive "Preferred Customer Discount".
5. Free brake inspection every 3,500 miles or at any time customer requests. Authorized Repairs at Preferred Customer Discount.
6. Free rebalance every 3,500 miles or anytime at customer request.
7. Free flat repairs for life of tire. \*\*
8. We suggest that you also change your oil and lubricate your vehicle at 3,500 mile intervals. At your request we will perform this service at "Preferred Customer Price".

\* ROAD HAZARD NOT APPLICABLE ON RECREATION OR COMMERCIAL VEHICLES.  
 \*\* A TIRE IS WORN OUT AT 2/32'S TIRE DEPTH.

YES  NO

ACROSS FROM KAHULUI FIRE DEPT.  
 181 Dairy Road • Kahului, HI 96732  
 Mailing Address: P.O. Box 6253 • Kahului, HI 96733-6253  
 Phone (808) 877-2091 / Fax (808) 877-4492

I hereby authorize the repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An expressed mechanics lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto.

MAKE MERCEDES MODEL CP SL320R YEAR 97  
 LICENSE NO. MKU-621 MILEAGE 022217

APPT. TIME \_\_\_\_\_ DROP-OFF TIME \_\_\_\_\_ PICK-UP TIME \_\_\_\_\_ CUSTOMER WAITING \_\_\_\_\_

TIRE MILEAGE RATING:  40M  50M  60M  70M  80M  90M  100M

BATTERY WARRANTY:  40 mos.  50 mos.  60 mos.  72 mos.

AUTHORIZED PERSON TO ACT IN MY BEHALF: \_\_\_\_\_

USED PARTS: SAVE  DISCARD

DATE	STORE	QUAN.	DESCRIPTION	OP	CODE	INSTR #	PRICE	EXTENSION
11/15/00	00	4	Bos/55R16 Sport 9000				214.75	859.00
		4	HAWAII STATE ENVIRONMENTAL FEE				1.00	
		4	SHIP				60.00	240.00
			SHOP CHARGES					
		4	EXTENDED WARRANTY				3.00	20.00
		4	TUBELESS TIRE VALVES				12.75	51.00
		4	WHEEL BALANCE					
		1	TIRE DISPOSAL FEE					INC.
			ALIGNMENT/ CORRECTION RECOMMENDED					
			STANDARD					
			THRUST					
			4-WHEEL					

On this date the undersigned hereby purchases the listed merchandise for and on behalf of said customer, acknowledges receipt therefor, and agrees to pay the stated price therefor, or return said merchandise at option of seller, 30 days from the 10th of this month. Customer further agrees to pay 18% interest per annum, and all collection cost including attorney fees on overdue accounts. Aftermarket rim must retorqued 75 miles after install.

RECEIVED BY John D. Kelly THIS IS THE ONLY ITEMIZED INVOICE YOU WILL RECEIVE

CREDIT CARD NO. \_\_\_\_\_ EXP. DATE \_\_\_\_\_ CHECK NO. \_\_\_\_\_

SUB TOTAL	1,202.00
SALES TAX	57.09
PLEASE PAY THIS AMOUNT	1,259.09

AMEX  VISA/MC  CC1  DISC  CHECK  CASH  CHGE  CRDT MEMO  ROA  ADV





Lic. # RD3605

ACROSS FROM KAHULUI FIRE DEPT.  
181 Dairy Road • Kahului, HI 96732  
Mailing Address: P.O. Box 6253 • Kahului, HI 96733-6253  
Phone (808) 877-2091 / Fax (808) 877-4492

INVOICE NO. 66679

I hereby authorize the repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An expressed mechanics lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto.

MAKE <i>Mitsubishi</i>	MODEL <i>EP-513002</i>	YEAR <i>97</i>
LICENSE NO. <i>MKY-601</i>	MILEAGE <i>00017</i>	
APPT. TIME	DROP-OFF TIME	PICK-UP TIME
TIRE MILEAGE RATING		BATTERY WARRANTY
<input type="checkbox"/> 40M	<input type="checkbox"/> 50M <input type="checkbox"/> 60M <input type="checkbox"/> 70M <input type="checkbox"/> 80M	<input type="checkbox"/> 40 mos. <input type="checkbox"/> 50 mos. <input type="checkbox"/> 60 mos. <input type="checkbox"/> 72 mos.

WORK AUTHORIZED BY: *K. Jani*

AUTHORIZED PERSON TO ACT IN MY BEHALF: \_\_\_\_\_

USED PARTS: SAVE  DISCARD

DATE: 8/15/00 STORE: 80 RET. COMM.  WHSL. NO. TAX  OIA  A  F  W  Z  CASH  DISC  CC1  CC2  CC3  CC4  CC5  CC6  CC7  CC8  CC9  CC0

### LOW PROFILE TIRE NO ROAD HAZARD WARRANTY

## LIFETIME EXTENDED WARRANTY AND SERVICE POLICY

- Replacement on a pro-rata basis any tire that fails due to defects in workmanship and materials.
- Replacement on a Pro-rata basis any tire that fails due to a normal road hazard.
- Free rotations every 3,500 miles to insure maximum tire wear. (Includes Vehicle Maintenance Inspection.)
- Free alignment check every 3,500 miles or at any time customer requests. If needed you will receive "Preferred Customer Discount".
- Free brake inspection every 3,500 miles or at any time customer requests. Authorized Repairs at Preferred Customer Discount.
- Free rebalance every 3,500 miles or anytime at customer request.
- Free flat repairs for life of tire. \*\*
- We suggest that you also change your oil and lubricate your vehicle at 3,500 mile intervals. At your request we will perform this service at "Preferred Customer Price".

\* ROAD HAZARD NOT APPLICABLE ON RECREATION OR COMMERCIAL VEHICLES.  
\*\* A TIRE IS WORN OUT AT 2/32'S TIRE DEPTH.

YES  NO

DATE	QUAN.	DESCRIPTION	OP	CODE	INSTLR #	PRICE	EXTENSION
8/15/00		ROA					598.96
		HAWAII STATE ENVIRONMENTAL FEE				1.00	
		SHOP CHARGES					
		EXTENDED WARRANTY					
		TUBELESS TIRE VALVES					
		WHEEL BALANCE					
		TIRE DISPOSAL FEE					
		ALIGNMENT CORRECTION RECOMMENDED					
		STANDARD					
		THRUST					
		4-WHEEL					

On this date the undersigned hereby purchases the listed merchandise for and on behalf of said customer, acknowledges receipt therefor, and agrees to pay the stated price therefor, or return said merchandise at option of seller, 30 days from the 10th of this month. Customer further agrees to pay 18% interest per annum, and all collection cost including attorney fees on overdue accounts. Aftermarket rim must retorque 75 miles after install.

RECEIVED BY: *X* THIS IS THE ONLY ITEMIZED INVOICE YOU WILL RECEIVE

CREDIT CARD NO. 436616307945082 EXP. DATE 05/07 CHECK NO. \_\_\_\_\_

PLEASE PAY THIS AMOUNT 598.96

SALES TAX \_\_\_\_\_

SUB TOTAL \_\_\_\_\_

AMEX  VISA/MC  DISC  CHECK  CASH  CHGE  CRDT MEMO  ROA  ADV

**SMILE AUTO SPECIALISTS, INC.**

1759 WILI-PA LOOP  
 Wailuku, HI. 96793  
 Phone - 808-877-2095 Fax - 808-249-0307

INVOICE

**2901**

RD-1173  
 MR-2258

\*\* FOR MILES OF SMILES \*\*

**INVOICE**

Work Completed Date : 06/30/2005

Print Date : 07/01/2005

Home 4  
 Cust ID : 745

Ref # :

1997 Mercedes-Benz - SL320  
 3.2L, In-Line6, VIN (Not Avai  
 Lic # : MKU621  
 Unit # :  
 Vin # : WDBFA63F8VF153299  
 Hat # :

Odometer In : 21807  
 Odometer Out :

Part Description / Number	Qty	List	Extended	Labor Description	Hours	Extended
AIR MASS SENSOR 0000941048	1.00	504.00	504.00	FUEL INJECTION SYSTEM - DIAGNOSIS	1.50	135.00
FREIGHT p	1.00	8.00	8.00	[Includes: Visual inspection, fuel pressure test and electronic engine control system test.]		
				MASS AIR FLOW SENSOR - REMOVE & REPLACE	1.00	90.00
				CLEAR ALL DTC CODES & ROAD TEST, O/K @ THIS TIME.		

Org. Estimate \$691.69    Revisions \$0.00    Current Estimate \$ 691.69    Additional Cost    Revised Estimate

<b>Labor:</b>	<b>\$225.00</b>
<b>Parts:</b>	<b>\$512.00</b>
<b>Sublet:</b>	<b>\$0.00</b>
<b>Sub:</b>	<b>\$737.00</b>
	-----
<b>Tax:</b>	<b>\$30.73</b>
<b>Total:</b>	<b>\$767.73</b>
<b>Bal Due:</b>	<b>\$767.73</b>

[ Payments - ]

*MAHALO*

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

SIGNATURE..... Date..... Time.....  
<none>



HHT printout 28.06.05 Passenger cars  
HHT module HHTWIN Version: 03/05

Quick test result DTC memory

Chassis number: FA63F8VF153299  
Vehicle model: 4/97 ~~SL~~ SL 320 mileage 21,807  
License plate no.: MKU 621

ME2

MB number: 023 545 24 32  
Diagnostic version 2/02

P0170 A Self adaptation  
part load at limit  
(AB1)

ASR

MB number: 018 545 92 32  
Diagnostic version 3/04

No fault (DTC) stored

ETC.6

MB number: 020 545 92 32  
Diagnostic version 1/04

No fault (DTC) stored

RCL

MB number: 210 820 32 26  
Diagnostic version 0/00

No fault (DTC) stored

RST

MB number: 129 820 31 26  
Diagnostic version 2/02

112 Limit switch S84/1  
Soft top  
L locked  
032 Voltage supply  
Low voltage

ATA

MB number: 140 820 85 26  
Diagnostic version 1/00

020 LF door actuator S47  
No ground  
006 Alarm activated via  
LF/RF door switches  
S17/3, S17/4

W PL  
153

014 Alarm activated via  
stop lamp switch S9/1

012 Alarm activated via  
ignition/starter  
switch S2/1

---

AB

MB number: 001 820 00 26  
Diagnostic version 3/00

No fault (DTC) stored

---

IC

MB number: 129 440 07 11  
Diagnostic version 1/16

B1755 Serial interface K2  
from A/C pushbutton  
control module to  
instrument cluster

B1755 Serial interface K2  
from A/C pushbutton  
control module to  
instrument cluster

---

AAC

MB number: 202 830 12 85  
Diagnostic version 4/02

B1416 Coolant circulation  
pump A31m1

B1419 Electromagnetic  
clutch A9k1

B1421 Cycle module N65

---

---

---

---

**SMILE AUTO SPECIALISTS, INC.**

1759 WILI-PA LOOP  
 Wailuku, HI. 96793  
 Phone - 808-877-2095 Fax - 808-249-0307

INVOICE

**1627**

RD-1173  
 MR-2258

\*\* FOR MILES OF SMILES \*\*

**INVOICE**

Work Completed Date : 05/04/2004

Print Date : 05/04/2004

Home  
 Cust ID : 745

Ref # :

1997 Mercedes-Benz S500  
 5L, V8, VIN (Not Available)  
 Lic # :  
 Unit # :  
 Vin # : WDBFA63F8VF153299  
 Hat # :

Odometer In : 18847  
 Odometer Out :

Part Description / Number	Qty	List	Extended	Labor Description	Hours	Extended
ENG OIL P	7.00	3.35	23.45	CK, ENG OIL LEAK; Slight leak from front upper Timing Cover.	N/A	N/C
ENG OIL FILTER P	1.00	16.00	16.00	CK, H/LIGHT/WASHER; WASHER FLUID PUMPS OUT WHEN HEAD LIGHTS ON.	1.50	120.00
ENG OIL ADDITIVE P	1.00	6.90	6.90	Test as required Repl Right side H/L Wiper Motor.		
LEFT/SIDE HEADLIGHT WIPER MOTOR 129 820 04 42	1.00	214.20	214.20	Repl Washer Pump w/updated pump.		
WASHER PUMP (UPDATED) 202 869 00 21	1.00	35.70	35.70	SERVICE; LOF, NONSCHEDULED LUBE WHERE NEEDED, LINKAGES ETC.	1.00	80.00
FREIGHT P	1.00	9.00	9.00	REPL ENG OIL, OIL FILTER & CLEAN AIR FILTER CORRECT ALL FLUID LEVELS.		
				SAFTEY INSPECTION; Registration defect	N/A	15.00

Org. Estimate \$272.25    Revisions \$0.00    Current Estimate \$ 272.25    Additional Cost    Revised Estimate

Labor:	\$215.00
Parts:	\$305.25
Sublet:	\$0.00
Sub:	\$520.25
-----	
Tax:	\$21.70
Total:	\$541.95
Bal Due:	\$541.95



[ Payments - ]

MAHALO

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

SIGNATURE..... Date..... Time.....  
<none>



04/17/2003 at 03:01 PM  
44594

Job Number:

BLAKE'S AUTO BODY  
"REMEMBER"- BLAKE'S AUTO BODY  
1024 N. DUTTON AVE.

SANTA ROSA, CA 95401  
(707)544-7410 Fax: (707)544-7843

PRELIMINARY ESTIMATE

Written by: RICK ZIESCHE #  
Adjuster: Karen Conyers #

Insured: STATE FARM INSURED  
Owner:  
Address: Santa Rosa, CA 95404  
Evening:

Claim #05-4902-87102  
Policy #  
Deductible:  
Date of Loss: 04/11/2003 at 03:30 PM  
Type of Loss: Liability  
Point of Impact: 6. Rear

Inspect BLAKE'S AUTO BODY  
Location: 1024 N. DUTTON AVE.

Business: (707)544-7410

SANTA ROSA, CA 95401

Insurance STATE FARM INSURANCE COMPANIES  
Company:

Business: (800)440-6175  
5 Days to Repair

1997 BENZ SL320 6-3.2L-FI 2D CNVT BLUE Int:  
VIN: WDBFA63F8VF153299 Lic: 3WNL078 CA Prod Date: 04/1997 Odometer: 017119  
Air Conditioning Rear Defogger Cruise Control  
Auto Level Climate Control Theft Deterrent/Alarm  
Dual Mirrors Fog Lamps Clear Coat Paint  
Power Steering Power Brakes Power Windows  
Power Locks Power Driver Seat Power Passenger Seat  
Power Antenna Power Mirrors Power Trunk/Tailgate  
Anti-Lock Brakes (4) Driver Air Bag Passenger Air Bag  
Front Side Impact Air Bag 4 Wheel Disc Brakes Roll Bar  
Leather Seats Bucket Seats Recline/Lounge Seats

NO.	OP.	DESCRIPTION	QTY	EXT.	PRICE	LABOR	PAINT
1		TRUNK LID					
2*	Rpr	Lid				4.0	2.0
3		Add for Clear Coat					0.8
4		REAR LAMPS					
5	R&I	High mount lamp				0.5	
6		TRUNK LID					
7	Repl	Emblem Mercedes	1		9.25	0.3	
8	Repl	Emblem grommet	1		0.70	0.3	
9	Repl	Finish panel	1		10.00	0.6	
10	Repl	Cyl & keys w/infra-red system	1		208.00	0.3	
11		REAR BODY & FLOOR					
12	R&I	Trunk lid trim				0.3	

PRELIMINARY ESTIMATE  
1997 BENZ SL320 6-3.2L-FI 2D CNVT BLUE Int:

NO.	OP.	DESCRIPTION	QTY	EXT. PRICE	LABOR	PAINT
13*	Rpr	Panel below lid			4.5	1.5
14		Overlap Major Adj. Panel				-0.4
15		Add for Clear Coat				0.2
16	R&I	Rear panel trim upper			0.3	
17	R&I	Rear panel trim lower			0.3	
18*	R&I	Floor cover			0.2	
19		QUARTER PANEL				
N 20*	Rpr	LT Outer panel left side w/antenna hole			0.5	1.3
21		Overlap Major Adj. Panel				-0.4
22		Add for Clear Coat				0.2
23		ELECTRICAL				
24		REAR LAMPS				
25	R&I	RT Tail lamp assy			0.6	
26	R&I	RT License lamp			Incl.	
27	R&I	LT License lamp			Incl.	
28		REAR BUMPER				
29*	R&I	Bumper assy w/Sport			1.5	
N 30	Refn	Bumper assy w/Sport				2.6
31		Add for Clear Coat				1.0
32*	R&I	Antenna assy--ON LT QUARTER			1.5	
33#		COVER CAR TO PROTECT/OVERSPRAY	1	5.00	0.3	
34#		TINT COLOR	1		0.5	
35#		HAZ.WASTE EPA#CAD981170681	1	3.00 X		
36#		FLEX AGENT	1	6.00 T		
37#		CORROSION PROTECTION	1	10.00	0.3	
Subtotals ==>				251.95	16.8	8.8

Line 20 : PREP SCRATCH AND BLEND LT QUARTER PANEL WITH FULL CLEARCOAT.  
Line 30 : REFINISH REAR BUMPER COVER FOR SCRATCHES.

Parts		242.95
Body Labor	16.8 hrs @ \$ 65.00/hr	1092.00
Paint Labor	8.8 hrs @ \$ 65.00/hr	572.00
Paint Supplies	8.8 hrs @ \$ 25.00/hr	220.00
Sublet/Misc.		9.00
SUBTOTAL		\$ 2135.95
Sales Tax	\$ 468.95 @ 7.5000%	35.17
GRAND TOTAL		\$ 2171.12
ADJUSTMENTS:		
Deductible		0.00
CUSTOMER PAY		\$ 0.00
INSURANCE PAY		\$ 2171.12

04/24/2003 at 09:06 AM  
44594

Job Number:

BLAKE'S AUTO BODY  
"REMEMBER"- BLAKE'S AUTO BODY  
1024 N. DUTTON AVE.

SANTA ROSA, CA 95401  
(707)544-7410 Fax: (707)544-7843

PRELIMINARY ESTIMATE

Written by: RICK ZIESCHE #  
Adjuster:

Insured:  
Owner: J  
Address: Santa Rosa, CA 95404  
Evening:

Claim #CFO  
Policy #  
Deductible:  
Date of Loss:  
Type of Loss: Other  
Point of Impact: 3. Right T-Bone

Inspect BLAKE'S AUTO BODY  
Location: 1024 N. DUTTON AVE.

Business: (707)544-7410

SANTA ROSA, CA 95401

Insurance STATE FARM INSURANCE COMPANIES  
Company: SANTA ROSA

4 Days to Repair

1997 BENZ SL320 6-3.2L-FI 2D CNVT BLUE Int:  
VIN: WDBFA63F8VF153299 Lic: 3WNL078 CA Prod Date: 04/1997 Odometer: 17119  
Air Conditioning Rear Defogger Cruise Control  
Auto Level Climate Control Theft Deterrent/Alarm  
Dual Mirrors Fog Lamps Clear Coat Paint  
Power Steering Power Brakes Power Windows  
Power Locks Power Driver Seat Power Passenger Seat  
Power Antenna Power Mirrors Power Trunk/Tailgate  
Anti-Lock Brakes (4) Driver Air Bag Passenger Air Bag  
Front Side Impact Air Bag 4 Wheel Disc Brakes Roll Bar  
Leather Seats Bucket Seats Recline/Lounge Seats

NO.	OP.	DESCRIPTION	QTY	EXT.	PRICE	LABOR	PAINT
1		QUARTER PANEL					
2	Blnd	RT Outer panel right side					1.3
3		REAR LAMPS					
4	R&I	RT Tail lamp assy			0.6		
5		FENDER					
6	Blnd	RT Fender					1.3
7		FRONT LAMPS					
8*	R&I	RT Signal lens--corner lamp			0.3		
9*	R&I	R&I Rt HdLp-to access corner lamp R&I			0.6		
10		DOOR					
11*	Rpr	RT Door shell			5.0		2.5



PRELIMINARY ESTIMATE  
1997 BENZ SL320 6-3.2L-FI 2D CNVT BLUE Int:

NO.	OP.	DESCRIPTION	QTY	EXT. PRICE	LABOR	PAINT
12		Add for Clear Coat				1.0
13	R&I	RT Mirror w/o auto dim w/o folding			0.6	
14	R&I	RT Handle, outside			0.4	
15*	R&I	RT Trim panel 320, 500			0.6	
16*	R&I	RT Molding assy--clean & retape & reinstall			0.5	
17		FRONT BUMPER				
18*	R&I	R&I bumper assy--Loosen cover--Rt side			1.0	
19		REAR BUMPER				
20*	R&I	R&I bumper assy--Loosen cover--Rt side			1.0	
21#		HAZ.WASTE EPA#CAD981170681	1	3.00 X		
22#		TINT COLOR	1		0.5	
23#		COLOR SAND AND POLISH	1		2.0	
24#		COVER CAR TO PROTECT/OVERSPRAY	1	5.00	0.3	
Subtotals ==>				8.00	13.4	6.1

Estimate Notes:

PLEASE NOTE: DENTS IN RIGHT DOOR CAN BE TAKEN OUT VIA PAINTESS DENT REMOVAL FOR \$231.25. DENTS, FOR THE MOST PART, CAN BE TAKEN OUT COMPLETELY OR AT LEAST REDUCED TO AN ACCEPTABLE SIZE MUCH CHEAPER THAN REPAIRING THE DOOR VIA CONVENTIONAL MEANS.

THIS ESTIMATE WAS WRITTEN AT THE REQUEST OF THE OWNER,

ON 4/23/03.

Parts		5.00
Body Labor	13.4 hrs @ \$ 65.00/hr	871.00
Paint Labor	6.1 hrs @ \$ 65.00/hr	396.50
Paint Supplies	6.1 hrs @ \$ 25.00/hr	152.50
Sublet/Misc.		3.00
SUBTOTAL		\$ 1428.00
Sales Tax	\$ 157.50 @ 7.5000%	11.81
GRAND TOTAL		\$ 1439.81
ADJUSTMENTS:		
Deductible		0.00
CUSTOMER PAY		\$ 0.00
INSURANCE PAY		\$ 1439.81

# Blakes Auto Body-SANTA ROSA

1024 N. DUTTON AVE.

B A R # AH195698  
E P A # CAL000102704

*Customer Copy*

**SANTA ROSA, CA 95401-**  
**(707) 544-7410 -**  
**Fax: (707) 544-7843**

**Name:** \_\_\_\_\_ **Phone - Home:** \_\_\_\_\_  
**Address:** \_\_\_\_\_ **Phone - Work:** ( ) - \_\_\_\_\_  
Santa Rosa, CA 95404

**RO Nbr:** 70639 **Supp:** 2 **Estimate:** Auto Pathways 9  
**Year:** 97 **Make:** BENZ **Model:** SL320 **Style:** 2D CNVT **Color:** BLUE  
**VIN:** WDBFA63F8VF153299 **License:** 3WNL078 **Odometer:** 17119  
**Miles Out:** 17119

**Insurance:** STATE FARM INSURANCE COMPANIES **Phone:** ( ) - **Serv Writer:** ZIESCHE, RICK  
**Address:** \_\_\_\_\_ **Fax:** ( ) - **RO Create:** 04/17/03

**Claim Nbr:** 05-4902-87102 **Claimant:** Yes **Deduct \$:** 0.00 **Act Out:** / / 0 days

Oper	Description	Labor Units	Labor Type	Paint	Misc	Type Qty	Each	Total
	<b>TRUNK LID</b>							
Repair	Lid	4.0	Body	2.0				
	Add for Clear Coat			0.8				
	<b>REAR LAMPS</b>							
Remove&Install	High mount lamp	0.5	Body					
	<b>TRUNK LID</b>							
Remove&Replace	Emblem Mercedes	0.3	Body			OEM 1	12.65	12.65
Remove&Replace	Emblem grommet	0.3	Body			OEM 3	1.40	4.20
Remove&Replace	Finish panel	0.6	Body			OEM 1	94.00	94.00
	<b>REAR BODY &amp; FLOOR</b>							
	<b>TRUNK LID</b>							
Remove&Install	Cyl & keys w/infra-red system	0.3	Body					
Remove&Install	Trunk lid trim	0.3	Body					
Repair	Panel below lid	4.5	Body	1.5				
	Overlap Major Adj. Panel			-0.4				
	Add for Clear Coat			0.2				
Remove&Install	Rear panel trim upper	0.3	Body					
Remove&Install	Rear panel trim lower	0.3	Body					
Remove&Install	Floor cover	0.2	Body					
	<b>QUARTER PANEL</b>							
Repair	LT Outer panel left side w/antenna hole	0.5	Body	1.3				
	Overlap Major Adj. Panel			-0.4				
	Add for Clear Coat			0.2				
	<b>ELECTRICAL</b>							
	<b>REAR LAMPS</b>							
Remove&Install	RT Tail lamp assy	0.6	Body					
Remove&Install	RT License lamp							
Remove&Replace	LT Tail lamp assy	0.6	Body			OEM 1	238.00	238.00
Remove&Install	LT License lamp							
	<b>REAR BUMPER</b>							
Remove&Install	Bumper assy w/Sport	1.5	Body					
Refinish	Bumper assy w/Sport			2.6				
	Add for Clear Coat			1.0				

# Blakes Auto Body-SANTA ROSA

1024 N. DUTTON AVE.

BAR# AH195698  
EPA# CAL000102704

SANTA ROSA, CA 95401-  
(707) 544-7410 -  
Fax: (707) 544-7843

Name: \_\_\_\_\_ Phone - Home: \_\_\_\_\_  
Address: \_\_\_\_\_ Phone - Work: ( ) - \_\_\_\_\_

RO Nbr: 70639 Supp: 2 Estimate: Auto Pathways 9

Oper	Description	Labor Units	Labor Type	Paint	Misc	Type Qty	Each	Total
Remove&Install	Antenna assy--ON LT QUARTER COVER CAR TO PROTECT/OVERSPRAY TINT COLOR HAZ.WASTE EPA#CAD981170681 FLEX AGENT CORROSION PROTECTION S01= CORRECTION TO ORIG ESTIMATE <b>REMOVEABLE TOP</b>	1.5	Body	0.3 No Material 0.5 No Material	Yes \$5.00	1		
		0.3	Body		Yes \$6.00 Yes \$10.00	1		
Remove&Install	Roof assy steel roof fr VIN107603 <b>REAR BODY &amp; FLOOR QUARTER PANEL</b>	1.0	Body					
Blend	RT Outer panel right side			1.3				
Refinish	Upper panel Add for Clear Coat DATE IN = 4/21/03; DATE OUT = 4/25/03; *****FINAL BILL***** *****AUTHORIZATION & DIRECTION TO PAY SECURED***** *****			1.0 0.2				

Totals	Units	Rate	Units	Rate	Additional			
Parts						Parts	\$348.85	
Body	17.6	\$65.00		\$1,144.00		Body	\$1,144.00	
Paint			12.1	\$65.00	\$786.50	Paint	\$786.50	
Paint Materials			11.3	\$25.00	\$282.50	\$24.00	Paint Mat.	\$306.50
Tax		(\$652.35 @7.50%)				Tax	\$48.93	
						<b>Total</b>	<b>\$2,634.78</b>	



# Blakes Auto Body-SANTA ROSA

1024 N. DUTTON AVE.

BAR# AH195698  
EPA# CAL000102704

SANTA ROSA, CA 95401-  
(707) 544-7410 -  
Fax: (707) 544-7843

Name: \_\_\_\_\_

RO Nbr: 70639                      Supp: 2

		Supplement	Totals
		Original	\$2,171.12
		1	\$71.25
		2	\$392.41
Customer Pays		Insurance Pays	
Repair Work	\$0.00	Repair Work	\$2,634.78
Deductible	\$0.00		
Total	\$0.00	Total	\$2,634.78
		This Supplement	\$2,563.53

Blake's Auto Body would like to thank you for allowing us to repair your vehicle to its pre-accident condition. We hope that you are thoroughly satisfied with our repair work.

NOT RESPONSIBLE FOR LOSS OF ARTICLES LEFT IN CARS

I hereby authorized the above work to be done along with supplying the necessary material, and hereby grant you and/or your employees permission to operate the vehicle described on streets, highways or elsewhere for the purpose of testing and/or inspection. A statutory possessory lien is hereby acknowledged pursuant to California Code of Civil Procedures Sections 3051 and 3068 of seq. on the above vehicle to secure the amount of repairs thereto. Further, in the event that legal action is commented to enforce any provisions of this agreement, the party prevailing in such action shall be entitled to a reasonable sum, for their attorney's fees in such action.

Should the need of service ever rise again, please be assured that our staff will be happy to help you in any way we can. Once again, thank you for the opportunity to serve you.

I hereby authorize any and all supplements payable to BLAKE'S AUTO BODY. I authorize BLAKE'S AUTO BODY to act as POWER OF ATTORNEY TO SIGN any payments.

Authorized by: \_\_\_\_\_ Date: \_\_\_\_\_

In person: \_\_\_\_\_ Phone #: \_\_\_\_\_  
By phone: \_\_\_\_\_ Time: \_\_\_\_\_  
Driver's Lic #: \_\_\_\_\_



FOR YOUR CONVENIENCE OUR  
SERVICE DEPT. HOURS: MONDAY  
THRU FRIDAY 7:30 AM TO 5:00 PM


TERMS: CASH - VISA  
MASTERCARD

CHECK ACCEPTANCE POLICY:  
1. PREPRINTED CHECKS WITH NAME, ADDRESS  
AND PHONE NUMBER.

2. VALID UNITED STATES DRIVER LICENSE.

NO CARS RELEASED  
AFTER 5:00 PM

Mercedes-Benz



**Smothers**  
**EUROPEAN**  
2881 CORBY AVE.  
SANTA ROSA, CA 95407  
707-542-4810  
BAR #AH 096993  
CAL 000077883

RO NUMBER	DATE CLOSED	MILEAGE	S M R	T E C H	T Y P E	OP CODE	DESCRIPTION	OP CODE	DESCRIPTION	OP CODE	DESCRIPTION	OP CODE	DESCRIPTION

SHOWN ABOVE ARE THE MOST RECENT SERVICES  
PERFORMED ON YOUR VEHICLE.

CURRENT MILEAGE **12797**

BASED ON THE CURRENT MILEAGE OF YOUR  
VEHICLE. THE MANUFACTURER RECOMMENDS  
THAT THE SERVICES MARKED WITH AN "X" BE  
PERFORMED NOW.

value thereof or otherwise, against loss occasioned by theft, fire or vandalism while the property remains with the dealer.  
2. Customer states no articles of personal property have been left in the vehicle and dealer is not responsible for inspection thereof.  
3. The dealer is not responsible for unavailability of parts or delays in parts shipment beyond dealer's control.  
4. Due to the type of service requested some repairs must be subtle.  
5. All charges for repairs including labor and materials furnished are due and payable simultaneously with the delivery of the within described vehicle or prior to delivery upon the expiration of three (3) days after notice that the repairs have been completed. Notice shall be deemed to have been given upon the deposit in the United States mail, postage prepaid, of written notification to that effect addressed to the customer at the address given on the reverse side hereof.  
6. If the vehicle described herein is not called for within three (3) days after such notice is given, a storage charge of \$15.00 per day will be made for each day thereafter.

6. In addition to any and all other legal remedies available, I authorize Said Dealer to have a lien on the vehicle described herein for all charges for repairs, including labor and parts, storage and/or towing, and to enforce such lien. Said Dealer is hereby expressly authorized to sell said vehicle at public auction after giving a twenty (20) day written notice by certified mail to the legal owner, registered owner, and Department of Motor Vehicles of intent to do so. On the sale date, the vehicle shall be sold to the highest cash bidder and the proceeds of sale must be used first to satisfy the lien plus storage costs and costs incident to sale, and the balance shall be forwarded to the legal owner, or if none, to the registered owner, or if the address is unknown, it shall be forwarded to the Department of Motor Vehicles.  
Said expenses for sale shall also include a reasonable attorney's fee, which may be necessarily incurred.  
9. If any such charges remain unpaid for thirty (30) days after such request for payment, Said Dealer may also refer such charges to its attorneys for collection and the customer will pay a reasonable attorney's fee.

**EXCLUSION OF WARRANTIES**  
 Any warranties on the parts and accessories sold hereby are made by the manufacturer. The undersigned understands and agrees that dealer makes no warranties of any kind, express or implied and disclaims all warranties of merchantability or fitness for a particular purpose, with regard to the parts and/or accessories purchased, and that in no event shall dealer be liable for incidental or consequential damages or commercial losses arising out of such purchase. The undersigned purchaser further agrees that the warranties excluded by dealer, include, but are not limited to, any warranties that such parts and/or accessories are of merchantable quality or that they will enable any vehicle or any of its systems to perform with reasonable safety, efficiency, or comfort.

WASH  YES  NO  
 QUALITY CONTROLLED BY   
 STALL NUMBER   
 MILEAGE OUT  DATE OUT

DATE: \_\_\_\_\_ SIGNED: \_\_\_\_\_ X

CUST. NO. 66846 STOCK NO. \_\_\_\_\_ TAG NO. TU99 COLOR 012/268  
 VEHICLE IDENTIFICATION NUMBER WDBFA638VF153299  
 DELIVERY DATE 31 JUL 97 LICENSE NUMBER 3WNL078 MAKE AND MODEL 97 MERCEDES SL320R/95  
 MILEAGE 12797  
 P.O. NO. \_\_\_\_\_  
 AXLE NO. \_\_\_\_\_

NAME \_\_\_\_\_  
 ADDRESS \_\_\_\_\_  
 CITY/STATE/ZIP SANTA ROSA CA 95404  
 BUSINESS PHONE 707-546-4702  
 LABOR RA 96.00  
 CASH 05106  
 WARRANTY EXPIRES 30 JUL 01

ENGINE NO. 104991-12-027895  
 TRANSM. NO. 722605-00-337260  
 1) RADIO CODE#12111 SERIAL#T09677410  
 METHOD OF PAYMENT CASH  
 SELLING DEALER \_\_\_\_\_  
 GAS/OIL/GREASE \_\_\_\_\_  
 TOWING \_\_\_\_\_  
 MISC. CHARGES \_\_\_\_\_  
 SUBLETS \_\_\_\_\_  
 P.O. NO. \_\_\_\_\_

LINE	FC	OP CODE	LABOR INSTRUCTIONS AND DESCRIPTIONS	AMOUNT
A	40		OWNER REPORTS VIBRATION AT 60-65 MPH CHECK AND BALANCE TIRES AS NEEDED	
B	MBZ-15		15000 MAINT. SERVICE	
C	421423		BRAKE FLUID, REPLACE	
D	201140		ENGINE COOLANT, REPLACE AND CHECK FOR LEAK(S)	



CUSTOMER SIGNATURE \_\_\_\_\_ FOREMAN'S SIGNATURE \_\_\_\_\_  
 CUSTOMER \_\_\_\_\_ LOCKOUT  LEAVE OUT  SALES DEPT.



# smothers EUROPEAN

CORBY AVE.  
TA ROSA, CA 95407  
542-4810  
#AH 096993  
30077883



Mercedes-Benz

## SMOTHERS EUROPEAN CUSTOMER SATIS- FACTION POLICY

It is our intention to make service the number one priority at Smothers European. If there is any suggestion you can make to provide a better Service Department, please let us know. By law, you may choose another facility to perform any needed repairs or adjustments which the Smog Check test indicates are necessary.

PAGE 2

<b>SMOTHERS EUROPEAN</b> 2881 Corby Ave. Santa Rosa, CA 95407 707-542-4810	<b>ORIGINAL ESTIMATE</b>		\$			
	REVISED EST. \$	DATE	TIME	PERSON CONTACTED	PHONE NO.	
	REVISED EST. \$	DATE	TIME	PERSON CONTACTED	PHONE NO.	
	MEANS OF CONTACTING <input type="checkbox"/> IN PERSON <input type="checkbox"/> BY PHONE			MEANS OF CONTACTING <input type="checkbox"/> IN PERSON <input type="checkbox"/> BY PHONE		
NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK I acknowledge notice and oral approval of an increase in the original estimated price and/or also acknowledge and approve all repairs as itemized below.						
VEHICLE IDENTIFICATION		CUST. NO.	TAG NO.	P.O. NO.	INVOICE PRINTED	INVOICE NO.
A63F8VF153299		66846	TU99		05MAR02	180693
MAKE & MODEL	TELEPHONE NO.	CUST. PAY LABOR RATE	DELIVERY DATE	PREPARED BY	S/A	
SL320R/95		96.00	31 JUL 97	55	55	
MISCELLANEOUS COMMENT / LOCATION						

HOURS	LIST UNIT	NET UNIT	TOTAL
24.48		24.48	24.48
14.50		48.00	48.00
14.95		14.95	14.95
			2.00



DESCRIPTION	TOTALS		
LABOR AMOUNT	460.80	<p>STATEMENT OF DISCLAIMER</p> <p>The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.</p> <p>NOTICE TO CUSTOMERS</p> <p>WE MAKE A SEPARATE CHARGE FOR THE STORAGE AND DISPOSAL OF TOXIC WASTES. CAL 000077863</p> <p>RATHER THAN RECOVER THESE COSTS BY INCREASING OUR LABOR RATES TO ALL OF OUR SERVICE CUSTOMERS, WE MAKE THIS CHARGE ONLY ON THOSE PARTICULAR REPAIRS OR SERVICES WHICH GENERATE THESE WASTES.</p> <p>THESE ARE UNIFORM CHARGES WHICH ARE CALCULATED ANNUALLY FOR EACH PARTICULAR SERVICE AND ARE AVAILABLE ON REQUEST.</p>	
PARTS AMOUNT	184.78		
GAS. OIL, LUBE	20.00		
SUBLET AMOUNT	0.00		
MISC. CHARGES	2.00		
TOTAL CHARGES	667.58		
LESS INSURANCE	0.00		
SALES TAX	15.36		
PLEASE PAY THIS AMOUNT →	682.94		CUSTOMER SIGNATURE
NOTE TIRES ON REAR OF VEHICLE WORN ON OUTER EDGES WILL NEED REPLACEMENT SOON			

PAID BY  
CREDIT CARD

LOCKOUT  LEAVE OUT  SALES DEPT.

CUSTOMER

6888 3

# smothers

## EUROPEAN

CORBY AVE.  
 TA ROSA, CA 95407  
 542-4810  
 #AH 096993  
 00077883



Mercedes-Benz

### SMOTHERS EUROPEAN CUSTOMER SATIS- FACTION POLICY

It is our intention to make service the number one priority at Smothers European. If there is any suggestion you can make to provide a better Service Department, please let us know. By law, you may choose another facility to perform any needed repairs or adjustments which the Smog Check test indicates are necessary.


PAGE 1

<b>SMOTHERS EUROPEAN</b> 2881 Corby Ave. Santa Rosa, CA 95407 707-542-4810	<b>ORIGINAL ESTIMATE</b>		\$		
	REVISED EST. \$	DATE	TIME	PERSON CONTACTED	PHONE NO.
	REVISED EST. \$	DATE	TIME	PERSON CONTACTED	PHONE NO.
	MEANS OF CONTACTING <input type="checkbox"/> IN PERSON <input type="checkbox"/> BY PHONE		MEANS OF CONTACTING <input type="checkbox"/> IN PERSON <input type="checkbox"/> BY PHONE		
<small>NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK          I acknowledge notice and oral approval of an increase in the original estimated price and/or also acknowledge and approve all repairs as itemized below</small>					
<b>VEHICLE IDENTIFICATION</b>	<b>CUST. NO.</b>	<b>TAG NO.</b>	<b>P.O. NO.</b>	<b>INVOICE PRINTED</b>	<b>INVOICE NO.</b>
A63FBVF153299	66846	TU99		05MAR02	180693
<b>MAKE &amp; MODEL</b>	<b>TELEPHONE NO.</b>	<b>CUST. PAY LABOR RATE</b>	<b>DELIVERY DATE</b>	<b>PREPARED BY</b>	<b>S/A</b>
SL320R/95		96.00	31JUL97	55	55
MISCELLANEOUS COMMENT / LOCATION					

HOURS	LIST UNIT	NET UNIT	TOTAL
	60-65 MPH CHECK		
	REDED TIRES		
1.00		0.00	0.00
	FOR OIL		
		20.00	20.00
	W. AT FILES -		
1.80		364.80	364.80
	19.25	19.25	19.25
	3.00	3.00	3.00
	0.50	0.50	2.00



	1.05	1.05	1.05
ER	35.00	35.00	35.00
RK			
	2.52	2.52	15.12
ER	61.00	61.00	61.00
PLACE			
0.50		48.00	48.00



DESCRIPTION	TOTALS	
LABOR AMOUNT		<p>STATEMENT OF DISCLAIMER</p> <p>The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.</p> <p>NOTICE TO CUSTOMERS</p> <p>WE MAKE A SEPARATE CHARGE FOR THE STORAGE AND DISPOSAL OF TOXIC WASTES. CAL 000077883</p> <p>RATHER THAN RECOVER THESE COSTS BY INCREASING OUR LABOR RATES TO ALL OF OUR SERVICE CUSTOMERS, WE MAKE THIS CHARGE ONLY ON THOSE PARTICULAR REPAIRS OR SERVICES WHICH GENERATE THESE WASTES.</p> <p>THESE ARE UNIFORM CHARGES WHICH ARE CALCULATED ANNUALLY FOR EACH PARTICULAR SERVICE AND ARE AVAILABLE ON REQUEST.</p>
PARTS AMOUNT		
GAS, OIL, LUBE		
SUBLET AMOUNT		
MISC. CHARGES		
TOTAL CHARGES		
LESS INSURANCE		
SALES TAX		
PLEASE PAY THIS AMOUNT →		→ CUSTOMER SIGNATURE

LOCKOUT  LEAVE OUT  SALES DEPT.

CUSTOMER

6008 1

\* INVOICE \*

Invoice #: 172313  
Tag #: T690  
Customer #: 66846

**Smothers**  
**EUROPEAN**



2880 TALMADGE DR.  
SANTA ROSA, CA 95407  
(707) 542-4811

Mercedes-Benz  
EPA# CAL 000260231

Service  
Advisor: 101 NICK STAUER

CELL:

SANTA ROSA, CA 95401-7303

HOME:  
EMAIL: :om | home

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN	MILEAGE OUT
012/268	97	MERCEDES SL320R/95	WDBFA63F8VF	3WNL078	43479	43479
DEL DATE	PROD. DATE	WARR. EXP.	PO NO.	RATE	PAYMENT	R.O. OPENED
31JUL97	11APR97	30JUL2001	17:00	23JUL13	CASH	14:09 22JUL13
OPTIONS: DLR:05106 ENG:104991-12-027895 TRN:722605-00-337260 1RADIO CODE#12111 SERIAL#T09677410		SERIAL#T09677410		14:09 22JUL13		16:12 23JUL13

A CUST STATES BATTERY WONT HOLD A CHARGE CK AND ADVISE  
OO ELECTRICAL TESTING

LABOR: 236 CM 145.00 PARTS: 0.00 OTHER: 0.00  
...43479 had to jump start veh. to get it into shop, batt. is dead,  
...performed midtronics test, batt. failed test, performed alternator test  
... diodes and alternator good, batt. does not hold charge, recommend  
... replacing batt. with big white batt.

TOTAL LINE A: \$ 145.00

B LUBE, OIL AND FILTER SERVICE  
LOF LUBE, OIL AND FILTER SERVICE

LABOR: 236 CM 72.50 PARTS: 71.50 OTHER: 0.00  
1 104-180-01-09 OIL FILTER  
1 007603-014106 RING  
8 2050 ENG OIL  
...43479 REPLACED OIL AND FILTER AND SET OIL LEVEL TO PROPER  
... SPECIFICATION.

TOTAL LINE B: \$ 144.00

C ROTATE TIRES  
4040 ROTATE TIRES

LABOR: 236 IM 0.00 PARTS: 0.00 OTHER: 0.00  
...43479 rotated tires, torqued wheels, tires that were rotated to the  
... rear outer edges bald-4/32nds, recommend replacing 2 tires and  
... performing alignment, rotated tires back to original, dont want  
... customers good rear tires to be ruined by putting on front of veh.

TOTAL LINE C: \$ 0.00 (N/C)

JOAN DALY

Smothers

European

Would Like To

Thank You

For Your

Continued

Patronage



Thank You!

Original Estimate \$  
Please read the important information on the reverse side of invoice.  
I acknowledge receipt of this invoice.  
I acknowledge the warranty repairs performed.  
I acknowledge notice and oral approval of additional Warranty repairs discovered and corrected during this repair visit.

Signature X \_\_\_\_\_

I acknowledge notice and oral approval of an increase in the original estimated price.

STATEMENT OF DISCLAIMER  
The factory warranty constitutes all of the warranties with respect to the sale of this item. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item.  
NOTICE TO CUSTOMERS  
WE MAKE A SEPARATE CHARGE FOR THE DISPOSAL OF TOXIC WASTES.  
CAL 000077883  
RATHER THAN RECOVER THESE COSTS BY INCREASING OUR LABOR RATES TO ALL OF OUR SERVICE CUSTOMERS, WE MAKE THIS CHARGE ONLY ON THOSE PARTICULAR REPAIRS OR SERVICES WHICH GENERATE THESE WASTES. THESE ARE UNIFORM CHARGES WHICH ARE CALCULATED ANNUALLY FOR EACH PARTICULAR SERVICE AND ARE AVAILABLE UPON REQUEST.

SMOTHERS EUROPEAN CUSTOMER SATISFACTION POLICY  
It is our intention to make service the number one priority at Smothers European. If there is any suggestion you can make to provide a better Service Department, please let us know. By law, you may choose another facility to perform any needed repairs or adjustments which the Smog Check test indicates are necessary.

DESCRIPTION	LABOR AMOUNT	PARTS AMOUNT	GAS, OIL, LUBE	SUBLET AMOUNT	MISC. CHARGES	TOTAL CHARGES	ADJUSTMENTS	SALES TAX	PLEASE PAY THIS AMOUNT
TOTALS									

Mailing Address:

2881 Corby Ave. Santa Rosa, CA 95407

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK

Page 1 of 2

THANK YOU!



\*INVOICE\*

Invoice #: 172313  
Tag #: T690  
Customer #: 66846

SANT/ 7303  
HOME: PHS:  
EMAIL: j

Service Advisor: 101 NICK STAUER

Mercedes-Benz  
EPA# CAL 000280231

**Smothers**  
**EUROPEAN**  
2880 TALMADGE DR.  
SANTA ROSA, CA 95407  
(707) 542-4811



COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN	MILEAGE OUT
012/268	97	MERCEDES SL320R/95	WDBFA63F8VF 153299	3WVNL078	43479	43479
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT
31JUL97	11APR97	30JUL2001	17:00 23JUL13			CASH
OPTIONS: DLR:05106 ENG:104991-12-027895 TRN:722605-00-337260 1RADIO CODE#12111 SERIAL#T09677410						

**LABOR:** 236 CM  
**PARTS:** 0.00  
**OTHER:** 0.00  
**TOTAL LINE D:** 0.00

**LABOR:** 72.50  
**PARTS:** 165.00  
**OTHER:** 0.00  
**TOTAL LINE E:** 237.50

**LABOR:** 0.00  
**PARTS:** 0.00  
**OTHER:** 0.00  
**TOTAL LINE D:** 0.00

**LABOR:** 72.50  
**PARTS:** 165.00  
**OTHER:** 0.00  
**TOTAL LINE E:** 237.50

**LABOR:** 72.50  
**PARTS:** 165.00  
**OTHER:** 0.00  
**TOTAL LINE E:** 237.50

DESCRIPTION	LABOR AMOUNT	PARTS AMOUNT	GAS, OIL, LUBE	SUBLET AMOUNT	MISC. CHARGES	TOTAL CHARGES	ADJUSTMENTS	SALES TAX	PLEASE PAY THIS AMOUNT
<b>TOTALS</b>									
	290.00	236.50	0.00	0.00	0.00	526.50	0.00	20.69	547.19

**SMOTHERS EUROPEAN CUSTOMER SATISFACTION POLICY**  
 It is our intention to make service the number one priority at Smothers European. If there is any suggestion you can make to provide a better Service Department, please let us know. By law, you may choose another facility to perform any needed repairs or adjustments which the Smog Check test indicates are necessary.

**STATEMENT OF DISCLAIMER**  
 The factory warranty constitutes all of the warranties with respect to the sale of this item. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item.

**NOTICE TO CUSTOMERS**  
 WE MAKE A SEPARATE CHARGE FOR THE DISPOSAL OF TOXIC WASTES. RATHER THAN RECOVER THESE COSTS BY INCREASING OUR LABOR RATES TO ALL OF OUR SERVICE CUSTOMERS, WE MAKE THIS CHARGE ONLY ON THOSE PARTICULAR REPAIRS OR SERVICES WHICH GENERATE THESE WASTES. THESE ARE UNIFORM CHARGES WHICH ARE CALCULATED ANNUALLY FOR EACH PARTICULAR SERVICE AND ARE AVAILABLE UPON REQUEST.

I acknowledge notice and oral approval of an increase in the original estimated price.

Initials \_\_\_\_\_

Original Estimate \$ \_\_\_\_\_  
 Please read the important information on the reverse side of invoice.

I acknowledge receipt of this invoice.  
 I acknowledge the warranty repairs performed.  
 I acknowledge notice and oral approval of additional Warranty repairs discovered and corrected during this repair visit.

Signature X \_\_\_\_\_

**JOAN DALY**  
**Smothers**  
**European**  
**Would Like To**  
**Thank You**  
**For Your**  
**Continued**  
**Patronage**

**Thank You!**

Mercedes-Benz

Customer Copy

Mailing Address: 2881 Corby Ave. Santa Rosa, CA 95407



# MERCEDES-BENZ of Santa Rosa



## OUR VALUED CUSTOMER

**Carey Daly**

5533 OAK MEADOW DR  
SANTA ROSA, CA 95401-7303-0935  
(707) 542-6609  
JOAN@DALY-HOME.COM

**NICK STAUER**  
*Service Consultant*

**M. BENNETT**  
*Certified Technician*

### YOUR VEHICLE

Year 1997	Make Mercedes-Benz	Model SL320	Engine Type 3.2L 6 DOHC (MFI)
Odometer 43,479	VIN # WDBFA63F8VF153299	License # 3WNL078	Date 7/24/2013

# Vehicle Care Commitment

---

## It's about "Peace of Mind..."

Thank you for choosing our service department to handle your vehicle's service needs. In order to provide the quality service you deserve, we have invested in the latest diagnostic equipment and information systems. These help us fully understand your vehicle's service and maintenance requirements so that we can service your vehicle in the most comprehensive and economical way possible.



We are pleased to present to you a "Know Your Vehicle" report today. It's important to us that you leave our dealership with peace of mind, so we take the extra time necessary to analyze your vehicle's health to make sure it is operating at its optimum levels. This bumper-to-bumper inspection report will help you better understand your vehicle's performance and health. Staying on top of your vehicle's health is vitally important to ensuring your safety on the road.



Thank you for this opportunity to assist you. We appreciate your business. Please feel free to contact your service advisor if you have any questions or concerns. We will do everything we can to put your mind at ease and keep you and your family safe on the road.



## How we give you "Peace of Mind..."

---

To help you understand what your vehicle needs to stay in top operating condition, we:

- Perform a world class visual inspection on your vehicle every visit
- Review your vehicle's maintenance schedules and search our extensive database to uncover anything we believe you should know about your vehicle based on its odometer reading and time on the road
- Make recommendations and complete a Treatment Plan for your vehicle
- Offer a complete easy to read and understand report that enables you to make an educated decision for your vehicle's service needs. Items on the report will be classified as follows:
  - Pass - Items are new or "like new" and do not require service at this time
    - Items that are dirty or showing signs of wear and would benefit from being serviced soon
  - Fail - Items that have either worn below minimum specifications or are no longer doing what it was designed to do and need to be repaired immediately

*DISCLAIMER: Addressing any identified issues listed by the report, should improve the safety and performance of your vehicle. However, please remember that the inspection is limited to a visual inspection of the items listed on the report without disassembling or test driving your vehicle. Therefore, it is not possible for the technician to see or identify all potential defects, especially those that are internal to the engine, transmission, driveline, electrical system or other components. The cleanliness of the vehicle both inside and out at the time of the actual inspection may reduce the accuracy of the inspection. Your vehicle may have conditions that are not evident at the time of the inspection or otherwise not presented or noticed during the inspection process. Therefore, the inspection and condition report does not provide any guarantee or warranty that the vehicle will not break down in the future, or have conditions that were undetected during the inspection or were omitted from the report.*



## Original Customer Requests

The following is what you requested we perform or investigate regarding your vehicle:

- ✓ A. CUST STATES BATTERY WONT HOLD A CHARGE CK AND ADVISE (batt. dead)
- ✓ recommend replacing batt. (big white)
- ✓ B. LUBE,OIL AND FILTER SERVICE
- ✓ C. ROTATE TIRES
- ✓ D. COMPLIMENTARY MULTIPOINT INSPECTION



## Package Results

Mercedes Benz of Santa Rosa World Class  
Inspection (for Mobile)

Failed Task	Observation	Recommendation
Inspect transmission mounts and shift linkage	Found shift linkage bushing missing/ cracked	Replace shift linkage bushings
Measure right front tire tread depth	3/32: or less	
Inspect rear differential for leaks	Found left rear axle seal to be leaking	Replace left rear axle seal

Cautioned Task	Observation	Recommendation
Inspect Axles, Flex disk(s) and CV joints/boots	Found rear flex disc worn/cracked	Replace rear flex disc
Inspect overall tire wear and condition	Found both front tires abnormally worn	<ul style="list-style-type: none"> <li>• Mount and balance 2 new front tires</li> <li>• Perform four (4) wheel alignment</li> </ul>
Inspect all vehicle wiper blades	Found windshield wiper blades streaking	Replace windshield wiper blades
Inspect serpentine belt (drive belts)	Found all drive belts damaged/cracked	Replace serpentine belt
Measure left front tire tread depth	4/32: Will need tires soon	
Check brake fluid level/condition/leaks	Found brake fluid to be dirty/contaminated	Replace brake fluid

Passed Task	Observation	Recommendation
Check/Adjust front tire pressure	Set tire pressures to 34 psi - Check tire pressures monthly	



Passed Task	Observation	Recommendation
Fill windshield washer fluid	Found washer fluid level low : Filled to proper level	
Other brake system observations	All brakes wearing normally - Inspect next service	
Check/Adjust rear tire pressure	Set tire pressures to 34 psi - Check tire pressures monthly	

### Passed Tasks

- |   |  |  |
|---|--|--|
| ✓ Inspect exhaust system for leaks, damage, and loose parts             | ✓ Check/Adjust front tire pressure   | ✓ Inspect wheel bearings   |
| ✓ Inspect engine mounts   | ✓ Inspect engine air cleaner element   | ✓ Fill windshield washer fluid   |
| ✓ Inspect hazard light(s) operation                                     | ✓ Inspect brake light(s) operation   | ✓ Inspect back-up light(s) operation   |
| ✓ Inspect taillight, turn signal, side marker, and license plate lights | ✓ Inspect taillight, turn signal, fog lamps and side marker assemblies for cracks/damage | ✓ Inspect fog lamps, driving lamps and headlight (low and bright beam) operation |
| ✓ Inspect windshield wiper/washer operation                             | ✓ Inspect horn operation   | ✓ Inspect climate control operation  |
| ✓ Inspect dash and interior lights operation                            | ✓ Measure front brake lining thickness   | ✓ Other brake system observations  |
| ✓ Check/Adjust rear tire pressure                                       | ✓ Inspect instrument panel warning lamps   | ✓ Inspect all hoses and clamps   |
| ✓ Inspect steering and sway bar components                              | ✓ Inspect suspension components  | ✓ Inspect fuel injection/induction system  |
| ✓ Measure left rear tire tread depth                                    | ✓ Measure right rear tire tread depth  | ✓ Measure rear brake lining thickness  |
| ✓ Inspect left front tire   | ✓ Inspect right rear tire  | ✓ Inspect right front tire   |
| ✓ Inspect left rear tire  | ✓ Inspect front wiper blades   | ✓ Inspect rear window wipers (if equipped)                                       |
| ✓ Inspect instrument panel warning lamps                                | ✓ Inspect transfer case for leaks  | ✓ Check power steering fluid level/condition/leaks                               |
| ✓ Check engine coolant level/condition/leaks                            | ✓ Check automatic transmission fluid level/condition/leaks                               | ✓ Inspect front differential for leaks   |
| ✓ Check engine oil level/condition/leaks                                |  |  |

Additional Observations	Recommendation
found steering shock leaking	recommend replacing steering shock
fuel filter by time	recommend replacing fuel filter
3rd brake light inop	time to diag 3rd brake light all bulbs inop



## Recommended Services

Our technicians recommend the following services for your vehicle.

Original Customer Requests		Status	Cost	Declined	Approved	
A. CUST STATES BATTERY WONT HOLD A CHARGE CK AND ADVISE			\$145.00		X	
recommend replacing batt. (big white) (batt. dead)		Caution	\$237.50		X	
B. LUBE,OIL AND FILTER SERVICE			\$125.00		X	
C. ROTATE TIRES			\$20.00		X	
D. COMPLIMENTARY MULTIPOINT INSPECTION			\$0.00		X	
Subtotal			\$527.50		\$527.50	
Inspection & Additional Recommendations		Insp	Status	Cost	Declined	Approved
Replace shift linkage bushings (Found shift linkage bushing missing/ cracked)		x	Fail	\$150.95	X	
Replace left rear axle seal (Found left rear axle seal to be leaking)		x	Fail	\$374.77	X	See AI-108
recommend replacing steering shock (found steering shock leaking)			Fail	\$185.55	X	
Subtotal				\$711.27	\$711.27	
Replace rear flex disc (Found rear flex disc worn/cracked)		x	Caution	\$638.70	X	
Replace serpetine belt (Found all drive belts damaged/cracked)		x	Caution	\$251.55	X	See AI-11
Replace brake fluid (Found brake fluid to be dirty/contaminated)		x	Caution	\$167.00	X	See AI-13
Replace windshield wiper blades (Found windshield wiper blades streaking)		x	Caution	\$42.00	X	See AI-20
Mount and balance 2 new front tires (Found both front tires abnormally worn)		x	Caution	\$351.50	X	See AI-23
Perform four (4) wheel alignment (Found both front tires abnormally worn)		x	Caution	\$169.95	X	See AI-35
recommend replacing fuel filter (fuel filter by time)			Caution	\$206.60	X	
time to diag 3rd brake light all bulbs inop (3rd brake light inop)			Caution	\$145.00	X	
Subtotal				\$1,972.30	\$1,972.30	
Totals, Taxes and Fees			Cost	Declined	Approved	
Estimate Subtotal			\$3,211.07	\$2,683.57	\$527.50	
Tax			\$86.60		\$14.03	
<b>Estimate Total</b>			<b>\$3,297.67</b>		<b>\$541.53</b>	



For "See AI-" items   see the "Additional Info"

## Specifications & Capacities

We searched our database for specification and capacity information and found the following:

Description	Specification
Spark plugs	Electrode gap = .032 inches
Fuel Tank	21.5 US Gallons
Transmission	Special Lubricant Fluid OE Part No/Spec: MB 236.14 (722.6)

## Additional Information

Below is information we feel would help you better understand some of the reasons for taking preventive maintenance steps -- steps that help to ensure the reliability and safety of your vehicle for you and your family.

\*\* The following section may contain instructions for servicing various components of your vehicle. These are an overview of the process that will be performed by a skilled technician in our shop. They are not intended to be a guide for a "do-it-yourself" operation.

Belt replacement - serp, acc, fan, drive, v


AI-11

### Operation Description:

Loosen the drive belt tensioner and remove the old belt. Inspect the tensioner and idler pulley bearings for noise or signs of wear. Inspect tensioner and idler pulleys. Install the new belt. Start the engine, and after a minute or so, shut the engine off. Recheck the belt tension and make final adjustments as necessary.

### Significance:

The accessory drive belts on your vehicle perform many functions. The power steering system, alternator (charging system), and AC system are all driven by accessory drive belts. On some vehicles, accessory drive belts also drive the water pump, engine cooling fan, and air injection pump (emission control). Accessory drive belts wear during normal engine operation, and need to be checked and replaced periodically; you can lose one or more systems if a belt is broken. A broken fan or waterpump belt can cause severe overheating which could result in expensive repairs, or even total engine failure. A broken power steering belt can result in the loss of your vehicle's power steering system, which could make your vehicle very difficult to steer. A broken alternator belt could cause your vehicle to lose all of its electrical power, and could eventually result in a dead battery.



*Worn accessory drive belt*



*New accessory drive belt*



\* INVOICE \*

Invoice #: 155934  
Tag #: T795  
Customer #: 66846  
Service  
Advisor: 101 NICK STAUER

3 SANTA ROSA, CA 95403-0935  
HOME: 9 BUS: 3pm | home  
EMAIL: CELL: 1

**Smothers**  
**EUROPEAN**  
2880 TALMADGE DR.  
SANTA ROSA, CA 95407  
(707) 542-4811



Mercedes-Benz  
EPA# CAL 000250231

BAR# ARD 223139


COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN	MILEAGE OUT
012/268	97	MERCEDES SL320R/95	WDBFA63F8VF	3WNL078	39540	39540
DEL DATE	PROD. DATE	WARR. EXP.	PO NO.	INV. DATE	R.O. OPENED	READY
31 JUL 97	11 APR 97	30 JUL 2001	22:22 27 JUN 11	28 JUN 11	10:14 27 JUN 11	15:00 28 JUN 11
OPTIONS: DLR:05106 ENG:104991-12-027895 TRN:722605-00-337260 1RADIO CODE#12111 SERIAL#T09677410						

LIST NET TOTAL

A CAR TO BE SUBLETTERED TO BLAKES TO MATCH PAINT FOR TOW PORTION OF BUMPER, PART IS HERE TO BE PAINTED  
00 MATCH COLOR FOR BUMPER PAINT

LABOR: 299 IM PARTS: 0.00 OTHER: 0.00 TOTAL LINE A: \$ 0.00 (N/C)

\*\*\*\*\*



Mercedes-Benz

JOAN DALY

Smothers

European

Would Like To

Thank You

For Your

Continued

Patronage



Thank You!

Customer Copy

DESCRIPTION	LABOR AMOUNT	PARTS AMOUNT	GAS, OIL, LUBE	SUBLET AMOUNT	MISC. CHARGES	TOTAL CHARGES	ADJUSTMENTS	SALES TAX	PLEASE PAY THIS AMOUNT
SMOTHERS EUROPEAN CUSTOMER SATISFACTION POLICY									0.00
It is our intention to make service the number one priority at Smothers European. If there is any suggestion you can make to provide a better Service Department, please let us know. By law, you may choose another facility to perform any needed repairs or adjustments which the Smog Check test indicates are necessary.									0.00
STATEMENT OF DISCLAIMER									0.00
The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.									0.00
NOTICE TO CUSTOMERS									0.00
WE MAKE A SEPARATE CHARGE FOR THE DISPOSAL OF TOXIC WASTES. CAL 000077883									0.00
RATHER THAN RECOVER THESE COSTS BY INCREASING OUR LABOR RATES TO ALL OF OUR SERVICE CUSTOMERS, WE MAKE THIS CHARGE ONLY ON THOSE PARTICULAR REPAIRS OR SERVICES WHICH GENERATE THESE WASTES. THESE ARE UNIFORM CHARGES WHICH ARE CALCULATED ANNUALLY FOR EACH PARTICULAR SERVICE AND ARE AVAILABLE UPON REQUEST.									0.00
I acknowledge notice and oral approval of an increase in the original estimated price.									0.00
Initials _____									0.00
Original Estimate \$ _____									0.00
Please read the important information on the reverse side of invoice.									0.00
I acknowledge receipt of this invoice.									0.00
I acknowledge the warranty repairs performed.									0.00
I acknowledge notice and oral approval of additional Warranty repairs discovered and corrected during this repair visit.									0.00
Signature X _____									0.00
Mailing Address: 2881 Corby Ave. Santa Rosa, CA 95407									0.00

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK

Page 1 of 1

THANK YOU!



\* INVOICE \*

Invoice #: 154989  
Tag #: T860  
Customer #: 66846

**Smothers**  
**EUROPEAN**  
2880 TALMADGE DR.  
SANTA ROSA, CA 95407  
(707) 542-4811



Mercedes-Benz

BAR# ARD 223139  
EPA# CAL 000250231

Service  
Advisor: 101 NICK STAUER

SANTA ROSA, CA 95403-0935  
HOME: 7( )9 BUS:  
EMAIL: jc e.com | home

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN	MILEAGE OUT
012/268	97	MERCEDES SL320R/95	WDBFA63F8VF 153299	3WNL078	39106	39108
DEL DATE	PROD. DATE	WARR. EXP.	PO NO.	INV. DATE	R.O. OPENED	READY
31JUL97	11APR97	30JUL2001	22:22 12MAY11	13MAY11	09:21 12MAY11	13:14 13MAY11

OPTIONS: DLR:05106 ENG:104991-12-027895 TRN:722605-00-337260 1|RADIO CODE#12111 SERIAL#T09677410

LIST NET TOTAL

**A** MERCEDES-BENZ COMPLIMENTARY COURTESY VEHICLE PROVIDED (\$49.95 DAILY VALUE)  
MLOAN MERCEDES-BENZ COMPLIMENTARY COURTESY VEHICLE PROVIDED (\$49.95 DAILY VALUE)

LABOR: 299 CM  
0.00 PARTS: 0.00 OTHER: 0.00 TOTAL LINE A: \$ 0.00

**B** CUSTOMER STATES CHECK ENGINE LIGHT IS ON CK AND ADVISE  
CEL CUSTOMER STATES CHECK ENGINE LIGHT IS ON.

54 REPLACE CAMSHAFT SENSOR  
82 CM  
1 004-153-00-28 CAM SENDER  
LABOR: 270.00 PARTS: 189.20 OTHER: 0.00 TOTAL LINE B: \$ 459.20  
39108 CONFIRMED CHECK ENGINE LIGHT IS ON. PERFORMED SHORT TEST.  
CODE SET FOR CAMSHAFT SENSOR. REPALCED CAMSHAFT SENSOR AND ERASED  
CODES.

**C** PULL OR ORDER PART# 129-880-0205-9999  
00 SERVICE

299 CM  
1 129-880-02-05-9999 TOW HOOK COVER  
LABOR: 0.00 PARTS: 138.02 OTHER: 0.00 TOTAL LINE C: \$ 138.02

EST: 135.00 12MAY11 09:21 SA: 101

Thank You!

Original Estimate \$  
Please read the important information on the reverse side of invoice.  
I acknowledge receipt of this invoice.  
I acknowledge the warranty repairs performed.  
I acknowledge notice and oral approval of additional Warranty repairs discovered and corrected during this repair visit.

I acknowledge notice and oral approval of an increase in the original estimated price.

Signature X Initials

**STATEMENT OF DISCLAIMER**  
The factory warranty constitutes all of the warranties with respect to the sale of this item. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item.  
**NOTICE TO CUSTOMERS**  
WE MAKE A SEPARATE CHARGE FOR THE DISPOSAL OF TOXIC WASTES. RATHER THAN RECOVER THESE COSTS BY INCREASING OUR LABOR RATES TO ALL OF OUR SERVICE CUSTOMERS, WE MAKE THIS CHARGE ONLY ON THOSE PARTICULAR REPAIRS OR SERVICES WHICH GENERATE THESE WASTES. THESE ARE UNIFORM CHARGES WHICH ARE CALCULATED ANNUALLY FOR EACH PARTICULAR SERVICE AND ARE AVAILABLE UPON REQUEST.

**SMOTHERS EUROPEAN-CUSTOMER SATISFACTION POLICY**  
It is our intention to make service the number one priority at Smothers European. If there is any suggestion you can make to provide a better Service Department, please let us know. By law, you may choose another facility to perform any needed repairs or adjustments which the Smog Check test indicates are necessary.

DESCRIPTION	LABOR AMOUNT	PARTS AMOUNT	GAS, OIL, LUBE	SUBLET AMOUNT	MISC. CHARGES	TOTAL CHARGES	ADJUSTMENTS	SALES TAX	PLEASE PAY THIS AMOUNT
	270.00	327.22	0.00	0.00	0.00	597.22	0.00	31.09	628.31
<b>TOTALS</b>									

**Mailing Address:**  
2881 Corby Ave. · Santa Rosa, CA 95407

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK

Page 1 of 1

THANK YOU!



PAID BY CREDIT CARD  
Customer Copy



\*INVOICE\*

Invoice #: 149840  
Tag #: T739  
Customer #: 66846

**Smothers**  
**EUROPEAN**

SANTA ROSA, CA 95403-0935  
H  
EMAIL: j...  
BUS:

2880 TALMADGE DR.  
SANTA ROSA, CA 95407  
(707) 542-4811

Service  
Advisor: **NICK STAUER**

Mercedes-Benz  
EPA# CAL000250231

COLON	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN	MILEAGE OUT
012/268	97	MERCEDES SL320R/95	WDBFA63F8VF	3WNL078	37162	37162
DEL DATE	PROD. DATE	WARR. EXP.	PO NO.	INV. DATE	R.O. OPENED	READY
31JUL97	11APR97	30JUL2001	20:20	14SEP10	09:43	10SEP10
OPTIONS: DLR:05106 ENG:104991-12-027895 TRN:722605-00-337260 1)RADIO CODE#12111 SERIAL#T09677410						

AIR FILTER 92.75 BRAKE FLUSH  
165.00 5426609

LIST NET TOTAL

JOAN DALY

Smothers

European

Would Like To

Thank You


For Your

Continued

Patronage



Thank You!



Mercedes-Benz

PAID BY  
CREDIT CARD

Customer Copy

DESCRIPTION	LABOR AMOUNT	PARTS AMOUNT	GAS, OIL, LUBE	SUBLET AMOUNT	MISC. CHARGES	TOTAL CHARGES	ADJUSTMENTS	SALES TAX	PLEASE PAY THIS AMOUNT
SMOTHERS EUROPEAN CUSTOMER SATISFACTION POLICY									
STATEMENT OF DISCLAIMER									
NOTICE TO CUSTOMERS									
TOTALS									444.00
TOTALS									1202.85
TOTALS									0.00
TOTALS									0.00
TOTALS									0.00
TOTALS									1646.85
TOTALS									0.00
TOTALS									111.26
TOTALS									1758.11

Original Estimate \$ \_\_\_\_\_  
 Please read the important information on the reverse side of invoice.  
 I acknowledge receipt of this invoice.  
 I acknowledge the warranty repairs performed.  
 I acknowledge notice and oral approval of additional Warranty repairs discovered and corrected during this repair visit.

Signature X \_\_\_\_\_  
 Initials \_\_\_\_\_

Mailing Address:  
 2881 Corby Ave. Santa Rosa, CA 95407

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK

Page 3 of 3

THANK YOU!



\*INVOICE\*

Invoice #: 149840  
Tag #: T739  
Customer #: 66846  
Service Advisor: 101 NICK STAUER


**Smothers**  
**EUROPEAN**  
2880 TALMADGE DR.  
SANTA ROSA, CA 95407  
(707) 542-4811  
Mercedes-Benz  
EPA# CAL 000250231

3  
SANTA ROSA, CA 95403-0935  
HOME: '2 BUS:  
EMAIL: j com home

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN	MILEAGE OUT
012/268	97	MERCEDES SL320R/95	WDBFA63F8VF	3WNL078	37162	37162
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	INV. DATE	R.O. OPENED	READY
31JUL97	11APR97	30JUL2001	20:20 10SEP10	14SEP10	09:43 10SEP10	09:05 14SEP10

OPTIONS: DLR:05106 ENG:104991-12-027895 TRN:722605-00-337260 1RADIO CODE#12111 SERIAL#T09677410

LIST	NET	TOTAL
D** REPLACE CAM MAGNET 05 REPLACE CAM MAGNET		
1 236 CM 1 119-051-00-77 CAM MAGNET	131.60	130.00
LABOR: 130.00 PARTS: 131.60 OTHER: 0.00		131.60
*****37162 REPLACED CAM MAGNET, APPLIED SEALANT, INSTALLED NEW CAM *****MAGNET, LET SEALANT SET		\$ 261.60
E** REPLACE AIR FILTER 00 REPLACE AIR FILTERS		
1 236 CM 1 003-094-73-04A AIR FILTER	53.75	39.00
LABOR: 39.00 PARTS: 53.75 OTHER: 0.00		53.75
*****37162 REPLACED ENGINE AIR FILTER		\$ 92.75
F** BG BRAKE FLUSH, REMOVE BRAKE FLUID, REFILL BRAKE FLUID AND BLEED BRAKES. TEST OPERATION. BGBF BG BRAKE FLUSH, REMOVE BRAKE FLUID, REFILL BRAKE FLUID AND BLEED BRAKES. TEST OPERATION.		
1 236 CM 1 84032 BRAKE FLUID	29.95	130.00
LABOR: 130.00 PARTS: 29.95 OTHER: 0.00		29.95
*****37162 PERFORMED BG BRAKE FLUSH, SET CORRECT FLUID LEVEL, TESTED *****OPERATION OF BRAKES		\$ 159.95

-----  
**JOAN DALY**  
**Smothers**  
**European**  
**Would Like To**  
**Thank You**  
**For Your**  
**Continued**  
**Patronage**  
  
 -----

**Thank You!**

Original Estimate \$ \_\_\_\_\_  
 Please read the important information on the reverse side of invoice.  
 I acknowledge receipt of this invoice.  
 I acknowledge the warranty repairs performed.  
 I acknowledge notice and oral approval of additional Warranty repairs discovered and corrected during this repair visit.  
 Signature X \_\_\_\_\_

I acknowledge notice and oral approval of an increase in the original estimated price.  
 Initials \_\_\_\_\_

STATEMENT OF DISCLAIMER  
 The factory warranty constitutes all of the warranties with respect to the sale of this item/terms. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/terms.  
 NOTICE TO CUSTOMERS  
 WE MAKE A SEPARATE CHARGE FOR THE DISPOSAL OF TOXIC WASTES. RATHER THAN RECOVER THESE COSTS BY INCREASING OUR LABOR RATES TO ALL OF OUR SERVICE CUSTOMERS. WE MAKE THIS CHARGE ONLY ON THOSE PARTICULAR REPAIRS OR SERVICES WHICH GENERATE THESE WASTES. THESE ARE UNIFORM CHARGES WHICH ARE CALCULATED ANNUALLY FOR EACH PARTICULAR SERVICE AND ARE AVAILABLE UPON REQUEST.

SMOTHERS EUROPEAN CUSTOMER SATISFACTION POLICY  
 It is our intention to make service the number one priority at Smothers European. If there is any suggestion you can make to provide a better Service Department, please let us know. By law, you may choose another facility to perform any needed repairs or adjustments which the Smog Check test indicates are necessary.

DESCRIPTION	LABOR AMOUNT	PARTS AMOUNT	GAS, OIL, LUBE	SUBLET AMOUNT	MISC. CHARGES	TOTAL CHARGES	ADJUSTMENTS	SALES TAX	PLEASE PAY THIS AMOUNT
TOTALS									

Mailing Address:  
 2881 Corby Ave. Santa Rosa, CA 95407

EST: 1,652.00 10SEP10 09:43 SA: 101  
 AUTH MR DALY 9.10 343PM FOR  
 CAM MAGNET ADDITIONAL AL 261.60

*Customer Copy*



\* INVOICE \*

Invoice #: 149840  
Tag #: T739  
Customer #: 66846

**Smothers**  
**EUROPEAN**  
2880 TALMADGE DR.  
SANTA ROSA, CA 95407  
(707) 542-4811



Service Advisor: **NICK STAUER**  
BAR# ARD 223139  
EPA# CAL-000250231

CELL: [REDACTED]  
HOME [REDACTED]  
BUS: [REDACTED]  
EMAIL: [REDACTED] om | home

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN	MILEAGE OUT
012/268	97	MERCEDES SL320R/95	WDBFA63F8VF	3WNL078	37162	37162
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	INV. DATE	R.O. OPENED	READY
31 JUL 97	11 APR 97	30 JUL 2001	20:20 10SEP10	14SEP10	09:43 10SEP10	09:05 14SEP10

OPTIONS: DLR:05106 ENG:104991-12-027895 TRN:722605-00-337260 1)RADIO CODE#12111 SERIAL#T09677410

DESCRIPTION	LABOR	PARTS	OTHER	TOTAL LINE A	TOTAL LINE B	TOTAL LINE C
<b>A REPLACE PASS FRONT WHEEL WITH SOP, REPLACE ALL 4 TIRES (MR CLARK ORDERED) M4 MOUNT AND BALANCE FOUR NEW TIRES</b>	146.00	0.00	0.00	146.00	11.50	0.00
236 CMT					11.50	
4 Q-8-40-0893 GDYR TIRE				146.00	1.20	
4 TIRE TIRE FEE				1.75	1.20	
1 6-6-47-0095 WHEEL				330.00	6.95	
<b>LABOR: 80.00 PARTS: 921.00 OTHER: 0.00</b>				330.00	5.20	
<b>*****37162 MOUNTED AND BALANCED 4 NEW TIRES, REPLACED FRONT PASS. RIM, SET *****</b>						
<b>*****TIRE PRESS., TORQUED WHEELS *****</b>						
<b>*****</b>						
<b>B LUBE, OIL AND FILTER SERVICE</b>						
LOF LUBE, OIL AND FILTER SERVICE						
236 CM						
1 104-180-01-09 OIL FILTER					11.50	
1 007603-014-106 RING					1.20	
7 Q-1-09-0144 5W40 MOBIL					6.95	
1 000000-006373A BULB					5.20	
<b>LABOR: 65.00 PARTS: 66.55 OTHER: 0.00</b>				65.00	11.50	
<b>*****37162 PERFORMED LOF SERV., CHANGED ENGINE OIL AND FILTER, TOPPED OFF *****</b>						
<b>*****FLUIDS, TESTED BATT., SET TIRE PRESS. IN SPARE, INSPECTED VEH., FRONT PADS *****</b>						
<b>*****8MM REAR PADS GMM, FOUND BRAKE FLUID DIRTY, ENGINE AIR FILTER DIRTY, CAM *****</b>						
<b>*****MAGNET LEAKING CONN. IS WET *****</b>						
<b>*****</b>						
<b>C CUST STATES CENTER FRONT BUMPER MOLDING IS STICKING OUTWARD, REINSTALL AS NEEDED</b>						
OO SERVICE						
236 CM						
<b>LABOR: 0.00 PARTS: 0.00 OTHER: 0.00</b>				0.00	0.00	0.00
<b>*****37162 CLIPPED CENTER BUMPER MOLDING BACK INTO PLACE *****</b>						

DESCRIPTION	LABOR AMOUNT	PARTS AMOUNT	GAS, OIL, LUBE	SUBLET AMOUNT	MISC. CHARGES	TOTAL CHARGES	ADJUSTMENTS	SALES TAX	PLEASE PAY THIS AMOUNT
SMOTHERS EUROPEAN CUSTOMER SATISFACTION POLICY									
It is our intention to make service the number one priority at Smothers European. If there is any suggestion you can make to provide a better Service Department, please let us know. By law, you may choose another facility to perform any needed repairs or adjustments which the Smog Check test indicates are necessary.									
STATEMENT OF DISCLAIMER									
The factory warranty constitutes all of the warranties with respect to the sale of this item. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item.									
NOTICE TO CUSTOMERS									
WE MAKE A SEPARATE CHARGE FOR THE DISPOSAL OF TOXIC WASTES. RATHER THAN RECOVER THESE COSTS BY INCREASING OUR LABOR RATES TO ALL OF OUR SERVICE CUSTOMERS, WE MAKE THIS CHARGE ONLY ON THOSE PARTICULAR REPAIRS OR SERVICES WHICH GENERATE THESE WASTES. THESE ARE UNIFORM CHARGES WHICH ARE CALCULATED ANNUALLY FOR EACH PARTICULAR SERVICE AND ARE AVAILABLE UPON REQUEST.									
I acknowledge notice and oral approval of an increase in the original estimated price.									
Initials									
Original Estimate \$									
Please read the important information on the reverse side of invoice.									
I acknowledge receipt of this invoice.									
I acknowledge the warranty repairs performed.									
I acknowledge notice and oral approval of additional Warranty repairs discovered and corrected during this repair visit.									
Signature X									

JOAN DALY

Smothers

European

Would Like To

Thank You

For Your

Continued

Patronage



Thank You!

Customer Copy

Mailing Address:

2881 Corby Ave. Santa Rosa, CA 95407

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK

Page 1 of 3

THANK YOU!







Customer Copy

CUSTOMER #: 66846

WORKORDER 140840

PAGE 2

Smothers EUROPEAN

2880 TALMADGE DR. SANTA ROSA, CA 95407 (707) 542-4811



Mercedes-Benz

BAR# ARD 223139

EPA# CAL 000250231

SANTA ROSA CA 95403-0935 HOME: 7 BUS: CELL EMAIL:

SERVICE ADVISOR: 217 LEONARD, JESSICA

Table with columns: COLOR, YEAR, MAKE/MODEL, VIN, LICENSE, MILEAGE IN/ OUT, TAG, DEL DATE, PROD. DATE, WARR. EXP., PROMISED, PO NO., RATE, PAYMENT, INV. DATE, R.O. OPENED, READY, OPTIONS.

Table with columns: LINE, OP CODE, TECH. TYPE, DESCRIPTIONS/INSTRUCTIONS

\*\*\*\*\*

Preliminary Estimate : \$260.00

\*\*\*\*\*

WDBFA63F8VF 153299

EXCLUSION OF WARRANTIES

Any warranties on the parts and accessories sold hereby are made by the manufacturer. The undersigned purchaser understands and agrees that dealer makes no warranties of any kind, express or implied, and disclaims all warranties, including warranties of merchantability or fitness for a particular purpose, with regard to the parts and/or accessories purchased; and that in no event shall dealer be liable for incidental or consequential damages or commercial losses arising out of such purchase.

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter.

DATE: \_\_\_\_\_ SIGNED: X \_\_\_\_\_

PRELIMINARY ESTIMATE \$ \_\_\_\_\_

AUTHORIZED BY: X

Table with columns: REVISED ESTIMATE(1) \$, DATE, TIME, BY, REVISED ESTIMATE(2) \$

I HEREBY ACKNOWLEDGE THAT I WAS NOTIFIED & GAVE ORAL APPROVAL OF THE ABOVE REVISED ESTIMATES:

X \_\_\_\_\_ CUSTOMER SIGNATURE

FOR YOUR CONVENIENCE OUR SERVICE DEPT. HOURS: MONDAY THRU FRIDAY 7:30 AM TO 5:00 PM

TERMS: CASH · VISA · MASTERCARD

CHECK ACCEPTANCE POLICY

- 1. PREPRINTED CHECKS WITH NAME ADDRESS AND PHONE NUMBER. 2. VALID UNITED STATES DRIVERS LICENSE.

NO CARS RELEASED AFTER 5:00 PM

Invoice #: 133690S  
 Tag #: T135  
 Customer #: 66840

**Smothers**  
**EUROPEAN**  
 2880 TALMADGE DR.  
 SANTA ROSA, CA 95407  
 (707) 542-4811



Mercedes-Benz  
 EPA# CAL 000250231

Service Advisor: 217 JESSICA LEONARD  
 BAR# RG 223139

CELL: :1


HOME: 5405-5589  
 BUS: 2

EMAIL: jr

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN	MILEAGE OUT
012/268	97	MERCEDES SL320R/95	WDBFA63F8VF	3WNL078	30893	30893
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	R.O. OPENED	READY
31JUL97	11APR97	30JUL2001	20:25 12SEP08		09:00 21AUG08	11:19 15SEP08

OPTIONS: DLR:05106 ENG:104991-12-027895 TRN:722605-00-337260 1RADIO CODE#12111 SERIAL#T09677410

LIST	NET	TOTAL
00 PART ONLY		
79 CM		
1 210-820-32-26 CONTROL UNIT	580.00	524.00
LABOR: 0.00 PARTS: 524.00 OTHER: 0.00		TOTAL LINE C: 524.00
***** EST: 2,038.00 15SEP08 11:19 SA: 217 CUSTOMER PAY SHOP CHARGE FOR REPAIR ORDER REVISED ESTIMATE ADDITIONAL \$1514.00 FOR CONTROL UNIT AND RECEIVER AUTHORIZED BY JOAN BY PHONE (707)775-7021 8/22/08 AT 11:51AM TOTAL REVISED \$1514.00. REVISED ESTIMATE ADDITIONAL \$524.00 FOR CONTROL UNIT AUTHORIZED BY JOAN BY PHONE (707) 775-7021 8/29/08 AT 10:06AM TOTAL REVISED \$2038.00. ***** 30893 INSTALL PROGRAMED IR AND DAS CONTROL MODULES AND REASSEMBLE DASH AND TRUNK AS WELL AW REAR CARGO BOX ASSY PROGRAMED ALL KEY VEHICLE STARTS AND UNLOCKS NORMALLY *****		
	524.00	5.00
		0.00
		524.00
		524.00
		\$ 524.00



Mercedes-Benz  
 CREDIT CARD

Customer Copy

DESCRIPTION	LABOR AMOUNT	PARTS AMOUNT	GAS, OIL, LUBE	SUBLET AMOUNT	MISC. CHARGES	TOTAL CHARGES	ADJUSTMENTS	SALES TAX	PLEASE PAY THIS AMOUNT
SMOTHERS EUROPEAN CUSTOMER SATISFACTION POLICY									
<p>It is our intention to make service the number one priority at Smothers European. If there is any suggestion you can make to provide a better Service Department, please let us know. By law, you may choose another facility to perform any needed repairs or adjustments which the Smog Check test indicates are necessary.</p>									
<p>STATEMENT OF DISCLAIMER            The factory warranty constitutes all of the warranties with respect to the sale of this item. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item.</p>									
<p>NOTICE TO CUSTOMERS            WE MAKE A SEPERATE CHARGE FOR THE DISPOSAL OF TOXIC WASTES. CAL RATHER THAN RECOVER THESE COSTS BY INCREASING OUR LABOR RATES TO ALL OF OUR SERVICE CUSTOMERS. WE MAKE THIS CHARGE ONLY ON THOSE PARTICULAR REPAIRS OR SERVICES WHICH GENERATE THESE WASTES. THESE ARE UNIFORM CHARGES WHICH ARE CALCULATED ANNUALLY FOR EACH PARTICULAR SERVICE AND ARE AVAILABLE UPON REQUEST.</p>									
<p>I acknowledge notice and oral approval of an increase in the original estimated price.</p>									
<p>I acknowledge receipt of this invoice.            I acknowledge the warranty repairs performed.            I acknowledge notice and oral approval of additional Warranty repairs discovered and corrected during this repair visit.</p>									
<p>Original Estimate \$ _____            Please read the important information on the reverse side of invoice.            Signature X _____</p>									
<p>INITIALS _____</p>									
<p>APPOINTMENTS: (707) 542-4811</p>									
<p>TOTALS</p>									
									512.00
									1536.00
									0.00
									0.00
									5.00
									2053.00
									0.00
									122.88
									2175.88

Thank You!





Invoice #: 133690S

Tag #: T195

Customer #: 66846

Service Advisor: 217 JESSICA LEONARD

SANTA ROSA, CA 95405-5589

HOME: BUS: |home

CELL: |home

**Smothers**  
**EUROPEAN**

2880 TALMADGE DR.  
SANTA ROSA, CA 95407

Mercedes-Benz

BAR# RG 223139

EPA# CAL 000250231

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN	MILEAGE OUT
012/268	97	MERCEDES SL320R/95	WDBFA63F8VF	3WNL078	30893	30893
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	INV. DATE	R.O. OPENED	READY
31JUL97	11APR97	30JUL2001	20:25 12SEP08	15SEP08	09:00 21AUG08	11:19 15SEP08
OPTIONS: DLR:05106 ENG:104991-12-027895 TRN:722605-00-337260 1 RADIO CODE#12111 SERIAL#T09677410						

**A** CHECK AND ADVISE CUSTOMER STATES VEHICLE INT WILL NOT UNLOCK WITH REMOTE, AFTER UNLOCKING CAR WITH KEY BLADE AFTER LOCKING CAR WITH KEY BLADE, ALARM WENT OFF AFTER DRIVING A BLOCK 541011 SHORT TEST, PERFORM

**LABOR:** 128.00 CM  
**PARTS:** 0.00 OTHER: 0.00  
**TOTAL LINE A:** 128.00 \$ 128.00

\*\*\*\*\* CUSTOMER STATES VEHICLE INTERMITTENTLY WILL NOT LOCK OR UNLOCK WITH REMOTES. VERIFY CONCERN TESTED BOTH KEYS BOTH ARE OK. PSE PUMP FUNCTIONING NORMALLY. IR SENSOR AT TRUNK IS INOP EVEN WHEN OTHERS ARE WORKING. REC REPLACING IR CONTROL MODULE AND TRUNK SENSOR. REMOVED LEFT SIDE KINCKANEL AND CARPET AND CHECKED CONNECTORS ON FLOORBOARD. THIS IS A COMMON PLACE FOR CORROSION CLEAN AT THIS TIME. REC REPLACING IR CONTROL MODULE

**B\*\*** INSTALL RF CONTROL UNIT AND TRUNK SENSOR 82 IR AND DAS CONTROL UNIT

**LABOR:** 384.00 CM  
**PARTS:** 1012.00 OTHER: 0.00  
**TOTAL LINE B:** 1396.00 \$ 1396.00

\*\*\*\*\* 30893 INSTALLED IR CONTROL MODULE ATTEMPTED TO PROGRAM KEYS COULD NOT TRIED ALL WAY LISTED IN WIS. RESEARCHED TAC AND OPENED CASE 735653 AFTER FURTHER RESEARCH FOUND IR AND DAS CONTROL UNIT NEED TO BE REPLACED TOGETHER AND MUST BE ORDERED FORM GERMANY AND VIN CODED.

**C\*\*** INSTALL PROGRAMED CONTROL UNIT FROM GERMANY WITH ADDITIONAL CONTROL UNIT 82 INSTALLED IR AND DAS CONTROL MODULES

CAREY DALY  
 Smothers  
 European  
 Would Like To  
 Thank You  
 For Your  
 Continued  
 Patronage



**Thank You!**

Original Estimate \$ \_\_\_\_\_  
 Please read the important information on the reverse side of invoice.  
 I acknowledge receipt of this invoice.  
 I acknowledge the warranty repairs performed.  
 I acknowledge notice and oral approval of additional Warranty repairs discovered and corrected during this repair visit.  
 Signature X \_\_\_\_\_

I acknowledge notice and oral approval of an increase in the original estimated price.  
 Initials \_\_\_\_\_

**STATEMENT OF DISCLAIMER**  
 The factory warranty constitutes all of the warranties with respect to the sale of this item. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.  
**NOTICE TO CUSTOMERS**  
 WE MAKE A SEPERATE CHARGE FOR THE DISPOSAL OF TOXIC WASTES. CAL RATHER THAN RECOVER THESE COSTS BY INCREASING OUR LABOR RATES TO ALL OF OUR SERVICE CUSTOMERS, WE MAKE THIS CHARGE ONLY ON THOSE PARTICULAR REPAIRS OR SERVICES WHICH GENERATE THESE WASTES. THESE ARE UNIFORM CHARGES WHICH ARE CALCULATED ANNUALLY FOR EACH PARTICULAR SERVICE AND ARE AVAILABLE UPON REQUEST.

**SMOTHERS EUROPEAN CUSTOMER SATISFACTION POLICY**  
 It is our intention to make service the number one priority at Smothers European. If there is any suggestion you can make to provide a better Service Department, please let us know. By law, you may choose another facility to perform any needed repairs or adjustments which the Smog Check test indicates are necessary.

DESCRIPTION	LABOR AMOUNT	PARTS AMOUNT	GAS, OIL, LUBE	SUBLET AMOUNT	MISC. CHARGES	TOTAL CHARGES	ADJUSTMENTS	SALES TAX	PLEASE PAY THIS AMOUNT
<b>TOTALS</b>									

**APPOINTMENTS: (707) 542-4811**

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK

**Customer Copy**



Invoice #: 133690

Tag #: T195

Customer #: 06846

Service Advisor: 217 JESSICA LEONARD

CELL

SANTA ROSA, CA 95405-5589

HOME: 707-542-4811

EMAIL: jessica.leonard@smothers.com

**Smothers**  
**EUROPEAN**

2880 TALMADGE DR.  
SANTA ROSA, CA 95407  
(707) 542-4811



Mercedes-Benz

BAR# RG 223139

EPA# CAL 000250231


COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN	MILEAGE OUT
012/268	97	MERCEDES SL320R/95	WDBFA63F8VF	3WNL078	30893	30893
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT
31 JUL 97	11 APR 97	30 JUL 2001	20:25 12SEP08			CASH
OPTIONS: DLR:05106 ENG:104991-12-027895 TRN:722605-00-337260 1RADIO CODE#12111 SERIAL#T09677410						

LIST NET TOTAL

B Moved to: 133690S Line: B  
C Moved to: 133690S Line: C

EST: 128.00 21AUG08 09:00 SA: 217  
EST: 2,038.00 29AUG08 10:24 SA: 217  
EST: 0.00 15SEP08 11:19 SA: 217

REVISED ESTIMATE ADDITIONAL \$1514.00 FOR CONTROL L UNIT AND RECEIVER AUTHORIZED BY JOAN BY PHONE (707)775-7021 8/22/08 AT 11:51AM TOTAL REVISED \$1514.00. REVISED ESTIMATE ADDITIONAL \$524.00 FOR CONTROL UNIT AUTHORIZED BY JOAN BY PHONE (707) 775-7021 8/29/08 AT 10:06AM TOTAL REVISED \$2038.00.



Mercedes-Benz

Thank You!

Customer Copy

DESCRIPTION	LABOR AMOUNT	PARTS AMOUNT	GAS, OIL, LUBE	SUBLET AMOUNT	MISC. CHARGES	TOTAL CHARGES	ADJUSTMENTS	SALES TAX	PLEASE PAY THIS AMOUNT
SMOTHERS EUROPEAN CUSTOMER SATISFACTION POLICY									0.00
It is our intention to make service the number one priority at Smothers European. If there is any suggestion you can make to provide a better Service Department, please let us know. By law, you may choose another facility to perform any needed repairs or adjustments which the Smog Check test indicates are necessary.									
STATEMENT OF DISCLAIMER The factory warranty constitutes all of the warranties with respect to the sale of this item. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item.									
NOTICE TO CUSTOMERS WE MAKE A SEPERATE CHARGE FOR THE DISPOSAL OF TOXIC WASTES. CAL 000077883 RATHER THAN RECOVER THESE COSTS BY INCREASING OUR LABOR RATES TO ALL OF OUR SERVICE CUSTOMERS. WE MAKE THIS CHARGE ONLY ON THOSE PARTICULAR REPAIRS OR SERVICES WHICH GENERATE THESE WASTES. THESE ARE UNIFORM CHARGES WHICH ARE CALCULATED ANNUALLY FOR EACH PARTICULAR SERVICE AND ARE AVAILABLE UPON REQUEST.									
I acknowledge notice and oral approval of an increase in the original estimated price.									
I acknowledge receipt of this invoice.									
I acknowledge the warranty repairs performed.									
I acknowledge notice and oral approval of additional Warranty repairs discovered and corrected during this repair visit.									
Signature X _____ Initials _____									
APPOINTMENTS: (707) 542-4811									
TOTALS									
									0.00

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK

Page 2 of 2

THANK YOU!



Invoice #: 133690

Tag #: T195

Customer #: 66846

Service

Advisor: 217 JESSICA LEONARD

CELL:

SANTA ROSA, CA 95405-5589

HOME: 2 BUS:

EMAIL: joa

**Smothers**  
EUROPEAN

2880 TALMADGE DR.  
SANTA ROSA, CA 95407  
(707) 542-4811



Mercedes-Benz

BAR# RG 223139

EPA# CAL 000250231

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN	MILEAGE OUT
012/268	97	MERCEDES SL320R/95	WDBFA63F8VF 153299	3WNL078	30893	30893
DEL DATE	PROD DATE	WARR EXP	PO NO	INV DATE	R.O OPENED	READY
31JUL97	11APR97	30JUL2001	20:25 12SEP08	15SEP08	09:00 21AUG08	11:19 15SEP08

OPTIONS: DLR:05106 ENG:104991-12-027895 TRN:722605-00-337260 1)RADIO CODE#12111 SERIAL#T09677410

LIST NET TOTAL

LINE	DESCRIPTION	LABOR	PARTS	OTHER	TOTAL
A	Moved to: 133690S Line: A DIAG Moved to: 133690S Line: A 299 CM	0.00	0.00	0.00	0.00
B	Moved to: 133690S Line: B DIAG Moved to: 133690S Line: B 299 CM	0.00	0.00	0.00	0.00
C	Moved to: 133690S Line: C DIAG Moved to: 133690S Line: C 299 CM	0.00	0.00	0.00	0.00
D	82 INSTALLED SPECIALLY CODED CONTROL MODULE 79 WM93 1 129-820-29-26 control unit	0.00	0.00	0.00	0.00
TOTAL LINE A:					0.00
TOTAL LINE B:					0.00
TOTAL LINE C:					0.00
TOTAL LINE D:					0.00

CAREY DALY

Smothers

European

Would Like To

Thank You

For Your

Continued

Patronage



Thank You!

Original Estimate \$ \_\_\_\_\_

Please read the important information on the reverse side of invoice.

I acknowledge receipt of this invoice.

I acknowledge the warranty repairs performed.

I acknowledge notice and oral approval of additional Warranty repairs discovered and corrected during this repair visit.

Signature X \_\_\_\_\_

I acknowledge notice and oral approval of an increase in the original estimated price.

Initials \_\_\_\_\_

**STATEMENT OF DISCLAIMER**  
The factory warranty constitutes all of the warranties with respect to the sale of this item. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item.

**NOTICE TO CUSTOMERS**  
WE MAKE A SEPARATE CHARGE FOR THE DISPOSAL OF TOXIC WASTES. CAL 000077883  
RATHER THAN RECOVER THESE COSTS BY INCREASING OUR LABOR RATES TO ALL OF OUR SERVICE CUSTOMERS, WE MAKE THIS CHARGE ONLY ON THOSE PARTICULAR REPAIRS OR SERVICES WHICH GENERATE THESE WASTES. THESE ARE UNIFORM CHARGES WHICH ARE CALCULATED ANNUALLY FOR EACH PARTICULAR SERVICE AND ARE AVAILABLE UPON REQUEST.

**SMOTHERS EUROPEAN CUSTOMER SATISFACTION POLICY**  
It is our intention to make service the number one priority at Smothers European. If there is any suggestion you can make to provide a better Service Department, please let us know. By law, you may choose another facility to perform any needed repairs or adjustments which the Smog Check test indicates are necessary.

LABOR AMOUNT	PARTS AMOUNT	GAS, OIL, LUBE	SUBLET AMOUNT	MISC. CHARGES	TOTAL CHARGES	ADJUSTMENTS	SALES TAX	PLEASE PAY THIS AMOUNT
<b>TOTALS</b>								

APPOINTMENTS: (707) 542-4811

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK

Page 1 of 2

THANK YOU!

Customer Copy

CUSTOMER #: 66846

PAGE 2

**Smothers**  
**EUROPEAN**

2880 TALMADGE DR.  
SANTA ROSA, CA 95407  
(707) 542-4811



Mercedes-Benz

BAR# RG 223139

EPA# CAL 000250231

JOHN JR  
SANTA ROSA, CA 95405-5589

HOME: \_\_\_\_\_ BUS: \_\_\_\_\_ CELL: \_\_\_\_\_

EMAIL: \_\_\_\_\_ E.COM|HOME

SERVICE ADVISOR: 217 LEONARD, JESSICA

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG	
012/268	97	MERCEDES SL320R/95	WDBFA63F8VF 153299	3WNL078	30893	T787	
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
31JUL97	11APR97	30JUL2001	20:25 21AUG08			CASH	
R.O. OPENED	READY	OPTIONS: DLR:05106 ENG:104991-12-027895 TRN:722605-00-337260 1)RADIO CODE#12111 SERIAL#T09677410					
21AUG2008	09:00						

LINE	OP	CODE	TECH.	TYPE	DESCRIPTIONS/INSTRUCTIONS
#	A	00		CM	CHECK AND ADVISE CUSTOMER STATES VEHICLE INT WILL NOT UNLOCK WITH REMOTE, AFTER UNLOCKING CAR WITH KEY BLADE AFTER LOCKING CAR WITH KEY BLADE, ALARM WENT OFF AFTER DRIVING A BLOCK

\*\*\*\*\*

Preliminary Estimate : \$128.00

\*\*\*\*\*

WDBFA63F8VF 153299

**EXCLUSION OF WARRANTIES**

Any warranties on the parts and accessories sold hereby are made by the manufacturer. The undersigned purchaser understands and agrees that dealer makes no warranties of any kind, express or implied, and disclaims all warranties, including warranties of merchantability or fitness for a particular purpose, with regard to the parts and/or accessories purchased; and that in no event shall dealer be liable for incidental or consequential damages or commercial losses arising out of such purchase. The undersigned purchaser further agrees that the warranties excluded by dealer include, but are not limited to, any warranties that such parts and/or accessories are of merchantable quality or that they will enable any vehicle or any of its systems to perform with reasonable safety, efficiency, or comfort.

DATE: \_\_\_\_\_ SIGNED: X \_\_\_\_\_

FOR YOUR CONVENIENCE OUR  
SERVICE DEPT. HOURS:  
MONDAY THRU FRIDAY  
7:30 AM TO 5:00 PM

TERMS: CASH · VISA · MASTERCARD

- CHECK ACCEPTANCE POLICY**
- PREPRINTED CHECKS WITH NAME ADDRESS AND PHONE NUMBER.
  - VALID UNITED STATES DRIVERS LICENSE.
- NO CARS RELEASED AFTER 5:00 PM**

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount or repairs thereto. Not responsible for damage from freezing due to lack of antifreeze.

PRELIMINARY ESTIMATE \$ \_\_\_\_\_

AUTHORIZED BY: X

REVISED ESTIMATE(1) \$	DATE	TIME	BY
REVISED ESTIMATE(2) \$			

I HEREBY ACKNOWLEDGE THAT I WAS NOTIFIED & GAVE ORAL APPROVAL OF THE ABOVE REVISED ESTIMATES:

X \_\_\_\_\_  
CUSTOMER SIGNATURE





Invoice #: 131088  
 Tag #: T466  
 Customer #: 66846



**Snothers**  
**EUROPEAN**  
 2880 TALMADGE DR.  
 SANTA ROSA, CA 95407  
 (707) 542-4811

SANTA ROSA, CA 95405-5589  
 HOME: BUS: 1  
 EMAIL: 1|home

Service Advisor: 43 KEN STANFEL

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN	MILEAGE OUT
012/268	97	MERCEDES SL320R/95	WDBFA63F8VF	3WVNL078	30072	30072
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	R.O. OPENED	READY
31JUL97	11APR97	30JUL2001	16:00 07MAY08		08MAY08	09:05 05MAY08
OPTIONS: DLR:05106 ENG:104991-12-027895 TRN:722605-00-337260 1 RADIO CODE#12111 SERIAL#T09677410						

LIST	NET	TOTAL
42 REPLACE BRAKE PADS FRT		
1 56 CM		
1 005-420-02-20 BRAKE PADS	89.61	126.50
2 126-540-20-17 SENSOR	7.00	89.61
1 001-989-47-51 BRAKE PASTE	4.42	14.00
1 52 BRAKEWASH	3.10	4.42
LABOR: 126.50		3.10
*****2 REPLACED FRONT BRAKE PADS*****		
OTHER: 0.00		
<b>TOTAL LINE 1:</b>		<b>\$ 237.63</b>



EST: 1,105.00 05MAY08 09:05 SA: 43  
 CUSTOMER PAY SHOP CHARGE FOR REPAIR ORDER

Mercedes-Benz

PAID BY  
 CREDIT CARD

Customer Copy



Thank You!

Original Estimate \$	2340.25
Please read the important information on the reverse side of invoice.	1269.25
I acknowledge receipt of this invoice.	0.00
I acknowledge the warranty repairs performed.	100.00
I acknowledge notice and oral approval of additional Warranty repairs discovered and corrected during this repair visit.	5.00
Signature X	3714.50
Initials	0.00
<b>TOTALS</b>	
LABOR AMOUNT	2340.25
PARTS AMOUNT	1269.25
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	100.00
MISC. CHARGES	5.00
TOTAL CHARGES	3714.50
ADJUSTMENTS	0.00
SALES TAX	101.54
PLEASE PAY THIS AMOUNT	3816.04

**SMOTHERS EUROPEAN CUSTOMER SATISFACTION POLICY**  
 It is our intention to make service the number one priority at Smothers European. If there is any suggestion you can make to provide a better Service Department, please let us know. By law, you may choose another facility to perform any needed repairs or adjustments which the Smog Check test indicates are necessary.

**STATEMENT OF DISCLAIMER**  
 The factory warranty constitutes all of the warranties with respect to the sale of this item/terms. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/terms.  
 WE MAKE A SEPERATE CHARGE FOR THE DISPOSAL OF TOXIC WASTES. CAL 000077883  
 RATHER THAN RECOVER THESE COSTS BY INCREASING OUR LABOR RATES TO ALL OF OUR SERVICE CUSTOMERS, WE MAKE THIS CHARGE ONLY ON THOSE PARTICULAR REPAIRS OR SERVICES WHICH GENERATE THESE WASTES. THESE ARE UNIFORM CHARGES WHICH ARE CALCULATED ANNUALLY FOR EACH PARTICULAR SERVICE AND ARE AVAILABLE UPON REQUEST.

I acknowledge notice and oral approval of an increase in the original estimated price.  
 \_\_\_\_\_  
 Initials

APPOINTMENTS: (707) 542-4811

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK

Page 4 of 4

THANK YOU!



Invoice #: 131088

Tag #: T466

Customer #: 66846

Service Advisor: 43 KEN STAMFEL

CELL:

SANTA ROSA CA 95405-5589

HOME: 707-542-4811

EMAIL: joar@smothers.com



2880 TALMADGE DR.  
SANTA ROSA, CA 95407  
(707) 542-4811

Mercedes-Benz  
EPA# CAL 000250231

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN	MILEAGE OUT
012/268	97	MERCEDES SL320R/95	WDBFA63F8VF 153299	3WNL078	30072	30072
DEL DATE	PROD DATE	WARR EXP	PROMISED	PO NO.	RATE	PAYMENT
31 JUL 97	11 APR 97	30 JUL 2001	16:00 07 MAY 08			CASH
OPTIONS: DLR:05106 ENG:104991-12-027895 TRN:722605-00-337260 1RADIO CODE#12111 SERIAL#T09677410						

AND FOUND THAT THE HEAD GASKET AND THE FRONT TIMING COVER IS LEAKING  
 OIL. BOTH NEED TO BE RESEALED. REPLACED CYLINDER HEAD GASKET AND  
 RESEALED FRONT UPPER TIMING COVER. ROAD TEST AND THERE IS NO LEAK AT  
 THIS TIME.

CUST REPORTS PROBLEM WITH RIGHT FRT MIRROR ADJUSTMENT AND OPERATION ADVISE.  
 54 REPLACE MIRROR MOTOR

56 CM  
 1 140-820-23-08 RT MIRROR MTR 204.00  
 LABOR: 126.50 PARTS: 204.00 OTHER: 0.00 TOTAL LINE F: 330.50

30072 PERFORMED AN INSPECTION OF THE RIGHT MIRROR OPERATION. FOUND  
 THAT THE MIRROR MOTOR IS BROKEN AND NEEDS TO BE REPLACED. REPLACED  
 RIGHT OUTSIDE MIRROR MOTOR. MIRROR IS WORKING GOOD AT THIS TIME.

REMOTE BATTERY, BOTH PLEASE  
 C25 COMPLETED AT NO CHARGE

56 CM  
 2 000-828-03-88 BATTERY 13.91  
 LABOR: 0.00 PARTS: 27.82 OTHER: 0.00 TOTAL LINE G: 27.82

CUST REQUESTS 40TH ANNIVERSARY FLOOR MATS ADVISE.  
 60 MAT SET COMING

56 CM  
 1 Q-6-68-0356 40TH MAT SET 116.39  
 LABOR: 0.00 PARTS: 116.39 OTHER: 0.00 TOTAL LINE H: 116.39

REPLACE FRT PADS

CAREY DALY

Smothers  
 European  
 Would Like To  
 Thank You  
 For Your  
 Continued  
 Patronage

Thank You!

DESCRIPTION	LABOR AMOUNT	PARTS AMOUNT	GAS, OIL, LUBE	SUBLET AMOUNT	MISC. CHARGES	TOTAL CHARGES	ADJUSTMENTS	SALES TAX	PLEASE PAY THIS AMOUNT
SMOTHERS EUROPEAN CUSTOMER SATISFACTION POLICY									
It is our intention to make service the number one priority at Smothers European. If there is any suggestion you can make to provide a better Service Department, please let us know. By law, you may choose another facility to perform any needed repairs or adjustments which the Smog Check test indicates are necessary.									
STATEMENT OF DISCLAIMER The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.									
NOTICE TO CUSTOMERS WE MAKE A SEPERATE CHARGE FOR THE DISPOSAL OF TOXIC WASTES. CAL RATHER THAN RECOVER THESE COSTS BY INCREASING OUR LABOR RATES TO ALL OF OUR SERVICE CUSTOMERS, WE MAKE THIS CHANGE ONLY ON THOSE PARTICULAR REPAIRS OR SERVICES WHICH GENERATE THESE WASTES. THESE ARE UNIFORM CHARGES WHICH ARE CALCULATED ANNUALLY FOR EACH PARTICULAR SERVICE AND ARE AVAILABLE UPON REQUEST.									
I acknowledge notice and oral approval of an increase in the original estimated price.									
I acknowledge receipt of this invoice.									
I acknowledge the warranty repairs performed.									
I acknowledge notice and oral approval of additional Warranty repairs discovered and corrected during this repair visit.									
Signature X _____									
INITIALS _____									
APPOINTMENTS: (707) 542-4811									

Customer Copy



Invoice #: 131088

Tag #: T466

Customer #: 66846

Service Advisor: 43 KEN STANFEL

CELL:

SANTA ROSA, CA 95405-5589

HOME: BUS: n|home

EMAIL:

**Smothers**  
**EUROPEAN**

2880 TALMADGE DR.  
SANTA ROSA, CA 95407  
(707) 542-4811



Mercedes-Benz

BAR# RG 223139 EPA# CAL 000250231

VIN: WDBFA63F8VF153299

LICENSE: 3WNL078

INVOICE DATE: 08MAY08

PAYMENT: CASH

MAKE/MODEL: MERCEDES SL320R/95

COLOR: 97

YEAR: 97

DEL DATE	PROD DATE	WARR EXP	PROMISED	PO NO	RATE	PAYMENT	INV DATE	MILEAGE IN	MILEAGE OUT
31JUL97	11APR97	30JUL2001	16:00	07MAY08		CASH	08MAY08	30072	30072

OPTIONS: DLR:05106 ENG:104991-12-027895 TRN:722605-00-337260 1RADIO CODE#12111 SERIAL#T09677410

LIST	NET	TOTAL
C25 COMPLETED AT NO CHARGE		
LABOR: 56 CM	51.25	0.00
PARTS: 0.00		51.25
OTHER: 0.00		
<b>TOTAL LINE C:</b>		<b>\$ 51.25</b>
LABOR: 56 CM	63.25	0.00
PARTS: 0.00		63.25
OTHER: 0.00		
<b>TOTAL LINE D:</b>		<b>\$ 63.25</b>

**CAREY DALY**  
**Smothers**  
**European**  
**Would Like To**  
**Thank You**  
**For Your**  
**Continued**  
**Patronage**

**Thank You!**

\*\*\*\*\*  
D ROTATE TIRES  
4040 ROTATE TIRES  
LABOR: 63.25 PARTS: 0.00 OTHER: 0.00  
\*\*\*\*\*30072 ROTATED ALL FOUR TIRES.  
\*\*\*\*\*  
E CUST REPORTS LEAK FROM UNDER VEHICLE, DRIPPING TO THE GROUND  
01 REPLACE HEADGASKET AND FRT UPPER TIMING COVER  
LABOR: 1518.00 PARTS: 445.25 OTHER: 0.00  
\*\*\*\*\*30072 PERFORMED AN INSPECTION OF THE OIL LEAKING UNDER THE VEHICLE.  
\*\*\*\*\*

DESCRIPTION	LABOR AMOUNT	PARTS AMOUNT	GAS, OIL, LUBE	SUBLET AMOUNT	MISC. CHARGES	TOTAL CHARGES	ADJUSTMENTS	SALES TAX	PLEASE PAY THIS AMOUNT
1 104-010-21-30 GASKET KIT	95.45								95.45
1 104-015-02-20 GASKET	17.77								17.77
1 104-010-37-20 HEAD SET	176.00								176.00
1 003-989-98-20-10 SEALANT	20.00								20.00
1 Q-1-03-0002 ANTI/FREEZE	23.18								23.18
8 2050 MOBIL DRIVE CLEAN20/50	4.14								4.14
2 52 BRAKEWASH	3.10								3.10
1 110-200-05-15 THERMOSTAT	22.66								22.66
1 104-203-04-82 HOSE	18.75								18.75
2 026 SMALL CLAMP	4.25								4.25
3 53 3M PAD	1.95								1.95
1 104-015-02-20 GASKET	17.77								17.77
<b>LABOR:</b>	<b>1518.00</b>								<b>1518.00</b>
<b>PARTS:</b>	<b>445.25</b>								<b>445.25</b>
<b>OTHER:</b>	<b>0.00</b>								<b>0.00</b>
<b>TOTAL LINE E:</b>									<b>\$ 1963.25</b>

Original Estimate \$  
Please read the important information on the reverse side of invoice.  
I acknowledge receipt of this invoice.  
I acknowledge the warranty repairs performed.  
I acknowledge notice and oral approval of additional Warranty repairs discovered and corrected during this repair visit.  
Signature X Initials

**SMOTHERS EUROPEAN CUSTOMER SATISFACTION POLICY**  
It is our intention to make service the number one priority at Smothers European. If there is any suggestion you can make to provide a better Service Department, please let us know. By law, you may choose another facility to perform any needed repairs or adjustments which the Smog Check test indicates are necessary.

**STATEMENT OF DISCLAIMER**  
The factory warranty constitutes all of the warranties with respect to the sale of this item. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item.

**NOTICE TO CUSTOMERS**  
WE MAKE A SEPERATE CHARGE FOR THE DISPOSAL OF TOXIC WASTES. CAL RATHER THAN RECOVER THESE COSTS BY INCREASING OUR LABOR RATES TO ALL OF OUR SERVICE CUSTOMERS. WE MAKE THIS CHARGE ONLY ON THOSE PARTICULAR REPAIRS OF SERVICES WHICH GENERATE THESE WASTES. THESE ARE UNIFORM CHARGES WHICH ARE CALCULATED ANNUALLY FOR EACH PARTICULAR SERVICE AND ARE AVAILABLE UPON REQUEST.

**APPOINTMENTS: (707) 542-4811**

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK

Page 2 of 4

THANK YOU!



Invoice #: 131088  
 Tag #: T466  
 Customer #: 66846

SANTA ROSA, CA 95405-5589  
 HOME: BUS:  
 EMAIL: jo

**Smothers**  
**EUROPEAN**

2880 TALMADGE DR.  
 SANTA ROSA, CA 95407  
 (707) 542-4811



Mercedes-Benz

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN	MILEAGE OUT
012/268	97	MERCEDES SL320R/95	WDBFA63F8VF	3WNL078	30072	30072
DEL DATE	PROD DATE	WARR EXP	PROMISED	PO NO	RATE	PAYMENT
31 JUL 97	11 APR 97	30 JUL 2001	16:00 07MAY08			CASH
OPTIONS: DLR:05106 ENG:104991-12-027895 TRN:722605-00-337260 1RADIO CODE#12111 SERIAL#T09677410						

BAR# RG 223139

EPA# CAL 000250231

LIST	NET	TOTAL
A MB30 K SERVICE		
00 SERVICE		
6 003-159-67-03 SPARK PLUG	5.95	506.00
1 104-180-01-09 OIL FILTER	11.33	35.70
1 007603-014106 RING	2.50	11.33
7 Q-1-09-0144 5W40 MOBIL	7.24	2.50
1 N301 W/W SOLV	3.50	50.68
1 MOA OIL ADDITIVE	10.50	3.50
1 44K DEPOSIT CLNR	24.00	10.50
1 000-466-21-04 P/S FLTR	23.13	24.00
1 000-466-16-80 P/S GASKET	6.65	23.13
1 Q-1-46-0001 P/S FLUID	16.15	6.65
1 003-094-73-04 AIR FILTER	41.72	16.15
LABOR: 506.00		41.72
PARTS: 225.86		
OTHER: 0.00		
TOTAL LINE A:		\$ 731.86



\*\*\*\*\*  
 CUST STATES FRONT PANEL UNDER BUMPER IS MISSING. CHECK AND ADVISE.  
 \*\*\*\*\*  
 56 CM  
 1 129-880-02-05-9999 COVER  
 SUBL PAINT LOWER SPOILER TRIM PO#63532  
 \*\*\*\*\*  
 CUST STATES REPLACE WIPERS  
 \*\*\*\*\*  
 LABOR: 0.00 PARTS: 87.55 OTHER: 100.00  
 TOTAL LINE B: \$ 187.55  
 \*\*\*\*\*  
 CUST STATES REPAIR BRAKES, NEEDS FRONT BRAKE PADS THERE  
 ABOUT 1MM, REAR ARE 5MM. TIRE TREAD DEPTH IS 7MM ALL. PERFORMED FOUR  
 WHEEL TIRE ROTATION.  
 \*\*\*\*\*

**Mercedes-Benz**

**Thank You!**

**Customer Copy**

Original Estimate \$	Signature X	LABOR AMOUNT	100.00
Please read the important information on the reverse side of invoice.		PARTS AMOUNT	87.55
I acknowledge receipt of this invoice.		GAS, OIL, LUBE	0.00
I acknowledge the warranty repairs performed.		SUBLET AMOUNT	87.55
I acknowledge notice and oral approval of additional Warranty repairs discovered and corrected during this repair visit.		MISC. CHARGES	0.00
		TOTAL CHARGES	187.55
		ADJUSTMENTS	
		SALES TAX	
		PLEASE PAY THIS AMOUNT	
		TOTALS	
		SMOTHERS EUROPEAN CUSTOMER SATISFACTION POLICY	
		It is our intention to make service the number one priority at Smothers European. If there is any suggestion you can make to provide a better Service Department, please let us know. By law, you may choose another facility to perform any needed repairs or adjustments which the Smog Check test indicates are necessary.	
		STATEMENT OF DISCLAIMER The factory warranty constitutes all of the warranties with respect to the sale of this item. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item.	
		NOTICE TO CUSTOMERS WE MAKE A SEPERATE CHARGE FOR THE DISPOSAL OF TOXIC WASTES. CAL RATHER THAN RECOVER THESE COSTS BY INCREASING OUR LABOR RATES TO ALL OF OUR SERVICE CUSTOMERS, WE MAKE THIS CHARGE ONLY ON THOSE PARTICULAR REPAIRS OR SERVICES WHICH GENERATE THESE WASTES. THESE ARE UNIFORM CHARGES WHICH ARE CALCULATED ANNUALLY FOR EACH PARTICULAR SERVICE AND ARE AVAILABLE UPON REQUEST.	
		APPOINTMENTS: (707) 542-4811	

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK

Page 1 of 4

THANK YOU!



**Customer Copy**

CUSTOMER #: 66846

**WORKORDER  
131088**

PAGE 2

**Smother's  
EUROPEAN**

2880 TALMADGE DR.  
SANTA ROSA, CA 95407  
(707) 542-4811



Mercedes-Benz

BAR# RG 223139

EPA# CAL 000250231

R  
SANTA ROSA, CA 95405-5589  
HOME: 707-542-4811  
EMAIL: JOHNSON@SMOTHERS.COM

CELL: 707-542-4811

SERVICE ADVISOR: 43 STANFEL, KEN

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG	
012/268	97	MERCEDES SL320R/95	WDBFA63F8VF 153299	3WNL078	30072	T466	
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
31JUL97	11APR97	30JUL2001	16:00 05MAY08			CASH	
R.O. OPENED	READY	OPTIONS: DLR:05106 ENG:104991-12-027895 TRN:722605-00-337260 1)RADIO CODE#12111 SERIAL#T09677410					
05MAY2008	09:05						

LINE #	OP	CODE	TECH.	TYPE	DESCRIPTIONS/INSTRUCTIONS
# A	00			CM	MB30 K SERVICE
# B	00			CM	CUST STATES FRONT PANEL UNDER BUMPER IS MISSING. CHECK AND ADVISE.
# C	00			CM	CUST STATES REPLACE WIPERS
# D	4040			CM	ROTATE TIRES
# E	01			CM	CUST REPORTS LEAK FROM UNDER VEHICLE, DRIPPING TO THE GROUND
# F	54			CM	CUST REPORTS PROBLEM WITH RIGHT FRT MIRROR ADJUSTMENT AND OPERATION ADVISE.
# G	54			CM	REMOTE BATTERY , BOTH PLEASE

WDBFA63F8VF 153299

**EXCLUSION OF WARRANTIES**

Any warranties on the parts and accessories sold hereby are made by the manufacturer. The undersigned purchaser understands and agrees that dealer makes no warranties of any kind, express or implied, and disclaims all warranties, including warranties of merchantability or fitness for a particular purpose, with regard to the parts and/or accessories purchased; and that in no event shall dealer be liable for incidental or consequential damages or commercial losses arising out of such purchase. The undersigned purchaser further agrees that the warranties excluded by dealer include, but are not limited to, any warranties that such parts and/or accessories are of merchantable quality or that they will enable any vehicle or any of its systems to perform with reasonable safety, efficiency, or comfort.

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount or repairs thereto. Not responsible for damage from freezing due to lack of antifreeze.

DATE: \_\_\_\_\_ SIGNED: X \_\_\_\_\_

PRELIMINARY ESTIMATE \$ \_\_\_\_\_

AUTHORIZED BY: X \_\_\_\_\_

REVISED ESTIMATE(1) \$	DATE	TIME	BY
REVISED ESTIMATE(2) \$			

I HEREBY ACKNOWLEDGE THAT I WAS NOTIFIED & GAVE ORAL APPROVAL OF THE ABOVE REVISED ESTIMATES:

X \_\_\_\_\_  
CUSTOMER SIGNATURE

FOR YOUR CONVENIENCE OUR  
SERVICE DEPT. HOURS:  
MONDAY THRU FRIDAY  
7:30 AM TO 5:00 PM

**TERMS: CASH · VISA · MASTERCARD**  
**CHECK ACCEPTANCE POLICY**  
1. PREPRINTED CHECKS WITH NAME  
ADDRESS AND PHONE NUMBER.  
2. VALID UNITED STATES DRIVERS LICENSE.  
**NO CARS RELEASED AFTER 5:00 PM**



SANTA ROSA, CA 95405-5589

HOME: 70

BUS:

CELL

1

BAR# RG 223139

EPA# CAL 000250231

EMAIL: JC... HOME.COM|HOME

SERVICE ADVISOR: 43 STANFEL, KEN

Table with columns: COLOR, YEAR, MAKE/MODEL, VIN, LICENSE, MILEAGE IN/ OUT, TAG, DEL DATE, PROD. DATE, WARR. EXP., PROMISED, PO NO., RATE, PAYMENT, INV. DATE, R.O. OPENED, READY, OPTIONS.

Table with columns: LINE, OP, CODE, TECH, TYPE, DESCRIPTIONS/INSTRUCTIONS

\*\*\*\*\*

Preliminary Estimate : \$1,105.00

\*\*\*\*\*

WDBFA63F8VF 153299

EXCLUSION OF WARRANTIES

Any warranties on the parts and accessories sold hereby are made by the manufacturer. The undersigned purchaser understands and agrees that dealer makes no warranties of any kind, express or implied, and disclaims all warranties, including warranties of merchantability or fitness for a particular purpose, with regard to the parts and/or accessories purchased; and that in no event shall dealer be liable for incidental or consequential damages or commercial losses arising out of such purchase. The undersigned purchaser further agrees that the warranties excluded by dealer include, but are not limited to, any warranties that such parts and/or accessories are of merchantable quality or that they will enable any vehicle or any of its systems to perform with reasonable safety, efficiency, or comfort.

DATE: \_\_\_\_\_ SIGNED: X \_\_\_\_\_

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount or repairs thereto. Not responsible for damage from freezing due to lack of antifreeze.

PRELIMINARY ESTIMATE \$ \_\_\_\_\_

AUTHORIZED BY: X

Table with columns: REVISED ESTIMATE(1) \$, DATE, TIME, BY, REVISED ESTIMATE(2) \$

I HEREBY ACKNOWLEDGE THAT I WAS NOTIFIED & GAVE ORAL APPROVAL OF THE ABOVE REVISED ESTIMATES:

X \_\_\_\_\_ CUSTOMER SIGNATURE

FOR YOUR CONVENIENCE OUR SERVICE DEPT. HOURS: MONDAY THRU FRIDAY 7:30 AM TO 5:00 PM

TERMS: CASH · VISA · MASTERCARD

CHECK ACCEPTANCE POLICY

- 1. PREPRINTED CHECKS WITH NAME ADDRESS AND PHONE NUMBER. 2. VALID UNITED STATES DRIVERS LICENSE. NO CARS RELEASED AFTER 5:00 PM



\* INVOICE \*

Mercedes-Benz of Santa Rosa  
2880 TALMADGE DR.  
SANTA ROSA, CA 95407  
(707) 542-4811



Mercedes-Benz  
BAR# ARD 223139



EPA# CAL 000250231

Invoice #: 213953  
Tag #: T828  
Customer #: 66846

Service Advisor: 267 SARAH HARVEY

SANTA ROSA, CA 95409-6107  
HOME: 71  
EMAIL: CELI

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN	MILEAGE OUT
012/268	97	MERCEDES SL320R/95	WDBFA63F8VF	3WNL078	49308	49309
DEL DATE	PROD. DATE	WARR. EXP.	PO NO.	PAYMENT	INV. DATE	R.O. OPENED
31JUL97	11APR97	30JUL2001	17:00	20JUL17	07:27	20JUL17

OPTIONS: DLR:05106 ENG:104991-12-027895 TRN:722605-00-337260 1RADIO CODE#12111 SERIAL#T09677410

A PLEASE REMOVE AND REPLACE REAR VIEW MIRROR 12981032179116 SOP PART IN STOCK TO INSTALL. SEE LAST REPAIR ORDER FOR HISTORY T64

SOP SPECIAL ORDERED PART 64 REED,DUNCAN LIC#: 64

LABOR: 1 129-810-32-17-9116 MIRROR 399.20  
PARTS: 1102.50 1102.50  
OTHER: 0.00 0.00  
TOTAL LINE A: 1102.50 1102.50 \$ 1501.70

CM  
Remove rear view mirror disconnecting electrical connector.  
Install new rear view mirror and check adjustments.

B COMPLIMENTARY MULTIPOINT INSPECTION  
MPI COMPLIMENTARY MULTIPOINT INSPECTION 64 REED,DUNCAN LIC#: 64

LABOR: 0.00 0.00  
PARTS: 0.00 0.00  
OTHER: 0.00 0.00  
TOTAL LINE B: 0.00 0.00

CM  
49309 PERFORMED COMPLIMENTARY WORLD CLASS INSPECTION AND PROVIDED SUPPORTING DOCUMENTATION. FRONT BRAKES 8MM REAR BRAKES 5MM LF TIRE 9/32" RF TIRE 9/32" LR TIRE 10/32" RR TIRE 10/32"

C TIRE PRESSURE CHECK AND INFLATE.  
TPC TIRE PRESSURE CHECK AND INFLATE. 64 REED,DUNCAN LIC#: 64

LABOR: 0.00 0.00  
PARTS: 0.00 0.00  
OTHER: 0.00 0.00  
TOTAL LINE C: 0.00 0.00

CM  
49309 TIRE PRESSURE SET @ 30psi front 33psi rear

-----  
**JOAN DALY**  
 Smothers  
 European  
 Would Like To  
 Thank You  
 For Your  
 Continued  
 Patronage  
 ✂  
 Thank You!  
 -----

Thank You!

LABOR AMOUNT	399.20
PARTS AMOUNT	1102.50
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	0.00
TOTAL CHARGES	1501.70
ADJUSTMENTS	100.00
SALES TAX	95.09
PLEASE PAY THIS AMOUNT	1496.79
<b>TOTALS</b>	
Mercedes-Benz of Santa Rosa <b>CUSTOMER SATISFACTION POLICY</b> It is our intention to make service the number one priority at Mercedes-Benz of Santa Rosa. If there is any suggestion you can make to provide a better Service Department, please let us know. By law, you may choose another facility to perform any needed repairs or adjustments which the Smog Check test indicates are necessary.	
STATEMENT OF DISCLAIMER The factory warranty constitutes all of the warranties with respect to the sale of this item. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item.	
NOTICE TO CUSTOMERS WE MAKE A SEPARATE CHARGE FOR THE DISPOSAL OF TOXIC WASTES. CAL 000077883 RATHER THAN RECOVER THESE COSTS BY INCREASING OUR LABOR RATES TO ALL OF OUR SERVICE CUSTOMERS, WE MAKE THIS CHARGE ONLY ON THOSE PARTICULAR REPAIRS OR SERVICES WHICH GENERATE THESE WASTES. THESE ARE UNIFORM CHARGES WHICH ARE CALCULATED ANNUALLY FOR EACH PARTICULAR SERVICE AND ARE AVAILABLE UPON REQUEST.	
I acknowledge notice and oral approval of an increase in the original estimated price.	Initials _____
Original Estimate \$ _____ Please read the important information on the reverse side of invoice. I acknowledge receipt of this invoice. I acknowledge the warranty repairs performed. I acknowledge notice and oral approval of additional Warranty repairs discovered and corrected during this repair visit.	
Signature X _____	

Mailing Address: 2881 Corby Ave. Santa Rosa, CA 95407

Customer Copy

**Mercedes-Benz of Santa Rosa**

2881 Corby Ave.  
Santa Rosa , CA 95407  
(707) 542-4811

**RECEIPT**

**Customer Information:**

\_\_\_\_\_  
\_\_\_\_\_  
SANTA ROSA 95409-6107

**Invoice Details:**

Invoice #: 7VI8X4442J  
Invoice Date: Thursday, July 20, 2017  
01:17 PM

Repair Order/Ref #: 213953

---

**Description of Product/Services** **Amount**

Service Performed \$ 1496.79

---

**Payment Details:**

Paid On: Thursday, July 20, 2017 02:26 PM  
Credit Card: XXXXXXXXXXXXX1123 exp XX  
/XXXX  
Card Type: Visa  
Cardholder Name: DALY JOAN  
Payment Type: Swiper  
Confirmation #: 055002  
Elli Gordon

-----  
Customer Signature

THANK YOU!

---

**Mercedes-Benz of Santa Rosa**

Processed by myKaarma eBridge  
Payments



**BNC Auto Care Smog Tires & Brakes**

164 Calistoga Road  
 Santa Rosa, CA. 95409  
 Phone: 707-540-0248 Fax: 707-843-3328  
 HOME OF THE \$22.95 OIL CHANGE!

**INVOICE**

**38740**

Org. Est. # 053624  
 ARD00267015 103112  
 CAL000368026

**INVOICE**

Date: 06/13/2017

64 1997 Mercedes-Benz - SL320 - 3.2L, In-Line6 (195CI) VIN(Not /  
 Lic # : - CA Odometer In : 49221

Home : JOHN Office : 7 ELLY VIN# : WDBFA63F8 VF153299

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
---------------------------	-----	------	-----	-------------------	-----

				SMOG INSPECTION	36.70
				SMOG CERTIFICATE	8.25

Org. Estimate 44.95 Revisions 0.00 Current Estimate 44.95

Labor:	36.70
Parts:	0.00
Sublet:	8.25
<b>SubTotal:</b>	<b>44.95</b>
Tax:	0.00
<b>Total:</b>	<b>44.95</b>
Bal Due:	\$0.00

[ Payments - Visa - \$44.95 ]

**HOME OF THE \$22.95 OIL CHANGE!**

Vehicle Received: 6/13/2017

An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

I acknowledge notice and oral approval of an increase in the original estimated price.

If parts are provided by customer there is no warranty. If used parts are installed there is a six month warranty. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLES.

Signature \_\_\_\_\_ Date \_\_\_\_\_ Time \_\_\_\_\_

# SMOG CHECK VEHICLE INSPECTION REPORT

(06/13/2017 @ 10:02:31 am)

## Vehicle Information

Model Year..... 1997	Make..... MERCEDES-BENZ	Model..... SL320
License..... 5ZLN888	State..... California	VIN..... WDBFA63F8VF153299
Engine Size..... 3.2 Liters	Type..... Passenger	Transmission..... Automatic
BVMR..... N/A	Test Weight..... N/A	Cylinders..... 6
Odometer..... 49221	Certification..... California	VLT Record #..... 27847
Fuel Type..... Gasoline	Exhaust..... Single	Inspection Reason..... HEP
Engine Year..... N/A	Engine Make..... N/A	Bar Number..... N/A
Fleet BAR File #..... N/A		

## Overall Test Results

Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Visual Inspection..(Pass) Functional Check..(Pass) Emissions Test..(Pass)

DMV ID Number..(9212T123Z309)  
Smog Check Certificate Number..(ZT934298)

Your Smog Check certificate has been electronically transmitted to the DMV.  
This certificate is valid for ninety (90) days from the date of issuance.

Please keep this copy for your records.

## Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist the identification of oxides of nitrogen, crankcase, and cold start emissions which are not measured during the idle tests)

<u>ECS</u>	<u>Result</u>	<u>ECS</u>	<u>Result</u>	<u>ECS</u>	<u>Result</u>
PCV.....	Pass	Fuel Evaporative Controls.....	Pass	Catalytic Converter.....	Pass
Spark Controls.....	Pass	Fuel Injection.....	Pass	Pump Air Injection.....	Pass
Oxygen Sensor.....	Pass	Wiring to Sensors.....	Pass	Vacuum lines sensors/switches..	Pass
Other related emis. components.	Pass	Liquid Fuel Leak.....	Pass	Fuel Cap Visual.....	Pass
OBD System Check.....	Pass	Ignition Timing.....	N/A		

## Idle Emission Test Results

Test	RPM		%CO2			HC (PPM)			CO (%)			Result
	MEAS	MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS			
M1: 0 MPH	687	15.0	0.0	100	17	10	1.00	0.00	0.00	Pass		
M2: 0 MPH	2535	14.8	0.1	130	12	9	1.00	0.10	0.00	Pass		

MAX = Maximum Allowed Emissions    AVE = Average Emissions For Passing Vehicles    MEAS = Amount Measured

## Smog Check Station Information

Technician Name/Number..... HUETTER, ETHAN/EO637456  
Repair Tech Name/Number..... N/A  
Software Version/EIS Number... 1401/SX790110  
Station Number..... RC267015

1( ) -

I certify under penalty of perjury under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and correct.

6-13-17  
Date
  
Technician's Signature



\* INVOICE \*

DUPLICATE 1  
Invoice #: 212006  
Tag #: T016  
Customer #: 66846

Mercedes-Benz of Santa Rosa  
2880 TALMADGE DR.  
SANTA ROSA, CA 95407  
(707) 542-4811



Mercedes-Benz  
BAR# ARD 223139  
EPA# CAL 000250231

SANTA ROSA, CA 95409-6107  
HOME: 7  
BUS: n|home  
EMAIL:

CELL: 7

Service  
Advisor: 267 SARAH HARVEY

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN	MILEAGE OUT
012/268	97	MERCEDES SL320R/95	WDBFA63F8VF	3WNL078	49173	49175
DEL DATE	PROD. DATE	WARR. EXP.	P.O. NO.	INV. DATE	R.O. OPENED	READY
31 JUL 97	11 APR 97	30 JUL 2001		23 MAY 17	07:30 18 MAY 17	14:30 23 MAY 17

OPTIONS: DLR:05106 ENG:104991-12-027895 TRN:722605-00-337260 1)RADIO CODE#12111 SERIAL#T09677410

LIST	NET	TOTAL
A	CUSTOMER STATES A/C INOP INTERMITTENTLY. IT WILL BLOW COLD SOMETIMES OTHERS IT WILL NOT. CHECK AND ADVISE.	
	00 CUSTOMER STATES 64 REED,DUNCAN LIC#: 64	
	CM	
	1 129-821-33-51A BOWR RISISTR	663.20
	1 129-820-90-42A BLWR MOTOR	237.96
	1 129-835-00-47 CABIN FILTER	415.83
	LABOR: 663.20 PARTS: 701.17 OTHER: 0.00	47.38
	49175	TOTAL LINE A: \$ 1364.37

JOAN DALY

Smothers

European

Would Like To

Thank You

For Your

Continued

Patronage



Thank You!

Original Estimate \$ \_\_\_\_\_  
 Please read the important information on the reverse side of invoice.  
 \_\_\_\_\_ I acknowledge receipt of this invoice.  
 \_\_\_\_\_ I acknowledge the warranty repairs performed.  
 \_\_\_\_\_ I acknowledge notice and oral approval of additional Warranty repairs discovered and corrected during this repair visit.

Signature X \_\_\_\_\_

Initials \_\_\_\_\_

I acknowledge notice and oral approval of an increase in the original estimated price.

STATEMENT OF DISCLAIMER  
 The factory warranty constitutes all of the warranties with respect to the sale of this item. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item.

NOTICE TO CUSTOMERS  
 WE MAKE A SEPARATE CHARGE FOR THE DISPOSAL OF TOXIC WASTES. RATHER THAN RECOVER THESE COSTS BY INCREASING OUR LABOR RATES TO ALL OF OUR SERVICE CUSTOMERS, WE MAKE THIS CHARGE ONLY ON THOSE PARTICULAR REPAIRS OR SERVICES WHICH GENERATE THESE WASTES. THESE ARE UNIFORM CHARGES WHICH ARE CALCULATED ANNUALLY FOR EACH PARTICULAR SERVICE AND ARE AVAILABLE UPON REQUEST.

Mercedes-Benz of Santa Rosa  
 CUSTOMER SATISFACTION POLICY  
 It is our intention to make service the number one priority at Mercedes-Benz of Santa Rosa. If there is any suggestion you can make to provide a better Service Department, please let us know. By law, you may choose another facility to perform any needed repairs or adjustments which the Smog Check test indicates are necessary.

DESCRIPTION	LABOR AMOUNT	PARTS AMOUNT	GAS, OIL, LUBE	SUBLET AMOUNT	MISC. CHARGES	TOTAL CHARGES	ADJUSTMENTS	SALES TAX	PLEASE PAY THIS AMOUNT
TOTALS									

Mailing Address:

2881 Corby Ave. Santa Rosa, CA 95407

TOTAL LINE B: \$ 0.00 (N/C)  
Customer Copy



\*INVOICE\*

Invoice #: 212006

Mercedes-Benz of Santa Rosa  
2880 TALMADGE DR.  
SANTA ROSA, CA 95407  
(707) 542-4811

Tag #: T016

Customer #: 66846

CELL:

SANTA ROSA, CA 95409-6107

HOME: BUS:

EMAIL: car: ie

Service

Advisor: 267 SARAH HARVEY



Mercedes-Benz



BAR# ARD 223139

EPA# CAL 000250231

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN	MILEAGE OUT
012/268	97	MERCEDES SL320R/95	WDBFA63F8VF	3WNL078	49173	49175
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	R.O. OPENED	READY
31JUL97	11APR97	30JUL2001	17:00 18MAY17		07:30 18MAY17	14:30 23MAY17

OPTIONS: DLR:05106 ENG:104991-12-027895 TRN:722605-00-337260 1)RADIO CODE#12111 SERIAL#T09677410

LIST NET TOTAL

-----  
**JOAN DALY**  
 Smothers  
 European  
 Would Like To  
 Thank You  
 For Your  
 Continued  
 Patronage  
 ✂  
**Thank You!**

.... While detaching mirror assembly smoke started coming out of it.

.... Turned of ignition and remove rear view mirror.

.... Disassemble and found broken plastic anchor points for retaining

.... springs and springs loose inside of mirror housing.

.... Recommend replace rear view mirror.

.... Replacement declined.

.... Attempt repair by gluing mounting plate directly to back of mirror

.... glass.

.... Reinstall.

C CUSTOMER STATES PASSANGER SIDE VIEW MIRROR HAS FALLEN OFF. CHECK AND ADVISE.

00 CUSTOMER STATES 64 REED, DUNCAN LIC#: 64

CM

LABOR: 80.00 PARTS: 0.00 OTHER: 0.00 TOTAL LINE C: \$ 80.00

....49173

.... Remove drivers side view mirror cover, inspect fasteners.

.... Reinstall side view mirror cover.

.... Snapped into place well.

D CUSTOMER REQUESTS ORDER NEW KEY . please provide estimate

00 CUSTOMER STATES

CM

299 IM

1 140-760-23-06 VALET KEY

LABOR: 0.00 PARTS: 0.00 OTHER: 0.00 TOTAL LINE D: \$ 0.00

CUSTOMER REQUESTS REPLACE WIPER BLADES. CHECK AND ADVISE.

00 CUSTOMER STATES 64 REED, DUNCAN LIC#: 64

CM

1 129-820-08-45 WIPER

LABOR: 0.00 PARTS: 58.80 OTHER: 0.00 TOTAL LINE E: 58.80

....49173 Replace single wiper blade.

F CUSTOMER STATES BELT REPLACEMENT WAS RECCOMENDED IN THE PAST. CHECK AND ADVISE. previous mpi shows serpentine belt. please provide

Original Estimate \$ \_\_\_\_\_  
 Please read the important information on the reverse side of invoice.  
 I acknowledge receipt of this invoice.  
 I acknowledge the warranty repairs performed.  
 I acknowledge notice and oral approval of additional Warranty repairs discovered and corrected during this repair visit.

Signature X \_\_\_\_\_

I acknowledge notice and oral approval of an increase in the original estimated price.

Initials \_\_\_\_\_

STATEMENT OF DISCLAIMER  
 The factory warranty constitutes all of the warranties with respect to the sale of this item. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

NOTICE TO CUSTOMERS  
 WE MAKE A SEPARATE CHARGE FOR THE DISPOSAL OF TOXIC WASTES. RATHER THAN RECOVER THESE COSTS BY INCREASING OUR LABOR RATES TO ALL OF OUR SERVICE CUSTOMERS. WE MAKE THIS CHARGE ONLY ON THOSE PARTICULAR REPAIRS OR SERVICES WHICH GENERATE THESE WASTES. THESE ARE UNIFORM CHARGES WHICH ARE CALCULATED ANNUALLY FOR EACH PARTICULAR SERVICE AND ARE AVAILABLE UPON REQUEST.

Mercedes-Benz of Santa Rosa  
 CUSTOMER SATISFACTION POLICY  
 It is our intention to make service the number one priority at Mercedes-Benz of Santa Rosa. If there is any suggestion you can make to provide a better Service Department, please let us know. By law, you may choose another facility to perform any needed repairs or adjustments which the Smog Check test indicates are necessary.

DESCRIPTION	LABOR AMOUNT	PARTS AMOUNT	GAS, OIL, LUBE	SUBLET AMOUNT	MISC. CHARGES	TOTAL CHARGES	ADJUSTMENTS	SALES TAX	PLEASE PAY THIS AMOUNT
TOTALS	58.80	0.00	0.00	0.00	0.00	58.80	0.00	58.80	58.80

Mailing Address:

2881 Corby Ave. Santa Rosa, CA 95407

Customer Copy



\*INVOICE\*

DUPLICATE 1 Invoice #: 212006  
Tag #: T016  
Customer #: 66846

SANTA ROSA, CA 95409-6107  
HOME: BUS: CELL  
EMAIL: ie

Mercedes-Benz  
Advisor: 267 SARAH HARVEY

Mercedes-Benz of Santa Rosa  
2880 TALMADGE DR.  
SANTA ROSA, CA 95407  
(707) 542-4811



COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN	MILEAGE OUT
012/268	97	MERCEDES SL320R/95	WDBFA63F8VF	3WNL078	49173	49175
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	INV. DATE	R.O. OPENED	READY
31JUL97	11APR97	30JUL2001	17:00 18MAY17	23MAY17	07:30 18MAY17	14:30 23MAY17

OPTIONS: DLR:05106 ENG:104991-12-027895 TRN:722605-00-337260 1RADIO CODE#12111 SERIAL#T09677410

LIST	NET	TOTAL
00 CUSTOMER STATES 64 REED,DUNCAN LIC#: 64		
1 011-997-21-92 BELT CM	67.50	160.00
LABOR: 160.00 PARTS: 54.00 OTHER: 0.00	54.00	54.00
*****49173 Remove fan shroud and perform serpentine belt replacement.		
G COMPLIMENTARY MULTIPOINT INSPECTION MPI COMPLIMENTARY MULTIPOINT INSPECTION 64 REED,DUNCAN LIC#: 64		
LABOR: 0.00 PARTS: 0.00 OTHER: 0.00		0.00
*****49173 PERFORMED COMPLIMENTARY WORLD CLASS INSPECTION AND PROVIDED SUPPORTING DOCUMENTATION. FRONT BRAKES 9MM REAR BRAKES 6MM LF TIRE 9/32" RF TIRE 7/32" LR TIRE 9/32" RR TIRE 9/32"		
H TIRE PRESSURE CHECK AND INFLATE. TPC TIRE PRESSURE CHECK AND INFLATE. 64 REED,DUNCAN LIC#: 64		
LABOR: 0.00 PARTS: 0.00 OTHER: 0.00		0.00
*****49173 TIRE PRESSURE SET @ 32psi front 33psi rear.		
TOTAL LINE F:	54.00	54.00
TOTAL LINE G:		0.00
TOTAL LINE H:		0.00
TOTAL		\$ 214.00

Mercedes-Benz

Customer Copy

-----  
**JOAN DALY**  
 Smothers  
 European  
 Would Like To  
 Thank You  
 For Your  
 Continued  
 Patronage  
 ✂  
 Thank You!  
 -----

Original Estimate \$ \_\_\_\_\_  
 Please read the important information on the reverse side of invoice.  
 I acknowledge receipt of this invoice.  
 I acknowledge the warranty repairs performed.  
 I acknowledge notice and oral approval of additional warranty repairs discovered and corrected during this repair visit.  
 Signature X \_\_\_\_\_  
 Intials \_\_\_\_\_

DESCRIPTION	LABOR AMOUNT	PARTS AMOUNT	GAS, OIL, LUBE	SUBLET AMOUNT	MISC. CHARGES	TOTAL CHARGES	ADJUSTMENTS	SALES TAX	PLEASE PAY THIS AMOUNT
Mercedes-Benz of Santa Rosa CUSTOMER SATISFACTION POLICY It is our intention to make service the number one priority at Mercedes-Benz of Santa Rosa. If there is any suggestion you can make to provide a better Service Department, please let us know. By law, you may choose another facility to perform any needed repairs or adjustments which the Smog Check test indicates are necessary.									
STATEMENT OF DISCLAIMER The factory warranty constitutes all of the warranties with respect to the sale of this item. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item. NOTICE TO CUSTOMERS WE MAKE A SEPARATE CHARGE FOR THE DISPOSAL OF TOXIC WASTES. CAL 000077883 RATHER THAN RECOVER THESE COSTS BY INCREASING OUR LABOR RATES TO ALL OF OUR SERVICE CUSTOMERS, WE MAKE THIS CHARGE ONLY ON THOSE PARTICULAR REPAIRS OR SERVICES WHICH GENERATE THESE WASTES. THESE ARE UNIFORM CHARGES WHICH ARE CALCULATED ANNUALLY FOR EACH PARTICULAR SERVICE AND ARE AVAILABLE UPON REQUEST.									
TOTALS	903.20	813.97	0.00	0.00	0.00	1717.17	0.00	70.20	1787.37

Mailing Address: 2881 Corby Ave. Santa Rosa, CA 95407



\*INVOICE\*

Invoice #: 222373  
Tag #: T1879  
Customer #: 66846

Mercedes-Benz of Santa Rosa  
2880 TALMADGE DR.  
SANTA ROSA, CA 95407  
(707) 542-4811



SPRINTER

Mercedes-Benz  
BAR# ARD 223139  
EPA# CAL 000250231

328 GREEN FIELD CIR  
HOME 107  
BUS: 3  
EMAIL: home

CELL: 7

Service

Advisor: 267 SARAH HARVEY

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN	MILEAGE OUT
012/268	97	MERCEDES SL320R/95	WDBFA63F8VF	3WNLO78	50396	50396
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT
31 JUL 97	11 APR 97	30 JUL 2001	17:00 29 MAR 18		175.00	CASH
OPTIONS: DLR:05106 ENG:104991-12-027895 TRN:722605-00-337260 1RADIO CODE#12111 SERIAL#T09677410						

LIST	NET	TOTAL
A	CUSTOMER REQUESTS HARD TOP FABRIC CHECKED/REPAIRED. IT IS NOT TORN BUT IS COMING UNGLUED FROM THE ROOF. PLEASE OPERATE SOFT TOP AND CHECK TO MAKE SURE IS OK. IT HAS NOT BEEN USED IN SOME TIME. CHECK AND ADVISE 60 CUST STATES BODY 64 REED, DUNCAN LIC#: 64	
LABOR:	350.00	350.00
PARTS:	430.00	430.00
OTHER:	0.00	0.00
TOTAL LINE A:		780.00

1 129-790-01-45-7C53 HEADLINER  
CM

LABOR: 350.00 PARTS: 430.00 OTHER: 0.00

50396  
Remove hard top, remove quarter window trim, remove grab handles,  
release weather-stripping left and right, unclip head liner front and  
rear and transfer retaining clips to new headliner.  
Install new head liner and reassemble in reverse order.

B PERFORM COMPLIMENTARY MULTIPOINT INSPECTION- SEE ATTACHED DOCUMENTS  
MPI PERFORM COMPLIMENTARY MULTIPOINT INSPECTION- SEE ATTACHED DOCUMENTS 64  
REED, DUNCAN LIC#: 64

LABOR: 0.00 PARTS: 0.00 OTHER: 0.00

50396 PERFORMED COMPLIMENTARY WORLD CLASS INSPECTION AND PROVIDED  
SUPPORTING DOCUMENTATION. FRONT BRAKES 6MM REAR BRAKES 5MM LF TIRE  
8/32" RF TIRE 8/32" LR TIRE 9/32" RR TIRE 9/32"

C TIRE PRESSURE CHECK AND INFLATE.  
TPC TIRE PRESSURE CHECK AND INFLATE. 64 REED, DUNCAN LIC#: 64

LABOR: 0.00 PARTS: 0.00 OTHER: 0.00

50396 TIRE PRESSURE SET @ 30psi front 33psi rear.

JOAN DALY  
Smothers  
European  
Would Like To  
Thank You  
For Your  
Continued  
Patronage



Thank You!

DESCRIPTION	LABOR AMOUNT	PARTS AMOUNT	GAS, OIL, LUBE	SUBLET AMOUNT	MISC. CHARGES	TOTAL CHARGES	ADJUSTMENTS	SALES TAX	PLEASE PAY THIS AMOUNT
Mercedes-Benz of Santa Rosa CUSTOMER SATISFACTION POLICY It is our intention to make service the number one priority at Mercedes-Benz of Santa Rosa. If there is any suggestion you can make to provide a better Service Department, please let us know. By law, you may choose another facility to perform any needed repairs or adjustments which the Smog Check test indicates are necessary.	350.00	430.00	0.00	0.00	0.00	780.00	0.00	37.09	817.09
STATEMENT OF DISCLAIMER The factory warranty constitutes all of the warranties with respect to the sale of this item. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items. NOTICE TO CUSTOMERS WE MAKE A SEPARATE CHARGE FOR THE DISPOSAL OF TOXIC WASTES. CAL 000077883 RATHER THAN RECOVER THESE COSTS BY INCREASING OUR LABOR RATES TO ALL OF OUR SERVICE CUSTOMERS, WE MAKE THIS CHARGE ONLY ON THOSE PARTICULAR REPAIRS OR SERVICES WHICH GENERATE THESE WASTES. THESE ARE UNIFORM CHARGES WHICH ARE CALCULATED ANNUALLY FOR EACH PARTICULAR SERVICE AND ARE AVAILABLE UPON REQUEST.									
I acknowledge notice and oral approval of an increase in the original estimated price. Initials _____									
Original Estimate \$ _____ Please read the important information on the reverse side of invoice. I acknowledge receipt of this invoice. I acknowledge the warranty repairs performed. I acknowledge notice and oral approval of additional Warranty repairs discovered and corrected during this repair visit. Signature X _____									

Mailing Address:  
2881 Corby Ave. Santa Rosa, CA 95407

Customer Copy



**BNC Auto Care Smog Tires & Brakes**

164 Calistoga Road

Santa Rosa, CA. 95409

Phone: 707-540-0248 Fax: 707-843-3328

HOME OF THE \$22.95 OIL CHANGE!

**INVOICE**

**52815**

Org. Est. # 068313

ARD00267015 103112

CAL000368026

**INVOICE**

Date: 06/24/2019

1997 Mercedes-Benz - SL320 - 3.2L, In-Line6 (195CI) VIN(Not A

Lic # :

Odometer In : 52356

Home JOHN -- Office LLY VIN # : WDBFA63F8 VF153299

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
				SMOG INSPECTION	36.70
				SMOG CERTIFICATE	8.25

Org. Estimate 48.40 Revisions 0.00 Current Estimate 48.40

Labor:	36.70
Parts:	0.00
Sublet:	8.25
<b>SubTotal:</b>	<b>44.95</b>
Tax:	0.00
<b>Total:</b>	<b>44.95</b>
Bal Due:	\$0.00

[ Payments - Visa - \$44.95 ]

**HOME OF THE \$22.95 OIL CHANGE!**

Vehicle Received: 6/24/2019

Customer Number : 564

An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

I acknowledge notice and oral approval of any increase in the original estimated price.

If parts are provided by customer there is no warranty. if used parts are installed there is a six month warranty. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLES.

Signature \_\_\_\_\_ Date \_\_\_\_\_



www.esp-global.com

# Smog Check Vehicle Inspection Report (VIR)



www.autorepair.ca.gov

## Vehicle Information

Test Date/Time: 06/24/2019@08:32:21

Model Year: 1997	Make: MERCEDES-BENZ	Model: SL320
License: 5ZLN888	State: CA	VIN: WDBFA63F8VF153299
Engine Size: 3.20 L	Type: Passenger Car	Transmission: Automatic
GVWR: N/A	Test Weight: N/A	Cylinders: 6
Odometer: 52,356	Certification: California	VLT Record #: 27847
Fuel Type: Gasoline	Exhaust: Single	Inspection Reason: High Emitter Profile

## Overall Test Results

**Congratulations!** Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

**Smog Check Certificate Number: QU342353**

**DMV ID Number: 9513U628Q919**

Your Smog Check certificate has been electronically transmitted to DMV. Your certificate is valid for 90 days from date of issuance. Please keep this copy for your records.

## Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of oxides of nitrogen, crankcase and cold start emissions which are not measured during the Idle test.)

Result	ECS	Result	ECS	Result	ECS
Pass	PCV	Not applicable	Thermostatic Air Cleaner	Pass	Fuel Evaporative Controls
Pass	Catalytic Converter	Pass	Air Injection	Pass	OBD System Checks
Not applicable	EGR Visual	Pass	Vacuum Lines to Sensors / Switches	Pass	Carb. / Fuel Injection
Not applicable	EGR Functional	Not applicable	Ignition Timing	Pass	Other Emission Related Components
Not applicable	Fuel Cap Functional	Pass	Wiring to Sensors	Pass	Oxygen Sensor
Not applicable	Fuel Cap Visual	Not applicable	Fillpipe Restrictor	Pass	Liquid Fuel Leaks
Pass	Spark Controls	Not applicable	Fuel Evaporative Controls Functional		

## Idle Emission Test Results

Test	RPM	%CO2		HC (PPM)			CO (%)			Results
		MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	
Idle	700	15.7	0.0	100	17	14	1.00	0.00	0.01	Pass
2500 RPM	2349	15.6	0.0	130	12	10	1.00	0.10	0.01	Pass

MAX = Maximum Allowable Emissions

AVE = Average Emissions For Passing Vehicles

MEAS = Amount Measured

## Smog Check Inspection Station Information

BNC AUTO CARE SMOG TIRES & BRAKES  
 164 CALISTOGE R D, SANTA ROSA, CA 95409  
 707-540-0248  
 Station Number: RA267015

Technician Name/Number: ACOSTA FLORES, VALEN/EO640584  
 Repair Tech Name/Number:  
 Software Version/EIS Number: 1805 / EP729611

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

06-24-2019  
Date

Technician's Signature



\* INVOICE \*

Mercedes-Benz of Santa Rosa  
2880 TALMADGE DR.  
SANTA ROSA, CA 95407  
(707) 542-4811

Invoice #: 248135  
Tag #: T1548  
Customer #: 66846

Service Advisor: 267 SARAH HARVEY

CELL:

HOME: SANTA ROSA, CA 95409-6107  
EMAIL: c [home] BUS:



EPA# CAL 000250231

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN	MILEAGE OUT
012/268	97	MERCEDES SL320R/95	WDBFA63F8VF 153299	3WNL078	52966	52975
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT
31JUL97	11APR97	30JUL2001	17:00 01MAY20		195.00	CASH
OPTIONS: DLR:05106 ENG:104991-12-027895 TRN:722605-00-337260 1RADIO CODE#12111 SERIAL#T09677410						

LIST NET TOTAL

**A** CUSTOMER STATES VEH HAD SAT A FEW WEEKS. BATTERY WAS REPLACED BUT HE FEELS SOMETHING MAY BE WRONG WITH STARTER AS HE HEARD THE CLASSIC SCREECH SOUND. CHECK AND ADVISE T1.0  
01 DIAGNOSIS 64 REED,DUNCAN LIC#: 64

JOAN DALY

Smothers  
European  
Would Like To  
Thank You  
For Your  
Continued  
Patronage



Thank You!

LABOR: 195.00 PARTS: 0.00 OTHER: 0.00 TOTAL LINE A: \$ 195.00  
CM

Vehicle is starting normally at this time.  
Perform amp test of starter, 260amps OK.  
Perform draw test, 0.03 ohms OK  
Perform charging system test, 13.80 w/o loads, 13.60 volts w/loads  
OK.  
Battery production 07/13, Not OK.  
Perform Midtronics battery test, 'charge; result. Recommend replace battery.

**B** PERFORM COMPLIMENTARY MULTIPOINT INSPECTION- VISUALLY INSPECT TIRES, BRAKES, SUSPENSION, ENGINE AND TRANSMISSION, SOME ITEMS MAY NOT BE INSPECTED DEPENDING UPON VEHICLE CONFIGURATION  
MPI PERFORM COMPLIMENTARY MULTIPOINT INSPECTION- VISUALLY INSPECT TIRES, BRAKES, SUSPENSION, ENGINE AND TRANSMISSION, SOME ITEMS MAY NOT BE INSPECTED DEPENDING UPON VEHICLE CONFIGURATION 64 REED,DUNCAN LIC#: 64

LABOR: 0.00 PARTS: 0.00 OTHER: 0.00 TOTAL LINE B: \$ 0.00  
IM

52966 PERFORMED COMPLIMENTARY WORLD CLASS INSPECTION AND PROVIDED SUPPORTING DOCUMENTATION. FRONT BRAKES 5MM REAR BRAKES 3MM LF TIRE 7/32" RF TIRE 7/32" LR TIRE 9/32" RR TIRE 9/32"

**C** TIRE PRESSURE CHECK AND INFLATE.  
TPC TIRE PRESSURE CHECK AND INFLATE. 64 REED,DUNCAN LIC#: 64

LABOR: 0.00 PARTS: 0.00 OTHER: 0.00 TOTAL LINE C: \$ 0.00  
IM

Customer Copy

DESCRIPTION	LABOR AMOUNT	PARTS AMOUNT	GAS, OIL, LUBE	SUBLET AMOUNT	MISC. CHARGES	TOTAL CHARGES	ADJUSTMENTS	SALES TAX	PLEASE PAY THIS AMOUNT
<p>Original Estimate \$ _____</p> <p>Please read the important information on the reverse side of invoice.</p> <p><input type="checkbox"/> I acknowledge receipt of this invoice.</p> <p><input type="checkbox"/> I acknowledge the warranty repairs performed.</p> <p><input type="checkbox"/> I acknowledge notice and oral approval of additional Warranty repairs discovered and corrected during this repair visit.</p> <p>Signature X _____</p> <p>Initials _____</p> <p>STATEMENT OF DISCLAIMER The factory warranty constitutes all of the warranties with respect to the sale of this item. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item.</p> <p>NOTICE TO CUSTOMERS WE MAKE A SEPARATE CHARGE FOR THE DISPOSAL OF TOXIC WASTES. RATHER THAN RECOVER THESE COSTS BY INCREASING OUR LABOR RATES TO ALL OF OUR SERVICE CUSTOMERS, WE MAKE THIS CHARGE ONLY ON THOSE PARTICULAR REPAIRS OR SERVICES WHICH GENERATE THESE WASTES. THESE ARE UNIFORM CHARGES WHICH ARE CALCULATED ANNUALLY FOR EACH PARTICULAR SERVICE AND ARE AVAILABLE UPON REQUEST.</p> <p>Mercedes-Benz of Santa Rosa CUSTOMER SATISFACTION POLICY It is our intention to make service the number one priority at Mercedes-Benz of Santa Rosa. If there is any suggestion you can make to provide a better Service Department, please let us know. By law, you may choose another facility to perform any needed repairs or adjustments which the Smog Check test indicates are necessary.</p>									
<b>TOTALS</b>									
2881 Corby Ave. Santa Rosa, CA 95407									



\* INVOICE \*

Invoice #: 248135  
Tag #: T1548  
Customer #: 66846

Mercedes-Benz of Santa Rosa  
2880 TALMADGE DR.  
SANTA ROSA, CA 95407  
(707) 542-4811



SPRINTER

SANTA ROSA, CA 95409-6107  
HOME: 707-542-4811  
BUS: 707-542-4811  
EMAIL: sarah.harvey@mercedes-benz.com

Advisor: 267 SARAH HARVEY  
BAR# ARD 223139  
EPA# CAL 000250231

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN	MILEAGE OUT
012/268	97	MERCEDES SL320R/95	WDBFA63F8VF 153299	3WNL078	52966	52975
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT
31JUL97	11APR97	30JUL2001	17:00 01MAY20		195.00	CASH
OPTIONS: DLR:05106 ENG:104991-12-027895 TRN:722605-00-337260 1)RADIO CODE#12111 SERIAL#T09677410						

LIST	NET	TOTAL
D** PLEASE REPLACE BATTERY		
54 REPLACED BATTERY 64 REED,DUNCAN LIC#: 64		
CM		
1 000-982-33-08 BATTERY	177.00	97.50
1 BATT BATT FEE	1.00	177.00
LABOR: 97.50 PARTS: 178.00 OTHER: 0.00	1.00	1.00
*****52966 Remove trunk panel for access, replace battery, set clock and enter radio code.		\$ 275.50
TOTAL LINE D:		
E** PLEASE REPLACE HOOD INSULATION T.80		
01 HOOD INSULATION 64 REED,DUNCAN LIC#: 64		
CM		
1 129-680-20-25 INSULATION	165.00	156.00
LABOR: 156.00 PARTS: 165.00 OTHER: 0.00		165.00
*****52966 Clean old hood insulation and adhesive. Apply high temp adhesive and install new hood insulation.		
TOTAL LINE E:		\$ 321.00
F** PLEASE REPLACE AXLE SEAL T2.0		
00 AXLE SEAL 66 GRAMAJO,ORVILLE LIC#: 66		
CM		
2 025-997-26-47 SEAL RING	21.06	390.00
1 003-989-98-20-10 SEALANT	24.30	42.12
6 Q-1-09-0096 8090LUBE	6.50	24.30
LABOR: 390.00 PARTS: 105.42 OTHER: 0.00	6.50	39.00
*****52966 removed rear differential and replaced both axle seals and resealed rear cover. topped off with differential fluid		
TOTAL LINE F:		\$ 495.42

D\*\* PLEASE REPLACE BATTERY  
54 REPLACED BATTERY 64 REED,DUNCAN LIC#: 64  
CM

E\*\* PLEASE REPLACE HOOD INSULATION T.80  
01 HOOD INSULATION 64 REED,DUNCAN LIC#: 64  
CM


F\*\* PLEASE REPLACE AXLE SEAL T2.0  
00 AXLE SEAL 66 GRAMAJO,ORVILLE LIC#: 66  
CM

G\*\* PLEASE REPLACE REAR BRAKE PADS AND ROTORS  
42 CUSTOMER STATES CHECK BRAKES FOR WEAR AND NEED OF REPLACEMENT 66  
GRAMAJO,ORVILLE LIC#: 66  
CM

STATEMENT OF DISCLAIMER  
The factory warranty constitutes all of the warranties with respect to the sale of this item. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item.

NOTICE TO CUSTOMERS  
WE MAKE A SEPARATE CHARGE FOR THE DISPOSAL OF TOXIC WASTES. RATHER THAN RECOVER THESE COSTS BY INCREASING OUR LABOR RATES TO ALL OF OUR SERVICE CUSTOMERS, WE MAKE THIS CHARGE ONLY ON THOSE PARTICULAR REPAIRS OR SERVICES WHICH GENERATE THESE WASTES. THESE ARE UNIFORM CHARGES WHICH ARE CALCULATED ANNUALLY FOR EACH PARTICULAR SERVICE AND ARE AVAILABLE UPON REQUEST.

Mercedes-Benz of Santa Rosa  
CUSTOMER SATISFACTION POLICY  
It is our intention to make service the number one priority at Mercedes-Benz of Santa Rosa. If there is any suggestion you can make to provide a better Service Department, please let us know. By law, you may choose another facility to perform any needed repairs or adjustments which the Smog Check test indicates are necessary.

-----  
**JOAN DALY**  
 Smothers  
 European  
 Would Like To  
 Thank You  
 For Your  
 Continued  
 Patronage  
 -----  
  
**Thank You!**

Original Estimate \$ \_\_\_\_\_  
 Please read the important information on the reverse side of invoice.  
 I acknowledge receipt of this invoice.  
 I acknowledge the warranty repairs performed.  
 I acknowledge notice and oral approval of additional Warranty repairs discovered and corrected during this repair visit.  
 Signature X \_\_\_\_\_  
 Initials \_\_\_\_\_

Mailing Address:  
2881 Corby Ave. Santa Rosa, CA 95407

Customer Copy

LABOR AMOUNT	PARTS AMOUNT	GAS, OIL, LUBE	SUBLET AMOUNT	MISC. CHARGES	TOTAL CHARGES	ADJUSTMENTS	SALES TAX	PLEASE PAY THIS AMOUNT
390.00	184.00							
<b>TOTALS</b>								





Mercedes-Benz

# Mercedes-Benz of Santa Rosa



2880 TALMADGE DR. SANTA ROSA, CA 95407

Mailing Address:  
2881 Corby Ave.  
Santa Rosa, CA 95407

**707-542-4811**

PARTS DIRECT 707-542-4830  
WHOLESALE ONLY 1-800-675-5030  
FAX 707-541-7456  
PARTS DEPARTMENT HOURS  
7:30-5:30 MON. - FRI.

### DISCLAIMER OF WARRANTIES

Any warranties on the product sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

DATE ENTERED 29SEP2021	YOUR ORDER NO.	DATE SHIPPED 29SEP2021	INVOICE DATE 29SEP2021	INVOICE NUMBER 247226	13:41
---------------------------	----------------	---------------------------	---------------------------	--------------------------	-------

S  
O  
L  
D  
T  
O

ACCOUNT NO. 200  
CASH & TAX

S  
H  
I  
P  
T  
O

CASH & TAX

PAGE 1 OF 1

SHIP VIA		SLSM.	B/L NO.	TERMS	F.O.B. POINT		
		27		CASH	SANTA ROSA, CA		
QUANTITY	DESCRIPTION	PART NO.	LIST	NET	AMOUNT		
1	BAT BATTERY	000-982-33-08	177.00	177.00	177.00		
	BATTERY FEE	102			1.00		
1	SP BATTCORE	982-548-30-89-01	27.00	27.00	27.00		
<b>PAID BY CREDIT CARD</b>							
<p>***ATTENTION WHOLESALE CUSTOMERS*** THIS SIGNED INVOICE IS CONFIRMATION THAT THE PARTS WERE RECEIVED IN GOOD CONDITION. NO SCRATCHES, DENTS, DINGS OR BREAKAGE. PLEASE INSPECT CAREFULLY</p>							
CUSTOMER'S SIGNATURE					PARTS		
X					205.00		
					SUBLET		
					FREIGHT		
					0.00		
					SALES TAX		
					18.96		
					<b>TOTAL</b>		
					<b>\$223.96</b>		

NO REFUNDS WITHOUT THIS INVOICE

20% HANDLING ON RETURNED PARTS

NO REFUNDS AFTER 30 DAYS

NO RETURNS ON ELECTRICAL ITEMS

NO RETURNS OR REFUNDS ON SPECIAL ORDERED ITEMS

BAR# ARD 223139  
EPA# CAL 000250231

"THANK YOU FOR CHOOSING MERCEDES-BENZ OF SANTA ROSA"

CUSTOMER COPY

**TRI\*STAR AUTOMOTIVE**  
 484 KENWOOD COURT  
 SANTA ROSA CA 95407-7895  
 707-571-8866

BAR # AK 163405-----E.P.A. #CAL000073672

12/30/2021 2:36 PM

page 1

Repair Order #83943

Vehicle : 1997 Mercedes-Benz SL320 3.2 L 3199 CC L6  
 VIN : WDBFA63F8VF153299  
 Created : 12/30/2021 2:34:27 PM  
 Srv Writer: JD

Day Phone  
 Tag/State : 5ZLN888 / CA  
 Last Mileage : 53677  
 Odometer In : 53677  
 Odometer Out : 53677

**Labor/Notes**

Code/Tech*	Description	Price
16*	CALIFORNIA SMOG INSPECTION	\$71.75

NOTE: VEHICLES ARE TESTED AS BROUGHT IN TO THE SHOP.

WE WILL PERFORM A PRETEST ON REQUEST FOR AN ADDITIONAL EXPENSE.  
 "BY LAW, YOU MAY CHOOSE ANOTHER LICENSED SMOG CHECK FACILITY TO PERFORM  
 ANY NEEDED REPAIRS OR ADJUSTMENTS THAT THE SMOG CHECK TEST INDICATES  
 ARE NECESSARY."

16*	CALIFORNIA STATE SMOG CERTIFICATE	\$8.25
-----	-----------------------------------	--------

CERT # SG366246  
DMV ID # 9877G721S689

16*	TIRE PRESSURE CHECK & INFLATION	\$0.00
-----	---------------------------------	--------

TIRES INFLATED TO (PSI) AS PER CARB'S TIRE INFLATION REGULATION  
FRONT TIRES / REAR TIRES---- PSI > 32 / 32

Labor	\$71.75
Parts	\$0.00
Sublet/Misc.	\$0.00
Other Charges	\$0.00
Charges	\$8.25
Sales Tax	Tax @ \$0.00 * 9.2500%
<b>Repair Total</b>	<b>\$80.00</b>

Tech	Certification #
16	

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express garagekeeper's lien is hereby acknowledged on above vehicle to secure the amount or repairs thereto.

All Vehicles left over 48 hrs. after repairs are completed WILL INCUR A \$50.00 PER DAY STORAGE FEE. 24 Month or 24,000 Mile Warranty On Repairs.

Customer Signature \_\_\_\_\_





www.esp-global.com

# Smog Check Vehicle Inspection Report (VIR)



www.autorepair.ca.gov

## Vehicle Information

Test Date/Time: 12/30/2021@13:32:02

Model Year:	1997	Make:	MERCEDES-BENZ	Model:	SL320
License:	5ZLN888	State:	CA	VIN:	WDBFA63F8VF153299
Engine Size:	3.20 L	Type:	Passenger Car	Transmission:	Automatic
GVWR:	N/A	Test Weight:	N/A	Cylinders:	6
Odometer:	53,677	Certification:	California	VLT Record #:	27847
Fuel Type:	Gasoline	Exhaust:	Single	Inspection Reason:	High Emitter Profile

## Overall Test Results

Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Smog Check Certificate Number: SG366246

DMV ID Number: 9877G721S689

Your Smog Check certificate has been electronically transmitted to DMV.  
Your certificate is valid for 90 days from date of issuance.  
Please keep this copy for your records.

## Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of oxides of nitrogen, crankcase and cold start emissions which are not measured during the Idle test.)

Result	ECS	Result	ECS	Result	ECS
Pass	PCV	Not applicable	Thermostatic Air Cleaner	Pass	Fuel Evaporative Controls
Pass	Catalytic Converter	Pass	Air Injection	Pass	OBD System Checks
Not applicable	EGR Visual	Pass	Vacuum Lines to Sensors / Switches	Pass	Carb. / Fuel Injection
Not applicable	EGR Functional	Not applicable	Ignition Timing	Pass	Other Emission Related Components
Not applicable	Fuel Cap Functional	Pass	Wiring to Sensors	Pass	Oxygen Sensor
Not applicable	Fuel Cap Visual	Not applicable	Fillpipe Restrictor	Pass	Liquid Fuel Leaks
Pass	Spark Controls	Bypass	Fuel Evaporative Controls Functional		

## Idle Emission Test Results

Test	RPM	%CO2		HC (PPM)			CO (%)			Results
		MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	
Idle	695	16.0	0.0	100	17	82	1.00	0.00	0.02	Pass
2500 RPM	2457	15.9	0.0	130	12	35	1.00	0.10	0.06	Pass

MAX = Maximum Allowable Emissions

AVE = Average Emissions For Passing Vehicles

MEAS = Amount Measured

## Smog Check Inspection Station Information

TRI STAR AUTOMOTIVE  
484 KENWOOD CT, SANTA ROSA, CA 95407  
707-571-8866  
Station Number: RC163405

Technician Name/Number: WELTER, LUCAS/EO152995  
Repair Tech Name/Number:  
Software Version/EIS Number: 1905 / EP830778

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

12-30-21  
Date

*[Signature]*  
Technician's Signature

**Larkfield Auto Center**  
 4809 Old Redwood Highway  
 Santa Rosa, CA. 95403  
 Phone - 707-546-6881 Fax - 707-546-1784  
 Specializing In Your Car

INVOICE

**16695**

BAR-AE239884  
 EPA CAL000350118

**INVOICE**

Print Date : 10/08/2021

**N**  
 Santa Rosa, CA 95403  
 Cust ID : 4427 Ref # :  
 1997 Mercedes-Benz - S320  
 3.2L, In-Line6, VIN (Not Avail)  
 Lic # : 5ZLN888 Odometer In : 53245  
 Unit # : Odometer Out : 53245  
 Vin # : **WDBFA63F8VF153299**  
 Hat # :

Part Description / Number	Qty	Sale	Extended	Labor Description	Extended
				PERFORM SMOG CHECK INSPECTION	90.00
				FRONT TIRES AT 30 PSI	
				REAR TIRES AT 36 PSI	
				VEHICLE FAIL	
				RETEST 30	N/C

Org. Estimate \$90.00	Revisions \$0.00	Current Estimate \$ 90.00	Additional Cost	Revised Estimate	<b>Labor: 90.00</b>
					<b>Parts: 0.00</b>
					<b>Sublet: 0.00</b>
					-----
					<b>Sub: 90.00</b>
					<b>Tax: 0.00</b>
					<b>Total: 90.00</b>
					<b>Bal Due: \$90.00</b>

[ Payments - ]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

SIGNATURE..... Date..... Time.....





# Smog Check Vehicle Inspection Report (VIR)



www.esp-global.com

www.autorepair.ca.gov

Test Date/Time: 10/08/2021@15:36:28

Model Year:	1997	Make:	MERCEDES-BENZ	Model:	SL320
License:	5ZLN888	State:	CA	VIN:	WDBFA63F8VF153299
Engine Size:	3.20 L	Type:	Passenger Car	Transmission:	Automatic
GWWR:	N/A	Test Weight:	N/A	Cylinders:	6
Odometer:	53,245	Certification:	California	VLT Record #:	27847
Fuel Type:	Gasoline	Exhaust:	Single	Inspection Reason:	High Emitter Profile

## Overall Test Results

Comprehensive Visual Inspection: **Pass** Functional Check: **Fail** Emissions Test: **Pass**

Repairing your vehicle is necessary to help California reduce smog-forming emissions and reach our air quality goals.

## Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of oxides of nitrogen, crankcase and cold start emissions which are not measured during the Idle test.)

Result	ECS	Result	ECS	Result	ECS
Pass	PCV	Not applicable	Thermostatic Air Cleaner	Pass	Fuel Evaporative Controls
Pass	Catalytic Converter	Pass	Air Injection	Fail	OBD System Checks
Not applicable	EGR Visual	Pass	Vacuum Lines to Sensors / Switches	Pass	Carb. / Fuel Injection
Not applicable	EGR Functional	Not applicable	Ignition Timing	Pass	Other Emission Related Components
Not applicable	Fuel Cap Functional	Pass	Wiring to Sensors	Pass	Oxygen Sensor
Not applicable	Fuel Cap Visual	Not applicable	Fillpipe Restrictor	Pass	Liquid Fuel Leaks
Pass	Spark Controls	Bypass	Fuel Evaporative Controls Functional		

This vehicle did not pass the OBD system check because its OBD system was not ready to test.

## Idle Emission Test Results

Test	RPM	%CO2		%O2			HC (PPM)			CO (%)			Results
		MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	MAX	AVE		
Idle	698	15.9	0.0	100	17	15	1.00	0.00	0.01			Pass	
2500 RPM	2544	15.8	0.0	130	12	10	1.00	0.10	0.02			Pass	

MAX = Maximum Allowable Emissions

AVE = Average Emissions For Passing Vehicles

MEAS = Amount Measured

Failed smog check? Financial assistance may be available. To get an application, visit the Bureau of Automotive Repair's website at www.smogcheck.ca.gov or call toll-free at 800.952.5210.

Si usted ha fallado el examen de smog, asistencia financiera puede estar disponible. Para obtener una solicitud, visite www.smogcheck.ca.gov o llámenos a BAR al 800.952.5210.

## Smog Check Inspection Station Information

LARKFIELD AUTO CENTER  
 4809 OLD REDWOOD HWY SANTA ROSA, CA 95403  
 (707) 546-6881  
 Station Number: RC239884

Technician Name/Number: NGUYEN, KEVIN/EO038502  
 Repair Tech Name/Number:  
 Software Version/EIS Number: 1905 / EP728897

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

Date: 10/8/21 Technician's Signature: [Signature]

**Mercedes-Benz of Santa Rosa**  
 2880 TALMADGE DR.  
 SANTA ROSA, CA 95407  
 (707) 542-4811



**SPRINTER**

Mercedes-Benz  
 BAR# ARD 223139 EPA# CAL 000250231

Invoice #: **264912**  
 Tag #: **T4073**  
 Customer #: **66846**

Service Advisor: **267 SARAH HARVEY**

SANTA ROSA, CA 95403-8061  
 HOME: BUS: 7  
 EMAIL: home

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN	MILEAGE OUT
PERIWINKLE	97	MERCEDES BENZ SL320R	WDBFA63F8VF	<b>5ZLN888</b>	53420	53555
DEL DATE	PROD. DATE	WARR. EXP.	PO. NO.	INV. DATE	R.O. OPENED	READY
31 JUL 97	11 APR 97	30 JUL 2001	17:00 11 JAN 22	12 JAN 22	09:00 08 DEC 21	15:20 12 JAN 22
OPTIONS: DLR:05106 ENG:104991-12-027895 TRN:722605-00-337260 1RADIO CODE#12111 SERIAL#T09677410						

**A** CUSTOMER STATES THE VEHICLE WILL NOT PASS SMOG. THE PAPERWORK FROM THE SMOG SHOP IS IN THE GLOVE BOX. CUSTOMER IS NOT SURE WHAT IT NEEDS. POSSIBLE ISSUE WITH INST CLUSTER. CHECK AND ADVISE T1.0  
 01 ENGINE 84 CABOT, BERNARD LIC#: 84

**B** CUSTOMER STATES THE REAR VIEW MIRROR IS BLURRING AND OR GIVING DOUBEL VISION. CHECK ANCX ADVISEER STATES CAR IS NOT PASSING SMOG  
 00 GENERAL REPAIR 84 CABOT, BERNARD LIC#: 84

**C** PERFORM COMPLIMENTARY MULTIPOINT INSPECTION- VISUALLY INSPECT TIRES, BRAKES, SUSPENSION, ENGINE AND TRANSMISSION, SOME ITEMS MAY NOT BE INSPECTED DEPENDING UPON VEHICLE CONFIGURATION  
 MPI PERFORM COMPLIMENTARY MULTIPOINT INSPECTION- VISUALLY INSPECT TIRES, BRAKES, SUSPENSION, ENGINE AND TRANSMISSION, SOME ITEMS MAY NOT BE INSPECTED DEPENDING UPON VEHICLE CONFIGURATION 84 CABOT, BERNARD LIC#: 84

**JOAN DALY**  
**Smothers**  
**European**  
**Would Like To**  
**Thank You**  
**For Your**  
**Continued**  
**Patronage**



**Thank You!**

LABOR: 615.00 PARTS: 0.00 OTHER: 0.00 TOTAL LINE A: 615.00

CM  
 \*\*\*\*\*53420 CHECK FOR TROUBLE CODES. NONE FOUND. THERE IS ONE MONITOR THE  
 \*\*\*\*\*HAS NOT RUN YET PREVENTING SMOG CHECK PASS. AIR PUMP MONITOR NOT RUN.  
 \*\*\*\*\*AIR INJECTION SYSTEM INSPECTION. CHECK FUSE, AIR PUMP AND CHECK VALVE.  
 \*\*\*\*\*SEND OUT FOR A DRIVE TO SEE IF THE MONITORS WOULD SET. CONNECT SDS AND  
 \*\*\*\*\*GO TO HFM-ME. GO TO ACTUATION AND ACTIVATE AIR PUMP. O2 SENSOR SHOULD  
 \*\*\*\*\*DROP TO 40 MV WITH AIR PUMP GOING. ONLY DROPPING TO 120MV. CHECK AIR  
 \*\*\*\*\*VALVE AND PIPES. FOUND SMALL CRACK IN PLASTIC VACUUM LINE TO AIR VALVE  
 \*\*\*\*\*CAUSING VALVE TO OPEN ABOUT 1/2 WAY. REPLACE LINE, NOW THE AIR VALVE  
 \*\*\*\*\*OPENS FULLY DROPPING THE O2 VOLTAGE TO 35 MV.

LABOR: 0.00 PARTS: 0.00 OTHER: 0.00 TOTAL LINE B: (N/C) \$ 0.00

IM  
 \*\*\*\*\*53555  
 PERFORM COMPLIMENTARY MULTIPOINT INSPECTION- VISUALLY INSPECT TIRES, BRAKES, SUSPENSION, ENGINE AND TRANSMISSION, SOME ITEMS MAY NOT BE INSPECTED DEPENDING UPON VEHICLE CONFIGURATION  
 MPI PERFORM COMPLIMENTARY MULTIPOINT INSPECTION- VISUALLY INSPECT TIRES, BRAKES, SUSPENSION, ENGINE AND TRANSMISSION, SOME ITEMS MAY NOT BE INSPECTED DEPENDING UPON VEHICLE CONFIGURATION 84 CABOT, BERNARD LIC#: 84

LABOR: 0.00 PARTS: 0.00 OTHER: 0.00 TOTAL LINE C: (N/C) \$ 0.00

IM  
 \*\*\*\*\*53420 PERFORMED COMPLIMENTARY WORLD CLASS INSPECTION


**Customer Copy**

Original Estimate \$	LABOR AMOUNT
Please read the important information on the reverse side of invoice.	PARTS AMOUNT
I acknowledge receipt of this invoice.	GAS, OIL, LUBE
I acknowledge the warranty repairs performed.	SUBLET AMOUNT
I acknowledge notice and oral approval of additional Warranty repairs discovered and corrected during this repair visit.	MISC. CHARGES
Signature X	TOTAL CHARGES
Initials	ADJUSTMENTS
	SALES TAX
	PLEASE PAY THIS AMOUNT
	TOTALS

Mailing Address:  
 2881 Corby Ave. Santa Rosa, CA 95407



**Mercedes-Benz of Santa Rosa**  
 2880 TALMADGE DR.  
 SANTA ROSA, CA 95407  
 (707) 542-4811



Mercedes-Benz  
 BAR# ARD 223139  
 EPA# CAL 000250231

Invoice #: **264912**  
 Tag #: **T4073**  
 Customer #: **66846**

Service Advisor: **SARAH HARVEY**  
 VIN: **WDBFA63F8VF 153299**  
 LICENSE: **5ZLN888**

PERIWINKLE	DEL DATE	PROD. DATE	WARR. EXP.	MAKE/MODEL	VIN	PAYMENT	INV. DATE	MILEAGE IN	MILEAGE OUT
31 JUL 97	11 APR 97	30 JUL 2001	17:00 11 JAN 22	MERCEDES BENZ SL320R	WDBFA63F8VF 153299	CASH	12 JAN 22	53420	53555

OPTIONS: DLR:05106 ENG:104991-12-027895 TRN:722605-00-337260 1RADIO CODE#12111 SERIAL#T09677410

**D** SUPPORTING DOCUMENTATION. FRONT BRAKES 6 MM REAR BRAKES 10 MM LF TIRE 7  
 "/>32" RF TIRE 7 /32" LR TIRE 8 /32" RR TIRE 8 /32"

**E\*\*** CHECK AND SET TIRE PRESSURES TO THEIR RECOMMENDED TIRE PRESSURE RATING PER CARB REGULATIONS.  
 SECTION 95550 TITLE 17  
 TPC CHECK AND SET TIRE PRESSURES TO THEIR RECOMMENDED TIRE PRESSURE RATING PER CARB REGULATIONS. SECTION 95550 TITLE 17 84 CABOT, BERNARD LIC#: 84


**F\*\*** LABOR: 0.00 PARTS: 0.00 OTHER: 0.00 TOTAL LINE D: \$ 0.00  
 "/>32" TIRE PRESSURE SET @ LF 30 PSI RF 30PSI LR 35PSI RR 35 PSI  
 S/PARE 30 PSI

**F\*\*** PLEASE REPLACE THERMOSTAT T1.0  
 01 ENGINE 84 CABOT, BERNARD LIC#: 84  
 CM  
 1 110-200-05-15 THERMOSTAT  
 1 0-1-03-0004 ANTI FREEZE  
 1 000-158-14-35 LINE

**F\*\*** LABOR: 205.00 PARTS: 92.85 OTHER: 0.00 TOTAL LINE E: \$ 297.85  
 "/>53555 DRAIN COOLANT. REMOVE AND REPLACE THERMOSTAT. FILL WITH NEW  
 "/>COOLANT AND PRESSURE TEST.

**F\*\*** 9 CUSTOMER STATES FRONT 02 SENSOR  
 00 CUSTOMER STATES 84 CABOT, BERNARD LIC#: 84  
 CM  
 LABOR: 0.00 PARTS: 0.00 OTHER: 0.00 TOTAL LINE F: \$ 0.00  
 "/>53555 02 SENSOR NOT NECESSARY, THIS VEHICLE CAN PASS WITH ONLY 1  
 "/>SENSOR.

**G\*\*** 0.0 CUSTOMER STATES REPLACE THE OIL CAP  
 00 CUSTOMER STATES 84 CABOT, BERNARD LIC#: 84  
 CM  
 1 000-010-12-85 OIL CAP

-----  
**JOAN DALY**  
 Smothers  
 European  
 Would Like To  
 Thank You  
 For Your  
 Continued  
 Patronage  
 -----  


**Thank You!**

LABOR AMOUNT	PARTS AMOUNT	GAS, OIL, LUBE	SUBLET AMOUNT	MISC. CHARGES	TOTAL CHARGES	ADJUSTMENTS	SALES TAX	PLEASE PAY THIS AMOUNT
0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
205.00	62.70	23.50	6.65	0.00	0.00	0.00	0.00	297.85
<b>TOTALS</b>								
<b>DESCRIPTION</b>								
<p><b>Mercedes-Benz of Santa Rosa CUSTOMER SATISFACTION POLICY</b>          It is our intention to make service the number one priority at Mercedes-Benz of Santa Rosa. If there is any suggestion you can make to provide a better Service Department, please let us know. By law, you may choose another facility to perform any needed repairs or adjustments which the Smog Check test indicates are necessary.</p>								
<p><b>STATEMENT OF DISCLAIMER</b>          The factory warranty constitutes all of the warranties with respect to the sale of this item. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller, neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item.</p>								
<p><b>NOTICE TO CUSTOMERS</b>          WE MAKE A SEPARATE CHARGE FOR THE DISPOSAL OF TOXIC WASTES. CAL 000077863 RATHER THAN RECOVER THESE COSTS BY INCREASING OUR LABOR RATES TO ALL OF OUR SERVICE CUSTOMERS, WE MAKE THIS CHARGE ONLY ON THOSE PARTICULAR REPAIRS OR SERVICES WHICH GENERATE THESE WASTES. THESE ARE UNIFORM CHARGES WHICH ARE CALCULATED ANNUALLY FOR EACH PARTICULAR SERVICE AND ARE AVAILABLE UPON REQUEST.</p>								
<p>I acknowledge notice and oral approval of an increase in the original estimated price.</p> <p>Initials _____</p>								
<p>Original Estimate \$ _____          Please read the important information on the reverse side of invoice.          I acknowledge receipt of this invoice.          I acknowledge the warranty repairs performed.          I acknowledge notice and oral approval of additional Warranty repairs discovered and corrected during this repair visit.</p>								
<p>Signature X _____</p>								

**Mailing Address:**  
 2881 Corby Ave. Santa Rosa, CA 95407

**Customer Copy**



\* INVOICE \*

DUPLICATE 1  
Invoice #: 264912  
Tag #: T4073  
Customer #: 66846

5/ PL  
SANTA ROSA, CA 95403-8061  
HOME: BUS: 7C  
EMAIL: carey@daly-home.com | home

Mercedes-Benz of Santa Rosa  
2880 TALMADGE DR.  
SANTA ROSA, CA 95407  
(707) 542-4811



Mercedes-Benz  
BAR# ARD 223139  
EPA# CAL 000250231



COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN	MILEAGE OUT
PERIWINKLE	97	MERCEDES BENZ SL320R	WDBFA63F8VF	5ZLN888	53420	53555
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	INV. DATE	R.O. OPENED	READY
31 JUL 97	11 APR 97	30 JUL 2001	17:00 11 JAN 22	12 JAN 22	09:00 08 DEC 21	15:20 12 JAN 22

OPTIONS: DLR:05106 ENG:104991-12-027895 TRN:722605-00-337260 1RADIO CODE#12111 SERIAL#T09677410

LABOR:	0.00	PARTS:	14.00	OTHER:	0.00	TOTAL LINE G:	\$	14.00
H** .60 CUSTOMER STATES REPLACE LEFT SIDE MIRROR GLASS 00 CUSTOMER STATES 84 CABOT, BERNARD LIC#: 84								
LABOR: 123.00 PARTS: 386.00 OTHER: 0.00 TOTAL LINE H: \$ 509.00								
I** 1.0 PERFORM BRAKE SYSTEM FLUID FLUSH AND VERIFY PROPER OPERATION + CAUSE: PERFORMED BRAKE SYSTEM FLUID FLUSH WBF PERFORM BRAKE SYSTEM FLUID FLUSH AND VERIFY PROPER OPERATION + \$3.26 HAZ WASTE 84 CABOT, BERNARD LIC#: 84								
LABOR: 159.47 PARTS: 27.50 OTHER: 3.49 TOTAL LINE I: \$ 190.46								
J** 1.0 CUSTOMER STATES REPLACE SHIFT BUSHING 00 CUSTOMER STATES 84 CABOT, BERNARD LIC#: 84								
LABOR: 205.00 PARTS: 15.40 OTHER: 0.00 TOTAL LINE J: \$ 220.40								
K** .50 CUSTOMER STATES PERFORM TIRE ROTATION ROT CUSTOMER STATES PERFORM TIRE ROTATION 84 CABOT, BERNARD LIC#: 84								
LABOR: 29.95 PARTS: 0.00 OTHER: 0.00 TOTAL LINE K: \$ 29.95								

-----  
**JOAN DALY**  
 Smothers  
 European  
 Would Like To  
 Thank You  
 For Your  
 Continued  
 Patronage  
 ✂  
 Thank You!  
 -----

Original Estimate \$ \_\_\_\_\_  
 Please read the important information on the reverse side of invoice.  
 I acknowledge receipt of this invoice.  
 I acknowledge the warranty repairs performed.  
 I acknowledge notice and oral approval of additional Warranty repairs discovered and corrected during this repair visit.  
 Signature X \_\_\_\_\_

LABOR AMOUNT	PARTS AMOUNT	GAS, OIL, LUBE	SUBLET AMOUNT	MISC. CHARGES	TOTAL CHARGES	ADJUSTMENTS	SALES TAX	PLEASE PAY THIS AMOUNT
27.50	386.00	8.40	7.00	205.00	27.50	0.00	0.00	29.95
<b>TOTALS</b>								
Mercedes-Benz of Santa Rosa <b>CUSTOMER SATISFACTION POLICY</b> It is our intention to make service the number one priority at Mercedes-Benz of Santa Rosa. If there is any suggestion you can make to provide a better Service Department, please let us know. By law, you may choose another facility to perform any needed repairs or adjustments which the Smog Check test indicates are necessary.								
STATEMENT OF DISCLAIMER The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items. NOTICE TO CUSTOMERS WE MAKE A SEPARATE CHARGE FOR THE DISPOSAL OF TOXIC WASTES. RATHER THAN RECOVER THESE COSTS BY INCREASING OUR LABOR RATES TO ALL OF OUR SERVICE CUSTOMERS, WE MAKE THIS CHARGE ONLY ON THOSE PARTICULAR REPAIRS OR SERVICES WHICH GENERATE THESE WASTES. THESE ARE UNIFORM CHARGES WHICH ARE CALCULATED ANNUALLY FOR EACH PARTICULAR SERVICE AND ARE AVAILABLE UPON REQUEST.								
I acknowledge notice and oral approval of an increase in the original estimated price. _____ Initials _____								
Mailing Address: 2881 Corby Ave. Santa Rosa, CA 95407								

Customer Copy



**Mercedes-Benz of Santa Rosa**  
 2880 TALMADGE DR.  
 SANTA ROSA, CA 95407  
 (707) 542-4811

Invoice #: **264912**  
 Tag #: **T4073**  
 Customer #: **66846**

\*INVOICE\*  
 DUPLICATE 1  
**CAREY DALY**  
**JOAN DALY**  
 5620 DEMPSEY PL  
 SANTA ROSA, CA 95403-8061  
 HOME: 707-542-6609 BUS: 707-775-7021 CELL: 707-775-7020  
 EMAIL: carey@daly-home.com | home



Mercedes-Benz  
 BAR# ARD 223139  
 EPA# CAL 000250231  
 MILEAGE IN 53420  
 MILEAGE OUT 53555  
 R.O. OPENED READY

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	INV. DATE	INVENTORY	R.O. OPENED	MILEAGE IN	MILEAGE OUT
PERIWINKLE	97	MERCEDES BENZ SL320R	WDBFA63F8VF	5ZLN888	153299	PAYMENT		53420	53555
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE				
31JUL97	11APR97	30JUL2001	17:00 11JAN22		205.00	CASH	09:00 08DEC21	15:20 12JAN22	


OPTIONS: DLR:05106 ENG:104991-12-027895 TRN:722605-00-337260 1|RADIO CODE#12111 SERIAL#T09677410

53555 PERFORMED TIRE ROTATION, TORQUED WHEEL STUDS TO PROPER SPECIFICATION AND SET TIRES TO CORRECT AIR PRESSURE. LF TIRE 8 /32" RF TIRE 8 /32" LR TIRE 7 /32" RR TIRE 7 /32." SET PRESSURE TO 30 LBS FRONT 35 LBS REAR.


L\*\* REPLACE ANTENNA THAT BROKE IN THE WASH 00 CUSTOMER STATES 84 CABOT, BERNARD LIC#: 84 IM 1 140-827-00-01A ANTENNA MAST

LABOR: 0.00 PARTS: 0.00 OTHER: 0.00  
 --ADDITIONAL OPERATION PERFORM VEH. W/ TRIP COM PUTER

TOTAL LINE L: \$ 0.00  
 (N/C) (N/C) 0.00



NET TOTAL

-----  
**JOAN DALY**  
**Smothers**  
**European**  
**Would Like To**  
**Thank You**  
**For Your**  
**Continued**  
**Patronage**  


Mercedes-Benz

**Thank You!**

Customer Copy

DESCRIPTION	LABOR AMOUNT	PARTS AMOUNT	GAS, OIL, LUBE	SUBLET AMOUNT	MISC. CHARGES	TOTAL CHARGES	ADJUSTMENTS	SALES TAX	PLEASE PAY THIS AMOUNT
Mercedes-Benz of Santa Rosa CUSTOMER SATISFACTION POLICY									
It is our intention to make service the number one priority at Mercedes-Benz of Santa Rosa. If there is any suggestion you can make to provide a better Service Department, please let us know. By law, you may choose another facility to perform any needed repairs or adjustments which the Smog Check test indicates are necessary.									
STATEMENT OF DISCLAIMER									
The factory warranty constitutes all of the warranties with respect to the sale of this item. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.									
NOTICE TO CUSTOMERS									
WE MAKE A SEPARATE CHARGE FOR THE DISPOSAL OF TOXIC WASTES. CAL 000077883 RATHER THAN RECOVER THESE COSTS BY INCREASING OUR LABOR RATES TO ALL OF OUR SERVICE CUSTOMERS, WE MAKE THIS CHARGE ONLY ON THOSE PARTICULAR REPAIRS OR SERVICES WHICH GENERATE THESE WASTES. THESE ARE UNIFORM CHARGES WHICH ARE CALCULATED ANNUALLY FOR EACH PARTICULAR SERVICE AND ARE AVAILABLE UPON REQUEST.									
I acknowledge notice and oral approval of an increase in the original estimated price.									
Initials									
Original Estimate \$	1337.42	535.75	0.00	0.00	3.49	1876.66	0.00	49.56	1926.22
Please read the important information on the reverse side of invoice.									
I acknowledge receipt of this invoice.									
I acknowledge the warranty repairs performed.									
I acknowledge notice and oral approval of additional Warranty repairs discovered and corrected during this repair visit.									
Signature X									
Mailing Address:									
2881 Corby Ave. Santa Rosa, CA 95407									