

2008 Porsche 911 Carrera S Cabriolet

HISTORY OVERVIEW

DATE	MILES	EVENT	HAVE RECORD	RECORD	NOTES	LOCATION
20110215	22474	SERVICED	NO	CARFAX	INSPECT, BRAKE FLUID, SMOG, ETC	DEALER
20120224	25776	SERVICED	NO	CARFAX	CONV TOP, OIL	DEALER
20130409	27970	SERVICED	YES	CARFAX	BRAKE FLUID, OIL	DEALER
20140123	28745	SMOG	YES	CARFAX	SMOG	INDEPENDENT
20140213	28784	SERVICED	YES	CARFAX	BATTERY, OIL, INSPECTION	DEALER
20140422	29059	SERVICED	YES	CARFAX	COOLING SYSTEM	DEALER
20160115	29978	SMOG	YES		SMOG	INDEPENDENT
20160315	30084	SERVICED	YES	CARFAX	MAINT, OIL, INSPECT	DEALER

PAGES 1-4: CARFAX REPORT

PAGES 5-19 SERVICE RECORDS

For Personal Use Only



CARFAX® Vehicle History Report™

An independent company established in 1986



US \$39.99

<p>Vehicle Information: 2008 PORSCHE 911 CARRERA S CAB VIN: WP0CB29918S776111 CONVERTIBLE 3.8L H6 FI DOHC</p>	     	<p>No accident / damage reported to CARFAX</p> <p>2 Previous owners</p> <p>6 Service records available</p> <p>Types of owners: Personal lease, Personal</p> <p>Last owned in California</p> <p>30,084 Last reported odometer reading</p>
---	--	---



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 4/19/16 at 4:23:41 PM (EDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

 Ownership History	Owner 1	Owner 2
The number of owners is estimated		
Year purchased	2008	2011
Type of owner	Personal lease	Personal
Estimated length of ownership	2 yrs. 7 mo.	5 yrs. 1 mo.
Owned in the following states/provinces	Florida	California
Estimated miles driven per year	8,569/yr	1,486/yr
Last reported odometer reading	22,474	30,084

 Title History	Owner 1	Owner 2
CARFAX guarantees the information in this section		
Salvage Junk Rebuilt Fire Flood Hail Lemon	Guaranteed No Problem	Guaranteed No Problem
Not Actual Mileage Exceeds Mechanical Limits	Guaranteed No Problem	Guaranteed No Problem
 <p>GUARANTEED - None of these major title problems were reported by a state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, CARFAX will buy this vehicle back. Register View Terms View Certificate</p>		

 Additional History	Owner 1	Owner 2
Not all accidents / issues are reported to CARFAX		

Total Loss No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Structural Damage No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall Check with an authorized Porsche dealer for any open recalls.	<input checked="" type="checkbox"/> No Recalls Reported	<input checked="" type="checkbox"/> No Recalls Reported
Basic Warranty <u>Original warranty</u> estimated to have expired. Interested in an <u>extended warranty</u> ?	Warranty Expired	Warranty Expired

Tell us what you know about this vehicle

View other PORSCHE 911 CARRERA S CAB vehicles with FREE CARFAX Reports



2008 Porsche 911
\$63,900
22,206 miles



2009 Porsche 911
\$71,500
37,529 miles



2007 Porsche 911
\$38,950
43,853 miles




2008 Porsche 911
\$47,998
43,934 miles

[See more cars](#)




Detailed History

[Glossary](#)

<p>Owner 1 Purchased: 2008 Type: Personal lease Where: Florida Est. miles/year: 8,569/yr Est. length owned: 6/14/08 - 1/27/11 (2 yrs. 7 mo.)</p> <p>Low mileage! This owner drove less than the industry average of 15,000 miles per year.</p> 	Date:	Mileage:	Source:	Comments:
	06/14/2008	5	Florida Motor Vehicle Dept.	Vehicle purchase reported Titled or registered as personal lease vehicle
	06/25/2008		Florida Motor Vehicle Dept. Lisle, IL Title #0100939995	Title issued or updated First owner reported Titled or registered as personal lease vehicle Loan or lien reported Vehicle color noted as Black
	09/28/2008		Florida Motor Vehicle Dept. Tampa, FL Title #0100939995	Registration issued or renewed Titled or registered as personal lease vehicle Loan or lien reported Vehicle color noted as Black
	07/07/2009		Florida Motor Vehicle Dept. Tampa, FL	Registration issued or renewed Titled or registered as personal lease vehicle Loan or lien reported

Two states? Vehicle leasing companies often title a car in one state but register it to be driven in another.

		Title #0100939995	Vehicle color noted as Black
08/02/2010		Florida Motor Vehicle Dept. Tampa, FL Title #0100939995	Registration issued or renewed Loan or lien reported Vehicle color noted as Black
01/27/2011	22,474	Dealer Inventory Livermore, CA	Vehicle offered for sale
02/08/2011		Dealer Inventory	Vehicle sold
02/15/2011		Porsche of Livermore Livermore, CA 925-447-6400 livermore.porschedea ler.com	Pre-delivery inspection completed Brake fluid flushed/changed Tire condition and pressure checked Wheels checked Emissions inspection performed
02/15/2011		California Inspection Station	Passed emissions inspection
02/22/2011		Livermore Land Rover Jaguar Livermore, CA 925-373-7000 landroverlivermore.c om	Vehicle offered for sale

<p>Owner 2</p> <p>Purchased: 2011 Type: Personal Where: California Est. miles/year: 1,486/yr Est. length owned: 3/9/11 - present (5 yrs. 1 mo.)</p> <p>Low mileage! This owner drove less than the industry average of 15,000 miles per year.</p> 	Date:	Mileage:	Source:	Comments:	
	03/09/2011	22,617	California Motor Vehicle Dept. Sonoma, CA	Odometer reading reported	
	03/12/2011		Dealer Inventory	Vehicle sold	
	04/12/2011		California Motor Vehicle Dept. Sonoma, CA	Title issued or updated New owner reported	
	02/24/2012	25,776	Sonnen Porsche San Rafael, CA 415-380-8000 sonnenporsche.com	Battery/charging system checked Convertible top operation checked Oil and filter changed	
	04/09/2013	27,970	Sonnen Porsche San Rafael, CA 415-380-8000 sonnenporsche.com	Maintenance inspection completed Brake fluid flushed/changed Oil and filter changed	
	01/23/2014	28,745	California Inspection Station Sonoma, CA	Passed emissions inspection	
	02/13/2014	28,784	Sonnen Porsche San Rafael, CA 415-380-8000 sonnenporsche.com	Battery replaced Battery/charging system checked Oil and filter changed Tire pressure monitoring system checked	
	04/22/2014	29,059	Sonnen Porsche San Rafael, CA 415-380-8000 sonnenporsche.com	Cooling system checked	
	01/15/2016	29,978	California Inspection Station	Passed safety inspection Passed emissions inspection	
	03/15/2016	30,084	Sonnen Porsche San Rafael, CA 415-380-8000 sonnenporsche.com	Maintenance inspection completed Oil and filter changed Radio/sound system checked	
	Print this CARFAX Report and take it to your pre-purchase inspection				

Tell us what you know about this vehicle

Have Questions? Please visit our Help Center at www.carfax.com.



Glossary

[View Full Glossary](#)

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

New Owner Reported

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:  [facebook.com/CARFAX](https://www.facebook.com/CARFAX)  [@CarfaxReports](https://twitter.com/CarfaxReports)  [CARFAX on Google+](#)

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. CARFAX®

© 2016 CARFAX, Inc., a unit of IHS Inc. All rights reserved.

Covered by United States Patent Nos. 7,113,853; 7,778,841; 7,596,512, 8,600,823; 8,595,079; 8,606,648; 7,505,838.

4/19/16 4:23:41 PM (EDT)

Steve's Smog & Auto Repair

18968 Sonoma Hwy
 Sonoma, CA 95476
 Phone (707) 996-7664 Fax (707) 996-1568

Date 1/15/2016
 Invoice # 25573
 PO #
 Bar # AB232242
 EPA # Cal000334165
 S/W

Customer Information:

Company
 Customer
 Address
 301 Fowler Creek Rd
 SONOMA, CA 95476

Home
 Cell
 Work
 Ext

Vehicle Information:

Vehicle 2008 Porsche 911
 VIN #
 License 6RTM345 Tag #
 Engine Mileage 29978
 Trans

Vehicle Problem:

Recommendations:

Parts Detail:

Labor Detail:

Type ID	Labor Description	Emp ID	Time	Labor Rate	Labor Costs
SMGCHK	Smog Check		1.00	46.75	\$46.75

Sublet Detail:

Sublet Description	Total
Cer	\$8.25

Parts installed are not warranted beyond warranties given by the respective manufacture's. No other warranties are made except as listed on this invoice.

Parts and Labor are warranted for 6000 miles or 6 months, whichever comes first. This warranty is limited to the work mentioned on this form only and is not transferable. Vehicle must be returned to our workshop, at customers expenses, to honor warranty, warranty is void in case of misuse and/or neglect.

A Storage Fee of \$20.00 a day will be charged on all vehicles left over 48 hours after completion.

The Parts and Accessories sold and installed by this Repair Shop and the Service connected with the installation and adjustments of the Parts and Accessories sold and installed by this Repair Shop, are Guaranteed to be free from defects in material and workmanship under normal service and use until such Parts and Accessories have been driven, used, or operated for a distance of 4000 miles or a period of 90 days, from date of Service, whichever first occurs, unless otherwise stated under the Part or service listed above.

Parts Total	\$0.00
Labor Total	\$46.75
Hazard Waste	\$0.00
Sublet	\$8.25
Subtotal	\$55.00
Sales Tax	\$0.00
Sales Tax 2	\$0.00
Work Order Total	\$55.00
Total Payments	\$55.00
Payment Method	Discover
Amount Due	\$0.00

Signature- _____

Smog Check Vehicle Inspection Report (VIR)

Vehicle Information

Test Date/Time: 01/15/2016 @ 2:08 PM

Model Year: 2008	Vehicle Make: PORSCHE	Vehicle Model: 911 CARRERA S CAB
VIN (scanned from vehicle):	WP0CB29918S776111	
VIN (manually entered or from DMV document):	WP0CB29918S776111	
License Plate: 6RTM534	License State: CA	Inspection Reason: Biennial
Fuel Type: Gasoline	Certification Type: California	Odometer: 29978

Overall Test Result

PASS

Congratulations! Your vehicle passed the Smog Check inspection, which helps California reach its daily goal of removing smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Visual Inspection: PASS Functional Inspection: PASS

Smog Check Certificate Number: YV685347C

DMV ID Number: 1340V910Y581

Your Smog Check certificate has been electronically transmitted to DMV.

Your certificate is valid for 90 days from date of issuance.

Please keep this copy for your records.

Visual Inspection Result Information

<u>Result</u>	<u>Inspection Category</u>	<u>Result</u>	<u>Inspection Category</u>
PASS	Air Injection System	PASS	Catalyst
PASS	Computers, Sensors, Switches, and Wiring	PASS	Crankcase Emission Controls
NOTAPPLICABLE	Exhaust Gas Recirculation (EGR)	PASS	Fuel Evaporative System (EVAP)
PASS	Fuel Metering System	PASS	Other Emission Related Components/Systems
NOTAPPLICABLE	Turbocharger/Supercharger	PASS	Vacuum Lines to Sensors/Switches

Emission Control Systems Functional Check Results

<u>Result</u>		<u>Result</u>	
PASS	Liquid Fuel Leak Check	PASS	OBDII
PASS	Smoke Check		

Smog Check Inspection Station Information

Station ID: RC232242
STEVES SMOG & AUTO REPAIR
18968 SONOMA HWY
SONOMA, CA 95476
(707) 938-8848

Inspector Name/ID:
Software Version/OIS ID:

BALL, CLAYTON/EO138467
6.4.919.0/CV006948

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

1-15-16

Date



Inspector's Signature

SONNEN PORSCHE

INVOICE

900 REDWOOD HIGHWAY • MILL VALLEY, CA 94941

Ph: (415) 380-8000

PORSCHE

415-380-8000

BAR # AA 219898

CPA # CA10002863218

CUSTOMER NO. 104071	ADVISOR RUSSELL FONG	TAG NO. 1346 9544	INVOICE DATE 04/22/14	INVOICE NO. POCS357425
DONALD WISER 1301 FOWLER CREEK RD SONOMA, CA 95476 [REDACTED] [REDACTED] [REDACTED]	LICENSE NO. 6RTM534	MILEAGE 29,059	COLOR BLACK/	STOCK NO.
	YEAR / MAKE / MODEL 08/PORSCHE/911 CARRERA/2DR CABRIOLET	DELIVERY DATE 06/14/08	DELIVERY MILES	
	VEHICLE I.D. NO. W P O C B 2 9 9 1 8 S 7 7 6 1 1 1	SELLING DEALER NO.	PRODUCTION DATE	
	F.T.E. NO.	P.O. NO.	R.O. DATE 04/22/14	
RESIDENCE PHONE	BUSINESS PHONE	COMMENTS	MO: 29060	

JOB# 1 CHARGES-----

LABOR-----
 J# 1 19POZZ02 COOLING SYSTEM LEAKS TECH(S):1417 2015 WARRANTY

CUSTOMER STATES COOLANT LEAKING FROM ENGINE AREA.
 INSPECT AND REPORT:
 CONFIRMED CUSTOMER COMPLAINT OF COOLANT LEAKING FROM VEHICLE. PRESSURE TESTED COOLING SYSTEM. FOUND THAT COOLANT PUMP HAS FAILED AND IS LEAKING. REPLACEMENT IS NEEDED.
 REMOVED AND REPLACED COOLANT PUMP. VACUUM BLED COOLING SYSTEM. PRESSURE TESTED COOLING SYSTEM AGAIN, NO FURTHER LEAKS FOUND. ROAD TESTED VEHICLE AND RECORRECTED COOLANT LEVEL. OK

PARTS-----	QTY----	FP-NUMBER-----	DESCRIPTION-----	UNIT PRICE-	
	1	997-106-011-05	AS WATER PUMP		WARRANTY
	1	996-106-340-54	GASKET, WATER P		WARRANTY
	2	000-043-301-49	ANTIFREEZE 3.79		WARRANTY
				TOTAL - PARTS	0.00

JOB# 1 TOTALS-----
 JOB# 1 JOURNAL PREFIX POCS JOB# 1 TOTAL 0.00

JOB# 2 CHARGES-----

LABOR-----
 J# 2 99POZZTOW VEHICLE TOWED IN TECH(S):98 INTERNAL

VEHICLE WAS TOWED IN - INSPECT
 INSPECT VEHICLE

JOB# 2 TOTALS-----
 JOB# 2 JOURNAL PREFIX POCS JOB# 2 TOTAL 0.00

THANK YOU

SONNEN PORSCHE

INVOICE

900 REDWOOD HIGHWAY • MILL VALLEY, CA 94941

Ph: (415) 380-8000

PORSCHE

415-380-8000

BAR # AA 219898
 EPA # CA10072864218

CUSTOMER NO. 104071	ADVISOR RUSSELL FONG	TAG NO. 1346 9544	INVOICE DATE 04/22/14	INVOICE NO. POCS357425
RONALD WISER 301 FOWLER CREEK ROAD SONOMA, CA 95476	LICENSE NO. 6RTM534	MILEAGE 29,059	COLOR BLACK/	STOCK NO.
RONALD WISER 301 FOWLER CREEK ROAD SONOMA, CA 95476	YEAR / MAKE / MODEL 08/PORSCHE/911 CARRERA/2DR CABRIOLET	VEHICLE I.D. NO. WP0CB29918S776111	DELIVERY DATE 06/14/08	DELIVERY MILES
RESIDENCE PHONE 707-938-4218	BUSINESS PHONE	COMMENTS	SELLING DEALER NO.	PRODUCTION DATE
			R.O. DATE 04/22/14	

MO: 29060

TOTALS-----

*****	TOTAL LABOR....	0.00
* [] CASH [] CHECK CK NO. [] *	TOTAL PARTS....	0.00
* [] VISA [] MASTERCARD *	TOTAL SUBLET....	0.00
* [] OTHER [] CHARGE *	TOTAL G.O.G....	0.00
*****	TOTAL MISC CHG.	0.00
	TOTAL MISC DISC	0.00
	TOTAL TAX.....	0.00
	TOTAL INVOICE \$	0.00

CUSTOMER SIGNATURE

THANK YOU

SONNEN PORSCHE

INVOICE

900 REDWOOD HIGHWAY • MILL VALLEY, CA 94941

Ph: (415) 380-8000

PORSCHE

415-380-8000

BAR # AA 219898
 CFA # CA10002064218

CUSTOMER NO. 104071	ADVISOR RUSSELL FONG	TAG NO. 1346 2012	INVOICE DATE 03/15/16	INVOICE NO. POCS406392
[REDACTED]	LICENSE NO. 6RTM534	MILEAGE 30,084	COLOR BLACK/	STOCK NO.
[REDACTED]	YEAR / MAKE / MODEL 08/PORSCHE/911 CARRERA/2DR CABRIOLET	DELIVERY DATE 06/14/08	DELIVERY MILES	PRODUCTION DATE
[REDACTED]	VEHICLE ID. NO. WP0CB299185776111	SELLING DEALER NO.	R.O. DATE 03/15/16	
[REDACTED]	BUSINESS PHONE	COMMENTS		

MO: 100002

JOB# 1 CHARGES-----

LABOR-----
 # 1 03POZ OIL CHNG / GEN MAINT TECH(S):1445 161.50

OIL AND FILTER CHANGE, CHECK AND SET TIRE PRESSURE, TOP OFF
 FLUID LEVELS
 --- RESET SERVICE LIGHT ---
 COMPLETED OIL CHANGE SERVICE

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	PRICE
	1	996-107-225-53	OIL-FILTER INSER	32.29	32.29
	1	900-123-106-30	ALUM SEAL RING	1.52	1.52
	9	040	MOBILE1 0W40	6.99	62.91
TOTAL - PARTS					96.72

MISC	CODE	DESCRIPTION	CONTROL NO	PRICE
	P-WOF	PORSCHE HAZ WASTE/OIL & FILTER		4.50
	P-DP	DISCOUNT PARTS		-9.22
TOTAL - MISC				-4.72

JOB# 1 TOTALS-----
 LABOR 161.50
 PARTS 96.72
 MISC -4.72

JOB# 2 CHARGES----- JOB# 1 JOURNAL PREFIX POCS JOB# 1 TOTAL 253.50

LABOR-----
 # 2 03POZ002 MULTI-POINT INSPECT TECH(S):1445 0.00

PERFORM COURTESY INSPECTION AS REQUESTED. CHECK BRAKES, TIRES,
 AND ALL EXTERIOR LIGHTS. CHECK OIL, BRAKE, COOLANT, AND WASHER
 FLUID LEVELS. PLEASE NOTE RESULTS BELOW
 PERFORMED INSPECTIONS AS PER ATTACHED CHECKLIST
 PERFORMED INSPECTION. FRONT AND REAR BRAKES 60%. ALL TIRES
 ARE OK. TOPPED OFF ALL FLUID. RETORQUED ALL WHEEL BOLTS TO
 SPECIFICATION. ERASED ALL FAULT MEMORY./

JOB# 2 TOTALS-----

JOB# 3 CHARGES----- JOB# 2 JOURNAL PREFIX POCS JOB# 2 TOTAL 0.00

LABOR-----
 # 3 91POZ ENTERTAINMENT SYSTEM TECH(S):1445 0.00

CUSTOMER REQUESTS RADIO KNOBS REPLACED
 SPECIAL ORDERED TWO RADIO KNOBS.

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	PRICE
	0	997-645-913-00	ROTARY KNOB	33.42	0.00
PART ON SPECIAL ORDER					
** QUANTITY 2 IS SPECIAL ORDERED **					
TOTAL - PARTS					0.00

THANK YOU

SONNEN PORSCHE

INVOICE

900 REDWOOD HIGHWAY • MILL VALLEY, CA 94941

Ph: (415) 380-8000

PORSCHE

415-380-8000

BAR # AA 219898

CPA # CA10002064218

CUSTOMER NO. 104071	ADVISOR RUSSELL FONG	TAG NO. 1346	INVOICE DATE 03/15/16	INVOICE NO. POCS406392
RONALD WISER 1301 FOWLER CREEK ROAD SONOMA, CA 95476	LICENSE NO. 6RTM534	YEAR / MAKE / MODEL 2012	COLOUR BLACK/	STOCK NO.
RONALD WISER@aol.com	VEHICLE I.D. NO. 08/PORSCHE/911 CARRERA/2DR CABRIOLET	DELIVERY DATE 30,084	DELIVERY DATE 06/14/08	DELIVERY MILES
415-706-4318	F.P.E. NO. W P O C B 2 9 9 1 8 5 7 7 6 1 1 1	SELLING DEALER NO.	R.O. DATE 03/15/16	PRODUCTION DATE
BUSINESS PHONE	COMMENTS	MO: 100002		

JOB# 3 TOTALS-----

JOB# 3 JOURNAL PREFIX POCS JOB# 3 TOTAL 0.00

ESTIMATE-----
CUSTOMER HEREBY ACKNOWLEDGES RECEIVING
ORIGINAL ESTIMATE OF \$255.00 (+TAX)

TOTALS-----	TOTAL LABOR....	161.50
*****	TOTAL PARTS....	96.72
* [] CASH [] CHECK CK NO. [] *	TOTAL SUBLET...	0.00
* [] VISA [] MASTERCARD	TOTAL G.O.G....	0.00
* [] OTHER [] CHARGE	TOTAL MISC CHG.	4.50
*****	TOTAL MISC DISC	-9.22
	TOTAL TAX.....	8.22
	TOTAL INVOICE \$	261.72

CUSTOMER SIGNATURE

THANK YOU

SONNEN PORSCHE

INVOICE


740 FRANCISCO BLVD. WEST • SAN RAFAEL, CA 94901

Ph: (415) 380-8000

PORSCHE

415-380-8000

BAR # AA 219898
~~CPA # CA10072064218~~

CUSTOMER NO. 104071	ADVISOR RUSSELL FONG	TAG NO. 1346 9651	INVOICE DATE 02/13/14	INVOICE NO. POCS353162
	LICENSE NO. 6RTM534	MILEAGE 28,784	COLOR BLACK/	STOCK NO.
	YEAR / MAKE / MODEL 08/PORSCHE/911 CARRERA/2DR CABRIOLET	DELIVERY DATE 06/14/08	DELIVERY MILES	PRODUCTION DATE
	VEHICLE I.D. NO. WP0CB29918S776111	SELLING DEALER NO.		
RESIDENCE PHONE	BUSINESS PHONE	COMMENTS	R.O. DATE 02/12/14	

MO: 28784

JOB# 1 CHARGES-----

LABOR-----
 J# 1 27POZ CHARGING SYSTEM TECH(S):1417 WARRANTY
 CUSTOMER STATES ENGINE CRANKS OVER SLOW WHEN ENGINE IS WARMED UP. INSPECT AND REPORT: VOLTAGE DROP OF 1.5VOLTS, ALTERNATOR PUSHING OUT 14VOLTS, AT BATTERY WAS 12.5 VOLTS. REMOVED INTAKE MANIFOLD, REMOVED AIR BOX, REMOVED REAR RIGHT WHEEL, REPLACED CHARGING HARNESS, RETESTED OKAY. NO LABOR OP.

PARTS-----	QTY----	FP-NUMBER-----	DESCRIPTION-----	UNIT PRICE-	
	1	997-607-019-03	AS CABLE LOOM		
				TOTAL - PARTS	0.00

JOB# 1 TOTALS-----
 JOB# 1 JOURNAL PREFIX POCS JOB# 1 TOTAL 0.00

JOB# 2 CHARGES-----

LABOR-----
 J# 2 27POZZ02 REPLACE BATTERY TECH(S):1417 90.00
 CUSTOMER STATES BATTERY WEAK AND HAD TO JUMP START. INSPECT AND REPORT: FOUND BATTERY FAILING LOAD TEST. REPLACED BATTERY TO CORRECT.

PARTS-----	QTY----	FP-NUMBER-----	DESCRIPTION-----	UNIT PRICE-	
	1	MTP-94R	BATTERY	225.00	225.00
				TOTAL - PARTS	225.00

JOB# 2 TOTALS-----
 LABOR 90.00
 PARTS 225.00

JOB# 2 JOURNAL PREFIX POCS JOB# 2 TOTAL 315.00

JOB# 3 CHARGES-----

LABOR-----
 J# 3 04POZ2 TPM LIGHT TECH(S):1417 WARRANTY
 CUSTOMER STATES TPC INACTIVE WARNING MESSAGE ON. INSPECT AND REPORT: LOW TPM SENSOR BATTERY LIFE. RECOMMEND ALL NEW TPM SENSORS. REPLACED ALL TPM SENSORS.

PARTS-----	QTY----	FP-NUMBER-----	DESCRIPTION-----	UNIT PRICE-	
	4	997-606-021-01	TIRE INFLATATION		
				TOTAL - PARTS	0.00

JOB# 3 TOTALS-----
 JOB# 3 JOURNAL PREFIX POCS JOB# 3 TOTAL 0.00

JOB# 4 CHARGES-----

LABOR-----

THANK YOU

SONNEN PORSCHE

INVOICE

740 FRANCISCO BLVD. WEST • SAN RAFAEL, CA 94901

Ph: (415) 380-8000

PORSCHE

415-380-8000

BAR # AA 219898

CPAL# CA10073064218

CUSTOMER NO. 104071	ADVISOR RUSSELL FONG	TAG NO. 9651	INVOICE DATE 02/13/14	INVOICE NO. POCS353162
RONALD WISER 1301 FOWLER CREEK ROAD SONOMA, CA 95476	LICENSE NO. 6RTM534	MILEAGE 28,784	COLOR BLACK/	STOCK NO.
	YEAR / MAKE / MODEL 08 / PORSCHE / 911 CARRERA / 2DR CABRIOLET	DELIVERY DATE 06/14/08	DELIVERY MILES	PRODUCTION DATE
	VEHICLE I.D. NO. W P O C B 2 9 9 1 8 S 7 7 6 1 1 1	SELLING DEALER NO.	R.O. DATE 02/12/14	
F.T.E. NO.	P.O. NO.			
RESIDENCE PHONE 415-796-4218	BUSINESS PHONE	COMMENTS	MO: 28784	

LABOR-----
 # 4 03POZ OIL CHNG / GEN MAINT TECH(S):1417 155.00
 OIL AND FILTER CHANGE, CHECK AND SET TIRE PRESSURE, TOP OFF
 FLUID LEVELS
 --- RESET SERVICE LIGHT ---
 PERFORMED LOF, RESET SERVICE LIGHT.

PARTS-----	QTY----	FP-NUMBER-----	DESCRIPTION-----	UNIT PRICE-	
	1	996-107-225-53	OIL-FILTER INSER	39.57	39.57
	1	900-123-106-30	ALUM SEAL RING	1.46	1.46
	10	040	MOBILE1 OW40	6.99	69.90
	1	CRC	PART WASH	4.95	4.95
TOTAL - PARTS					115.88

MISC-----	CODE-----	DESCRIPTION-----	CONTROL NO-----	
	P-WOF	PORSCHE HAZ WASTE/OIL & FILTER		4.50
	P-DP	DISCOUNT PARTS		-21.88
TOTAL - MISC				-17.38

JOB# 4 TOTALS-----
 LABOR 155.00
 PARTS 115.88
 MISC -17.38
 JOB# 4 JOURNAL PREFIX POCS JOB# 4 TOTAL 253.50

JOB# 5 CHARGES-----
 LABOR-----
 # 5 99POZZRENTAL INTERNAL RENTAL TECH(S):98 INTERNAL
 CUSTOMER PROVIDED GOOD WILL RENTAL VEHICLE BY SONNEN
 PORSCHE.

SUBLET-----	PO#-----	VEND INV#-----	INV.DATE-----	DESCRIPTION-----	
	60728		02/13/14	CAR RENTAL	INTERNAL
TOTAL - SUBLET					0.00

JOB# 5 TOTALS-----
 JOB# 5 JOURNAL PREFIX POCS JOB# 5 TOTAL 0.00

ESTIMATE-----
 CUSTOMER HEREBY ACKNOWLEDGES RECEIVING
 ORIGINAL ESTIMATE OF \$255.00 (+TAX)
 APPROVED REVISED ESTIMATE (# 1) OF \$590.00 (+TAX) ON 02/13/14 AT 01:12pm
 BY RONALD WISER COMMENTS

THANK YOU

SONNEN PORSCHE

INVOICE

740 FRANCISCO BLVD. WEST • SAN RAFAEL, CA 94901

Ph: (415) 380-8000

PORSCHE

415-380-8000

BAR # AA 219898

CPA # CA10072864218

CUSTOMER NO. 104071	ADVISOR RUSSELL FONG	TAG NO. 1346 9651	INVOICE DATE 02/13/14	INVOICE NO. POCS353162
DONALD WISER 1301 FOLLER CREEK ROAD SONOMA, CA 95476	LICENSE NO. 6RTM534	MILEAGE 28,784	COLOR BLACK/	STOCK NO.
	YEAR / MAKE / MODEL 08/PORSCHE/911 CARRERA/2DR CABRIOLET		DELIVERY DATE 06/14/08	DELIVERY MILES
	VEHICLE I.D. NO. WP0CB29918S776111		SELLING DEALER NO.	PRODUCTION DATE
	F.T.E. NO.	P.O. NO.	R.O. DATE 02/12/14	
RESIDENCE PHONE 440-796-4218	BUSINESS PHONE	COMMENTS	MO: 28784	

TOTALS-----

*****	TOTAL LABOR....	245.00
* [] CASH [] CHECK CK NO. [] *	TOTAL PARTS....	340.88
* [] VISA [] MASTERCARD	TOTAL SUBLET...	0.00
* [] OTHER [] CHARGE	TOTAL G.O.G....	0.00
*****	TOTAL MISC CHG.	4.50
	TOTAL MISC DISC	-21.88
	TOTAL TAX.....	28.97
	TOTAL INVOICE \$	597.47

CUSTOMER SIGNATURE _____

THANK YOU

Steve's Smog & Auto Repair

18968 Sonoma Hwy
 Sonoma, CA 95476
 Phone (707) 996-7664 Fax (707) 996-1568

Date 1/23/2014
 Invoice # 18646
 PO #
 Bar # AB232242
 EPA # Cal000334165
 S/W

Customer Information:		Vehicle Information:	
Company	Home	Vehicle	2008 Porsche 911
Customer	Cell	VIN #	
Address	Work	License	6RTM345 Tag #
	Ext	Engine	Mileage 28745
		Trans	

Vehicle Problem:	Recommendations:

Parts Detail:

Labor Detail:

Type ID	Labor Description	Emp ID	Time	Labor Rate	Labor Costs
SMGCHK	Smog Check		1.00	46.75	\$46.75

Sublet Detail:

Sublet Description	Total
cert	\$8.25

Parts installed are not warranted beyond warranties given by the respective manufacture's. No other warranties are made except as listed on this invoice.

Parts and Labor are warranted for 6000 miles or 6 months, whichever comes first. This warranty is limited to the work mentioned on this form only and is not transferable. Vehicle must be returned to our workshop, at customers expenses, to honor warranty, warranty is void in case of misuse and/or neglect.

A Storage Fee of \$20.00 a day will be charged on all vehicles left over 48 hours after completion.

The Parts and Accessories sold and installed by this Repair Shop and the Service connected with the installation and adjustments of the Parts and Accessories sold and installed by this Repair Shop, are Guaranteed to be free from defects in material and workmanship under normal service and use until such Parts and Accessories have been driven, used, or operated for a distance of 4000 miles or a period of 90 days, from date of Service, whichever first occurs, unless otherwise stated under the Part or service listed above.

Parts Total	\$0.00
Labor Total	\$46.75
Hazard Waste	\$0.00
Sublet	\$8.25
Subtotal	\$55.00
Sales Tax	\$0.00
Sales Tax 2	\$0.00
Work Order Total	\$55.00
Total Payments	\$55.00
Payment Method	Master Card
Amount Due	\$0.00

Signature- _____

Smog Check Vehicle Inspection Report (VIR)

Vehicle Information

Test Date/Time: 01/23/2014 @ 01:31 PM	Make: PORSC	Model: 911
Model-Year: 2008	State: CA	VIN: WP0CB29918S776111
License: 6RTM534	Type: PASSENGER CAR	Transmission: MANUAL
Engine Size: 3.8L	Test Sequence: 1	Cylinders: 6
GVWR:	Certification: CALIFORNIA	VLT Record #: 02272
Odometer: 028745	Exhaust: Single	Inspection Reason: Biennial Inspection
Fuel-Type: GASOLINE		

Overall Test Results - PASS

Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Comprehensive Visual Inspection: PASS Functional Check: PASS Emissions Test: PASS

Smog Check Certificate Number: PC706805
DMV ID Number: 1918C318P191

Your Smog Check certificate will be electronically transmitted to DMV.
Your certificate is valid for 90 days from date of issuance.

DO NOT MAIL

Please keep this copy for your records.

Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of oxides of nitrogen, crankcase and cold start emissions which are not measured during the idle tests.)

<u>RESULT</u>	<u>ECS</u>	<u>RESULT</u>	<u>ECS</u>	<u>RESULT</u>	<u>ECS</u>
PASS	PCV	NOT APPL	Thermostatic Air Cleaner	PASS	Fuel Evaporative Controls
PASS	Catalytic Converter	PASS	Air Injection	PASS	Oxygen Sensor
NOT APPL	Exhaust Gas Recirculation	PASS	Spark Controls	PASS	Carb./Fuel Injection
PASS	Wiring to Sensors	PASS	Vacuum Lines to Sensors/Switches	PASS	Other Emission Related Components
PASS	Fuel Cap Visual Test	NOT APPL	Ignition Timing:	PASS	System Malfunction Light
NOT APPL	Fuel Cap Functional Test	NOT APPL	EGR Functional Test	PASS	Liquid Fuel Leaks
NOT APPL	Fuel EVAP Test				

Idle Emission Test Results

Test	RPM	%CO2		HC (PPM)			CO (%)			Results
		MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	
Idle	769	12.16	4.1	100	17	0	1.00	0.00	0.00	PASS
2500 RPM	2551	15.10	0.3	130	12	0	1.00	0.10	0.00	PASS

MAX=Maximum Allowable Emissions

AVE=Average Emissions For Passing Vehicles

MEAS=Amount measured

Smog Check Inspection Station Information

STEVE'S SMOG & AUTO REPAIR
18968 SONOMA HWY.
SONOMA, CA 95476-0000
(707) 996-7664

Station Number: RC232242

Technician Name/Number: SQUIRES, BRADLEY /EA075141
Repair Tech Name/Number: N/A
Software Version/EIS Number: 1101/SO260319

I certify, under penalty of perjury under the laws of the State of California, that I inspected the vehicle described above, that I performed the inspection in accordance with all current requirements, and that the information listed on this vehicle inspection report is true and correct.

Date

Technician's Signature

SONNEN PORSCHE

900 REDWOOD HIGHWAY • MILL VALLEY, CA 94941

Ph: (415) 380-8000

WORK ORDER



PORSCHE

BAR# ARD219898
EPA# CAL00023433

RECOMMENDED SERVICES

OPERATION	OPERATION DESCRIPTION	MO/MI	TOTAL	OPERATION	OPERATION DESCRIPTION	MO/MI	TOTAL

SERVICE HISTORY

DATE	REPAIR ORDER	MILEAGE	ADVISOR	TECHNICIAN	TYPE	OPERATION	OPERATION DESCRIPTION
02/24/12	314870	25774	1346	1284 1284 1284 98	C W W W	03POZ 61POZZ 27POZ 99POZZLOANER	OIL CHNG / GEN MAINT CONVERTIBLE TOP CHARGING SYSTEM PORSCHE LOANER

SALESPERSON NO.

S E R V I C E

STATE REG# AG133681

VEHICLE ID NO. WP0CB29918S776111	YEAR/MAKE/MODEL 08/PORSCHE/911 CARRERA/2DR CABRIOLE	PRODUCTION DATE	STOCK NO.	LICENSE NO. 6RTM534	R.O. NO. 335739
CUSTOMER NO. 104071		SERVICE CONTRACT	DELIVERY DATE	DELIVERY MILES	SELLING DEALER NO.
SONOMA, CA 95476		COLOR BLACK/	CONTRACT NO.	EXPIRATION DATE	EXPIRATION MILES
TURBO N	M/MC POZZ	AIR COND. Y	P. S. Y	TRANS. M	MILEAGE 27,970
RESIDENTIAL	BUSINESS PHONE	ADVISOR NO. 942	ADVISOR GARY WRIGHT	TAG NO. 1315	R.O. DATE 04/09/13
TIME RECEIVED 08:54am	DATE/TIME PROMISED 04/09/13 06:00pm	PRIORITY 5	REPAIR AUTHORIZATION & VEHICLE DEPOSITARY RECEIPT (AB 409 amending civil code) I hereby authorize the repair work to be done along with the necessary materials. You and your employees may operate vehicle for purpose of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on vehicle to secure the amount of repairs thereto. In the event legal action is necessary to enforce this contract, I will pay reasonable attorney's fees and court costs. I acknowledge this deposited property is not insured or protected to the amount of actual cash value thereof by the dealer against loss occasioned by theft, fire and vandalism while such property remains with the depository. I also acknowledge no articles of personal property remains with the depository. I also acknowledge no articles of personal property have been left in vehicle and the dealer is not responsible for the inspection therefor.		
APPOINTMENT <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	MILEAGE OUT	<input checked="" type="checkbox"/> SAVE PARTS			

ORIGINAL CUSTOMER ESTIMATE: TOTAL 490.00	ORIGINAL ESTIMATE X	HAZARDOUS WASTE REMOVAL EST. \$
X	TEARDOWN ESTIMATE	
I understand that my vehicle will be reassembled within ___ days of the date shown above if I choose not to authorize the services recommended.		
1ST REV. EST.	ADD. COST	AUTHORIZED BY:
DATE	TIME	PHONE
CONTACTED BY: <input type="checkbox"/> IN PERSON <input type="checkbox"/> BY FAX <input type="checkbox"/> BY PHONE <input type="checkbox"/> BY EMAIL		
REVISION DETAILS:		
1ST REV. EST.	ADD. COST	AUTHORIZED BY:
DATE	TIME	PHONE
CONTACTED BY: <input type="checkbox"/> IN PERSON <input type="checkbox"/> BY FAX <input type="checkbox"/> BY PHONE <input type="checkbox"/> BY EMAIL		
"I acknowledge notice and oral approval of an increase in the original estimate"		
X		
CUSTOMER SIGNATURE		
I hereby designate the individual named below to authorize any additional work not specified or parts not included in the original written estimated price for parts and labor		
Name of Designee:	Phone Number:	
E-Mail Address:	Fax Number:	
Customer's Signature	Date	
X		
BY LAW, YOU MAY CHOOSE ANOTHER FACILITY TO PERFORM ANY NEEDED REPAIRS OR ADJUSTMENTS WHICH THE SMOG CHECK TEST INDICATES ARE NECESSARY		
ALL PARTS REMOVED WILL BE DISCARDED UNLESS OTHERWISE REQUESTED PRIOR TO BEGINNING WORK.		
ALL PARTS ARE NEW OR FACTORY REMANUFACTURED UNLESS OTHERWISE SPECIFIED.		

SONNEN PORSCHE

INVOICE


900 REDWOOD HIGHWAY • MILL VALLEY, CA 94941

Ph: (415) 380-8000

PORSCHE

415-380-8000

BAR # AA 219898
 EPA # CA10078864218

CUSTOMER NO. 104071	ADVISOR GARY WRIGHT	TAG NO. 942 1315	INVOICE DATE 04/09/13	INVOICE NO. POCS335739
 <p>RONALD WISER 1301 FOWLER CREEK ROAD SONOMA, CA 95476</p>	LICENSE NO. 6RTM534	MILEAGE 27,970	COLOR BLACK/	STOCK NO.
	YEAR / MAKE / MODEL 08 / PORSCHE / 911 CARRERA / 2DR CABRIOLET	DELIVERY DATE	DELIVERY MILES	PRODUCTION DATE
	VEHICLE I.D. NO. WP0CB29918S776111	SELLING DEALER NO.	PRODUCTION DATE	
	F.T.E. NO.	P.O. NO.	R.O. DATE 04/09/13	
RESIDENCE PHONE	BUSINESS PHONE	COMMENTS	MO: 27971	

JOB# 1 CHARGES

LABOR
 J# 1 03POZ OIL CHNG / GEN MAINT TECH(S):103247 155.00
 OIL AND FILTER CHANGE, CHECK AND SET TIRE PRESSURE, TOP OFF
 FLUID LEVELS
 RESET SERVICE LIGHT.
 COMPLETED OIL CHANGE SERVICE

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	PRICE
	1	996-107-225-53	OIL-FILTER INSER	29.75	29.75
	1	900-123-106-30	ALUM SEAL RING	1.42	1.42
	9	040	MOBILE1 0W40	6.99	62.91
TOTAL - PARTS					94.08

JOB# 1 TOTALS
 LABOR 155.00
 PARTS 94.08
 JOB# 1 JOURNAL PREFIX POCs JOB# 1 TOTAL 249.08

JOB# 2 CHARGES

LABOR
 J# 2 03POZ002 MULTI-POINT INSPECT TECH(S):103247 INTERNAL
 PERFORM COURTESY INSPECTION AS REQUESTED.CHECK BRAKES,TIRES,
 AND ALL EXTERIOR LIGHTS.CHECK OIL,BRAKE,COOLANT,AND WASHER
 FLUID LEVELS.PLEASE NOTE RESULTS BELOW
 PERFORMED INSPECTIONS AS PER ATTACHED CHECKLIST
 FRONT AND REAR BRAKES 80% REMAIN APPROX.
 FRONT AND REAR TIRE TREAD 6.0MM REMAIN.

JOB# 2 TOTALS
 JOB# 2 JOURNAL PREFIX POCs JOB# 2 TOTAL 0.00

JOB# 3 CHARGES

LABOR
 J# 3 46POZZ02 BRAKE FLUID SERVICE TECH(S):103247 161.24
 CUSTOMER REQUESTS A BRAKE SYSTEM FLUSH AND FLUID
 REPLACEMENT.
 COMPLETED BRAKE SYSTEM FLUSH AND FLUID REPLACEMENT.

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	PRICE
	1	000-043-203-666	BRAKE FLUID	48.76	48.76
TOTAL - PARTS					48.76

JOB# 3 TOTALS
 LABOR 161.24
 PARTS 48.76
 JOB# 3 JOURNAL PREFIX POCs JOB# 3 TOTAL 210.00

JOB# 4 CHARGES

LABOR

THANK YOU

SONNEN PORSCHE

INVOICE

900 REDWOOD HIGHWAY • MILL VALLEY, CA 94941


Ph: (415) 380-8000

PORSCHE

415-380-8000

BAR # AA 219898

CPA # CA109079064218

CUSTOMER NO. 104071	ADVISOR GARY WRIGHT	TAG NO. 942 1315	INVOICE DATE 04/09/13	INVOICE NO. POCS335739
 RONALD WISER 1301 FOWLER CREEK ROAD SONOMA, CA 95476	LICENSE NO. 6RTM534	MILEAGE 27,970	COLOR BLACK/	STOCK NO.
	YEAR / MAKE / MODEL 08 / PORSCHE / 911 CARRERA / 2DR CABRIOLET	VEHICLE ID. NO. WP0CB299185776111	DELIVERY DATE	DELIVERY MILES
	F.P.E. NO.	P.O. NO.	SELLING DEALER NO.	PRODUCTION DATE
RESIDENCE PHONE 415-796-4218	BUSINESS PHONE	COMMENTS	04/09/13	R.O. DATE

MO: 27971

LABOR-----

J# 4 99POZZRENTAL	INTERNAL RENTAL	TECH(S): 103247	INTERNAL
CUSTOMER PROVIDED GOOD WILL RENTAL VEHICLE BY SONNEN PORSCHE.			

SUBLET-----PO#-----VEND INV#-INV.DATE-DESCRIPTION-----

57261		04/09/13	CAR RENTAL	INTERNAL
TOTAL - SUBLET				0.00

JOB# 4 TOTALS-----

JOB# 4 JOURNAL PREFIX POCS JOB# 4 TOTAL 0.00

ESTIMATE-----
 CUSTOMER HEREBY ACKNOWLEDGES RECEIVING
 ORIGINAL ESTIMATE OF \$490.00 (+TAX)
 TOTALS-----

*****	TOTAL LABOR....	316.24
* [] CASH [] CHECK CK NO. [] *	TOTAL PARTS....	142.84
* [] VISA [] MASTERCARD *	TOTAL SUBLET...	0.00
* [] OTHER [] CHARGE *	TOTAL G.O.G....	0.00
*****	TOTAL MISC CHG.	0.00
	TOTAL MISC DISC	0.00
	TOTAL TAX.....	12.14
	TOTAL INVOICE \$	471.22

CUSTOMER SIGNATURE

THANK YOU



PORSCHE

The Porsche Multi-Point Inspection Report

The Porsche Multi-Point Inspection Report is a series of thorough vehicle "health checks" performed by factory-trained Porsche technicians. It is designed to keep your Porsche operating in top condition and to minimize your chances of being inconvenienced on the road. If additional service is recommended on any listed item, your Porsche Service Advisor will be happy to speak with you about your options.

Customer Name [REDACTED]

Year/Model 08/

Engine Size 3.8

RO/Tag 335739 Mileage 27,970

VIN

Date 4/9/10

Checked and Okay at this Time

May Require Future Attention

Requires Immediate Attention

Check Fluid Levels and Fill

OK	FILL	OK	FILL
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Engine Oil		Brake Reservoir	
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Windshield Washer		Headlamp Washer	
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Power Steering		Coolant Recovery Reservoir	
<input type="checkbox"/>	<input type="checkbox"/>		
Transmission (if equipped w/ dipstick)			

Check Following Systems / Components

- Operation of horn, interior lights, exterior lamps, turn signals, hazard and brake lamps
- Visually inspect headlamp alignment
- Windshield washer spray, wiper operation and wiper blades
- Windshield cracks and/or chips
- Heating, ventilation and air conditioning check
- Engine air cleaner filter
- Oil and/or fluid leaks
- Constant velocity (CV) drive axle boots (if equipped)
- Exhaust system (leaks, damage, loose parts)
- Steering and steering linkages
- Shocks/struts, air suspension and other suspension components for leaks and/or damage
- Brake system (including lines, hoses and parking brake)
- Engine cooling system, hoses and clamps
- Radiator, heater and air conditioning hoses for leaks / damage
- Accessory drive belt(s)
- Clutch operation (if equipped)
- State inspection due (if applicable) _____ / _____ / _____
Month Day Year
- Your last completed maintenance _____ Mileage ; _____ / _____
Month Year
- Your next factory scheduled maintenance is due at _____ Mileage ; _____ / _____
Month Year

Comments:


Check Battery Condition

- Good
 - Recharge
 - Bad
- Comments:

Check Brakes

Measure Front / Rear Brake Linings

- RF
- RR
- LF
- LR



Over 5mm or 7/32"

3 to 5mm or 4/32" to 7/32"

Less than 3mm or 4/32"

Brake Measurements Not Taken This Service Visit

Comments:

Check Tires

LF	TREAD DEPTH	RF
<input checked="" type="checkbox"/> 7/32" or Greater		<input checked="" type="checkbox"/> 7/32" or Greater
<input type="checkbox"/> 4/32" to 6/32"		<input type="checkbox"/> 4/32" to 6/32"
<input type="checkbox"/> 3/32" or Less		<input type="checkbox"/> 3/32" or Less
<input checked="" type="checkbox"/> 7/32" or Greater		<input checked="" type="checkbox"/> 7/32" or Greater
<input type="checkbox"/> 4/32" to 6/32"		<input type="checkbox"/> 4/32" to 6/32"
<input type="checkbox"/> 3/32" or Less		<input type="checkbox"/> 3/32" or Less
LR		RR
<input checked="" type="checkbox"/> <input type="checkbox"/> LF	Wear Pattern / Damage	RF <input checked="" type="checkbox"/> <input type="checkbox"/>
<input checked="" type="checkbox"/> <input type="checkbox"/> LR	Tire Wear Indicators	RR <input checked="" type="checkbox"/> <input type="checkbox"/>

Alignment Check Recommended

Wheel Balance Recommended

Comments:

Tire Pressure Set to

Factory Recommendations PSI 25 Front 30 Rear

This Courtesy Inspection Completed By Your Porsche Service Team

Service Advisor: _____

Technician: _____

Customer Signature: _____