



2011 Porsche Boxster Spyder

WP0CB2A89BS745442

Left Coast Classics
www.leftcoastclassics.com
707-332-8331

Hi-Tec Automotive

Independent Porsche & Audi Service & Sales
We buy, sell & consign cars!

Order Date 05/23/19 11:30 am

Paid: 05/23/19 04:52 pm

Invoice No. 16851

BAR #: AM 122034
779 Andersen Drive
San Rafael, CA 94901
Phone: 415-258-9619 FAX: 415-258-1627



11 PORSCHE BOXSTER black
43364 Mi. Last in 12/27/2016
Lic: CGNSPYD/CA H6Cyl 3.4
Vin: WP0CB2A89BS745442
Eq:

Oil Service, 997/987 II **Labor: \$180.00**

Replace engine oil and filter, set tire pressure, inspect vehicle for safety, re-set service indicator, test drive.

Brakes: front=9MM rear=7MM
Tires: front=6/32 rear=5/32

GASKET	Copper Gasket	1.0 @	1.00 =\$	1.00	
MOTUL 5W40	Engine Oil 102870	7.5 @	11.00 =\$	82.50	
9A1 107 224 00	Oil Filter OX366	1.0 @	28.50 =\$	28.50	112.00
				Job Subtotal: \$292.00	

Payments to Hi Tec Auto **Cost Summary**

Status: Paid Work Order

Payments: \$314.08
1 05/23/19 314.08 Visa 4

Labor	180.00
Parts	112.00
Haz Waste	12.00
Tax	10.08
Total	\$314.08
Payments	314.08
Bal Due	0.00

Thank you for choosing Hi Tec Auto

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) _____

Hi-Tec Automotive

Independent Porsche & Audi Service & Sales
We buy, sell & consign cars!

Order Date 12/27/16 09:49 am

Paid: 12/27/16 03:28 pm

Invoice No. 13000

BAR #: AM 122034

779 Andersen Drive

San Rafael, CA 94901

Phone: 415-258-9619 FAX: 415-258-1627

[Redacted Name]

[Redacted Address]

[Redacted City, CA 94947]

Home Phone: 415-244-5900

Work Phone: [Redacted]

12 PORSCHE BOXSTER black

41847 Mi.

Lic: CGNSPYD/CA H6Cyl 3.4

Vin: WPOCB2A89BS745442

Eq:

Oil Service, 997/987 II

Labor: \$155.00

Replace engine oil and filter, set tire pressure, inspect vehicle for safety, re-set service indicator.

Brakes: front= 10mm

rear=8mm

Tires: front=7/32

rear=6/32

MOBIL 1	Engine Oil	8.0 @	9.75 =\$	78.00	
GASKET	Copper Gasket	1.0 @	1.00 =\$	1.00	
948 107 222 00	Oil Filter	1.0 @	22.50 =\$	22.50	101.50
				Job Subtotal:	\$256.50

Payments to Hi Tec Auto

Status: Paid Work Order

Payments: \$273.89

1 12/27/16 273.89 Visa

02159d 004

Cost Summary

Labor	155.00
Parts	101.50
Haz Waste	8.00
Tax	9.39
Total	\$273.89
Payments	273.89
Bal Due	0.00

Thank you for choosing Hi Tec Auto

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) _____


Hi-Tec Automotive

Independent Porsche & Audi Service & Sales
We buy, sell & consign cars!

Order Date: 12/27/16 09:49 am

Work Order No. 13000

BAR #: AM 122034
779 Andersen Drive
San Rafael, CA 94901
Phone: 415-258-9619 FAX: 415-258-1627

 12 PORSCHE BOXSTER black
41847 Mi.
Lic: CGNSPYD/CA H6Cyl 3.4
Vin: WPOCB2A89BS745442
Eq:

Oil Service, 997/987 II Labor: 1.00 hrs
Replace engine oil and filter, set tire pressure, inspect vehicle for safety, re-set service indicator.

Brakes: front= 10 mm rear= 8 mm
Tires: front= 7 rear= 6

MOBIL 1	Engine Oil Evergreen	8.0 @	9.75 =\$	78.00	_____
GASKET	Copper Gasket Bulk	1.0 @	1.00 =\$	1.00	_____
948 107 222 00	Oil Filter OEA	1.0 @	22.50 =\$	22.50	_____

- CLEANED the HORN PAD. And LUBRICANT

Porsche 987 Minor Service Inspection

INTERIOR

- Horn *HORN SETS STUCK*
- Windshield wipers
- Windshield washer system
- Dash warning light illumination
- Interior Light function
- Exterior light function
- Opening and closing of doors, and window drop down function
- Hand Brake Operation
- Perform system scan test
- Clear Service light

FRONT

- Battery
 - scan test, CCA:
 - hold down
- Brake fluid scan *< 1% OK*
- Lubricate hinges
- Check sunroof/top drains
- Check and clear debris from radiators

REAR

- Coolant level and condition & inspect expansion tank
- Check top drains

UNDERSIDE

- Brake hose condition
- Brakes: front = 10 mm rear = 8 mm
 - additional observations:
- Tires: front = 7 rear = 6
 - additional observations:
- Wheel side/side & up/down free-play
- Engine oil leaks
- Transmission leaks
- Steering system leaks
- Axle boot condition
- Suspension damper leaks
- Suspension control arm and bushing condition
- Suspension sway bar end link condition
- Steering rack boot and tie rod condition
- Inspect oil filter for debris *NO DEBRIS*

TEST DRIVE

- Clutch engagement, smooth shifting, steering wheel centered and vehicle drives strait and even, vibration in steering wheel or vehicle at any speeds, clunks, rattles or other unusual noises, brake function, over all driving impression: *OK*

PAK

SONNEN PORSCHE

900 REDWOOD HIGHWAY • MILL VALLEY, CA 94941

Ph: (415) 380-8000

415-380-8000

2800 each


↑
Neil

PORSCHE

INVOICE

BAR # AA 219898

CRA # CA15902463900

CUSTOMER NO. 177500	ADVISOR TRISTAN BAYLESS	TAG NO. 1513	INVOICE DATE 07/03/15	INVOICE NO. POCS387186
	LICENSE NO. 6NKK555	MILEAGE 40,094	COLOR BLACK/	STOCK NO. B11501
	YEAR / MAKE / MODEL 11/PORSCHE/BOXSTER/2DR ROADSTER SPYD	DELIVERY DATE 11/02/10	DELIVERY MILES 31,058	
	VEHICLE I.D. NO. W P O C B 2 A 8 9 B S 7 4 5 4 4 2	SELLING DEALER NO.	PRODUCTION DATE 05/28/10	
	F.T.E. NO.	P.O. NO.	R.O. DATE 07/01/15	
RESIDENCE PHONE	BUSINESS PHONE	COMMENTS	MO: 40096	

JOB# 1 CHARGES-----

LABOR-----
 # 1 03POZ OIL CHNG / GEN MAINT TECH(S):2015 180.00
 OIL AND FILTER CHANGE, CHECK AND SET TIRE PRESSURE, TOP OFF
 FLUID LEVELS
 --- RESET SERVICE LIGHT ---
 COMPLETED OIL CHANGE SERVICE

PARTS-----QTY---FP-NUMBER-----DESCRIPTION-----UNIT PRICE-
 1 9A1-107-224-00 OIL-FILTER INSER 32.66 32.66
 1 900-123-106-30 ALUM SEAL RING 1.45 1.45
 9 040 MOBILE1 OW40 6.99 62.91
 TOTAL - PARTS 97.02

MISC-----CODE-----DESCRIPTION-----CONTROL NO-----
 P-WOF PORSCHE HAZ WASTE/OIL & FILTER 4.50
 P-DCP15 PORSCHE 15% DISCOUNT COUP PARTS -14.55
 TOTAL - MISC -10.05

JOB# 1 TOTALS-----
 LABOR 180.00
 PARTS 97.02
 MISC -10.05

JOB# 2 CHARGES----- JOB# 1 JOURNAL PREFIX POCS JOB# 1 TOTAL 266.97

LABOR-----
 # 2 03POZ002 MULTI POINT INSPECT TECH(S):2015 INTERNAL
 PERFORM COURTESY INSPECTION AS REQUESTED.CHECK BRAKES,TIRES,
 AND ALL EXTERIOR LIGHTS.CHECK OIL,BRAKE,COOLANT,AND WASHER
 FLUID LEVELS.PLEASE NOTE RESULTS BELOW
 PERFORMED INSPECTIONS AS PER ATTACHED CHECKLIST
 FRONT AND REAR TIRES AT 7/32" TREAD DEPTH
 FRONT AND REAR BRAKES AT 5MM+ PAD MATERIAL REMAINING
 RECOMMEND 40K MAJOR SERVICING

JOB# 2 TOTALS-----
 JOB# 2 JOURNAL PREFIX POCS JOB# 2 TOTAL 0.00

JOB# 3 CHARGES-----

LABOR-----
 # 3 99POZZSHUTTLE SHUTTLE RIDE TECH(S):98 INTERNAL
 CUSTOMER PROVIDED A SHUTTLE RIDE.
 CUSTOMER PICKED UP UPON REPAIR COMPLETION

JOB# 3 TOTALS-----
 JOB# 3 JOURNAL PREFIX POCS JOB# 3 TOTAL 0.00

JOB# 4 CHARGES-----

LABOR-----

THANK YOU

SONNEN PORSCHE

900 REDWOOD HIGHWAY • MILL VALLEY, CA 94941

Ph: (415) 380-8000

PORSCHE

415-380-8000

INVOICE

BAR # AA 219898

CPA # CA150020463900

CUSTOMER NO. 177500	ADVISOR TRISTAN BAYLESS	TAG NO. 1513	INVOICE DATE 07/03/15	INVOICE NO. POCS387186
RENE HENKE 35 CEDAR COURT MILL VALLEY, CA 94947	LICENSE NO. 6NKK555	MILEAGE 40,094	COLOR BLACK/	STOCK NO. B11501
	YEAR / MAKE / MODEL 11/PORSCHE/BOXSTER/2DR ROADSTER SPYD	DELIVERY DATE 11/02/10	DELIVERY MILES 31,058	PRODUCTION DATE 05/28/10
	VEHICLE I.D. NO. W P 0 C B 2 A 8 9 B S 7 4 5 4 4 2	SELLING DEALER NO.	R.O. DATE 07/01/15	
	F.T.E. NO.	P.O. NO.		
RESIDENCE PHONE	BUSINESS PHONE 415-244-5900	COMMENTS		

MO: 40096

LABOR-----
 J# 4+03POZ026K 40K 987/997 SVC TECH(S):2015 480.00
 PER RECOMMENDATION DUE TO TIME AND MILEAGE, PERFORM 40K MAJOR SERVICING AS PER PORSCHE MAINTENANCE SCHEDULE. COMPLETED 40,000 MILE INTERVAL SERVICE. PLEASE SEE ATTACHED CHECK LIST.

PARTS-----	QTY----	FP-NUMBER-----	DESCRIPTION-----	UNIT PRICE-	
	1	502	OIL COND.	14.95	14.95
	1	CRC	PART WASH	4.95	4.95
	1	997-571-219-01	CABIN-AIR FILTER	81.73	81.73
	1	987-110-133-00	AIR FILTER INSER	51.52	51.52
	6	999-170-130-90	SPARK PLUG	23.92	143.52
			TOTAL - PARTS		296.67

MISC-----	CODE-----	DESCRIPTION-----	CONTROL NO-----	
	P-WOF	PORSCHE HAZ WASTE/OIL & FILTER		4.50
	P-DCP15	PORSCHE 15% DISCOUNT COUP PARTS		-44.50
		TOTAL - MISC		-40.00

JOB# 4 TOTALS-----
 LABOR 480.00
 PARTS 296.67
 MISC -40.00
 JOB# 4 JOURNAL PREFIX POCS JOB# 4 TOTAL 736.67

JOB# 5 CHARGES-----

LABOR-----
 J# 5+46POZZ02 BRAKE FLUID SERVICE TECH(S):2015 160.00
 PER RECOMMENDATION DUE TO AGE, PERFORM A BRAKE FLUID FLUSH AND FLUID REPLACEMENT. COMPLETED BRAKE SYSTEM FLUSH AND FLUID REPLACEMENT.

PARTS-----	QTY----	FP-NUMBER-----	DESCRIPTION-----	UNIT PRICE-	
	1	000-043-203--666	BRAKE FLUID	37.50	37.50
			TOTAL - PARTS		37.50

MISC-----	CODE-----	DESCRIPTION-----	CONTROL NO-----	
	P-DCP15	PORSCHE 15% DISCOUNT COUP PARTS		-5.63
		TOTAL - MISC		-5.63

JOB# 5 TOTALS-----
 LABOR 160.00
 PARTS 37.50
 MISC -5.63
 JOB# 5 JOURNAL PREFIX POCS JOB# 5 TOTAL 191.87

ESTIMATE-----
 CUSTOMER HEREBY ACKNOWLEDGES RECEIVING ORIGINAL ESTIMATE OF \$0.00 (+TAX)
 APPROVED REVISED ESTIMATE (# 1) OF \$1200.00 (+TAX) ON 07/01/15 AT 01:32pm
 BY RENE HENKE COMMENTS OK FOR 40K & BRAKE FLUSH

THANK YOU

SONNEN PORSCHE

INVOICE

900 REDWOOD HIGHWAY • MILL VALLEY, CA 94941



Ph: (415) 380-8000

PORSCHE

415-380-8000

BAR # AA 219898

CPA # CA19020463900

CUSTOMER NO. 177500		ADVISOR TRISTAN BAYLESS 1513		TAG NO. 1752	INVOICE DATE 07/03/15	INVOICE NO. POCS387186	
		LICENSE NO. 6NKK555	MILEAGE 40,094	COLOR BLACK/	STOCK NO. B11501		
		YEAR / MAKE / MODEL 11/PORSCHE/BOXSTER/2DR ROADSTER SPYD		DELIVERY DATE 11/02/10	DELIVERY MILES 31,058		
		VEHICLE I.D. NO. W P 0 C B 2 A 8 9 B S 7 4 5 4 4 2		SELLING DEALER NO.	PRODUCTION DATE 05/28/10		
		F.T.E. NO.	P.O. NO.	R.O. DATE 07/01/15			
E RESIDENCE PHONE	BUSINESS PHONE 	COMMENTS		MO: 40096			

COMMENTS-----
SHUTTLE TO SAN RAFAEL

TOTALS-----

*****	TOTAL LABOR....	820.00
* [] CASH [] CHECK CK NO. [] *	TOTAL PARTS....	431.19
* [] VISA [] MASTERCARD *	TOTAL SUBLET...	0.00
* [] OTHER [] CHARGE *	TOTAL G.O.G....	0.00
*****	TOTAL MISC CHG.	9.00
	TOTAL MISC DISC	-64.68
	TOTAL TAX.....	36.65
	TOTAL INVOICE \$	1232.16

CUSTOMER SIGNATURE _____

THANK YOU



PORSCHE

The Porsche Multi-Point Inspection Report

The Porsche Multi-Point Inspection Report is a series of thorough vehicle "health checks" performed by factory-trained Porsche technicians. It is designed to keep your Porsche operating in top condition and to minimize your chances of being inconvenienced on the road. If additional service is recommended on any listed item, your Porsche Service Advisor will be happy to speak with you about your options.

Customer Name: [Redacted] Year/Model: '11 Boxster Spider 3.4L F6 Engine Size: 3.4L F6
 RO/Tag: [Redacted] Mileage: 40,094 VIN: WPA0CB2A89BS745442 Date: 7/2/15

Checked and Okay at this Time **May Require Future Attention** **Requires Immediate Attention**

Check Fluid Levels and Fill

OK	FILL	OK	FILL
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Engine Oil		Brake Reservoir	
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Windshield Washer		Headlamp Washer	
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Power Steering		Coolant Recovery Reservoir	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Transmission (if equipped w/ dipstick)			

Check Following Systems / Components



- Operation of horn, interior lights, exterior lamps, turn signals, hazard and brake lamps
- Visually inspect headlamp alignment
- Windshield washer spray, wiper operation and wiper blades
- Windshield cracks and/or chips
- Heating, ventilation and air conditioning check
- Engine air cleaner filter
- Oil and/or fluid leaks
- Constant velocity (CV) drive axle boots (if equipped)
- Exhaust system (leaks, damage, loose parts)
- Steering and steering linkages
- Shocks/struts, air suspension and other suspension components for leaks and/or damage
- Brake system (including lines, hoses and parking brake)
- Engine cooling system, hoses and clamps
- Radiator, heater and air conditioning hoses for leaks / damage
- Accessory drive belt(s)
- Clutch operation (if equipped)
- State inspection due (if applicable) / /
Month Day Year
- Your last completed maintenance Mileage ; /
Mileage Month Year
- Your next factory scheduled maintenance is due at / /
Mileage Month Year

Comments:

Check Battery Condition

Good Recharge Bad
 Comments:

Check Brakes



Over 5mm or 7/32"
 3 to 5mm or 4/32" to 7/32"
 Less than 3mm or 4/32"
 Brake Measurements Not Taken This Service Visit

Comments:

Check Tires

LF	TREAD DEPTH	RF
<input checked="" type="checkbox"/> 7/32" or Greater		<input checked="" type="checkbox"/> 7/32" or Greater
<input type="checkbox"/> 4/32" to 6/32"		<input type="checkbox"/> 4/32" to 6/32"
<input type="checkbox"/> 3/32" or Less		<input type="checkbox"/> 3/32" or Less
<input checked="" type="checkbox"/> 7/32" or Greater		<input checked="" type="checkbox"/> 7/32" or Greater
<input type="checkbox"/> 4/32" to 6/32"		<input type="checkbox"/> 4/32" to 6/32"
<input type="checkbox"/> 3/32" or Less		<input type="checkbox"/> 3/32" or Less
LR		RR


LF Wear Pattern / Damage RF
 LR Tire Wear Indicators RR
 Alignment Check Recommended Wheel Balance Recommended

Comments:

Tire Pressure Set to
 Factory Recommendations PSI Front Rear

This Courtesy Inspection Completed By Your Porsche Service Team

Service Advisor: TRISTAN BAPLESS
 Technician: Bryan Salvador
 Customer Signature: _____
 PNA 000 012 ed. 05/08





CARFAX® Vehicle History Report™


An independent company established in 1986


US \$39.99


Vehicle Information:
2011 PORSCHE BOXSTER S/SPYDER
 VIN:WP0CB2A89BS745442
 CONVERTIBLE
 3.4L H6 F
 GASOLINE
 REAR WHEEL DRIVE
[Standard Equipment](#) | [Safety Options](#)


 No accidents reported to CARFAX


 No damage reported to CARFAX

 **3** Previous owners

 **9** Service history records






 Types of owners: Personal lease, Personal








 **42,382** Last reported odometer reading



This CARFAX Vehicle History Report is based only on [information](#) supplied to CARFAX and available as of 7/1/19 at 4:54:37 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

 Ownership History	 Owner 1	 Owner 2	 Owner 3
The number of owners is estimated			
Year purchased	2010	2013	2015
Type of owner	Personal lease	Personal	Personal
Estimated length of ownership	2 yrs. 3 mo.	2 yrs. 1 mo.	4 yrs. 1 mo.
Owned in the following states/provinces	California	California	California
Estimated miles driven per year	13,380/yr	---	1,085/yr
Last reported odometer reading	31,058	39,307	42,382

 Title History	 Owner 1	 Owner 2	 Owner 3
CARFAX guarantees the information in this section			
Salvage Junk Rebuilt Fire Flood Hail Lemon	Guaranteed No Problem	Guaranteed No Problem	Guaranteed No Problem
Not Actual Mileage Exceeds Mechanical Limits	Guaranteed No Problem	Guaranteed No Problem	Guaranteed No Problem
 <p>GUARANTEED - None of these major title problems were reported by a state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, CARFAX will buy this vehicle back. Register View Terms View Certificate</p>			



 Additional History	 Owner 1	 Owner 2	 Owner 3
Not all accidents / issues are reported to CARFAX			
Total Loss No total loss reported to CARFAX.	 No Issues Reported	 No Issues Reported	 No Issues Reported

Structural Damage No structural damage reported to CARFAX.	No Issues Reported	No Issues Reported	No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	No Issues Reported	No Issues Reported	No Issues Reported
Odometer Check No indication of an odometer rollback.	No Issues Indicated	No Issues Indicated	No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	No Issues Reported	No Issues Reported	No Issues Reported
Manufacturer Recall Check with an authorized Porsche dealer for any open recalls.	No Recalls Reported	No Recalls Reported	No Recalls Reported
Basic Warranty Original warranty estimated to have expired. Interested in an extended warranty ?	Warranty Expired	Warranty Expired	Warranty Expired



Detailed History

[Glossary](#)

Owner 1	Date:	Mileage:	Source:	Comments:
Purchased: 2010 Type: Personal lease Where: California Est. miles/year: 13,380/yr Est. length owned: 9/2/10 - 12/25/12 (2 yrs. 3 mo.) Low mileage! This owner drove less than the industry average of 15,000 miles per year. 	07/15/2010	2	Porsche South Bay Hawthorne, CA 424-488-0729 porschesouthbay.com	Pre-delivery inspection completed
	07/15/2010	7	Pacific VW Hawthorne, CA 310-531-9400 lacarguy.com	Vehicle offered for sale
	09/02/2010	15	California Motor Vehicle Dept. Torrance, CA	Odometer reading reported Titled or registered as personal lease vehicle
	11/16/2010		California Motor Vehicle Dept. Torrance, CA	Title issued or updated First owner reported Loan or lien reported
	01/20/2012	16,863	Porsche South Bay Hawthorne, CA 424-488-0729 porschesouthbay.com	Tire condition and pressure checked
	02/20/2012	18,054	Porsche South Bay Hawthorne, CA 424-488-0729 porschesouthbay.com	Ignition switch replaced
	12/25/2012	30,991	Pacific VW Hawthorne, CA 310-531-9400 lacarguy.com	Vehicle offered for sale
	01/07/2013	31,002	Auto Auction Pacific Region	Listed as a dealer vehicle Vehicle sold
				 <div style="border: 1px solid black; padding: 5px; width: fit-content;"> Millions of used vehicles are bought and sold at auction every year. </div>
	01/14/2013		Porsche South Bay Hawthorne, CA 424-488-0729 porschesouthbay.com	Maintenance inspection completed Safety inspection performed

01/19/2013	31,019	California Inspection Station Mill Valley, CA	Passed emissions inspection
01/20/2013		Dealer Inventory	Vehicle offered for sale
01/21/2013		Sonnen Porsche San Rafael, CA 415-380-8000 sonnenporsche.com 4.8 ★★★★★ 25 Verified Reviews	Front brakes replaced Four tires balanced Four tires mounted Oil and filter changed Front brakes serviced Tire condition and pressure checked Safety inspection performed Cabin air filter replaced/cleaned Emissions inspection performed
02/05/2013		Dealer Inventory	Vehicle offered for sale
02/09/2013	31,058	Sonnen Porsche San Rafael, CA 415-380-8000 sonnenporsche.com 4.8 ★★★★★ 25 Verified Reviews	Vehicle sold

Owner 2
 Purchased: 2013
 Type: Personal
 Where: California
 Est. length owned: 2/21/13 - 3/21/15
 (2 yrs. 1 mo.)

Date:	Mileage:	Source:	Comments:
02/21/2013		California Motor Vehicle Dept. Hidden Valley Lake, CA	Title issued or updated New owner reported Loan or lien reported
06/06/2014	37,604	Sonnen Porsche San Rafael, CA 415-380-8000 sonnenporsche.com 4.8 ★★★★★ 25 Verified Reviews	Maintenance inspection completed Oil and filter changed
03/21/2015		Cammissa Motor Car Co Burlingame, CA 650-347-6677 cammisa.net	Vehicle washed/detailed Emissions inspection performed
03/21/2015		California Inspection Station	Passed safety inspection Passed emissions inspection
03/21/2015	39,293	Cammissa Motor Car Co Burlingame, CA 650-347-6677 cammisa.net	Vehicle offered for sale
04/23/2015	39,307	Cammissa Motor Car Co Burlingame, CA 650-347-6677 cammisa.net	Vehicle sold
05/14/2015		California Motor Vehicle Dept. Hidden Valley Lake, CA	Title issued or updated Loan or lien reported

Owner 3		Date:	Mileage:	Source:	Comments:
Purchased:	2015	05/16/2015		California Motor Vehicle Dept. Novato, CA	Title issued or updated New owner reported
Type:	Personal	07/01/2015	40,096	Sonnen Porsche San Rafael, CA 415-380-8000 sonnenporsche.com 4.8 ★★★★★ 25 Verified Reviews	Recommended maintenance performed Maintenance inspection completed 40,000 mile service performed Oil and filter changed Brake fluid flushed/changed
Where:	California	12/27/2016	41,847	Service Facility	Tire condition and pressure checked Oil and filter changed
Est. miles/year:	1,085/yr	08/08/2017	42,382	California Inspection Station	Passed safety inspection Passed emissions inspection
Est. length owned:	5/16/15 - present (4 yrs. 1 mo.)				

Low mileage!

This owner drove less than the industry average of 15,000 miles per year.



Have Questions? Please visit our Help Center at www.carfax.com.



Glossary

[View Full Glossary](#)

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

New Owner Reported

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us: [f facebook.com/CARFAX](https://www.facebook.com/CARFAX) [t @CarfaxReports](https://twitter.com/CarfaxReports)

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. CARFAX®

© 2019 CARFAX, Inc., a unit of IHS Markit. All rights reserved.

Covered by United States Patent Nos. 7,113,853; 7,778,841; 7,596,512, 8,600,823; 8,595,079; 8,606,648; 7,505,838.

7/1/19 4:54:37 PM (CDT)